



TXU Energy
Comanche Peak Steam
Electric Station
PO Box 1002 (E01)
Glen Rose, TX 76043
Tel. 254 897 8920
Fax 254 897 6652
lance.terry@txu.com

C. Lance Terry
Senior Vice President &
Principal Nuclear Officer

Ref. # 10CFR50.73(a)(2)(ii)(A)

CPSES-200203525
Log # TXX-02181
File # 10200

November 5, 2002

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)
DOCKET NO. 50-445
TECHNICAL SPECIFICATION REPORT FOR STEAM
GENERATORS MEETING C-3 CATEGORY
LICENSEE EVENT REPORT 445/02-002-00

Gentlemen:

Enclosed is Licensee Event Report (LER) 02-002-00 for Comanche Peak Steam
Electric Station Unit 1, "Steam Generator Tube Plugging".

JE22

A member of the **STARS** (Strategic Teaming and Resource Sharing) Alliance

Callaway • Comanche Peak • Diablo Canyon • Palo Verde • South Texas Project • Wolf Creek

TXX-02181

Page 2 of 2

This LER is submitted pursuant to CPSES Technical Specification 5.6.10.c. This report also meets the reporting requirements specified in CPSES Technical Specification 5.6.10.a. This communication contains the following new commitment which will be completed as noted:

Commitment Number

27274

Commitment

The condition of SG 1-02 tube R41 C71 will be more completely addressed in a supplement to this LER after consideration of results from the tubes that were removed for failure analysis.


The commitment number is used by TXU Generation Company LP for the internal tracking of CPSES commitments.

Sincerely,

TXU Generation Company LP

By: TXU Generation Management Company LLC,
Its General Partner

C. L. Terry
Senior Vice President and Principal Nuclear Officer


By: 
Roger D. Walker
Regulatory Affairs Manager

GLM/gm
Enclosures

c - E. W. Merschoff, Region IV
W. D. Johnson, Region IV
D. H. Jaffe, NRR
Resident Inspectors, CPSES

A member of the **STARS** (Strategic Teaming and Resource Sharing) Alliance

Callaway • Comanche Peak • Diablo Canyon • Palo Verde • South Texas Project • Wolf Creek

NRC FORM 366 (7-2001)				U.S. NUCLEAR REGULATORY COMMISSION				APPROVED BY OMB NO. 3150-0104 EXPIRES 07/31/2004 Estimated burden per response to comply with this mandatory information collection request 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records Management Branch (T-6 E6), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to bjs1@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor and a person is not required to respond to, the information collection.				
LICENSEE EVENT REPORT (LER)												
Facility Name (1) COMANCHE PEAK STEAM ELECTRIC STATION UNIT 1								Docket Number (2) 05000445		Page (3) 1 OF 5		
Title (4) TECHNICAL SPECIFICATION REPORT FOR STEAM GENERATORS MEETING C-3 CATEGORY												
Event Date (5)			LER Number (6)			Report Date (7)			Other Facilities Involved (8)			
Month	Day	Year	Year	Sequential Number	Revision Number	Month	Day	Year	Facility Name		Docket Numbers	
10	06	02	02	002	00	11	05	02	N/A		05000	
Operating Mode (9)			This report is submitted pursuant to the requirements of 10 CFR (Check all that apply) (11)									
6			20.2201(b)			20.2203(a)(3)(i)			50.73(a)(2)(i)(C)		50.73(a)(2)(vii)	
Power Level (10)			20.2201(d)			20.2203(a)(3)(ii)			X 50.73(a)(2)(ii)(A)		50.73(a)(2)(viii)(A)	
0			20.2203(a)(1)			20.2203(a)(4)			50.73(a)(2)(i)(B)		50.73(a)(2)(vii)(B)	
			20.2203(a)(2)(i)			50.36(c)(2)(i)(A)			50.73(a)(2)(iii)		50.73(a)(2)(ix)(A)	
			20.2203(a)(2)(ii)			50.36(c)(1)(ii)(A)			50.73(a)(2)(iv)(A)		50.72(a)(2)(x)	
			20.2203(a)(2)(iii)			50.36(c)(2)			50.73(a)(2)(v)(A)		73.71(a)(4)	
			20.2203(a)(2)(iv)			50.46(a)(3)(ii)			50.73(a)(2)(v)(B)		73.71(a)(5)	
			20.2203(a)(2)(v)			50.73(a)(2)(i)(A)			50.73(a)(2)(v)(C)		OTHER	
			20.2203(a)(2)(vi)			50.73(a)(2)(i)(B)			50.73(a)(2)(v)(D)		Specify in Abstract below or in NRC Form 366A	
Licensee Contact For This LER (12)												
Name Ben Mays - SMART Team I Systems Manager								Telephone Number (Include Area Code) 254-897-6816				
Complete One Line For Each Component Failure Described in This Report (13)												
Cause	System	Component	Manufacturer	Reportable To EPIX		Cause	System	Component	Manufacturer	Reportable To EPIX		
				N								
Supplemental Report Expected (14)								EXPECTED SUBMISSION DATE (15)		Month	Day	Year
X	YES (If YES, complete EXPECTED SUBMISSION DATE)				NO		03			31	03	
ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)												
<p>Comanche Peak Steam Electric Station (CPSES) Unit 1 was taken off line on September 28, 2002 for the ninth refueling outage (1RF09). As part of the scheduled surveillance requirements of CPSES Technical Specification (TS) 5.5.9, analysis of eddy current plus point testing data on the Steam Generators (SGs) indicated that greater than 1 percent of the total tubes inspected in 3 of 4 SGs were defective. The majority of the tube defects are attributed to circumferential outside diameter stress corrosion cracking (ODSCC) at the hot leg top of tubesheet (TTS) transition.</p> <p>TXU Generation Company LP (TXU Energy) has plugged and/or sleeved the defective tubes identified during the current refueling outage. With the exception of one tube (which is discussed in the Safety Consequences and Implications below), all defective tubes met the criteria of NUREG 1022, Revision 2, for structural integrity. TXU Energy maintains a comprehensive program to identify SG tube degradation.</p> <p>All times in this report are approximate and Central Daylight Savings Time unless noted otherwise.</p>												

LICENSEE EVENT REPORT (LER)

Facility Name (1)	Docket	LER Number (6)				Page(3)
		Year	Sequential Number	Revision Number		
COMANCHE PEAK STEAM ELECTRIC STATION UNIT 1	05000445	02	002	00		2 OF 5

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

I. DESCRIPTION OF REPORTABLE EVENT**A. REPORTABLE EVENT CLASSIFICATION**

The subject event is reportable pursuant to the requirements of CPSES TS 5.6.10, specifically 10CFR50.73(a)(2)(ii)(A).

B. PLANT OPERATING CONDITIONS PRIOR TO THE EVENT

On October 6, 2002, CPSES Unit 1 was in Mode 6, Refueling, during its ninth refueling outage.

C. STATUS OF STRUCTURES, SYSTEMS, OR COMPONENTS THAT WERE INOPERABLE AT THE START OF THE EVENT AND THAT CONTRIBUTED TO THE EVENT

Not Applicable – There were no structures, systems, or components that were inoperable at the start of the event which contributed to this event.

D. NARRATIVE SUMMARY OF THE EVENT, INCLUDING DATES AND APPROXIMATE TIMES

On September 28, 2002, CPSES Unit 1 began its ninth refueling outage. CPSES Technical Specification (TS) 5.5.9, "Steam Generator (SG) Tube Surveillance Program", requires that the results of each Steam Generator (EII: (AB)(SG)) tube inspection be classified as Category C-3 if more than 1 percent of the total tubes inspected are defective.

Additionally, if the results of the SG tube sample inspections are classified as Category C-3, then prompt NRC notification is required in accordance with TS 5.5.9 Table 5.5-2 and TS 5.6.10.c. During this ninth refueling outage, results of 3 SG inspections went into Category C-3 at separate times.

Two separate notifications were identified on the following dates and times:

1. On October 6, 2002, at 4:50 p.m., CPSES made notification of an event pursuant to the requirements of 10CFR50.72(b)(3)(ii)(A). The notification stated that analysis of eddy current testing data on SG 1-2 indicated that greater than 1 percent of the total tubes inspected in SG 1-2 were defective (Refer to NRC event number 39251).

LICENSEE EVENT REPORT (LER)

Facility Name (1)	Docket	LER Number (6)				Page(3)
COMANCHE PEAK STEAM ELECTRIC STATION UNIT 1	05000445	Year	Sequential Number	Revision Number		
		02	02	00	3 OF 5	

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

2. On October 6, 2002, at 9:30 p.m., CPSES made notification of an event pursuant to the requirements of 10CFR50.72(b)(3)(ii)(A). The notification stated that analysis of eddy current testing data on SGs 1-3 and 1-4 indicated that greater than 1 percent of the total tubes inspected in SGs 1-3 and 1-4 were defective (Refer to NRC event number 39251).

E. THE METHOD OF DISCOVERY OF EACH COMPONENT OR SYSTEM FAILURE, OR PROCEDURAL OR PERSONNEL ERROR

The defective tubes were found during scheduled eddy current testing of the CPSES Unit 1 SG tubing.

II. COMPONENT OR SYSTEM FAILURES

A. FAILURE MODE, MECHANISM, AND EFFECTS OF EACH FAILED COMPONENT

TXU Energy believes that the predominant degradation mechanism was ODSCC. Additional degradation mechanisms identified, to a very limited extent, (<0.5 percent) included Primary Water Stress Corrosion Cracking (PWSCC) and wear.

B. DURATION OF SAFETY SYSTEM TRAIN INOPERABILITY

Not Applicable – No safety system train was rendered inoperable.

C. SAFETY CONSEQUENCES AND IMPLICATIONS

The ODSCC associated with the hot leg expansion transition was found to be the predominant degradation mechanism seen during the CPSES 1RF09 inspection. A total of 667 tubes were repaired (plugged or sleeved) for this mode of degradation. SG 1-1 had 31 tubes affected; SG 1-2 had 186 tubes affected, SG 1-3 had 216 tubes affected, and SG 1-4 had 234 tubes affected. The total plugs and sleeves installed to date remain well below the 10 percent tube plugging allowance provided by the accident analysis described in CPSES FSAR Chapters 4 and 15. Eight tubes with ODSCC associated with the hot leg expansion transition were *in situ* pressure tested with no leakage or achieving the burst point.

However, during the *in situ* pressure testing on SG 1-02, tube R41 C71, leakage exceeded the pump capacity at 2.6 GPM and 2070 psig. Limited pump capacity prevented reaching the Structural Integrity Performance Criterion of NEI 97-06, "Steam Generator Program Guidelines," therefore meeting this criterion is indeterminate. Due to the inaccessibility of tube R41 C71 for removal, two tubes with similar indications to tube R41 C71 were removed

LICENSEE EVENT REPORT (LER)

Facility Name (1)	Docket	LER Number (6)			Page(3)
		Year	Sequential Number	Revision Number	
COMANCHE PEAK STEAM ELECTRIC STATION UNIT 1	05000445	02	02	00	4 OF 5

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

and sent to the vendor (Westinghouse) for failure analysis after successful *in situ* pressure testing was completed. It should be noted that 10 additional tubes with defects similar in nature to tube R41 C71 were also *in situ* pressure tested with satisfactory results. Actual SG tube leakage prior to the ninth refueling outage was well within the allowed CPSES TS limit of 150 gpd and there were no measurable offsite radiological consequences. The condition of SG 1-02 tube R41 C71 will be more completely addressed in a supplement to this LER after consideration of results from the tubes that were removed for failure analysis.

The condition of the tubes at the end of cycle (EOC) 9 for this damage mechanism meets the NRC accepted integrity levels. The number of indications for EOC 9 increased but the voltage amplitude distribution was equivalent to the results at the EOC 7 and EOC 8. Therefore, the structural and leakage integrity condition of the CPSES Unit 1 SGs is not significantly different from previous cycles and continues to meet the established regulations, codes, and standards, with the exception of tube R41 C71 as discussed above.

Based on the aforementioned, it was concluded that the event had no impact on the health and safety of the public

III. CAUSE OF THE EVENT

TXU Energy believes that the predominant damage mechanism (ODSCC) was caused by the temperature, chemistry, and residual stress effects on the tubing material (Inconel 600 MA).

IV. CORRECTIVE ACTIONS

TXU Energy believes that it has repaired the known defective tubes by plugging or sleeving as required by CPSES Technical Specifications.

V. PREVIOUS SIMILAR EVENTS

There have been three other previous events regarding SG inspections that went into Category C-3 at CPSES, which occurred during the SG tube inspections for the sixth, seventh, and eighth refueling outages. Corrective actions taken for the previous events would not have prevented this event.

LICENSEE EVENT REPORT (LER)

Facility Name (1)	Docket	LER Number (6)			Page(3)
COMANCHE PEAK STEAM ELECTRIC STATION UNIT 1	05000445	Year 02	Sequential Number 02	Revision Number 00	5 OF 5

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

VI. ADDITIONAL INFORMATION

The following information meets the requirements of the Special Report as defined in CPSES Technical Specification 5.6.10.a. Total tubes plugged and/or sleeved during this outage (this includes some previously plugged tubes which were recovered by sleeving):

CPSES UNIT 1 STEAM GENERATOR 1

48 tubes were plugged in this steam generator
 0 tubes were sleeved in this steam generator
 0 tubes were designated as an F* (as defined in CPSES TS) tube.

CPSES UNIT 1 STEAM GENERATOR 2

18 tubes were plugged in this steam generator
 213 tubes were sleeved in this steam generator
 0 tubes were designated as an F* (as defined in CPSES TS) tube.

CPSES UNIT 1 STEAM GENERATOR 3

23 tubes were plugged in the steam generator
 250 tubes were sleeved in this steam generator
 0 tubes were designated as an F* (as defined in CPSES TS) tube.

CPSES UNIT 1 STEAM GENERATOR 4

12 tubes were plugged in this steam generator
 273 tubes were sleeved in this steam generator
 0 tubes were designated as an F* (as defined in CPSES TS) tube.