

**Lewis Sumner**  
Vice President  
Hatch Project Support

**Southern Nuclear  
Operating Company, Inc.**  
40 Inverness Parkway  
Post Office Box 1295  
Birmingham, Alabama 35201  
  
Tel 205 992.7279  
Fax 205 992 0341



December 6, 2002

Docket No. 50-321

HL-6332

U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D.C. 20555

Edwin I. Hatch Nuclear Plant - Unit 1  
Licensee Event Report  
Water Level Transient Following Manual Reactor Scram  
Causes Group 2 PCIS Isolation

Ladies and Gentlemen:

In accordance with the requirements of 10 CFR 50.73(a)(2)(iv)(A), Southern Nuclear Operating Company is submitting the enclosed Licensee Event Report (LER) concerning a Group 2 Primary Containment Isolation System (PCIS) isolation resulting from a water level transient following a manual reactor scram.

Respectfully submitted,

A handwritten signature in black ink that reads "Lewis Sumner". The signature is written in a cursive, flowing style.

H. L. Sumner, Jr.

IFL/eb

Enclosure: LER 50-321/2002-005

cc: Southern Nuclear Operating Company  
Mr. P. H. Wells, Nuclear Plant General Manager  
SNC Document Management (R-Type A02.001)

U.S. Nuclear Regulatory Commission, Washington, D.C.  
Mr. Joseph Colaccino, Project Manager - Hatch

U.S. Nuclear Regulatory Commission, Region II  
Mr. L. A. Reyes, Regional Administrator  
Mr. J. T. Munday, Senior Resident Inspector - Hatch

Institute of Nuclear Power Operations  
LEREvents@inpo.org  
makucinjm@inpo.org

IE22

**LICENSEE EVENT REPORT (LER)**

(See reverse for required number of digits/characters for each block)

Estimated burden per response to comply with this mandatory information collection request: 50 hrs. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records Management Branch (T-6 E6), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to bjs1@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to,

1 FACILITY NAME  
Edwin I. Hatch Nuclear Plant - Unit 1

2. DOCKET NUMBER  
05000-321

3. PAGE  
1 OF 4

4 TITLE  
Water Level Transient Following Manual Reactor Scram Causes Group 2 PCIS Isolation

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER(S)
10	10	2002	2002	005	0	12	06	2002		05000
									FACILITY NAME	DOCKET NUMBER(S)
										05000
									FACILITY NAME	DOCKET NUMBER(S)
										05000

  

9. OPERATING MODE (9)	11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § : (Check all that apply)										
1	20.2201(b)	20.2203(a)(3)(ii)	50.73(a)(2)(ii)(B)	50.73(a)(2)(ix)(A)							
48.5	20.2201(d)	20.2203(a)(4)	50.73(a)(2)(iii)	50.73(a)(2)(x)							
	20.2203(a)(1)	50.36(c)(1)(i)(A)	X 50.73(a)(2)(iv)(A)	73.71(a)(4)							
	20.2203(a)(2)(i)	50.36(c)(1)(ii)(A)	50.73(a)(2)(v)(A)	73.71(a)(5)							
	20.2203(a)(2)(ii)	50.36(c)(2)	50.73(a)(2)(v)(B)	OTHER							
	20.2203(a)(2)(iii)	50.46(a)(3)(ii)	50.73(a)(2)(v)(C)	Specify in Abstract below or in NRC Form 366A							
	20.2203(a)(2)(iv)	50.73(a)(2)(i)(A)	50.73(a)(2)(v)(D)								
	20.2203(a)(2)(v)	50.73(a)(2)(i)(B)	50.73(a)(2)(vii)								
	20.2203(a)(2)(vi)	50.73(a)(2)(i)(C)	50.73(a)(2)(viii)(A)								
	20.2203(a)(3)(i)	50.73(a)(2)(ii)(A)	50.73(a)(2)(viii)(B)								

12. LICENSEE CONTACT FOR THIS LER

NAME Steven B. Tipps, Nuclear Safety and Compliance Manager, Hatch	TELEPHONE NUMBER (Include Area Code) (912) 537-5880
---	--

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX

14. SUPPLEMENTAL REPORT EXPECTED

YES (If yes, complete EXPECTED SUBMISSION DATE)	NO X	15. EXPECTED SUBMISSION DATE	MONTH	DAY	YEAR

16. ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On 10/10/2002 at 2220 EST, Unit 1 was in the Run mode at an approximate power level of 1341 CMWT (48.5 percent rated thermal power). At that time, Operations personnel manually scrambled the reactor per procedure 34GO-OPS-013-1S, "Normal Plant Shutdown," for a planned Unit outage for the replacement of three Safety Relief Valve (SRV) main bodies. Following the manual scram, water level decreased due to void collapse from the rapid reduction in power, reaching a minimum of approximately minus 10 inches (about 148 inches above the top of the active fuel). The decrease in water level resulted in receipt of a Group 2 Primary Containment Isolation System (PCIS) isolation signal and closure of the Group 2 Primary Containment Isolation Valves per design. The operating Reactor Feedwater Pump restored level to its desired value. Personnel reset the Group 2 isolation signal and restored the isolation valves to normal per procedure 34AB-C71-001-1S, "Scram Procedure."

This event was the result of the expected water level decrease from void collapse and proceduralized operator action following a reactor scram. Operations personnel increased water level to approximately 45.5 inches, about eight to ten inches above the normal operating level, in anticipation of the level decrease. Nevertheless, water level decreased to a point below the Group 2 PCIS isolation setpoint. Personnel actions were in accordance with approved procedures. These procedural instructions will be evaluated for revision, if needed, to improve the methodology used for reactor vessel level control during planned shutdowns.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL YEAR	REVISION NUMBER	
Edwin I. Hatch Nuclear Plant - Unit 1	05000-321	2002	-- 005	-- 00	2 OF 4

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

PLANT AND SYSTEM IDENTIFICATION

General Electric - Boiling Water Reactor  
Energy Industry Identification System codes appear in the text as (EIIIS Code XX).

DESCRIPTION OF EVENT

On 10/10/2002 at 2220 EST, Unit 1 was in the Run mode at an approximate power level of 1341 CMWT (48.5 percent rated thermal power). At that time, Operations personnel manually scrammed the reactor per plant procedure 34GO-OPS-013-1S, "Normal Plant Shutdown," to complete a planned reactor shutdown. Three Safety Relief Valves' main bodies, 1B21-F013J, K, and L were being replaced with refurbished main valve bodies. Therefore, the reactor was shut down to allow plant personnel to isolate and replace these valve bodies. Prior to inserting the manual scram signal, Operations personnel increased reactor vessel water level to approximately 45.5 inches, about eight to ten inches above the normal operating level, in anticipation of a level decrease caused by the planned scram.

Following the manual scram, vessel water level decreased due to void collapse from the rapid reduction in power, reaching a minimum of approximately minus ten inches (about 148 inches above the top of the active fuel). The decrease in water level resulted in receipt of Reactor Protection System (EIIIS Code JC) actuation and Group 2 Primary Containment Isolation System (PCIS, EIIIS Code JM) isolation signals on low reactor vessel water level. The Group 2 Primary Containment Isolation Valves (EIIIS Code JM) closed per design. Because the preceding manual scram resulted in the insertion of the control rods (EIIIS Code JD), the Reactor Protection System actuation on low water level did not result in control rod movement.

The operating Reactor Feedwater Pump (EIIIS Code SJ) automatically restored water level to the desired value. Operations personnel confirmed the Group 2 PCIS isolation valves closed as expected, reset the Group 2 isolation signal, and restored the isolation valves to their normal positions per plant procedure 34AB-C71-001-1S, "Scram Procedure."

CAUSE OF EVENT

This event was the result of the expected water level decrease from void collapse and proceduralized operator action following a reactor scram. Operations personnel increased water level to approximately 45.5 inches, about eight to ten inches above the normal operating level, in anticipation of the level decrease. Nevertheless, water level decreased to a point below the Group 2 PCIS isolation setpoint resulting in receipt of a Group 2 PCIS isolation signal and closure of the Group 2 isolation valves per design. Personnel actions were in accordance with approved procedures. These procedural instructions will be evaluated for revision, if needed, to improve the methodology used for reactor vessel level control during planned shutdowns.

**LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION**

FACILITY NAME (1)	DOCKET	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL YEAR	REVISION NUMBER	
Edwin I. Hatch Nuclear Plant - Unit 1	05000-321	2002	-- 005	-- 00	3 OF 4

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

REPORTABILITY ANALYSIS AND SAFETY ASSESSMENT

This report is required by 10 CFR 50.73 (a)(2)(iv) because of the unplanned actuation of Engineered Safety Feature systems. Following a manual scram, reactor vessel water level decreased due to void collapse. Level reached a minimum of about minus ten inches (about 148 inches above the top of the active fuel). The decrease in water level resulted in automatic Reactor Protection System actuation and Group 2 PCIS isolation on low water level and closure of the Group 2 Primary Containment Isolation Valves per design. The Reactor Protection System and PCIS are Engineered Safety Feature systems.

The operating Reactor Feedwater Pump automatically restored water to its desired value. Operations personnel verified correct system response and restored the isolation valves to their normal positions.

All systems functioned as expected and per their design given the water level transient. Water level was maintained well above the top of the active fuel throughout the transient and was restored to its desired value without the need for emergency core cooling system actuation. Therefore, it is concluded the event had no adverse impact on nuclear safety. This analysis is applicable to all power levels.

CORRECTIVE ACTIONS

Plant Hatch will take the following actions to prevent recurrence prior to the next Unit 2 scheduled refueling outage:

1. A comprehensive review will be performed to address both operational and engineering aspects of the optimum plant configuration and operational methodology for a planned reactor shutdown. An evaluation will be performed of the applicable operating and abnormal procedures to allow better operation in a broad set of conditions. Procedures will be revised, if needed, to reflect the results of these reviews.
2. The limitations of simulator and other training experience will be factored into the bases for changes in operating procedures to accomplish an optimum plant configuration for a planned reactor shutdown.

ADDITIONAL INFORMATION

Other Systems Affected: No systems other than those already mentioned in this report were affected by this event.

Failed Components Information: No failed components directly caused or resulted from this event.

Commitment Information: This report does not create any permanent licensing commitments.

**LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION**

FACILITY NAME (1)	DOCKET	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL YEAR	REVISION NUMBER	
Edwin I. Hatch Nuclear Plant - Unit 1	05000-321	2002	-- 005	-- 00	4 OF 4

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

Previous Similar Events: There has been one previous similar event in the past two years in which a planned manual reactor scram at low power level resulted in unplanned Engineered Safety Feature system actuations. In this event, reported in Licensee Event Report 50-321/2000-012, dated 12/1/2000, Unit 1 was scrammed manually with power level at approximately 16 percent rated thermal power. The resulting water level transient caused the Group 2 Primary Containment Isolation Valves to close on low reactor vessel water level. During this event, personnel actions, procedural instructions, and equipment operation were considered appropriate for the situation. Therefore, no corrective actions were required.