

December 20, 2002

Mr. J. A. Scalice  
Chief Nuclear Officer and  
Executive Vice President  
Tennessee Valley Authority  
6A Lookout Place  
1101 Market Street  
Chattanooga, Tennessee 37402-2801

SUBJECT: WATTS BAR NUCLEAR PLANT, UNIT 1 — SUMMARY OF CONFERENCE  
CALL WITH TENNESSEE VALLEY AUTHORITY CONCERNING THE 2002  
STEAM GENERATOR INSPECTION RESULTS (TAC NO. MB4425)

Dear Mr. Scalice:

On March 8, 2002, U.S. Nuclear Regulatory Commission staff held a conference call with Tennessee Valley Authority representatives regarding the ongoing steam generator tube inspection activities at Watts Bar Unit 1. Enclosed is a brief summary of the conference call. This letter closes TAC No. MB4425. Please contact me if you have any questions.

Sincerely,

***/RA/***

L. Mark Padovan, Project Manager, Section 2  
Project Directorate II  
Division of Licensing Project Management  
Office of Nuclear Reactor Regulation

Docket No. 50-390

Enclosure: Call summary

cc w/enclosure: See next page

December 20, 2002

Mr. J. A. Scalice  
Chief Nuclear Officer and  
Executive Vice President  
Tennessee Valley Authority  
6A Lookout Place  
1101 Market Street  
Chattanooga, Tennessee 37402-2801

SUBJECT: WATTS BAR NUCLEAR PLANT, UNIT 1 — SUMMARY OF CONFERENCE  
CALL WITH TENNESSEE VALLEY AUTHORITY CONCERNING THE 2002  
STEAM GENERATOR INSPECTION RESULTS (TAC NO. MB4425)

Dear Mr. Scalice:

On March 8, 2002, U.S. Nuclear Regulatory Commission staff held a conference call with Tennessee Valley Authority representatives regarding the ongoing steam generator tube inspection activities at Watts Bar Unit 1. Enclosed is a brief summary of the conference call.

This letter closes TAC No. MB4425. Please contact me if you have any questions.

Sincerely,

*/RA/*

L. Mark Padovan, Project Manager, Section 2  
Project Directorate II  
Division of Licensing Project Management  
Office of Nuclear Reactor Regulation

Docket No. 50-390

Enclosure: Call summary

cc w/enclosure: See next page

DISTRIBUTION:

PUBLIC	PDII-2 R/F	BFu	AHowe
BClayton (Hard Copy)	CKahn	MPadovan	LLund
OGC	ACRS	SCahill, RII	HBerkow
KKarwoski	MLesser		

ADAMS ACCESSION NO.ML023540520

OFFICE	PDII-2/PM		PDII-2/LA		PDII-2/SC	
NAME	MPadovan		BClayton		AHowe	
DATE	12/10/02		12/10/02		12/10/02	

OFFICIAL RECORD COPY

SUMMARY OF CONFERENCE CALL WITH  
TENNESSEE VALLEY AUTHORITY  
REGARDING 2002 STEAM GENERATOR INSPECTION RESULTS  
AT WATTS BAR UNIT 1

The U.S. Nuclear Regulatory Commission (NRC) staff participated in a conference call with Tennessee Valley Authority on March 8, 2002, to discuss the plans and preliminary results of the steam generator tube inspection activities at Watts Bar Unit 1. Topics discussed during the conference call consisted of the following:

- eddy current testing scope
- scope expansion plans
- indications identified to date
- repair/plugging plans
- new inspection findings
- in-situ pressure test plans
- actions taken in response to lessons learned from the Indian Point 2 tube failure

The inspection scope included a full length bobbin coil examination of 100 percent of the tubes in each of the four steam generators. In addition to the bobbin coil examinations, the plus-point probe was used to inspect the following:

- hot-leg (HL) top of the tubesheet (TTS) region for 100 percent of the tubes
- 100 percent of the hot-leg dented intersections over 2 volts
- 20 percent of freespan dings on the cold-leg side
- 100 percent of dents in the preheater region over 5 volts
- U-bend region of 100 percent of Row 1 and 20 percent of Row 2

The expansion criteria included the following:

- For TTS, if the results were categorized as C-3 as defined in the plant's technical specifications, the inspection would be expanded to include a 20 percent sample of the cold-leg tubes.
- For the U-bend region, if one indication is detected in Row 2, the inspection will be expanded to include 100 percent of the Row 2 tubes plus 20 percent of the Row 3 tubes in all four steam generators.
- For tube support plate (TSP) dented intersections, if a circumferential indication is detected at dents between 2 and 5 volts, the scope will be expanded to include 100 percent of the dents between 1 and 2 volts. If one circumferential indication is detected between 1 and 2 volts, the licensee will develop an expansion criteria for dents less than 1 volt which would include an evaluation of whether structural integrity would be affected by indications at dents less than 1 volt so as to warrant an inspection of these dents.

Enclosure

- At the time of this conference call, the inspections were 58 percent complete. As a result of the inspections, a large number of outside diameter (OD) circumferential indications were detected at TTS on the HL side. The licensee had predicted to have between 30 to 40 TTS circumferential indications. However, at the time of the call, 138 indications were identified. Specifically, 15 were identified in steam generator 1, 25 in steam generator 2, 16 in steam generator 3, and 82 in steam generator 4. The licensee is investigating the reason for the higher number of indications in steam generator 4. Plus-point voltages for these indications are very low (less than 1 volt). The licensee stated that the indications are believed to be circumferential segments (rather than one discrete crack) and shallow based on the low plus-point voltages.

The licensee adopted a more stringent in situ testing screening criteria for these indications than would be required by the Electric Power Research Institute (EPRI) Guidelines. Regardless of the depth of the indications, the licensee planned to in situ pressure test all indications with arc lengths exceeding 180 degrees. Based on the inspection results at the time of the call, the licensee planned to in situ pressure test the following:

- 3 tubes with circumferential indications in steam generator 1 (193°, 242°, 261° in arc length, respectively)
- 1 tube in steam generator 2 (210° in arc length)
- 2 tubes in steam generator 3 (267°, 299° in arc length, respectively)
- 12 tubes in steam generator 4 (185°, 196°, 236°, 245°, 269°, 286°, 291°, 300°, 309°, 314°, 333°, 360° in arc length, respectively)

Furthermore, the licensee planned to in situ pressure test the indication with the highest plus-point voltage in each steam generator. All in situ tests are partial length.

In addition to the circumferential OD Stress Corrosion Cracking (ODSCC) at the HL TTS, the licensee also detected the following:

- 21 axial primary water stress corrosion cracking (PWSCC) indications
- 1 circumferential PWSCC indication
- 2 axial ODSCC indications at the HL TTS

The licensee indicated that even though this is the first time circumferential PWSCC and axial ODSCC were detected at TTS, it was not unexpected given the industry experience with mill annealed alloy 600 tubing.

Although the licensee expected to have approximately 200 axial ODSCC indications at TSPs, only 58 axial ODSCC indications were detected at the time of the call. Seven of these are over 1 volt and will be plugged. The rest will be left in service based on the Generic Letter 95-05 Alternate Repair Criteria.

The licensee reviewed prior eddy current data to determine if indications would be identified with hindsight. The preliminary results indicated only about 20 to 25 percent of the indications were present in the last outage in 2000. The licensee also discussed lessons learned from the Indian Point Unit 2 tube failure and stated that they do not have a noise concern because the signal to noise ratio is significantly higher than the EPRI qualification data set.

The licensee stated that they had not found any locations with mix-mode indications (i.e., both axial and circumferential flaws at the same location). The licensee also stated that there was no detectable primary-to-secondary side leakage prior to shut-down. The licensee did not perform a secondary-side pressure test, nor did they plan to pull a tube for destructive examination. At the time of the call, the licensee did not identify any indications in the U-bend region.

The licensee indicated that they will promptly notify the NRC staff if they find any new degradation mechanisms, if any tube fails the structural and leakage integrity criteria during in situ testing, or if they detect any unusual indications.

Based on the information discussed during the conference calls, the staff did not identify any issues requiring further discussion.

Mr. J. A. Scalice  
Tennessee Valley Authority

**WATTS BAR NUCLEAR PLANT**

cc:

Mr. Karl W. Singer, Senior Vice President  
Nuclear Operations  
Tennessee Valley Authority  
6A Lookout Place  
1101 Market Street  
Chattanooga, TN 37402-2801

Mr. Paul L. Pace, Manager  
Licensing and Industry Affairs  
Watts Bar Nuclear Plant  
Tennessee Valley Authority  
P.O. Box 2000  
Spring City, TN 37381

Mr. James E. Maddox, Acting Vice President  
Engineering & Technical  
Tennessee Valley Authority  
6A Lookout Place  
1101 Market Street  
Chattanooga, TN 37402-2801

Mr. Larry S. Bryant, Manager  
Watts Bar Nuclear Plant  
Tennessee Valley Authority  
P.O. Box 2000  
Spring City, TN 37381

Mr. William R. Lagergren  
Site Vice President  
Watts Bar Nuclear Plant  
Tennessee Valley Authority  
P.O. Box 2000  
Spring City, TN 37381

Senior Resident Inspector  
Watts Bar Nuclear Plant  
U.S. Nuclear Regulatory Commission  
1260 Nuclear Plant Road  
Spring City, TN 37381

General Counsel  
Tennessee Valley Authority  
ET 11A  
400 West Summit Hill Drive  
Knoxville, TN 37902

Rhea County Executive  
375 Church Street  
Suite 215  
Dayton, TN 37321

Mr. Robert J. Adney, General Manager  
Nuclear Assurance  
Tennessee Valley Authority  
6A Lookout Place  
1101 Market Street  
Chattanooga, TN 37402-2801

County Executive  
Meigs County Courthouse  
Decatur, TN 37322

Mr. Mark J. Burzynski, Manager  
Nuclear Licensing  
Tennessee Valley Authority  
4X Blue Ridge  
1101 Market Street  
Chattanooga, TN 37402-2801

Mr. Lawrence E. Nanney, Director  
Division of Radiological Health  
Dept. of Environment & Conservation  
Third Floor, L and C Annex  
401 Church Street  
Nashville, TN 37243-1532

Ms. Ann P. Harris  
341 Swing Loop Road  
Rockwood, Tennessee 37854