

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF NUCLEAR MATERIAL SAFETY AND SAFEGUARDS
WASHINGTON, D.C. 20555

January 7, 1993

NRC INFORMATION NOTICE NO. 93-04: INVESTIGATION AND REPORTING OF
MISADMINISTRATIONS BY THE RADIATION
SAFETY OFFICER

Addressees

All U.S. Nuclear Regulatory Commission medical licensees.

Purpose

The NRC is issuing this information notice to provide guidance to licensees on the investigation of events surrounding a misadministration. On January 27, 1992, the "Quality Management Program and Misadministrations" rule became effective. The current (1992) 10 CFR 35.33(a)(2) requires that a report of a misadministration must be submitted to NRC and must include, in part, why the event occurred. This superseded the previous requirement in 10 CFR 35.33(c) that the Radiation Safety Officer (RSO) should promptly investigate the cause of a diagnostic misadministration and make a record for NRC review. Furthermore, in 10 CFR 35.21(b)(1), the RSO is required, in part, to investigate overexposures and misadministrations, and implement corrective action, as necessary. Information contained in this notice does not constitute a new requirement, and no written response is required.

Description of Circumstances

The following case of a diagnostic misadministration reported to the NRC involved inaccurate information provided by the licensee and a failure of the RSO to adequately investigate the incident.

A diagnostic misadministration report (DMR), submitted by the licensee, stated that a nuclear medicine technologist, called in from vacation to administer a dose of I-131 sodium iodide for a thyroid uptake study, inadvertently administered 112 microcuries instead of the intended dose of 10 microcuries. The DMR indicated that the error occurred because the technologist incorrectly read the dose calibrator as 11.2 microcuries instead of 112 microcuries. This implies that the technologist assayed a single iodine capsule, which she subsequently administered to the patient. The DMR also stated that, instead of five capsules for a total of 100 microcuries, an order was placed for five capsules of 100 microcuries each. No explanation was provided for the order of five 20 microcurie capsules for a diagnostic procedure utilizing 10 microcuries. During the inspection, the technologist indicated that she had assayed five capsules at the same time and then mathematically determined the activity of a single capsule. Thus the measured activity expressed on the dose calibrator would have read 560 microcuries instead of 112 microcuries as reported in the licensee's report. This inaccuracy of the DMR obscured a

9212300319

PDR I RE Notice 93-004 930107
ID&R-11c 1/11

ccj

violation of 10 CFR 35.53 involving a failure to assay each dosage before administration, which very likely contributed to the misadministration. The RSO was also on vacation at the time of the incident and was not made aware of it until his return. There were inconsistencies between the DMR and verbal explanations of the misadministration event given by the licensee's technologists during an NRC inspection. The RSO indicated that he performed an investigation, but he did not personally make a report or maintain any records of the investigation, and his efforts did not uncover the fact that the DMR, which was prepared by the Chief Technologist, was inaccurate and inconsistent. Thus, the violation of 10 CFR 35.53 remained uncorrected, and could have resulted in future misadministrations.

Discussion:

Although this event occurred before January 27, 1992, and therefore was defined as a misadministration under the old rule, it would continue to meet the definition of a misadministration under the "Quality Management Program and Misadministrations" rule. Of greater importance, however, is the lack of complete and accurate information in the misadministration report and the failure of the RSO to identify and investigate the cause of the misadministration and implement the necessary corrective action. 10 CFR 30.9(a) requires, in part, that information provided to the Commission by a licensee or information required by the Commission's regulations to be maintained by the licensee must be complete and accurate in all material respects.

Currently, 10 CFR 35.33(a)(2) requires, in part, that the licensee submit a written report within 15 days after the discovery of a misadministration to include a brief description of the event, why the event occurred, effect on the patient, necessary improvements to prevent recurrence, and actions taken to prevent recurrence as well as other information. 10 CFR 35.21(a) states, in part, that the licensee, through the RSO, shall ensure that radiation safety activities are being performed in accordance with approved procedures and regulatory requirements in the daily operation of the licensee's byproduct material program. Furthermore, 10 CFR 35.21(b)(1) requires, in part, that the RSO shall investigate misadministrations, and implement corrective action, as necessary. An investigation may include: 1) talking to all persons involved in the misadministration, to include the technologists, authorized user, and patient (if acceptable to the referring physician and necessary to the investigation), in order to determine the correct details and sequence of events; 2) reviewing the records associated with the procedure including the requesting physician's order(s) and/or the written directive; 3) performing an independent assessment of the dose delivered to the patient; and 4) reviewing any other circumstances associated with the incident. This information would be used to identify the best course of corrective action. If there appear to be any discrepancies, the RSO should reexamine all the available information to resolve these discrepancies and make the best determination of the root cause of the misadministration.

Licensees should ensure that the RSO at their facility is aware of and understands the requirements to: 1) conduct a thorough investigation

following a misadministration; 2) determine improvements needed to prevent recurrence; 3) implement any necessary corrective action; 4) submit a written report of the investigation as stated above; and 5) retain a record for five years of the written report and any other records required by 10 CFR 35.33. Furthermore, it is essential that the RSO provide sufficient time and attention to fulfill properly his/her radiation safety program responsibilities, including all of the requirements in 10 CFR 35.21.

This information notice requires no specific action or written response. If you have any questions about the information in this notice, please contact the technical contact listed below, or the appropriate NRC regional office.

Richard E. Cunningham

Richard E. Cunningham, Director
Division of Industrial and
Medical Nuclear Safety
Office of Nuclear Material Safety
and Safeguards

Technical contact: Patricia K. Holahan, NMSS
(301) 504-2694

Attachments:

1. List of Recently Issued NMSS Information Notices
2. List of Recently Issued NRC Information Notices

See file jacket

LIST OF RECENTLY ISSUED
 NRC INFORMATION NOTICES

Information Notice No.	Subject	Date of Issuance	Issued to
93-03	Recent Revision to 10 CFR Part 20 and Change of Implementation Date to January 1, 1994	01/05/93	All byproduct, source, and special nuclear material licensees.
93-02	Malfunction of A Pressurizer Code Safety Valve	01/04/93	All holders of OLs or CPs for nuclear power reactors.
93-01	Accuracy of Motor-Operated Valve Diagnostic Equipment Manufactures by Liberty Technologies	01/04/93	All holders of OLs or CPs for nuclear power reactors.
92-86	Unexpected Restriction to Thermal Growth of Reactor Coolant Piping	12/24/92	All holders of OLs or CPs for nuclear power reactors.
92-85	Potential Failures of Emergency Core Cooling Systems Caused by Foreign Material Blockage	12/23/92	All holders of OLs or CPs for nuclear power reactors.
92-84	Release of Patients Treated with Temporary Implants	12/17/92	All Nuclear Regulatory Commission Medical Licensees
88-23, Supp. 4	Potential for Gas Binding of High-Pressure Safety Injection Pumps during A Design Basis Accident	12/18/92	All holders of OLs or CPs for nuclear power reactors.
92-83	Thrust Limits for Limitorque Actuators and Potential Over-stressing of Motor-Operated Valves	12/17/92	All holders of OLs or CPs for nuclear power reactors.

OL = Operating License
 CP = Construction Permit

LIST OF RECENTLY ISSUED
NMSS INFORMATION NOTICES

Information Notice No.	Subject	Date of Issuance	Issued to
93-03	Recent Revision to 10 CFR Part 20 and Change of Implementation Date to January 1, 1994	01/05/93	All byproduct, source, and special nuclear material licensees.
92-84	Release of Patients Treated with Temporary Implants	12/17/92	All Nuclear Regulatory Commission Medical Licensees.
92-72	Employee Training and Shipper Registration Requirements for Transporting Radioactive Materials	10/18/92	All U.S. Nuclear Regulatory Commission Licensees.
92-62	Emergency Response Information Requirements for Radioactive Material Shipments	08/24/92	All U.S. Nuclear Regulatory Commission Licensees.
92-58	Uranium Hexafluoride Cylinders - Deviations in Coupling Welds	08/12/92	All fuel cycle licensees.
92-38	Implementation Date for the Revision to the EPA Manual of Protective Action Guides and Protective Actions for Nuclear Incidents	05/12/92	All holders of OLs or CPs for nuclear power reactors, non-power reactors and materials licensees authorized to possess large quantities of radioactive material.
92-37	Implementation of the Deliberate Misconduct Rule	05/08/92	All Nuclear Regulatory Commission Licensees.
92-34	New Exposure Limits for Airborne Uranium and Thorium	05/06/92	All licensees whose operations can cause airborne concentrations of uranium and thorium.

following a misadministration; 2) determine improvements needed to prevent recurrence; 3) implement any necessary corrective action; 4) submit a written report of the investigation as stated above; and 5) retain a record for five years of the written report and any other records required by 10 CFR 35.33. Furthermore, it is essential that the RSO provide sufficient time and attention to fulfill properly his/her radiation safety program responsibilities, including all of the requirements in 10 CFR 35.21.

This information notice requires no specific action or written response. If you have any questions about the information in this notice, please contact the technical contact listed below, or the appropriate NRC regional office.

Richard E. Cunningham, Director
 Division of Industrial and
 Medical Nuclear Safety
 Office of Nuclear Material Safety
 and Safeguards

Technical contact: Patricia K. Holahan, NMSS
 (301) 504-2694

Attachments:

1. List of Recently Issued NMSS Information Notices
2. List of Recently Issued NRC Information Notices

See previous concurrence*

OFC	IMAB *		IMAB *		IMAB *		IMOB *	
NAME	PKHolahan		LWCamper		JEGlenn		FCombs	
DATE	12/16/92		12/17/92		12/18/92		12/22/92	
OFC	OGC *		DD/IMNS *		D/IMNS *		TechEd *	
NAME	STreby		JTGreeves		RECunningham		EKraus	
DATE	12/29/92		12/29/92		12/30/92		08/04/92	

Ticket

DATE RECEIVED: 10/22/92 ORIGINAL DUE DT: 01/05/93 CONTROL NO: 9200608
DIVISION DATE: 12/30/92 DOC DT: 10/19/92
FROM: TIME: COMP DT:

Taylor/Holahan
EDO/NMSS

TO:

Commission

FOR SIGNATURE OF: ** SPEC ** SECY NO:

ASSIGNED TO: CONTACT:
IMNS Camper/Holahan

DESC: ROUTING:
STAFF ACTIONS TO DEVELOP GUIDANCE ON WHAT Bernero
CONSTITUTES A SUFFICIENT INVESTIGATION BY A RSO Arlotto
AFTER A MISADM - STAFF IS PREPARING AN INFO NOTICE Knapp
TO INFORM LICENSEES OF THE ESSENTIAL COMPONENTS OF Jacobs-Baynard
AN ADEQUATE INVESTIGATION OF A MISADMINISTRATION Poland

SPECIAL INSTRUCTIONS OR REMARKS:

SAME AS EDO WITS NUMBER 9200164

Due to NMSS - 12/30/92
Due to EDO - 01/05/93