From:

Joelle Starefos

To:

Art Howell; David A Timm; Joseph Donoghue; Patrick Castleman; Robert Haag; Ron

Date:

Lloyd; Russ Bywater; Thomas Koshy 7/25/02 4:39PM

Subject:

**DB LLRT List** 

#### Predecisional and Sensitive Information

Joelle Starefos, NRC Resident Inspector **Browns Ferry Nuclear Plant** (256) 729-6196

0/4

#### **Davis-Besse Lessons Learned Task Force Meeting**

(7/24-25/2002)

#### NRC-PreDecisional

Art Howell

Ron Lloyd

Joe Donoghue

**Bob Haag** 

Tom Koshy

Pat Castleman

Russ Bywater

Joelle Starefos

Sonia Eischen (State of Ohio; Observer)

David Timm (Office of Inspector General)

Using modified IAEA approach. Fact Level. What Level. Conclusion Level.

	1	
	а	NRC failed to adequately assess symptoms of RCS leakage.
12	Α	CAC/Rad Monitor cleaning known by NRC through BC level
13	Α	BA on head known by SRI during RFO12
16	A	RIII (Grant) knowledge of Rad Monitor
18	A	BCs logs on CAC/RMs & discussed in morning meetings
19	A	CAC cleaning observed by inspectors (DRS)
20	Α	PM knew about CACs
22	Α	DRP BC listed CAC cleaning (2001)
23	Α	RIII didn't see CAC/RM cleaning as important
38	Α	No one suggested NRC look at RCS leakage in containment during PIR
41	Α	3 inspection reports discussing RMs without conclusions
52	Α	RIII didn't view leakage as a problem
58	Α	Multiple cleaning of CACs
76	Α	No documentation of CAC evaluation inspection
77	Α	No NRC doc of RM leak detection reliability insp.
83	Α	No open items for CAC/RM or BA on head
87	Α	Pzr safety valve mod increased leakage; NRC accepted without question
88	Α	Assumed Pzr safety valve leakage was reason for CAC fouling
97 •	Α	CR for CAC/RM not seen as safety-sig would be screened out
98	Α	NRC Briefing package for Merrified didn't include BA problems
107	A	TS requirements for CAC/RM were relaxed

\6

# **Davis-Besse Lessons Learned Task Force Meeting**

(7/24-25/2002)

118 A BC didn't tell R1 to pursue BA issues  125 A RA knew of CAC issues  b NRC failed to follow-up on Generic Communications.  59 B 62001 not used for DB (precursor events)  61 B 62001 used 15 reactors (all RIV PWRs)  62 B No insp followup of GL97-01  66 B NRC followup for 88-05 audited 10 plants; DB acceptable  129 B TI on BU2001-01 didn't address BA issues  132 B 2515 IP do not look at BA/GC followup  133 B The old inspection program (9000 series) looked at OE issues  154 B # of Generic Comm (NRC) not corrected with # of events  155 B MD8.5 can't be followed because it hasn't been updated  160 B No NRC programmatic guidance for effectiveness review of generic comm.  161 B Sample/shotgun method for verification of generic comm implementation  164 B IP62001 deleted w/o considering why it existed  165 B NRC generated 17 boric acid generic communication  167 B 11/93 SER recommended inspection (visual) or leak detection system  188 B 11/93 SER recognized circumferential cracking, but didn't make recommendations  190 B Staff action plan GL97-01 can't be found  201 B GL97-01 closcout for DB based on generic info  202 B DB was the only B&W licensee that didn't do inspections (ref GL97-01) NRC  203 B J972 requested enhanced ISI for BA corrosion  c NRC failed to understand implications of BA corrosion.  1 C Licensee stated that NRR knew about BA on head  2 C SRI saw CR on BA on head  2 C SRI saw CR on BA on head  2 C SRI knew of flange leaks  C No apparent NRC followup of 96, 98 PCAQs  4 C Aware of BA on RPV head and didn't inspect  2 SRI knew of flange leaks  C SRI saw CR-2 as a material control problem -vs- boric acid prog prob  C NRC doesn't review owner's group input  116 C BC/SRI/RI didn't observe RPV head videos			
b NRC failed to follow-up on Generic Communications.  59 B 62001 not used for DB (precursor events)  61 B 62001 used 15 reactors (all RIV PWRs)  62 B No insp followup of GL97-01  66 B NRC followup for 88-05 audited 10 plants; DB acceptable  129 B TI on BU2001-01 didn't address BA issues  132 B 2515 IP do not look at BA/GC followup  133 B The old inspection program (9000 series) looked at OE issues  154 B # of Generic Comm (NRC) not corrected with # of events  156 B MD8.5 can't be followed because it hasn't been updated  160 B No NRC programmatic guidance for effectiveness review of generic comm.  161 B Sample/shotgun method for verification of generic comm implementation  164 B IP62001 deleted w/o considering why it existed  165 B NRC generated 17 boric acid generic communication  187 B 11/93 SER recommended inspection (visual) or leak detection system  189 B 11/93 SER recognized circumferential cracking, but didn't make recommendations  190 B Staff action plan GL97-01 can't be found  201 B GL97-01 closeout for DB based on generic info  202 B DB was the only B&W licensee that didn't do inspections (ref GL97-01) NRC  232 B 1972 requested enhanced ISI for BA corrosion  14 C Licensee stated that NRR knew about BA on head  28 C BA CRs not selected for PIR  29 C Abbreviated version (issue) of BA CRs not represented  30 C No apparent NRC followup of 96, 98 PCAQs  42 C Abreviated version (issue) of BA CRs not represented  43 C SRI knew of flange leaks  44 C Neither of Residents received training on BA  45 C Neither of Residents received training on BA  46 C DRP BC and former SRI (only) knew of flange leaks  50 C Flange leaks not pursued  51 C RIII saw RC-2 as a material control problem -vs- boric acid prog prob  105 C NRC doesn't review owner's group input	-	Α	BC didn't tell RI to pursue BA issues
Section   B   Good   Section   Good	125	Α	RA knew of CAC issues
61 B 62001 used 15 reactors (all RIV PWRs) 62 B No insp followup of GL97-01 63 NRC followup of R8-05 audited 10 plants; DB acceptable 64 To n RU2001-01 didn't address BA issues 65 To n BU2001-01 didn't address BA issues 66 B To n BU2001-01 didn't address BA issues 67 To n BU2001-01 didn't address BA issues 68 To n BU2001-01 didn't address BA issues 69 To n BU2001-01 didn't address BA issues 60 B To n Bu2001-01 didn't address BA issues 60 B The old inspection program (9000 series) looked at OE issues 61 B # of Generic Comm (NRC) not corrected with # of events 61 B MD8.5 can't be followed because it hasn't been updated 61 B No NRC programmatic guidance for effectiveness review of generic comm. 61 B Sample/shotgun method for verification of generic comm implementation 61 B IP62001 deleted w/o considering why it existed 62 B NRC generated 17 boric acid generic communication 63 B NRC generated 17 boric acid generic communication 64 B 11/93 SER recommended inspection (visual) or leak detection system 65 B 11/93 SER recommended inspection (visual) or leak detection system 66 B 11/93 SER recognized circumferential cracking, but didn't make recommendations 67 B 11/93 SER recognized circumferential cracking, but didn't make recommendations 68 B 11/93 SER recognized circumferential cracking, but didn't make recommendations 69 B Staff action plan GL97-01 can't be found 60 B DB was the only B&W licensee that didn't do inspections (ref GL97-01) NRC 61 B DB was the only B&W licensee that didn't do inspections (ref GL97-01) NRC 61 B DB was the only B&W licensee that didn't do inspections (ref GL97-01) NRC 61 B DB was the only B&W licensee that didn't do inspections (ref GL97-01) NRC 61 B DB was the only B&W licensee that didn't do inspections (ref GL97-01) NRC 62 B DB was the only B&W licensee that didn't inspect on head 63 C BA CRs not selected for PIR 64 C BA CRs not selected for PIR 65 C BA CRs not selected for PIR 66 C BA CRs not selected for PIR 67 C BA CRs not selected for PIR 68 C BA CRs not selected for PIR 69 C BA CRs		b	NRC failed to follow-up on Generic Communications.
B	59	В	62001 not used for DB (precursor events)
B	61	В	62001 used 15 reactors (all RIV PWRs)
129 B TI on BU2001-01 didn't address BA issues 132 B 2515 IP do not look at BA/GC followup 133 B The old inspection program (9000 series) looked at OE issues 154 B # of Generic Comm (NRC) not corrected with # of events 156 B MD8.5 can't be followed because it hasn't been updated 160 B No NRC programmatic guidance for effectiveness review of generic comm. 161 B Sample/shotgun method for verification of generic comm implementation 164 B IP62001 deleted w/o considering why it existed 165 B NRC generated 17 boric acid generic communication 167 B 11/93 SER recommended inspection (visual) or leak detection system 168 B 11/93 SER recognized circumferential cracking, but didn't make recommendations 169 B Staff action plan GL97-01 can't be found 170 B GL97-01 closeout for DB based on generic info 170 B GL97-01 closeout for DB based on generic info 170 B DB was the only B&W licensee that didn't do inspections (ref GL97-01) NRC 171 Requested enhanced ISI for BA corrosion 172 requested enhanced ISI for BA corrosion 173 requested enhanced ISI for BA corrosion 174 C Licensee stated that NRR knew about BA on head 175 C SRI saw CR on BA on head 176 C SRI saw CR on BA on head 177 C Abbreviated version (issue) of BA CRs not represented 178 C No apparent NRC followup of 96, 98 PCAQs 179 C Abbreviated version (issue) of BA CRs not represented 189 C SRI knew of flange leaks 190 C Neither of Residents received training on BA 190 C DRP BC and former SRI (only) knew of flange leaks 190 C RIII saw RC-2 as a material control problem -vs- boric acid prog prob 190 C NRC doesn't review owner's group input	62	В	No insp followup of GL97-01
132 B   2515 IP do not look at BA/GC followup     133 B   The old inspection program (9000 series) looked at OE issues     154 B   # of Generic Comm (NRC) not corrected with # of events     156 B   MD8.5 can't be followed because it hasn't been updated     160 B   No NRC programmatic guidance for effectiveness review of generic comm.     161 B   Sample/shotgun method for verification of generic comm implementation     164 B   IP62001 deleted w/o considering why it existed     165 B   NRC generated 17 boric acid generic communication     187 B   11/93 SER recommended inspection (visual) or leak detection system     189 B   11/93 SER recognized circumferential cracking, but didn't make recommendations     190 B   Staff action plan GL97-01 can't be found     201 B   GL97-01 closeout for DB based on generic info     202 B   DB was the only B&W licensee that didn't do inspections (ref GL97-01) NRC     232 B   1972 requested enhanced ISI for BA corrosion     c   NRC failed to understand implications of BA corrosion.     14 C   Licensee stated that NRR knew about BA on head     15 C   SRI saw CR on BA on head     28 C   BA CRs not selected for PIR     29 C   Abbreviated version (issue) of BA CRs not represented     33 C   No apparent NRC followup of 96, 98 PCAQs     42 C   Aware of BA on RPV head and didn't inspect     33 C   No apparent NRC followup of 96, 98 PCAQs     44 C   SRI knew of flange leaks     50 C   Flange leaks not pursued     50 C   Flange leaks not pursued     51 C   SRI saw RC-2 as a material control problem -vs- boric acid prog prob     51 C   NRC doesn't review owner's group input	66	В	NRC followup for 88-05 audited 10 plants; DB acceptable
The old inspection program (9000 series) looked at OE issues	129	В	TI on BU2001-01 didn't address BA issues
B	132	В	2515 IP do not look at BA/GC followup
MD8.5 can't be followed because it hasn't been updated	133	В	The old inspection program (9000 series) looked at OE issues
No NRC programmatic guidance for effectiveness review of generic comm.	154	В	# of Generic Comm (NRC) not corrected with # of events
161       B       Sample/shotgun method for verification of generic comm implementation         164       B       IP62001 deleted w/o considering why it existed         165       B       NRC generated 17 boric acid generic communication         187       B       11/93 SER recommended inspection (visual) or leak detection system         189       B       11/93 SER recognized circumferential cracking, but didn't make recommendations         190       B       Staff action plan GL97-01 can't be found         201       B       GL97-01 closeout for DB based on generic info         202       B       DB was the only B&W licensee that didn't do inspections (ref GL97-01) NRC         232       B       1972 requested enhanced ISI for BA corrosion         c       NRC failed to understand implications of BA corrosion.         14       C       Licensee stated that NRR knew about BA on head         15       C       SRI saw CR on BA on head         28       C       BA CRs not selected for PIR         29       C       Abbreviated version (issue) of BA CRs not represented         33       C       No apparent NRC followup of 96, 98 PCAQs         42       C       Aware of BA on RPV head and didn't inspect         43       C       SRI knew of flange leaks         45	156	В	MD8.5 can't be followed because it hasn't been updated
161       B       Sample/shotgun method for verification of generic comm implementation         164       B       IP62001 deleted w/o considering why it existed         165       B       NRC generated 17 boric acid generic communication         187       B       11/93 SER recommended inspection (visual) or leak detection system         189       B       11/93 SER recognized circumferential cracking, but didn't make recommendations         190       B       Staff action plan GL97-01 can't be found         201       B       GL97-01 closeout for DB based on generic info         202       B       DB was the only B&W licensee that didn't do inspections (ref GL97-01) NRC         232       B       1972 requested enhanced ISI for BA corrosion         c       NRC failed to understand implications of BA corrosion.         14       C       Licensee stated that NRR knew about BA on head         15       C       SRI saw CR on BA on head         28       C       BA CRs not selected for PIR         29       C       Abbreviated version (issue) of BA CRs not represented         33       C       No apparent NRC followup of 96, 98 PCAQs         42       C       Aware of BA on RPV head and didn't inspect         43       C       SRI knew of flange leaks         45	160	В	No NRC programmatic guidance for effectiveness review of generic comm.
164       B       IP62001 deleted w/o considering why it existed         165       B       NRC generated 17 boric acid generic communication         187       B       11/93 SER recommended inspection (visual) or leak detection system         189       B       11/93 SER recognized circumferential cracking, but didn't make recommendations         190       B       Staff action plan GL97-01 can't be found         201       B       GL97-01 closeout for DB based on generic info         202       B       DB was the only B&W licensee that didn't do inspections (ref GL97-01) NRC         232       B       1972 requested enhanced ISI for BA corrosion         c       NRC failed to understand implications of BA corrosion.         14       C       Licensee stated that NRR knew about BA on head         15       C       SRI saw CR on BA on head         28       C       BA CRs not selected for PIR         29       C       Abbreviated version (issue) of BA CRs not represented         33       C       No apparent NRC followup of 96, 98 PCAQs         42       C       Aware of BA on RPV head and didn't inspect         43       C       SRI knew of flange leaks         45       C       Neither of Residents received training on BA         49       C       DRP B	161	В	
165       B       NRC generated 17 boric acid generic communication         187       B       11/93 SER recommended inspection (visual) or leak detection system         189       B       11/93 SER recognized circumferential cracking, but didn't make recommendations         190       B       Staff action plan GL97-01 can't be found         201       B       GL97-01 closeout for DB based on generic info         202       B       DB was the only B&W licensee that didn't do inspections (ref GL97-01) NRC         232       B       1972 requested enhanced ISI for BA corrosion         c       NRC failed to understand implications of BA corrosion.         14       C       Licensee stated that NRR knew about BA on head         15       C       SRI saw CR on BA on head         28       C       BA CRs not selected for PIR         29       C       Abbreviated version (issue) of BA CRs not represented         33       C       No apparent NRC followup of 96, 98 PCAQs         42       C       Aware of BA on RPV head and didn't inspect         43       C       SRI knew of flange leaks         45       C       Neither of Residents received training on BA         49       C       DRP BC and former SRI (only) knew of flange leaks         50       C       Fla	164	В	IP62001 deleted w/o considering why it existed
187       B       11/93 SER recommended inspection (visual) or leak detection system         189       B       11/93 SER recognized circumferential cracking, but didn't make recommendations         190       B       Staff action plan GL97-01 can't be found         201       B       GL97-01 closeout for DB based on generic info         202       B       DB was the only B&W licensee that didn't do inspections (ref GL97-01) NRC         232       B       1972 requested enhanced ISI for BA corrosion         c       NRC failed to understand implications of BA corrosion.         14       C       Licensee stated that NRR knew about BA on head         15       C       SRI saw CR on BA on head         28       C       BA CRs not selected for PIR         29       C       Abbreviated version (issue) of BA CRs not represented         33       C       No apparent NRC followup of 96, 98 PCAQs         42       C       Aware of BA on RPV head and didn't inspect         43       C       SRI knew of flange leaks         45       C       Neither of Residents received training on BA         49       C       DRP BC and former SRI (only) knew of flange leaks         50       C       Flange leaks not pursued         65       C       1992 precursor insp no perf i	165	В	
190 B Staff action plan GL97-01 can't be found 201 B GL97-01 closeout for DB based on generic info 202 B DB was the only B&W licensee that didn't do inspections (ref GL97-01) NRC 232 B 1972 requested enhanced ISI for BA corrosion  c NRC failed to understand implications of BA corrosion.  Licensee stated that NRR knew about BA on head  15 C SRI saw CR on BA on head 28 C BA CRs not selected for PIR 29 C Abbreviated version (issue) of BA CRs not represented 33 C No apparent NRC followup of 96, 98 PCAQs 42 C Aware of BA on RPV head and didn't inspect 43 C SRI knew of flange leaks 45 C Neither of Residents received training on BA 49 C DRP BC and former SRI (only) knew of flange leaks 50 C Flange leaks not pursued 65 C RIII saw RC-2 as a material control problem -vs- boric acid prog prob 105 C NRC doesn't review owner's group input	187	В	
190 B Staff action plan GL97-01 can't be found 201 B GL97-01 closeout for DB based on generic info 202 B DB was the only B&W licensee that didn't do inspections (ref GL97-01) NRC 232 B 1972 requested enhanced ISI for BA corrosion  c NRC failed to understand implications of BA corrosion.  14 C Licensee stated that NRR knew about BA on head 15 C SRI saw CR on BA on head 28 C BA CRs not selected for PIR 29 C Abbreviated version (issue) of BA CRs not represented 33 C No apparent NRC followup of 96, 98 PCAQs 42 C Aware of BA on RPV head and didn't inspect 43 C SRI knew of flange leaks 45 C Neither of Residents received training on BA 49 C DRP BC and former SRI (only) knew of flange leaks 50 C Flange leaks not pursued 65 C RIII saw RC-2 as a material control problem -vs- boric acid prog prob 105 C NRC doesn't review owner's group input	189	В	11/93 SER recognized circumferential cracking, but didn't make recommendations
DB was the only B&W licensee that didn't do inspections (ref GL97-01) NRC  1972 requested enhanced ISI for BA corrosion  NRC failed to understand implications of BA corrosion.  Licensee stated that NRR knew about BA on head  SRI saw CR on BA on head  BA CRs not selected for PIR  BA CR hot selected for PIR  Abbreviated version (issue) of BA CRs not represented  No apparent NRC followup of 96, 98 PCAQs  C Aware of BA on RPV head and didn't inspect  SRI knew of flange leaks  C SRI knew of flange leaks  Neither of Residents received training on BA  DRP BC and former SRI (only) knew of flange leaks  C Flange leaks not pursued  SRI saw RC-2 as a material control problem -vs- boric acid prog prob  NRC doesn't review owner's group input	190	В	
B 1972 requested enhanced ISI for BA corrosion  c NRC failed to understand implications of BA corrosion.  14 C Licensee stated that NRR knew about BA on head  15 C SRI saw CR on BA on head  28 C BA CRs not selected for PIR  29 C Abbreviated version (issue) of BA CRs not represented  33 C No apparent NRC followup of 96, 98 PCAQs  42 C Aware of BA on RPV head and didn't inspect  43 C SRI knew of flange leaks  45 C Neither of Residents received training on BA  49 C DRP BC and former SRI (only) knew of flange leaks  50 C Flange leaks not pursued  65 C 1992 precursor insp no perf issues/no F/U of BA control prog  95 C RIII saw RC-2 as a material control problem -vs- boric acid prog prob  105 C NRC doesn't review owner's group input	201	В	GL97-01 closeout for DB based on generic info
c NRC failed to understand implications of BA corrosion.  Licensee stated that NRR knew about BA on head  SRI saw CR on BA on head  BA CRs not selected for PIR  BA CRs not selected for PIR  No apparent NRC followup of BA CRs not represented  No apparent NRC followup of 96, 98 PCAQs  C Aware of BA on RPV head and didn't inspect  SRI knew of flange leaks  C Neither of Residents received training on BA  DRP BC and former SRI (only) knew of flange leaks  DRP BC and former SRI (only) knew of flange leaks  C Inange leaks not pursued  SRI saw RC-2 as a material control problem -vs- boric acid prog prob  NRC doesn't review owner's group input	202	В	DB was the only B&W licensee that didn't do inspections (ref GL97-01) NRC
14 C Licensee stated that NRR knew about BA on head 15 C SRI saw CR on BA on head 28 C BA CRs not selected for PIR 29 C Abbreviated version (issue) of BA CRs not represented 33 C No apparent NRC followup of 96, 98 PCAQs 42 C Aware of BA on RPV head and didn't inspect 43 C SRI knew of flange leaks 45 C Neither of Residents received training on BA 49 C DRP BC and former SRI (only) knew of flange leaks 50 C Flange leaks not pursued 65 C 1992 precursor insp no perf issues/no F/U of BA control prog 95 C RIII saw RC-2 as a material control problem -vs- boric acid prog prob 105 C NRC doesn't review owner's group input	232	В	1972 requested enhanced ISI for BA corrosion
15 C SRI saw CR on BA on head 28 C BA CRs not selected for PIR 29 C Abbreviated version (issue) of BA CRs not represented 33 C No apparent NRC followup of 96, 98 PCAQs 42 C Aware of BA on RPV head and didn't inspect 43 C SRI knew of flange leaks 45 C Neither of Residents received training on BA 49 C DRP BC and former SRI (only) knew of flange leaks 50 C Flange leaks not pursued 65 C 1992 precursor insp no perf issues/no F/U of BA control prog 95 C RIII saw RC-2 as a material control problem -vs- boric acid prog prob 105 C NRC doesn't review owner's group input	-	С	NRC failed to understand implications of BA corrosion.
28 C BA CRs not selected for PIR 29 C Abbreviated version (issue) of BA CRs not represented 33 C No apparent NRC followup of 96, 98 PCAQs 42 C Aware of BA on RPV head and didn't inspect 43 C SRI knew of flange leaks 45 C Neither of Residents received training on BA 49 C DRP BC and former SRI (only) knew of flange leaks 50 C Flange leaks not pursued 65 C 1992 precursor insp no perf issues/no F/U of BA control prog 95 C RIII saw RC-2 as a material control problem -vs- boric acid prog prob 105 C NRC doesn't review owner's group input	14	С	Licensee stated that NRR knew about BA on head
29 C Abbreviated version (issue) of BA CRs not represented 33 C No apparent NRC followup of 96, 98 PCAQs 42 C Aware of BA on RPV head and didn't inspect 43 C SRI knew of flange leaks 45 C Neither of Residents received training on BA 49 C DRP BC and former SRI (only) knew of flange leaks 50 C Flange leaks not pursued 65 - C 1992 precursor insp no perf issues/no F/U of BA control prog 95 C RIII saw RC-2 as a material control problem -vs- boric acid prog prob 105 C NRC doesn't review owner's group input	15	С	SRI saw CR on BA on head
33 C No apparent NRC followup of 96, 98 PCAQs 42 C Aware of BA on RPV head and didn't inspect 43 C SRI knew of flange leaks 45 C Neither of Residents received training on BA 49 C DRP BC and former SRI (only) knew of flange leaks 50 C Flange leaks not pursued 65 C 1992 precursor insp no perf issues/no F/U of BA control prog 95 C RIII saw RC-2 as a material control problem -vs- boric acid prog prob 105 C NRC doesn't review owner's group input	28	1	BA CRs not selected for PIR
42 C Aware of BA on RPV head and didn't inspect 43 C SRI knew of flange leaks 45 C Neither of Residents received training on BA 49 C DRP BC and former SRI (only) knew of flange leaks 50 C Flange leaks not pursued 65 C 1992 precursor insp no perf issues/no F/U of BA control prog 95 C RIII saw RC-2 as a material control problem -vs- boric acid prog prob 105 C NRC doesn't review owner's group input		1	Abbreviated version (issue) of BA CRs not represented
43 C SRI knew of flange leaks 45 C Neither of Residents received training on BA 49 C DRP BC and former SRI (only) knew of flange leaks 50 C Flange leaks not pursued 65 - C 1992 precursor insp no perf issues/no F/U of BA control prog 95 C RIII saw RC-2 as a material control problem -vs- boric acid prog prob 105 C NRC doesn't review owner's group input	33		
45 C Neither of Residents received training on BA 49 C DRP BC and former SRI (only) knew of flange leaks 50 C Flange leaks not pursued 65 C 1992 precursor insp no perf issues/no F/U of BA control prog 95 C RIII saw RC-2 as a material control problem -vs- boric acid prog prob 105 C NRC doesn't review owner's group input	42		Aware of BA on RPV head and didn't inspect
49 C DRP BC and former SRI (only) knew of flange leaks 50 C Flange leaks not pursued 65 · C 1992 precursor insp no perf issues/no F/U of BA control prog 95 C RIII saw RC-2 as a material control problem -vs- boric acid prog prob 105 C NRC doesn't review owner's group input	43		SRI knew of flange leaks
50 C Flange leaks not pursued 65 · C 1992 precursor insp no perf issues/no F/U of BA control prog 95 C RIII saw RC-2 as a material control problem -vs- boric acid prog prob 105 C NRC doesn't review owner's group input	45		Neither of Residents received training on BA
65 · C 1992 precursor insp no perf issues/no F/U of BA control prog 95 C RIII saw RC-2 as a material control problem -vs- boric acid prog prob 105 C NRC doesn't review owner's group input			DRP BC and former SRI (only) knew of flange leaks
95 C RIII saw RC-2 as a material control problem -vs- boric acid prog prob 105 C NRC doesn't review owner's group input			Flange leaks not pursued
105 C NRC doesn't review owner's group input	65 -		1992 precursor insp no perf issues/no F/U of BA control prog
	95		RIII saw RC-2 as a material control problem -vs- boric acid prog prob
116 C BC/SRI/RI didn't observe RPV head videos	105		
	116	С	BC/SRI/RI didn't observe RPV head videos



(7/24-25/2002)

128	С	RI reviewed CR/equivalent in some manner
130a	С	BA buildup not a safety issue by NRC
155	С	NUREG 6245 (CRDM crack) NRC not aware of B&W content
169	С	NRC 1993 SER addressed RVH nozzle cracks as not immed. safety issue
197a	С	Risk significance of BA on RPV head is low NRC
222	С	NRC staff believed dry boric acid not corrosive
226	С	Postulated breech of RPV not considered
227	С	Industry and NRC were managing BA issue by leakage
228	С	NRC doesn't review all of the industry guidance on BA
229	С	NUMARC 1993 and NEI 1995 letters - GL88-05 will let the industry locate leaks
		before a real problem is identified
233	С	1993 2.206 Greenpeace response - cracking issues
	d	NRC failed to establish adequate requirements.
139	D	Enforcement history doesn't equate with OE
140	D	Lack of enforcement for RCS leakage
141	D	Enforcement/NRR trying to figure out what should be done for RCS leakage
142	D	1997 SONGS nozzle cracking cited Maintenance Rule
143	D	NRC response (policy) not consistent - SONGS/Oconee
145	D	No ASME Code requirement (of inspections/RCS leakage)
146	D	Code didn't require insulation to be removed for inspections
147	D	VC Summer had RCS leakage and didn't report it
149	D	Several "no color" issues design -vs- performance
205	D	12/31/2001 was an arbitrary date for shutdown; basis question
219	D	Code did not require insulation removal (VT-2)
243	D	Enhanced visual meant for circ, not axial cracking (vol NDE)
245	D	ANO a through wall CRDM crack is a statistical certainty
253	D	Several CRDM nozzles cracked, some through wall NRC
	e	NRC inspection and assessment programs failed to adequately assess DB
		performance
1	Е	Region viewed Davis-Besse as good performer.
8	E	PM inspection approach changing.
21	E	One PPR summary listed CAC cleaning
25	Е	PI&R/40500 did not review area
26 .	Е	PI&R samples began 1999 for 3/01 (gap issue)
27	E	Gap of 2 ½ years between CA inspections (missed events)
39	Е	Inspection reports don't list all docs reviewed (6 years of reports)
44	E	RC-2 escalated enforcement didn't require closeout inspection



## (7/24-25/2002)

#### NRG-PreDecisional.

46	Е	Inspection on RM didn't provide any performance issues
47	Е	Neither the old/new insp programs found/discussed RM issues
51	E	Former SRI did not perform any followup on leak hunt plan RFO12
55	Е	NRC prompted Lic regarding RCS leak on MUIA described as positive in IR
56	Е	DB PIR viewed as the best by RIII
60	E	62001 cancelled in 10/01
67	E	NRC audit of BAC didn't include Rx head/instr
71	E	Not enough hours in ROP for (BA) inspections didn't allow some inspection
72	Е	Verbatim comp. W/insp procedures (not there/can't do)
73	E	Can't go outside of the baseline unless you have a >green finding
74	E	Baseline inspection doesn't include structures or passive components
75	E	ROP eliminated good practice of containment closeout insp
82	E	ISI didn't look at A600
85	E	RIII issued SL3 for RC-2; would be a green finding today
86	Е	RC-2 event would have not gone beyond baseline
96	Е	RIII had differing views for RC-2 followup
100	E	Some interviews indicated RI/SRI not as visible in ctmt and CR post ROP
106	E	MC2515 AppD doesn't provide thorough guidance for review of CR
115	E	NRR PM limited visits to DB
121	E	NRC thought that the licensee was rigorous in their leak hunt
122	E	RI thought the RPV head was 100% cleaned
127	E	ALARA insp didn't show that CAC cleaning was largest dose
204	E	No process for verifying licensee info for continued operation
206	E	PM don't conduct site visits
207	E	Some PM haven't visited plants
208	E	PM didn't review commitment change reports
211	E	NRR not implementing procedures
212	Е	LA/SE for RM for RCS leakage didn't consider DB OE
213	E	NRR perception was that DB was a good performer
224	E	Risk informed process didn't alert the NRC to a potential risk
225	E	Over-reliance on risk information -vs- deterministic
252	E	62001 intended for 16 hours every other outage
270	E	Kerosene burner not eval'd for ctmt
271 -	E	No oper eval for the clogging of CACs
272	E	Non-conservative assumption of LOCA steam clean CACs
278	E	Lic didn't complete all RC2 CAs
290	E	No doc'd eval of CAC clogging



(7/24-25/2002)

293	Е	All PI's green prior to event
294	E	Inadequate temp mod safety eval on code safety seat leakage
294	f	<u> </u>
	F	NRC staff resources & experience
2		NRC staffing level not filled for all positions
3	F	One year period (1999), only one Resident on site.
4	F	Project Engineer - two 8-month gaps.
5	F	Resident inspectors not certified.
6	F	SRI position delayed in filling.
7	F	High Project Manager turnover rate (9 PMs in 10-years)
9	F	Limited commercial nuclear experience RI
10	F	Resident inspector had a materials background
11	F	SRI experience with only DB containment
40	F	Low number of inspection hours compared to other RIII sites (½ in 1999)
53	F	1998 events diverted inspection efforts re:BA issues
57	F	Resident not aware of OOS logs
63	F	PE little time at DB (1997&1999)
92	F	Between PE coverage gaps, 8 months/3months coverage/8 months
93	F	BC had Clinton 0350 plant coincident w/DB
110	F	RIII resources decreasing
111	F	RIII insp contractor support poor
112	F	RIII too many competing priorities which detract from insp.
131	F	No 1245 cert requirements for BA corrossion
158	F	Contract support after '98 report dried up (staff decreased/# reports decreased)
167	F	AEOD had 80+ FTE; now 2.5 FTE for OE (RES)
215	F	No guidance for background training for PM
	g	NRC failed to communicate critical information
17	G	Other than DD-DRP; others didn't recollect CAC/RM issues
94	G	NRR inspection branch has no feedback form on Plant status time as addressed by RI
		interview
101	G	Procedure for RIII morning meeting isn't followed
102	G	RIII not conducive to info exchange
103	G	Senior RIII Managers not the audience for the morning meeting
117	G	RI not aware of FeO on CAC
126 -	G	RA didn't know about BA on head
136	G	IRO didn't participate to follow MD8.3 for AIT determination
137	G	NRR/RIII didn't follow MD8.3
203	G	Deferral of DB shutdown not well documented

0/r

## **Davis-Besse Lessons Learned Task Force Meeting**

(7/24-25/2002)

## NRG-PreDecisional

216	G	Interviews indicate that NRR and RIII communications poor/nonexistent
291	G	Late arrival of calcs for crack propagation
	h	NRC failed to adequately assess relevant operating experience
157	Н	OE review in NRC not performed by independent or long review
163	Н	NRR is reactive for short-term/current event
166	Н	NRC generic issue program takes too long/too harduse bulletins instead
170	Н	Foreign OE was reviewed by NRC
171	Н	70 LERs about Boric Acid leaks
172	Н	Axial cracks known from early 1970s, Circumferential from 1980s
173	Н	LIC-503 references some wrong procedures in RES
183	Н	No clear process for using foreign experience
184	Н	French corrective actions were documented but never used
185	Н	Mind set that French CA was an over reaction from NRC perspective; aggressive
		inspection was reponse
186	Н	NRC never asked the French why they were replacing their RPV heads
188	Н	Swedish, Spanish, Japanese, French have replaced heads
193	Н	NRR staff not aware BA leakage OE
209	Н	RES procedure 2i not used/not known by staff
210	Н	Cracking/BA corrosion not considered by either NRR or RES to be a GI (MD 6.4)
230	Н	GI program relies on user needs before taking action
231	Н	Preferred process flow for OE: nothing; IN; BU; GL; GI (all else fails)
297	Н	No NRC review of submittals/reports (ISI)
	i	Licensee failed to implement owners group guidance.
202a	I	DB was the only B&W licensee that didn't do inspections (ref GL97-01) LIC
236	I	No BWOG verification for implementation of GL97-01
237	I	No BWOG verification for implementation of GL88-05
247	I	No tracking system to ensure that industry guidance was included in site guidance/
261	I	processes.  93 B&W report flange leaks need to be eval first
	I	BA corr handbook shows CAC/RM as evidence of RCS leak
289	<del></del>	Licensee failed to understand implications of BA corrosion.
22	j	BA on head was a "routine" CR
32 36	J	1996 CR on BA stayed open for ~2 years
	J	BA buildup not a safety issue by DB
130 -	]	NUREG 6245 (CRDM crack) Industry not aware of B&W content
155a		
178	J	BACC person also had many other duties as a system engineer
194	J	BWOG rep didn't know the significance of Brown/red tinted BA buildup



(7/24-25/2002)

	1 :-	
197	J	Risk significance of BA on RPV head is low LIC
217	J	BA procedure not "QA" until 5/02
234	J	Mod on service structure delays
239	J	Ombudsman & cleaning statements
274	J	PRG staff didn't viewed head tapes
275	J	Former VP viewed as-found, not after tape until Fall2001
282	J	Only staff involved in head cleaning
296	J	PCAQ 96-0551 was one of ten oldest CRs before it was resolved
298	J	Multiple people involved in head cleaning w/o raising issues
299	J	Same job done by Framatome at other plants?
	k	Licensee failed to resolve chronic RCS leakage.
24	K	Routine CAC cleaning
108	K	CAC/RM fouling may have been the impetus for TS change in #107
109	K	HEPA filter for RM may defeat the purpose of the RM workarounds -vs- fix the
		problem
119	K	Licensee not rigorous in finding RCS leaks
120	K	Licensee deleted Mode 3 walkdown for BA
235	K	CAC fouling and ALARA
244	K	DB entered a 6-hour shutdown TS situation because of RM Problems with BA
248	K	Ability to differentiate between flange leakage/ head penetration leakage
255	K	Until RFO13 lic had flange leaks
262	K	Heavy boron buildup on CACs
268	K	No systematic leak search for 12RFO
269	K	Deleted mode 3 walkdown
273	K	Long history of thermowell leaks
280	К	Triage plan for flange leak / didn't fix all flange leaks
287	K	100% NDE 5.7Rem estimate <past cleaning<="" head="" td=""></past>
300	K	Relief valve mod masking other leaks in 1998-99 time frame
	1	Licensee failed to properly implement an adequate BACC program.
34	L	1996 CR explicit on the BA concern
35	L	~50% of RPV head cleaned in 1996
70	L	BAC checklists not kept/tracked/trended
123	L	None of the RPV head cleanings were 100%
124 -	L	Lost control of video tapes
144	L	BAC procedure wasn't followed
251	L	Appropriate cleaning methods for RPV head (water-vs-vacuum)
431		

%

## **Davis-Besse Lessons Learned Task Force Meeting**

(7/24-25/2002)

	<del>,</del>	
260	L	Couldn't complete head cleaning due to schedule pressure
263	L	Potential CRDM G9 leak was crack, not dispositioned
266	L	RCS sys engr: scaffold was removed without permission
267	L	RP considered head cleaning as decon, so no procedure
279	L	No deviations from RFO12 WO to clean RPV head
281	L	RCS sys engineer upset that they head wouldn't be totally cleaned
283	L	Index of head tapes incomplete
284	L	4/17/00 head mislabeled as as-left
285	L	Head inspection tape not documented as to what was actually inspected - QA zip
	m	Licensee failed to learned from internal/external OE.
68	M	DB's BACC didn't include Rx head/instr until 5/02
151	М	Oconee OE not evaluated at DB until 5/2002
152	М	OE in USBoric acid leaks. #1 area was CRDM, DB considered not significant
153	М	100% B&W units had RCS PB leakage
162	М	DB OE procedure doesn't require NRC LER review
168	M	100% CE had RCS pressure boundary leakage
174	М	45% of Oconee cracking (CRDM) appears in the same quadrant as DB leakage
		problems
175	М	CE plants dominated RCS instrumentation nozzle leakage (10 of 13 leaks)
176	М	Average # of operating years prior to CRDM leakage ~22 years
179	M	Foreign experience would indicate that the "crack" model is flawed
191	M	NUREG/CR 6245 recommended enhanced online leakage detection systems (NRC?)
192	M	Calvert Cliffs LER indicated wet boron vs dry
198	M	Annealing nozzle temps were different than required
200	M	3 LERS involved pzr material wastage
218	M	B&W recommended the service structure mod
276	M	Two precursor BA eventsRC2, SG line
	n	Licensee staff resources & experience
159	N	40-50% DB staff decrease over 10 years
246	N	Multiple job assignments depending on cycle (outage, ops, EP)
277	N	Lack of system engineer continuity
	0	Licensee failed to communicate critical information
150	0	Lic Response to BU2001-01 contained many inaccurate info /response
177 .	0	Many licensee (DB) staff thought that a whole head inspection/cleaning was done
264	0	Lic Managers / staff knew of head cleaning %, lower staff thought that head was
L		100% cleaned
265	0	Lic managers said they showed NRC the as-found video tapes of the head

(7/24-25/2002)

#### NRG-PreDecisional

	w	Awaiting additional review
31	W	We rely on lic to give NRC correct info
37	W	Long time to close out CRs
54	W	CCW event (10/98) resulted in Spec Insp
64	W	Limited entries into containment by NRC
78	W	1997 NOP/NOT walkdown by NRC found no leaks
81	W	1992 uptake event insp closeout, then 1998 uptake occurred
84	W	RIII factored BU2001-01 commitments as part of Baseline prog.
89	w	RIII invoked MC0350 w/o DB having met criteria
90	W	DB event risk not completed yet
91	w	SDP has taken 5 months
113	W	Only 1 SES manager inside containment since 1996
114	W	Limited senior manager visits to DB
134	W	No NRC review of Ombudsman files
138	W	Range of opinions on whether an AIT/IIT/SI
180	W	Story differences between what DB told NRC -vs- what NRC thought they were told
		about BA by DB
181	W	NRR not told about red/brown BA buildup until after the DB event
182	W	After the RPV head videos were shown to the NRC, a vote was taken: 3 for shutdown;
		remaining (10-13) voted to allow continued operation
196	W	Conclusion in the EPRI guidebook not supported
199	W	"Boric acid on the head is good."
214	W	INPO ratings declined from 1 to 2 within the last few years
220	W	DB experienced no insulation deflections caused by BA buildup on the head
221	W	License Renewal report (GALL) addresses acceptability of GL88-05 for aging
	<u> </u>	management to be updated to reflect lessons learned
223	w	Extending the inspection for DB was largely based on the belief that a "strong" VT-2
		inspection was done at DB
238	W	O&M/capital budget and actuals have decreased over last 10-years
240	W	BU2001-01 documentation responses by DB not accurate
241	W	12-16 people at DB reviewed DB response to BU2001-01
242a	W	MNSA - repair of joints, boric acid issues NRC
242	W	MNSA - repair of joints, boric acid issues LIC
249	W	Bonus correlation with operations
256	W	VP - No NDE tools by 12/31
257	W	VP -Ops last know
259	W	Lic did not eval use of power washer

7



# <u>Davis-Besse Lessons Learned Task Force Meeting</u> (7/24-25/2002)

292	W	QA group didn't have a problem with BAC RFO12 report shows positive finding
295	W	NRC questioned how the licensee was able to do a visual insp. given that boron was left on the head
	x	Deleted
30	X	CRs reviewed for PI&R ~7000
48	X	SSDI insp in 2000 indicated performance was worse than expected
69	X	40500 insp in '98 indicated that commitment tracking NG
79	X	SRI 97-98 no recollection of flange leaks
80	X	Former SRI works for FENOC
99	X	PI&R doesn't allow independent look by inspectors
104	X	PI&R team leader thought that the short form description of CR was adequate
135	X	RIII inspector was told that DB was SALP 1 didn't take findings seriously (arrogant)
148	X	Nothing in allegation area was relevant to BA/cracking issues
195	X	BACC person indicated that the next major nuclear accident will be caused by BAC
250	X	Basis for dose estimates for RPV head inspections
258	X	Eng received closed door talking to for CR initiation
286	X	Lic is doing an assessment of BU2001-01 submittal
288	X	No VT-2 insp during RFO12 per RCS sys eng