

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF NUCLEAR REACTOR REGULATION
WASHINGTON, D.C. 20555

September 4, 1991

NRC INFORMATION NOTICE 91-53: FAILURE OF REMOTE SHUTDOWN SYSTEM
INSTRUMENTATION BECAUSE OF INCORRECTLY
INSTALLED COMPONENTS

Addressees

All holders of operating licenses or construction permits for nuclear power reactors.

Purpose

The U.S. Nuclear Regulatory Commission (NRC) is issuing this information notice to alert addressees to an event where the remote shutdown system at a nuclear power plant could have failed to perform certain functions because associated components were installed incorrectly. It is expected that licensees will review the information for applicability to their facilities and consider actions, as appropriate, to avoid similar problems. However, suggestions contained in this information notice are not NRC requirements; therefore, no specific action or written response is required.

Description of Circumstances

On May 18, 1991, Entergy Operations, Inc., the licensee for the Waterford Steam Electric Station, performed post-modification testing on a main steam isolation valve (MSIV) at the Waterford 3 reactor with the reactor in Mode 5. The testing included closing the subject valve using fire isolation switch FR-4 in the auxiliary relay room to ensure that the control wiring changes on the MSIV did not affect the function of the switch. If the control room is evacuated because of a fire, the switch is to be used to isolate control circuits for the MSIV and several other components from the control room and to ensure that power is supplied to the components to maintain them in the desired position. When the switch was operated, it travelled past the isolation position, allowing two of the adjacent make-before-break contacts to connect, which shorted the positive contact of one circuit to the negative contact of another circuit. The short circuit caused the power supply breaker for the switch to trip, but the switch was severely damaged by smoke and fire. The licensee quickly extinguished the fire. While replacing the switch, the licensee determined that stop screws that should have been installed when the switch was installed were missing. This allowed the switch to rotate past the intended stopping position. The licensee replaced the failed switch and successfully tested the replacement. The switch is a multideck rotary switch manufactured by Electroswitch. The licensee determined that the stop screws

9108280089

PDR IQE Notice 91-053 910904

W/IDR-11C

were supplied with the switch, but installation instructions did not specify that the stop screws be installed in this application. The licensee inspected several other isolation switches in adjacent panels and found another switch with missing stop screws. Further information may be found in NRC Inspection Report 50-382/91-18.

Discussion

Fire in certain plant areas such as the control room or the cable spreading room can affect the ability to achieve safe shutdown of the plant from the control room. In addition, the control room can become inaccessible for reasons other than a fire. These situations warrant the use of a remote shutdown system to achieve safe shutdown of the plant from a remote shutdown panel or emergency control stations that are independent of the control room. The remote shutdown system includes switches to isolate the control circuits of required safe shutdown equipment from the control room and to transfer controls to either the remote shutdown panel or emergency control stations. Therefore, licensees provide required instrumentation and controls for the remote shutdown system in accordance with the requirements of General Design Criterion (GDC) 19 of Appendix A and Appendix R to Part 50 of Title 10 of the Code of Federal Regulations (10 CFR Part 50). The significance of the problem described above is that the remote shutdown capability for the plant may be compromised if the control circuits and transfer switches (for shutdown equipment) fail because they are installed incorrectly. If these switches fail, certain instrumentation and control functions for the remote shutdown system may be lost.

Licensees may not recognize that stop screws have not been installed in the fire isolation (transfer) switches unless the operator challenges the mechanical stops of these switches. Although the switches were tested for MSIV operability during pre-operational testing at Waterford, the effectiveness of the mechanical stops of these switches was apparently never tested.

This information notice requires no specific action or written response. If you have any questions about the information in this notice, please contact one of the technical contacts listed below or the appropriate Office of Nuclear Reactor Regulation project manager.


Charles E. Rossi, Director
Division of Operational Events Assessment
Office of Nuclear Reactor Regulation

Technical contacts: T. Chandrasekaran, NRR
301-492-0859

C. Douthett, NRR
301-492-0847

Attachment: List of Recently Issued NRC Information Notices

LIST OF RECENTLY ISSUED
 NRC INFORMATION NOTICES

Information Notice No.	Subject	Date of Issuance	Issued to
91-52	Nonconservative Errors In Overtemperature Delta-Temperature (OTΔT) Set-point Caused by Improper Gain Settings	08/29/91	All holders of OLs or CPs for Westinghouse (W)-designed nuclear power reactors.
86-14, Supp. 2	Overspeed Trips of AFW, HPCI and RCIC Turbines	08/26/91	All holders of OLs or CPs for nuclear power reactors.
91-51	Inadequate Fuse Control Programs	08/20/91	All holders of OLs or CPs for nuclear power reactors.
91-50	A Review of Water Hammer Events After 1985	08/20/91	All holders of OLs or CPs for nuclear power reactors.
91-49	Enforcement of Safety Requirements for Radiographers	08/15/91	All Nuclear Regulatory Commission (NRC) licensees authorized to use sealed sources for industrial radiography.
91-48	False Certificates of Conformance Provided by Westinghouse Electric Supply Company for Refurbished Commercial-Grade Circuit Breakers	08/09/91	All holders of OLs or CPs for nuclear power reactors.
91-47	Failure of Thermo-Lag Fire Barrier Material to Pass Fire Endurance Test	08/06/91	All holders of OLs or CPs for nuclear power reactors.
89-56, Supp. 2	Questionable Certification of Material Supplied to the Defense Department by Nuclear Suppliers	07/19/91	All holders of OLs or CPs for nuclear power reactors.
91-46	Degradation of Emergency Diesel Generator Fuel Oil Delivery Systems	07/18/91	All holders of OLs or CPs for nuclear power reactors.

OL = Operating License
 CP = Construction Permit