OFFICE OF NUCLEAR REACTOR REGULATION WASHINGTON, D.C. 20555

December 6, 1991

NRC INFORMATION NOTICE 91-79:

: DEFICIENCIES IN THE PROCEDURES FOR INSTALLING THERMO-LAG FIRE BARRIER MATERIALS

Addressees

All holders of operating licenses or construction permits for nuclear power reactors.

Purpose

The U.S. Nuclear Regulatory Commission (NRC) is issuing this information notice to alert addressees to problems that could result from improperly installed THERMO-LAG 330-1 fire barriers that are used to satisfy NRC fire protection requirements for safe shutdown components. It is expected that recipients will review the information for applicability to their facilities and consider actions, as appropriate, to avoid similar problems. However, suggestions contained in this information notice are not new NRC requirements; therefore, no specific action or written response is required.

Description of Circumstances

NRC Information Notice (IN) 91-47, "Failure of THERMO-LAG Fire Barrier Material to Pass Fire Endurance Test," reported a number of installation deficiencies identified at the River Bend Station (RBS) and discussed a ASTM E-119 fire endurance test conducted for Gulf States Utilities (GSU) in October 1989 at Southwest Research Institute (SwRI) that ended with a failure of a 3-hour THERMO-LAG 330-1 cable tray protective envelope system. On August 23, 1991, the vendor, Thermal Science, Incorporated, (TSI), issued a letter to a number of licensees that discussed specific installation issues raised in IN 91-47 and concluded that the SwRI fire endurance test was not a valid test because of deficiencies in the installation of the test article.

Other licensees have also identified instances of THERMO-LAG fire barrier configurations that were not installed in accordance with the vendor's installation procedures manual. For example, Cleveland Electric Illuminating Company (CEI) reported in Licensee Event Report 91-020 that the mechanical fasteners (banding straps) on the fire barrier enclosures at Perry Nuclear Power Plant had not been installed in accordance with the vendor's installation procedures manual. CEI identified the installation discrepancies while conducting routine fire wrap inspections using revised inspection criteria. The licensee



IDHR-1R

IN 91-79 December 6, 1991 Page 2 of 3

ste:

identified that no fire endurance tests or engineering analysis had been performed to support the installed configuration. The licensees that have experienced installation problems have attributed most of the reported installation problems to contractor installer errors, incomplete or incorrect design documents, and inadequate quality control oversight. The NRC has also identified a number of installation variations as it has continued to review the vendor's installation procedures and the installation specifications, procedures, and practices for specific plants. Some of the installation variations observed by the NRC do not appear to be in accordance with the vendor's installation procedures manual and may comprise configurations that have not been qualified by fire endurance testing or engineering analyses. In several cases, such as at the River Bend Station (RBS) and Washington Nuclear Power Unit 2 (WNP2), the installation methods used during initial construction of the plant that deviated from the vendor's installation procedures manual were found unacceptable when subsequent qualification fire endurance testing resulted in fire barrier failures.

On October 17, 1991, the NRC met with TSI to discuss issues regarding installation and qualification testing. The vendor stated that it had not included several essential application steps and precautions in its installation procedures manual because the information was presented during the TSI certification training for installers. The vendor stressed the importance of using skilled and certified craftsmen, and qualified quality control inspectors to achieve an adequate fire barrier enclosure. In addition, several licensees have related to the NRC receiving supplementary written and verbal installation guidance-from TSI representatives that is not included in the TSI-installation procedures manual.

The NRC has discussed installation details with licensees, and visited a number of sites. The staff has observed variations among the installation procedures and practices regarding the following fabrication details:

- Methods for sealing and filling joints between panel sections.
- The orientation and application methods for stress skin.
- The requirements for raceway support protection.
- Allowable gap widths between panel sections.
- The configuration and orientation of structural ribs.
- Methods for installing vaults and firewalls.
- Banding material and application methods.
- Scoring and grooving of panels for fabricating and bending the panels around bends in raceways.
- Thickness acceptance criteria.

For example, an important task during the installation of THERMO-LAG fire barriers is the filling of the joints between adjoining prefabricated panel sections with trowel-grade material to the full depth of the panels. Some facilities use a method in which the ends of individual panel sections are butt joined to one another and the seam between the panel sections is filled and covered with THERMO-LAG trowel grade material (commonly referred to as "dry-fitting"). Some licensees fill the joints by "pre-buttering" the edges of the individual panel sections with trowel grade material before they join the

IN 91-79 December 6, 1991 Page 3 of 3

panels to ensure that the gap between the panels is completely filled. The vendor did not list this method as an option for installing cable tray enclosures in its current installation procedures manual. However, on October 17, 1991, the vendor stated to the NRC that this method was acceptable for installing THERMO-LAG panels to cable trays. In its August 23, 1991, letter to licensees, the vendor stated that stress skin must be placed over panel joints to ensure a continuous outer layer of stress skin for 3-hour barriers and a recent vendor procedure, TSI Technical Note 20684-AL, of October 1989, provides updated installation procedures for aluminum cable trays and requires that each butt joint be covered by an additional layer of stress skin and trowel grade material. The current vendor's generic installation procedures manual does not provide any guidance for installing a continuous layer of stress skin.

The NRC has not been able to verify that all of the specific installation variations observed have been qualified by independent qualification testing or engineering analyses. The NRC is continuing to review other technical issues regarding THERMO-LAG 330-1 fire barriers, including issues concerning the adequacy of qualification testing. Generic Letter 86-10, "Implementation of Fire Protection Requirements," provides additional NRC guidance on fire barrier qualification test acceptance criteria and evaluation of deviations from tested configurations to substantiate field installations.

This information notice requires no specific action or written response. If you have any questions about the information in this notice, please contact one of the technical contacts listed below or the appropriate Office of Nuclear Reactor Regulation (NRR) project manager.

Charles E Rom

Charles E. Rossi, Director Division of Operational Events Assessment Office of Nuclear Reactor Regulation


Technical contacts:

Ralph Architzel, NRR (301) 492-0804

Loren R. Plisco, NRR (301) 492-1013

K. Steven West, NRR (301) 492-1220

Attachment: List of Recently Issued NRC Information Notices



¢

٨

Attachment IN 91-79 December 6, 1991 Page 1 of 1

IN 91-79 December 6, 1991 Page 3 of 3

panels to ensure that the gap between the panels is completely filled. The vendor did not list this method as an option for installing cable tray enclosures in its current installation procedures manual. However, on October 17, 1991, the vendor stated to the NRC that this method was acceptable for installing THERMO-LAG panels to cable trays. In its August 23, 1991, letter to licensees, the vendor stated that stress skin must be placed over panel joints to ensure a continuous outer layer of stress skin for 3-hour barriers and a recent vendor procedure, TSI Technical Note 20684-AL, of October 1989, provides updated installation procedures for aluminum cable trays and requires that each butt joint be covered by an additional layer of stress skin and trowel grade material. The current vendor's generic installation procedures manual does not provide any guidance for installing a continuous layer of stress skin.

The NRC has not been able to verify that all of the specific installation variations observed have been qualified by independent qualification testing or engineering analyses. The NRC is continuing to review other technical issues regarding THERMO-LAG 330-1 fire barriers, including issues concerning the adequacy of qualification testing. Generic Letter 86-10, "Implementation of Fire Protection Requirements," provides additional NRC guidance on fire barrier qualification test acceptance criteria and evaluation of deviations from tested configurations to substantiate field installations.

This information notice requires no specific action or written response. If you have any questions about the information in this notice, please contact one of the technical contacts listed below or the appropriate Office of Nuclear Reactor Regulation (NRR) project manager.

> Charles E. Rossi, Director Division of Operational Events Assessment Office of Nuclear Reactor Regulation

Technical Contacts: Ralph Architzel, NRR (301)-492-0804

Loren R. Plisco, NRR (301)-492-1013

K. Steven West, NRR (301)-492-1220

	Attachme	nt: List of Rec	ently Issued N	RC Information N Dance W Jo Roisei	otick	11/26/91	memo,
OFC	:C/OGCB: DOTA:	NRR:D/DOEA:NRR:	In all	Jo Roixer.	cme	when	
NAME	:CBerlinger	CEROSS	Moraglie	OT O	LG:	and	Ted .
DATE	:12/02/91	:12/4-/91	OGC	mere	pri	rional	in ob tains
SI	OFFICIAL Document NRR J.Plisco M2/03/91		24to by	f. Misa	glia	ota	Declinger 12/2/21