

UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

MAY 5 1981



TO ALL LICENSEES OF OPERATING PLANTS AND HOLDERS OF CONSTRUCTION PERMITS

Gentlemen:

SUBJECT: ENGINEERING EVALUATION OF THE H. B. ROBINSON REACTOR COOLANT SYSTEM LEAK ON JANUARY 29, 1981 (GENERIC LETTER NO. 81-22)

Enclosed is our Engineering Evaluation Report for the Robinson Event. The primary reason for our evaluation was the loss of approximately 6,000 gallons of reactor coolant water from two separate leaks in the letdown train of the Chemical and Volume Control Letdown System (CVCS).

The evaluation is being forwarded for your information and training purposes. The evaluation of the event did not identify any safety concerns or any required immediate actions. There are four areas, however, which are under consideration for further action:

1. Whether a requirement should be placed upon operating plants to establish a procedure for identification and recovery from a spurious safety injection actuation (if such a procedure is not already in place).
2. Whether criteria for terminating SI should include provisions for isolating charging since charging flow could be considered high pressure safety injection for very small breaks.
3. Whether there is a need for a direct reactor trip on a safety injection actuation at other Westinghouse plants which do not have a direct trip.
4. Whether operation of the isolation valves in the CVCS at Robinson is causing the system to be operated in a manner which is contrary to its design bases.

If you have any questions regarding this evaluation, please contact your Project Manager.

Sincerely,


Darrell G. Eisenhut, Director
Division of Licensing
Office of Nuclear Reactor Regulation

Enclosure: *See jacket* As stated

ccw/encl: Service List

8106030321

Central Files

ALL POWER REACTOR LICENSEES

Docket No. 50-348
Farley Unit 1

Docket No. 50-313
Arkansas Unit 1

Docket No. 50-368
Arkansas Unit 2

Docket No. 50-317
Calvert Cliffs Unit 1

Docket No. 50-318
Calvert Cliffs Unit 2

Docket No. 50-293
Pilgrim Unit 1

Docket No. 50-325
Brunswick Unit 1

Docket No. 50-324
Brunswick Unit 2

Docket No. 50-261
H. B. Robinson Unit 2

Docket No. 50-10
Dresden Unit 1

Docket No. 50-237
Dresden Unit 2

Docket No. 50-249
Dresden Unit 3

Docket No. 50-254
Quad-Cities Unit 1

Docket No. 50-265
Quad-Cities Unit 2

Docket No. 50-295
Zion Unit 1

Docket No. 50-304
Zion Unit 2

Docket No. 50-213
Connecticut Yankee (Haddam Neck)

Docket No. 50-3
Indian Point Unit 1

Docket No. 50-247
Indian Point Unit 2

Docket 50-286
Indian Point Unit 3

Docket No. 50-155
Big Rock Point

Docket No. 50-255
Palisades

Docket No. 50-409
Lacrosse

Docket No. 50-269
Oconee Unit 1

Docket No. 50-270
Oconee Unit 2

Docket No. 50-287
Oconee Unit 3

Docket No. 50-334
Beaver Valley Unit 1

Docket No. 50-302
Crystal River 3

Docket No. 50-335
St. Lucie Unit 1

Docket No. 50-250
Turkey Point Unit 3

Docket No. 50-251
Turkey Point Unit 4

Docket No. 50-321
Edwin I. Hatch Unit 1

Docket No. 50-366
Edwin I. Hatch Unit 2

Docket No. 50-315
D. C. Cook Unit 1



8106080821

LDAR-5
INFO
LTR

DISTRIBUTION OF GENERIC LETTER 81-22, DTD 5/5/81

Braidwood
 Beaver Valley 2
 Bailly
 Bellefonte
 Byron

50-456/457
 50-412
 50-367
 50-438/439
 50-454/455



Callaway
 Comanche Peak
 Cherokee
 Catawba
 Clinton
 Diablo Canyon
 Farley 2
 Fermi 2

50-483/486
 50-445/446
 50-491/492/493
 50-413/414
 50-461/462
 50-275/323
 50-364
 50-341

Grand Gulf
 Hartsville
 Hope Creek
 Harris
 LaSalle
 Limerick
 Marble Hills
 Millstone 3
 McGuire
 Midland

50-416/417
 50-518/519/520/521
 50-354/355
 50-400/401/402/403
 50-373/374
 50-352/353
 50-546/547
 50-423
 50-369/370
 50-329/330

Nine Mile Point 2
 Phipps Bend
 Palo Verde
 Perry
 River Bend

50-410
 50-553/554
 50-528/529/530
 50-440/441
 50-458/459

Summer
 Susquehanna
 Shoreham
 San Onofre 2/3
 Salem 2
 St. Lucie 2
 Seabrook
 South Texas
 Sequoyah

50-395
 50-387/388
 50-322
 50-361/362
 50-311
 50-389
 50-443/444
 50-498/499
 50-327/328

Vogtle
 Wolf Creek
 Waterford
 WNP-2
 WNP 3&5
 Watts Bar
 WNP 1 & 4

50-424/425
 50-482
 50-382
 50-397
 50-508/509
 50-390/391
 50-460/513

Yellow Creek
 Zimmer

50-566/567
 50-358

*Rec'd w/ Ltr. dtd
1571#27 5/5/81*

ENGINEERING EVALUATION OF THE H. B. ROBINSON

REACTOR COOLANT SYSTEM LEAK ON JANUARY 29, 1981

by the

**Office for Analysis and Evaluation
of Operational Data**

March 23, 1981

**Prepared by: Wayne D. Lanning
Lead Reactor System
Engineer**

NOTE: This report documents results of studies completed to date by the Office for Analysis and Evaluation of Operational Data with regard to a particular operating event. The findings and recommendations contained in this report are provided in support of other ongoing NRC activities concerning this event. Since the studies are ongoing, the report is not necessarily final, and the findings and recommendations do not represent the position or requirements of the responsible program office of the Nuclear Regulatory Commission.

*FDH-5
Info Ltr.*

TABLE OF CONTENTS

	<u>Page</u>
1. EVENT DESCRIPTION	1
2. EVALUATION OF THE EVENT	3
2.1 Operator Actions	3
2.2 Charging Flow Termination.	4
2.3 Safety Injection Actuation	5
2.4 Pressurizer Spray.	7
2.5 Relief Valve Bellow Failure.	7
2.6 Letdown Isolation Valves	8
2.7 Leakage Inside Containment	10
2.8 Drain Valve and Pipe Cap	10
2.9 Failure of Fire Protection Isolation Valve	11
3. CONCLUSIONS	11
4. REFERENCES.	13

Table

Number

1 Sequence of Events.	14
-------------------------------	----

APPENDIX A - Information Provided by Licensee at Meeting on February 20, 1981

1. Draft Plant Operating Experience Report
2. Operator's Log
3. Shift Foreman Log
4. Strip Charts
5. Figure 1 - CVCS Diagram (excerpt)
6. Figure 2 - Containment Sump Volume

1. EVENT DESCRIPTION

A sequence of events is contained in Table 1. Problems with both oil pumps in the turbine electro-hydraulic (E-H) system forced the plant to initiate a plant shutdown. During the process a safety injection signal was generated by a high steam flow coincident with low RCS average temperature. The high steam flow signal was generated by the governor valves spiking open, believed to be caused by the erratic operation of the turbine E-H system. The low average temperature was the result of overcooling the RCS by excessive injection of boric acid solution. The safety injection (SI) signal tripped the reactor. The reactor power had been reduced from 100% to approximately 6% at the time of trip. The duration of the high steam flow/low average temperature signal was apparently not of sufficient duration to latch the "A" train nor close the main steam line isolation valves. Both were manually actuated. A containment fire alarm was received shortly after the SI.

After having determined that a spurious SI had occurred, the operators initiated actions (e.g., reset SI, feedwater isolation, restore letdown) to continue to hot standby condition. During the automatic isolation of the CVCS letdown line due to the spurious SI, it is believed that the outermost isolation valves (see Figure 1, valves 204A&B) closed faster than the two open orifice isolation valves (CVC-200B and C), or that leakage past the orifice isolation valves resulted in the opening of the relief valve and the rupturing of the bellows on the relief valve (CVC-RV-203). In addition, a pressure surge due to the isolation valves closing caused a drain cap to be blown off. Unaware of these two failures, letdown flow was reestablished. Subsequently, containment pressure and dew point increased. The containment pressure and humidity increases attached additional significance to the already decrease

RCS pressure. Letdown was secured (valves closed and sequence unknown) about 15 minutes after letdown was reestablished. A containment entry was made. A leak was identified in the letdown system area but no fire existed. The heat sensitive fire alarm detected the steam from the leak in the letdown system, which implies that this leak occurred in the CVCS during the first SI. Approximately 3,000 gallons was estimated to be in the containment sump based on level indication in the control room.

After the letdown was thought to be isolated, the pressurizer pressure continued to decrease and the level to increase. A second safety injection occurred on low pressurizer pressure. Both trains of safeguards equipment actuated. The level increase was the result of continued charging flow and heatup of the primary system (the MSIVs had been closed to recover average temperature earlier). The cause for the depressurization could not be identified positively.

Four hours after the first entry, a second containment entry was made and the leak was identified to be from a drain line which was still leaking. The drain line is located upstream of the orifice isolation valves (see Figure 1). The cap on the drain pipe was missing and valve (CVC-200E) was manually closed. Water in the containment sump had now increased to approximately 4,500-6,000 gallons. Evidently, the two level control valves (CVC-LCV-460A&B) were leaking at five to seven gallons per minute between 0650 and 1120. After the drain valve was closed during the second containment entry, the RCS pressure continued to decrease.

Many steps were taken to determine the cause of the decreasing RCS pressure after letdown had been isolated; e.g., isolating charging line auxiliary spray, checking pressurizer relief and safety valve leakage, and increasing pressurizer heater output. The cause was identified when the operators

stopped two of the three reactor coolant pumps in the loops with the pressurizer spray scoops and the pressure began to increase. One of the two pressurizer spray valves was not fully closed. Positive identification of spray valve RC-455B as the leaking valve was made later. The spray valve position is indicated by demand, not stem position, which delayed identification of the cause for depressurization.

During this event, steam generator samples indicated a primary-to-secondary leak of approximately 0.5 gpm based on activity of 10^{-4} $\mu\text{C}/\text{ml}$. Steam generator "B" was isolated on the secondary side. Subsequent samples indicated decreasing activity and no leak. The licensee has concluded that the increased activity was the result of "crud" being agitated during isolation of the steam generators during the event.

Repairs were made to the spray valve and the relief valve bellows. The cap was replaced on the drain line and all drain valves were verified closed. The unit was back online on February 1, 1981.

2. EVALUATION OF THE EVENT

2.1 Operator Actions

Operators responded to the events in a systematic and timely fashion. Data entered into the logs were detailed and accurate. After the plant was stabilized, the licensee contacted Westinghouse to ensure that their diagnoses were correct and no other unforeseen problems existed.

One shortcoming identified was the lack of a procedure for recovery from a spurious safety injection actuation. Guidelines should be available to the operators to differentiate between a real and spurious SI actuation. The licensee indicated that a procedure will be written for recovery from a spurious SI (identification criteria not included). For this event, resetting the SI

head and temperature. However, pressurizer pressure, level and average temperature had all been increasing prior to the SI and had "stabilized" for only about 10 minutes before resetting SI. In retrospect, there was still a small residual coolant leak and the spray valve was open. However, SI had been initiated on signals indicative of a steam line break and since secondary system conditions were stable and the governor valve position recorder indicated spurious valve opening, the operators correctly diagnosed the SI signal as spurious for this event.

An area of improvement would have been to test the safety injection actuation and main steamline isolation signals since one train of SI failed to latch and the MSIs failed to close. Both were manually actuated. Although both SI trains actuated on the second safety injection signal, this was not adequate verification of operability on high steam flow/low average temperature actuation before returning to power. These tests could have helped substantiate that the signal was not of sufficient duration to latch the SI relay and close the MSIs.

2.2 Charging Flow Termination

Although SI actuation occurred twice, no boric acid was injected into the RCS based on samples of the boric acid injection tank. This was because the RCS system pressure exceeded the shutoff head (1,500 psig) of the SI pumps at the times of actuation. Hence, the charging pumps were making up boron deficiency during the event.

During the attempts to identify the cause for the depressurization and recognizing that pressurizer spray could cause the depressurization, the charging flow was isolated (closed valve CVC-HCV-121) to terminate a possible leak from the auxiliary spray valve (Figure 1). This operator action did not terminate

all makeup flow to the RCS. The flow path was maintained to the RCP seals which would provide makeup flow (approximately 60 gpm). RCS conditions (approximately) at this time were: Pressure = 1,600 psig; T_{avg} = 542°F; pressurizer level = 56% and increasing; normal steam generator level for the condition; and margin to saturation was approximately 50-55°F.

The charging line was isolated from 0726 to sometime after 1932 (shift foreman's log). No consequences resulted from isolating the normal charging flow for this event although SI flow was not available due to the pump head limits. However, it is suggested that NRR determine whether isolating the charging flow is advisable for small loss-of-coolant accidents or when the system pressure is above the shutoff head of the SI pumps. Westinghouse has indicated that no credit was taken for charging flow for the ECCS analyses. The emergency procedure for depressurization (EI-1) does not include criteria for terminating charging flow. The charging pumps are a part of the CVCS and not considered a part of the safety injection system at Robinson. However, the charging pumps provide high pressure makeup flow when the RCS pressure exceeds the shutoff head of the SI pumps. Ensuring that charging flow is not interrupted for the systems employing low/medium heat SI pumps may be desirable to enhance safety.

2.3 Safety Injection Actuation

The first safety injection actuation occurred on a "high steam line flow/low T_{avg} " signal. The licensee's review of the event indicated that the momentary spike-opening of the turbine governor valves caused the steam flow, in at least two steam lines, to exceed the steam flow set point for a period of about 25 msec. The combination of high steam flow in 2/3 steam lines and the existing low average temperature of the reactor coolant generated a main steam isolation valve (MSIV) closure signal and a SI actuation signal.

however, only train B of safeguards equipment responded - the other train of safeguards equipment and all the MSIVs did not actuate. Licensee's observations are that the MSIVs require a signal duration of one second to close and that the SI actuation relays, including SI logic train latching relay, require a signal duration greater than 25 msec to actuate. Since the SI signal was of less than 25 msec duration, only the train B latching relay actuated. Reactor trip, emergency diesel start, feedwater isolation and other safeguards equipment actuations for train B occurred as a consequence of SI train B actuation.

Reviewing the logic diagram of Robinson's Safeguard Actuation Signals (Dwg CP 300-5379-2759 sh B, rev 5) it is seen that the reactor trip signal is initiated on SI actuation along with emergency diesel start, feedwater isolation and safeguards sequence actuation. A review of a later Westinghouse logic diagram (typical) shows that the reactor trip signal is derived separately from the SI actuation signal; i.e., the reactor trip signal is taken off "upstream" of the SI actuation signal, similar to the MSIV closure signal on Robinson. This could mean that on certain spurious SI actuation events of short signal duration, SI, feedwater isolation and auxiliary feedwater system actuations may occur with no simultaneous reactor trip occurring. The comparison of logic diagrams also shows that the P-4 interlock (reactor trip breaker position) in the the Reset/Block feature of SI logic of later Westinghouse units is not provided in the Robinson design. Additional analysis would be needed to ascertain the significance of different reactor trip logic for Westinghouse plants. The need to provide a direct reactor trip on spurious safety injection actuation is referred to NRR for review.

2.4 Pressurizer Spray

The open spray valve could not be identified due to lack of spray flow indication or actual spray valve position. The failure of the valve to close evidently did not affect the capability of the valve to open as evidenced by subsequent testing. The Licensee is evaluating the possibility of relocating and replacing the spray valves during the next refueling outage. Previous problems have been experienced with the spray valves and their location in containment reduces their accessibility for maintenance.

2.5 Relief Valve Bellows Failure

The licensee has experienced previous failures of this Crosby relief valve (number JB-36, Type B, shop drawing number H51380). Basic information about the valve and the discharge piping configuration were obtained from CP&L and Crosby Valve Company and are as follows:

Relief Valve

- 2" diameter inlet, 3" diameter outlet
- Set pressure, 600 psig
- System pressure, 300 psig (approximate)
- Dynamic backpressure, 25 psig (specified)
- Bellows tested to 150 psig

Piping

- A horizontal run exits from the relief valve before turning vertically up for at least 12 feet to the pressurizer relief tank.

CPR indicated that the bellows fails every time the relief valve lifts. Since the bellows has been tested to 150 psig, it would appear that the system is operating quite differently from the anticipated mode. The dynamic backpressure probably exceeds 150 psig (six times the specified 25 psig). A mechanism that could cause the high pressure might be stagnate water from either steam condensation or valve leakage in the line from the relief valve to the pressurizer relief tank. Boric acid crystal formations may also be a possibility. When the valve opens, water or other debris in this line could restrict steam flow and cause a high dynamic backpressure until the line is cleared. Also, if the line is filled with stagnate boric acid water, the bellows may be susceptible to corrosion attack, but corrosion has not been identified from previous failures and replacements. From an operational viewpoint, the failure mode for the bellows should be identified and changes necessary to prevent additional failures should be implemented. The operation of the CVCS isolation valves may be a major contributor to the bellows failures and is discussed in Section 2.6.

2.5 Letdown Isolation Valves

The isolation valves played a dominant role in the sequence of events at Robinson. The failure of the bellows on the relief valve was attributed to the closing of the out board valves (CVC-204A&B) before the closing of the orifice isolation valves (CVC 200B&C) upstream of the relief valve. Consequently, the set point (600 psig) of the relief valve was reached since this part of the CVCS was pressurized by the reactor coolant system which was at approximately 1,200 psi. The design pressure downstream of the valves (CVC-200 series) is 600 psig. The sequential operation of the isolation valves is evidently causing this part of the CVCS to be pressurized to at least the setpoint of the relief valve, as evidenced by the opening of the relief valve whenever the CVCS is isolated.

In addition to the isolation valves, valves LCV-460 A and B (Figure 1) were closed in an attempt to isolate the leaking drain valve/pipe. Both of these valves leaked which permitted an additional 3,000 gallons (approximately) to leak into the containment after the letdown system was thought to be isolated. The licensee did not perform any maintenance on these valves to ensure their operation before returning to power since these are not containment isolation valves. These valves are part of the reactor coolant pressure boundary and are designed to close on low pressurizer level to conserve RCS inventory.

The design and operation of this part of the CVCS raises two concerns: first, the potential for overpressurizing the system to 2,200 psia assuming the downstream isolation valves (CVC-200A&B) are closed; and secondly, the capability to isolate a potential break downstream of valves LCV-460A&B. The licensee has indicated that the relief valve is designed to prevent overpressurization of the CVCS. The failure of the bellows does not appear to affect the pressure relieving function of the relief valve. In addition, the flow control valves (CVC-LCV-460A&B) have been designed to isolate a break downstream of these valves for the maximum size break and RCS conditions.

The functional and testing requirements for the flow control valves are not clear. These valves should be ASME Class 1 since there are no valves upstream and the valves downstream are classified as ASME Class 2. However, these flow control valves are not identified in the Robinson Inservice Inspection and Testing Program (Reference 4). Since these valves are on the RCS pressure boundary and are designed to isolate the RCS on low pressurizer level, it is not clear why maintenance on the valves was not required after they were known to leak and before returning to power.

Both of these concerns could lead to a small loss-of-coolant event inside containment. This postulated event is within the scope of an analyzed small break loss-of-coolant accident and not a new safety concern. However, from an operational consideration, overpressurizing the CVCS could be prevented, provided the orifice isolation valves were closed before the outboard isolation valves. Correcting the valve closing sequence for isolation would also reduce the challenge to the relief valve.

2.7 Leakage Inside Containment

The licensee has acknowledged that the quantity of water that leaked into containment can only be approximated. The estimated 6,000 gallons (corresponding to approximately 15" in the sump) is a small fraction of the range of indication in a 65,000-gallon capacity sump (See Figure 2). A mass balance was not possible since neither charging flow nor volume control tank level are recorded. The major leak was after letdown flow had been reestablished between 0635 and 0650. This could account for approximately one half of the 3,000 gallons indicated at 0650. The drain valve could have also been leaking at an unknown reduced rate from the initial 5: until letdown was restored (approximately ten minutes). The ruptured bellows on the relief valve also contributed some amount to the inventory in the sump. These sources in combination with the inaccuracy of the sump measurements can lead to the conclusion that all the leak sources had been identified.

2.8 Drain Valve and Pipe Cap

The leaking valve was CVCS-200E (see Figure 1) not CVCS-204C as reported by IE (Reference 1). This helps to understand the leak rates and quantity of water reported in the LER (Reference 2) and the IE evaluation.

The licensee's explanation for the missing cap on the pipe was that when

the orifice isolation valves closed, a pressure pulse was applied to the valve and cap. Since the valve was partially open and the cap not tightly secured, the cap was blown off. The licensee believed that vibration in the CVCS (induced by the charging pumps) caused movement of the valve and cap. The valve position was last verified on October 11, 1990 during a refueling outage. Since the drain pipe is located close to the pressure reducing orifices, the flow instabilities at these orifices could also induce vibration in the CVCS. ²

All drain pipes with valves have been verified closed. Most valves have been chained and locked.

2.9 Failure of Fire Protection Isolation Valve

When a Phase A isolation signal was generated by the safety injection actuation, one (FP-248) of the four containment isolation valves failed to close due to a tripped breaker. Since the other isolation valve in the line closed, containment isolation was achieved. This failure had no bearing on the leak and was a separate reportable event.

3. CONCLUSIONS

The event at H. B. Robinson involved four separate, somewhat unrelated failures: (1) pump failures in the turbine EHC system; (2) two separate leaks in the CVCS (related failures); (3) an undetected open pressurizer spray valve; and (4) leaking valves in the CVCS. The event did not appear to include any safety concerns.

The following areas of review concerning this event are referred to NRR for consideration:

- a. Whether a requirement should be placed upon operating plants to establish a procedure for identification and recovery from a spurious safety injection actuation (if such a procedure is not already in place).
- b. Whether criteria for terminating SI should include provisions for isolating charging since charging flow could be considered high pressure safety injection for very small breaks.
- c. Whether there is a need for a direct reactor trip on a spurious safety injection actuation at other Westinghouse plants which do not have a direct trip.
- d. Whether operation of the isolation valves in the CVCS at Robinson is causing the system to be operated in a manner which is contrary to its design bases. The closing sequence for the isolation valves appears to cause part of the CVCS to be pressurized to the setpoint of the relief valve and may be contributing to the failure of the relief valve bellows whenever the system is isolated.

AEDD did not find any basis for a need to study this event further. A formal response from NRR is not requested.

This event and the operator's response provide a good example of an operating experience which should be disseminated to other licensees for information and training purposes.

4. REFERENCES

- (1) Memorandum, H. Woods to E. Jordan, Subject: H.B. Robinson Event on January 29, 1981, dated February 12, 1981.
- (2) Licensee Event Report 81-RMS, H.B. Robinson Steam Electric Plant, Unit 2, Docket 50-261, dated February 12, 1981.
- (3) Meeting with Carolina Power and Light Company in Bethesda on February 20, 1981.
- (4) Letter, E. E. Hiley, CP&L to S. Varga, Subject: H. B. Robinson Steam Electric Plant Unit No. 2, Inservice Inspection and Testing Program, dated March 10, 1981.

Table 1
SIGNIFICANCE OF EVENTS

January 20, 1981

Plant at 100%

Primary to secondary leak of approximately 0.7 gpm.

0500 "A" EHC oil pump seal leak, "B" EHC pump already out of service due to vibration.

0541 Started load reduction.

0542 Added horic acid to RCS.

0543 Started "C" charging pump, "B" charging pump running, "A" charging pump inoperable.
Opened CVC-200A orifice isolation valve, CVC-200C already open.

0549-

0549 Continued to add horic acid.

0617 Stopped "1" feedwater pump and condensate pump due to erratic FWP behavior.

0620 Tavg reached low Tavg setpoint (547°F) alarm.

0623 Generator output breaker opened.
Turbine governor valves spike open.
SI signal and MSIV closure signal on high steam flow/low Tavg.

SI train "B" automatically started.
Phase A isolation; safeguard B emergency equipment started.
Reactor trip on SI signal.
Tavg = 532°F.
PZR pressure = 2210 psia.
PZR level = 13%.

0625 Fire alarm in containment.
Pressurizer relief tank level alarm due to opening of CVC-RV-203 relief valve.
Bellows probably ruptured and drain cap was blown off.
MSIVs closed manually.
SI train "A" started manually. Started "A" DG, AFWP, RHR, manually.
Letdown valves CCV-460A&B manually closed (should have automatically closed on PZR level of 13%).

0627 Reset SI and feedwater isolation.

0634 Attempted to restore letdown flow but CVC-200A would not open (instrument air system isolated on Phase A isolation).
Restored letdown flow after resetting isolation signals.
Pressurizer pressure started decreasing sharply (-2000 psig).
Containment dew point and pressure started increasing.

0637 Received condensate collection alarm from the coolers.
Diesel generators A and B stopped manually.

- 0645 Isolated letdown flow. (Isolation valves closed from control room.)
Containment dew point and pressure decreased.
Pressurizer pressure still decreasing (1840 psig).
Tavg increasing.
Pressurizer pressure increasing.
Notified NRC by EMS.
- 0650 Containment sump level indicated approximately 3000 gallons.
- 0700 First containment entry to check for leak and fire.
- 0705 Second SI actuation on low pressurizer pressure.
Both trains and all equipment started.
Pressurizer pressure = 1715 psig.
Pressurizer level = 50%.
- 0705-
0727 Operators attempting to determine cause of depressurization.
- 0722 Steam dumps opened manually to control pressurizer level.
- 0727 Reactor coolant pumps B and C stopped and charging line
isolated to eliminate possibility of leaking auxiliary spray valves.
Increased pressurizer heater output to maximum.
Pressurizer pressure started increasing.
- 0729 Continued cooldown using steam dumps.
- 0735 Pressurizer pressure increasing (= 1720).
Tavg constant = 540.
Pressurizer level = 50%.
- 0738 Stopped diesel generators A&B.
- 0741 Stopped "B" RHR pump.
- 0745 Opened breakers on containment sump pumps.
- 0825 Secured SI pumps.
- 1000 Continued plant cooldown.
Sample on "A" steam generator indicated 0.5 gpm primary to secondary
leak. Isolated "B" steam generator.
Second sample showed decreased leakage (0.25 gpm).
- 1120 Second containment entry. Found CVC-200E open and cap missing.
Found bellows on relief valve CVC-203 ruptured.
Contacted Westinghouse.

171A Blocked low pressure SI.

1230 Closed CVC-200E.
Isolated letdown by closing CVC-3090.
Containment sump level was 4,500-6,000 gallons.

1445 "B" charging pump out of service due to leaking relief valve

1A30 Aligned "A" charging pump for operation after completing surveillance tests.

(late entry) Tested pressurizer spray valves.

1913 Started "B" RCP.

1937 Started "C" RCP.

(Later) Placed charging line and CVCS letdown in service. Removed excess letdown line from service.

2315 Spray valve RCS-455B identified as leaking spray valve
No additional primary to secondary leak identified.

January 30, 1981 at 1700 plant on-line

APPENDIX A

INFORMATION PROVIDED BY LICENSEE . MEETING ON FEBRUARY 20, 1981

Contents:

1. Draft Plant Operating Experience Report
2. Operators Log
3. Shift Foremen Log
4. Strip Charts
5. Figure 1 - CVCS Diagram (excerpt)
6. Figure 2 - Containment Sump Volume

PLANT OPERATING EXPERIENCE REPORT

1. Event Date

January 29, 1981

2. Identification of Occurrence

- A) A spurious safety injection signal initiated by a "High Steam Line Flow/Low T_{avg} " signal.
- B) Reactor Coolant System leak through letdown line drain valve CVC-200E.
- C) Primary plant depressurization leading to a second safety injection signal initiated by a "Low Pressurizer Pressure" signal.

3. Conditions Prior to Occurrence

A plant shutdown to hot standby was in progress to repair a secondary plant problem. The unit had been operating at 100% reactor power (725 MWe) with normal Reactor Coolant System pressure and temperature.

4. Description of Occurrence (All Times Are Approximate)

- A) At 0624 hours on January 29, 1981, a safety injection signal initiated "B" train of safeguards. "A" train equipment was manually started at 0625 hours.
- B) At 0635 hours on January 29, 1981, the chemical and volume control letdown system was restored and system pressure began decreasing with an increasing containment pressure and dew point. Letdown was secured at 0650 hours.
- C) At 0705 hours on January 29, 1981, a safety injection signal initiated both trains of safeguards.

3. Designation of Apparent Cause of Occurrence

At approximately 0400 hours, "A" turbine electro hydraulic (E-H) oil pump developed a seal leak. "B" E-H oil pump had been taken out of service earlier due to high vibrations. At 0541 hours, the decision was made to shut down to hot standby before receiving a trip signal due to the loss of E-H oil. Attachment No. 1 contains additional information on the failure of the E-H Oil System.

At 0624 hours, immediately following opening the generator output breakers, the reactor tripped and a safety injection was initiated by a "High Steam Line Flow/Low T_{avg} " signal. Only "B" train of the safeguards was activated. "A" train equipment was manually started at 0625 hours. It was determined that the erratic operation of the E-H Oil System and the fact that the operators were switching from "A" E-H oil pump to "B" E-H oil pump caused the governor valves to spike open. The resultant steam flow spike was high enough to cause a "High Steam Line Flow/Low T_{avg} " signal but it was of insufficient duration to fully latch the "A" safeguards train seal-in relay. The seal-in relays in the safeguard trains are latching relays that require a finite period of time in the energized mode to mechanically latch them into the closed position. Attachment No. 2 contains additional information on the partial safety injection.

The steam line isolation signal that was generated from the "High Steam Line Flow/Low T_{avg} " signal was of insufficient duration to allow the main steam isolation valves to go shut. The open signal was reinstated so quickly

3. Designation of Apparent Cause of Occurrence (Continued)

after the isolation signal that the valves were unable to travel far enough to isolate the steam flow. The main steam isolation valves were manually shut to reduce the secondary steam demand following the reactor trip, thereby promoting the return of T_{avg} to the no load setpoint.

At 0627 hours it was determined that safety injection conditions did not exist and that the initiation was spurious. The safety injection and feedwater isolation signals were reset. The chemical and volume control letdown system was restored at 0635 hours. The Reactor Coolant System pressure had been slowly decreasing, but when letdown was returned to service, the containment pressure and dew point began increasing. Another indication of abnormal containment conditions was a fire alarm from the area of the containment operating deck which was received at approximately 0624. Letdown was secured at 0650 hours with Reactor Coolant System pressure at 1850 psig. The initial containment entry made at 0700 hours to investigate the abnormal conditions confirmed that the RCS leakage was from the letdown line and that no fire existed. A subsequent containment entry at 1120 hours further identified the source of the leak as valve CVC-200E, a drain valve on the letdown line, which was found open and the pipe cap missing. The leak that resulted from the open drain valve was approximately 5 to 7 gpm with the letdown air operated valves closed and approximately 100 gpm with letdown flow established. The leak was completely stopped by shutting valve CVC-200E. The letdown flow was not restored until after the condition was found and repaired. Additional information regarding the RCS leak and containment fire alarm can be found in Attachment No. 3.

3. Designation of Apparent Cause of Occurrence (Continued)

However, even with the lutdown control valves closed, the pressurizer pressure continued to decrease, leading to the second safety injection initiation at 0705 hours from a "Low Pressurizer Pressure". Both trains of the safeguards equipment functioned as designed. At 0727 hours, charging was isolated (except reactor coolant pump seal injection) to eliminate auxiliary spray and "B" and "C" reactor coolant pumps were secured to prevent the pressurizer spray valves from circulating cooler water from the Reactor Coolant System into the pressurizer through the spray valves, decreasing the pressure. It was subsequently discovered that the pressurizer spray valve from "C" reactor coolant loop had probably opened and not fully reseated. The pressurizer pressure immediately started to increase. The reactor coolant system was stabilized at approximately 2050 psig and 535°F with pressure controlled by the pressurizer heaters and temperature controlled by the secondary steam dump. Attachment No. 4 contains additional information on the reactor coolant system pressure transient caused by the spray valve malfunction.

Coincidental with the decreasing pressurizer pressure, pressurizer level was increasing. This was caused by two factors. 1) The charging flow from two charging pumps was maintaining or increasing the system volume, including the system losses through CVC-200E. The slightly open pressurizer spray valve was causing the pressure to decrease. 2) The density changes in the reactor coolant due to the slowly increasing RCS temperatures and the heat up of the relatively cold water added by the charging system caused the system to expand. These factors combined to cause an increasing pressurizer level. The margin to subcooling remained

5. Designation of Apparent Cause of Occurrence (Continued)

greater than 55°F throughout the entire transient. The minimum subcooling margin occurred at 0720 hours, with reactor coolant system pressure at 1620 psig and temperature at 551°F.

The relief valve on the letdown line, CVC-RV-203, lifted following the first safety injection initiation. This was apparently due to the isolation valves, CVC-204A and CVC-204B, closing slightly faster than the orifice isolations, CVC-200A, CVC-200B and CVC-200C, or leakage past one or more of the orifice isolation valves. This caused the pressure between the valves to increase above the set pressure for CVC-RV-203 (600 psig). The valve reset after the letdown isolations closed, but the bellows had ruptured. Attachment No. 3 also contains additional information regarding valve CVC-RV-203.

6. Analysis of Occurrence

Several problems with the turbine E-H Oil System had occurred within approximately one week preceding the reactor trip and safety injection on January 29, 1981 which could have contributed to the initiation of the event. These problems are summarized as follows:

- 1) The E-H oil had become contaminated with water due to a ruptured E-H oil cooler approximately one week prior to this event. However, the E-H oil had been purified (replaced) and restored to specification prior to this event. It is not felt that this contributed to the following problems.
- 2) On January 28, 1981 "B" E-H pump unloader developed a fatigue crack in its discharge nipple. While replacing this nipple, air was introduced into the "B" E-H oil pump portion of the system. When

-DRAFT-

6. Analysis of Occurrence (Continued)

- "B" E-H oil pump was restarted. It caused excessive vibrations throughout the E-H Oil System. "A" E-H oil pump was restarted and "B" E-H oil pump was secured after a brief period of operation.
- 3) The seal leak which developed on "A" E-H oil pump on January 29, 1981 which necessitated the turbine shutdown is felt to have been caused by either age or the excessive-system vibration.
 - 4) As the seal leak on "A" E-H oil pump became larger during the remaining moments of the turbine shutdown, the operators decided to run "B" E-H oil pump despite the vibration problem in order to allow the leak to be isolated so a normal turbine shutdown could be completed. Coincidentally, "B" E-H oil pump was started as the generator output breakers were opened. When the generator output breakers are opened the turbine switches from Load control to speed control.

One, or some combination, of the above probably caused the turbine governor valves to spike open. The exact cause cannot be determined. This caused the first safety injection initiated on a low reactor coolant system average temperature coincident with high steam line flow. The high steam flow was of a very short duration, thus only "B" safeguards train was activated and the main steam isolation valves remained open.

Letdown line drain valve CVC-200E had vibrated open since it had last been verified shut on October 11, 1980. It is postulated that the pressure transient caused by the letdown line isolation caused the pipe cap to blow off. Thus, a Reactor Coolant System leak existed.

-DRAFT-

-DRAFT-

6. Analysis of Occurrence (Continued)

The continued decrease in pressurizer pressure was caused by the failure of the pressurizer spray valve from "C" reactor coolant system loop (RCS-455B) to fully shut after opening during the transient. The event identification was complicated by the letdown relief line lifting to the pressurizer relief tank which indicated that there were two separate leaks. The Reactor Coolant System pressure decrease was stopped when "B" and "C" reactor coolant pumps were secured and the charging line was isolated to eliminate auxiliary spray. With the pressure decrease stopped, operator control of the Reactor Coolant System was re-established and normal hot shutdown conditions were established.

Following the first safety injection at 0624 hours, the fire protection containment isolation valve FP-248 did not shut automatically and had to be manually closed. Attachment No. 5 contains additional information on the performance of the fire protection containment isolation valve.

A summary of the P250 computer output for this event is provided as Attachment No. 6.

7. Corrective Action

- A) The E-H oil was completely replaced with new oil.
- B) "A" E-H oil pump and unloader were replaced.
- C) The unloader and discharge nipple on "B" E-H oil pump were replaced.
- D) The valve stem on RCS-455B was lubricated, stroked and valve positioner was adjusted to ensure the valve will fully close. RCS-455A was also checked for proper operation.


-DRAFT-

7. Corrective Action (Continued)

- E) CVC-200E was locked closed and the pipe cap was replaced. Similar valves in the letdown and charging lines were also locked closed or otherwise verified to be secured.
- F) The breaker over current trip setpoints on the four Fire Protection System containment isolation valves have been adjusted and checked to insure proper valve performance.
- G) The event was fully analyzed by the plant staff and Westinghouse, and the results discussed with the NRC, Region II, to ensure that all safety concerns were identified and resolved prior to returning the unit to operation.


Unit 2 Operating Supervisor


Manager - Operations and Maintenance


General Manager

-DRAFT-

SEQUENCE OF EVENTS

- 0541 Unit shutdown was initiated due to E-H System trouble.
- 0620 Tavg reached the low Tavg setpoint (543°F) during plant shutdown.
- 0624 Generator output breaker is opened removing unit from system.
- Load on unit is 42.
- Turbine governor valve(s) spike open (see Attachment No. 1).
- High Steam Flow/Low Tavg signal generated.
- MSIV's closure signal (see Attachment No. 2).
- SI signal, train "B" actuates (see Attachment No. 2).
- CV isolation valve FP-248 fails to close (see Attachment No. 5).
- Minimum Tavg = 532°F (based on incore thermocouple).
- PZR pressure = 2100 psig.
- PZR level = 132.
- 0625 Fire alarm at CV operating deck (see Attachment No. 3).
- Pressurizer relief tank level alarms from CVC-203 discharge (see Attachment No. 3).

-DRAFT-

0625 (Contd.) Primary pressure begins to decrease (see Attachment No. 4).

MSIVs manually closed.

SI train "A" equipment manually started.

Letdown valves 460A & B manually shut.

0627 Manually reset SI.

0635 Restored letdown.

Containment dew point and pressure begin to increase.

0630 Isolated letdown (suspected leak in letdown system).

0656 Tavg reaches maximum value of 552°F and holds steady.

PZR pressure = 1750 psig.

PZR level = 50%.

0700 Containment entry to check for leak and fire (see Attachment No. 3).

0705 Second SI signal due to low PZR pressure, 1715 psig.

Both "A" and "B" trains activated.

0705-0727 Operators attempt to determine cause of depressurization. The following equipment was checked:

-DRAFT-

0705-0727
(Contd.)

- a) PZR safety valves flow indicators.
- b) PZR PORV discharge line temperature.
- c) PZR block valve position.
- d) PZR relief tank level.
- e) PZR relief tank pressure.
- f) PZR spray valve position (the valves indicated closed but since this indication is demand indication the valve controllers were again manually closed).

0722

The RCS temperature was lowered slightly using the secondary steam dumps to help control the increasing pressurizer level.

Tavg = 549°F.

PZR pressure = 1620 psig.

PZR level = 62%.

0727

The charging line was isolated to eliminate the possibility of auxiliary spray causing the depressurization. RCP "B" and "C" were stopped to eliminate the possibility of main spray flow causing the depressurization.

Pressurizer pressure begins to rise.

0735

Tavg = 543°F.

PZR pressure = 1715 psig.

PZR level = 60%.

0820 PZR pressure stabilized.

Tavg = 335°F.

PZR pressure = 2050 psig.

PZR level = 45%.

1120 Made second containment entry and isolated CVC-200E at 1230 hours.

1120 (1-29-81)

to 1700 (2-1-81) Review and analysis of transient with Westinghouse. Discussions of transient with NRC Region II.

2315 (1-29-81) RCS-453B positively identified as leaking spray valve.

1700 (2-1-81) Plant on-line.

-DRAFT-

ATTACHMENT NO. 1

E-H SYSTEM FAILURE

The E-H System had experienced several problems prior to the transient on 1-29-81. During the previous week the E-H fluid had become contaminated with water. (This contamination was restored to within specification.) On Wednesday morning, 1-28-81, a stainless steel nipple on the E-H System unloader on "B" pump cracked. This caused a loss of approximately X gallons of E-H fluid. The fluid and nipple were replaced and "B" pump restarted. However, the pump was immediately stopped due to noise and vibration. Several attempts were made to troubleshoot the problem but no definite cause was found. The system was left operating satisfactorily with one pump in service. At 0500 on 1-29-81 the second E-H pump, "A", developed a seal leak which caused E-H fluid to leak out of the system. At 0541 the operators began to take the unit off line to repair the E-H System. At 0624 while the unit was being separated from the system, the E-H System generated a pressure surge to the governor valves which resulted in the valves momentarily opening. Three factors could have contributed to the pressure surge. The turbine control was switching to speed control. The operators were trying to start "B" E-H oil pump to supply E-H oil during the final moments of the turbine shutdown. The E-H System had been contaminated by water during the previous week. This caused a momentary high steam flow to be sensed on at least 2 steam lines. The spike shows up on all three steam flow charts. The effect of this flow spike is described in Attachment No. 2.

The failure of "A" pump seal on the E-H System was due to age and transferred vibration from "B" pump. Subsequent to these pump failures, the unloader of pump "B" has been replaced and pump "A" was replaced in its entirety. The complete system was restored to service and is operating satisfactorily.

-DRAFT-

ATTACHMENT NO. 2

PARTIAL SI AT 0624 HOURS

On January 29, 1982 at 05:22 a unit shutdown was commenced to do repair work on the turbine E-H System. At approximately 0620 hours Tavg dropped below the low Tavg setpoint of 543°F due to an inadvertent overshoot during plant shutdown. At 0622 with the unit at 45% power the generator output breakers were opened disconnecting the unit from the system. At this time the turbine E-H control system switched to speed control and due to pressure instabilities in the E-H control system the turbine governor valves spiked open. A review of the event indicates that the spike caused an indicated steam flow in at least two areas lines to exceed the steam flow setpoint for a time period less than 25 msec. This indicated high steam flow in 2/3 steam lines combined with the low Tavg mentioned earlier generated a main steam isolation valve closure signal and a SI signal. The duration of this signal would be the same as the steam flow spike. It has been observed during periodic tests that the MSTVs require a signal duration of approximately 1 sec. to close and so none of the MSTVs closed on the momentary high flow/low Tavg signal. (The MSTVs were manually closed immediately by the operators in order to stabilize RCS temperature.) The SI signal is divided into 2 trains "A" and "B". Each of these trains contains several relays including a mechanical latching relay (Westinghouse Type MG6) which is used to lock in the SI train until manually reset. A signal duration greater than 25 msec. is required to insure that all relays close and the latching relays lock in. Since the SI signal was less than 25 msec. only the latching relay for train "B" fully engaged. The operators immediately noticed that train "A" had not engaged and so they manually started the train "A" equipment. Containment Isolation Phase A was initiated by train "B". No SI water was injected into the system since RCS pressure was ~2100 psig and the

-DRAFT-

-DRAFT-

ATTACHMENT NO. 2 (Continued)

shut off head of the SI pumps is 1500 psig. SI was manually reset at 0627 since the SI initiation was identified as spurious.

Once train "A" was manually initiated the SI System performed as expected, with the exception of CV isolation valve FF-148 (see Attachment No. 3). The actuation of the SI System did not effect the physical course of events during the transient, however it did obscure the cause of the RCS depressurization (stuck pressurizer spray valve). No repairs to the SI logic or components are considered necessary.

-DRAFT-

LETDOWN LINE LEAK

At 0624 an SI signal latched in the "B" train relay which generated a Phase A containment isolation. As part of the Phase A containment isolation five letdown valves closed (CVC-200A, B, C and CVC-204A, B). During this time the relief valve on the letdown line, CVC-RV-203, lifted. This was apparently due to the isolation valves, CVC-204A and CVC-204B, closing slightly faster than the orifice isolations, CVC-200A, CVC-200B and CVC-200C, or leakage past one or more of the orifice isolation valves. This then caused the pressurizer relief tank level to increase from approximately 70% (normal level) to 75.2% full. The pressure transient while causing relief valve CVC-RV-203 to lift also caused the relief valve bellows to rupture. At this same time, when the CVC-200A, B & C valves closed, a pressure surge was applied to CVC-200E. This valve is normally closed but had apparently vibrated partially open during plant operations. The valve position was last verified on 10-11-80. One possible cause for the vibration at CVC-200E is the positive displacement charging pumps. These pumps have a history of vibration induced problems for which solutions are currently under development. CVC-200E is also capped but the cap apparently was not tightly secured as evidenced by the stripped threads on the end of the pipe. When the pressure surge was applied to the CVC-200E cap the cap was blown off, causing a primary leak estimated at approximately 100 gpm. This estimate was based on the pipe diameter and quantity of water discharged to the CV sump. This leak was quickly reduced to 5-7 gpm when valves 460A & B were shut by the operators. Apparently some leakage occurred past these air operated control valves. The 100 gpm leak was restarted when letdown was re-established at 0635 causing containment dew point and pressure to rise (~.25 psi). At 0650 letdown was isolated and the leak rate again dropped to 5-7 gpm. Based on the sump level indication less than 6000 gallons of primary coolant was discharged into the containment sump. When the 100 gpm leak occurred

ATTACHMENT NO. 3 (Continued)

at 0624 it apparently caused a heat sensitive fire detector to go off in containment. The detector was located above the drain valve on the operating deck. Since the operators had indication of RCS leakage and a fire in the containment, an individual using respiratory protection was sent into the containment to investigate. This individual confirmed the leakage and identified the source as the letdown line but was unable to identify the exact leak point because his air supply was low. During the inspection no evidence of fire was found.

To prevent future occurrences the CVC-200E pipe threads were dressed and a new end cap installed. CVC-200E and several other valve/pipe cap arrangements which could be exposed to the same condition were inspected and physically locked or verified secured in the closed position.

-DRAFT-

ATTACHMENT NO. 4

PRIMARY SYSTEM DEPRESSURIZATION

The main concern during the transient of 1-29-81 was an unexplained decrease in RCS pressure. The pressure dropped from 2200 psig to 1620 psig in approximately one hour. Many steps were taken during the first hour of the transient to determine what was causing the depressurization. The pressurizer (Pzr) safety valves were checked by looking at the acoustic flow indicators downstream of the valves. No flow was indicated. The Pzr PORVs were checked by looking at the pipe temperature downstream of the valves. Again, no flow was indicated. The Pzr block valves were checked to verify that they were shut. The Pzr relief tank level and pressure were also checked to verify that they were not increasing. The main Pzr spray valves were then switched to manual control and closed by the operator. The indication on the RTGB showed the valve to be closed, however, since this indication is only of demand position, the operator tried to insure that the valves had closed by manually closing them. The charging line was then isolated to see if the auxiliary spray valve, CVC-311, was leaking. Additionally, RCP "B" and "C" were stopped so that flow through the main spray valves 455A & B was not possible. Pzr pressure began increasing. Later that night (2315 hours) spray valve 455B was positively identified as the leaking valve.

An inspection of the valve showed that the stem was binding on the valve packing. One reason the binding problem was not identified earlier is that the spray valves do not move much during power operation. RCS pressure control is accomplished by varying the Pzr heaters with the spray valve partially opened. The valve was repaired by lubricating the stem. The valve was then tested four times to insure proper operation. In addition, the electro-mechanical positioner zero setpoint was discovered to be slightly off and therefore was reset.

-DRAFT-

ATTACHMENT NO. 3

CONTAINMENT ISOLATION VALVE FAILURE (FP-248)

At 0624 on 1-29-81 a SI signal generated a Phase A containment isolation. As part of this isolation the newly installed fire protection containment isolation valves FP-248, FP-249, FP-256, FP-258 were signaled to shut. FP-248 did not shut. The valve was then manually shut. The cause of failure was a tripped breaker which would not allow power to the motor operator. Subsequent review indicated that the trip point on the magnetic overload breaker was not set high enough to insure proper operation.

The breakers had been tested successfully upon installation, however, the current demand of the valve motors can change with time and so if the trip point is not set with enough margin the breaker can pass a test and yet fail at a later time.

The setpoints on all four valves have been readjusted to compensate for the above problem and tested. This should correct any future problems with these valves.

-DRAFT-

ATTACHMENT NO. 6
SUMMARY OF P250 COMPUTER OUTPUT

<u>Time</u>	<u>Event</u>
0620	Alarm - Low Tavg Permissive Set
0620	Alarm - Low Tavg 541.2 (setpoint is 543.0)
0623	ORR - Control Rod Bank C Inserted (reactor trip)
0624	Alarm - RHR Pump "B" BKR Closed (SI signal)
0624	Alarm - Low Tavg 532.7 (minimum Tavg)
0625	INCR - Hi PZR Relief Tank 75.2% (Valve CVC-203 lifts)
0627	RETURN - RHR Pump "B" BKR Open (SI reset)
0705	Alarm - PZR Low P & L SI (Second SI signal)
0705	Alarm - RHR Pump "B" BKR Closed
0705	Alarm - RHR Pump "A" BKR Closed
0726	Alarm - RCLB Lo Flow (RCP "B" stopped)
0727	Alarm - RCLC Lo Flow (RCP "C" stopped)

JUN 2 1971

. 2 .

Thursday

0527 - Leave SI on FW 5501
0528 - Started "B" main pump

H. B. Robinson Plant Unit # 2 Critical Configuration

Date 6/29/71 Time 6:54 Oper. [Signature]
 Bank Position (Steps)
 A 224 B 224 C 2nd D 214^{2nd}
 Tave. 275 °F Pressure 2285 PSIG
 Boron Concentration 665 PPM
 Reactor Power Level 310³ Amps 101 %

- 0531 Stopped H₂ Y Valve to H₂ valves: C₁₀ - 200A will not open
- 0537 Closed Collection Area, ST/PC - P.S. 151
- 0550 Started "B" main pump 200/23 5501. L₁ DW and P₂ P₁ started increasing
- 0555 Started "A" press. SI, variable rate steam engine started
- 0557 investigated Cu for leakage
- 0600 Stopped "B" RHL pump
- 0625 Restarted L₁ DW - RCS press. started decreasing
- 0627 Stopped B₁C RCP's and P₂R press started increasing
- 0629 Started cooling down
- 0631 Stopped A₁ RHL
- 0635 Stopped L₁ DW 84 & 85 on B₁C 8/10 & P₂

Unit S/D, Alex on S/C. X-ferrus same range
 @ 2000 CPS, Cool Down in progress. AX 230KV
 0648 am C₁₀ except 524V: 52/4

Richard L. [Signature]
[Signature]

08-16 THURSDAY 1-21-51

REVIEW OF MARIUS SHIFTS LOGS. STATES MONTHS AGO RATE A.L.
ACTUAL VALUES IN PAPER RECORD FOR PUMP CONDITIONS EXCEPT
THAT INFLUX WITH BRIS FROM LOW TECH. STRES. AT 535-1576
SHUT ONE AIR ENTRANCE. RED 11. IN TEMP. RISE PER 100° SE
LEAKS AT + TON CENTRAL BYPASS. ~~WATER~~ ~~WATER~~ ~~WATER~~
PUMP'S C.C. 4. 2 VCS 25. ARE IN EFFECT. STOP PUMP
FURNITURE PUMP COS. UNIT OFF LINE. SI IN PROCESS. PER LINES
+ FLOW IN PROCESS. SI HAS BEEN RESET ALONG WITH F.W. LOGS.
ALSO NEW INTERSECTION RUNNING (NOT FEEDING). INVESTIGATING WORK
IN CL. "B" AIR PUMP RUNNING. "A" REF RUNNING.

Johnson (initials)

- 0130 STARTED SEC. LEAK RATE TEST (110.64 GPM)
- 0130 REC. PUMP 533 1/4"
- 0138 STARTED A/B PUMPS
- 0141 STARTED "B" AIR PUMP
- 0145 STOPPED BRIS ON CV. SURF. LAMP
- 0145 FILLED B REF. STANDPIPE TO CLING TO MOUNTING
- 0145 FILLED B REF. STANDPIPE
- 0147 STARTED R-11. Y. L. L. VAC PUMP
- 0148 STARTED SI PUMPS
- 0150 HOLDING RES. PRESS @ 700"
- 0159 STARTED HUE-4 FOR ADVANCED SET. RETURN
- 0146 STARTED RCS POSITION
- 0147 ALL 516 DOWNDOWN ISOLATED
- 0152 STOPPED HUE-4 + HUE-1
- 0152 RCS LOW 1026 / 1100
- 0150 STARTED LOW 11.6 ON "B" SET
- 0156 FT 7.3 + 20.1 COMPLETED
- 0155 STOPPED ADVANCED RES
- 0152 FILLED "B" REF STANDPIPE
- 0153 SI "B" 154 / 155 (SMOKE OVER SHUT)
- 0157 RESET IN AIR BRIS + RES CONTACT
- 1012 "A" SHUT DOWN SHUT FILLING SET N2 ON VET
- 1017 "B" SHUT DOWN SHUT SET
- 1018 BLOCKED LE INVC SI
- 1012 STARTED RES CD @ 570°

Handwritten notes and initials on the right margin.

1000

(...)

End of

2) ...
 1) ...
 2) ...
 3) ...
 4) ...
 5) ...
 6) ...
 7) ...
 8) ...
 9) ...
 10) ...

5) ...
 6) ...
 7) ...
 8) ...
 9) ...
 10) ...
 11) ...
 12) ...
 13) ...
 14) ...
 15) ...
 16) ...
 17) ...
 18) ...
 19) ...
 20) ...

...
 ...
 ...
 ...



DATE TIME

1100-2700

Blum



12/15

- 1) Reviewed previous data Logos Part
- 2) Condition on found: $\text{P} = 5.5 \times 5.5$ in inches; had 6-11, 50 and 100 ft pump, A + is charging pump, HVE = 15 + 15.5, 2' well diameter, inside was irregular; pump for 2000, 400, 400, 400 in inches as a circulating water pump; this water valve 1020A (EP-249) failed to close on ST + is under maintenance; A RCP running, RCP at 471°F + 1800 psi; 1020 B on B water tank in air program;
- 3) Checked books for valve 1020B (EP-249) which maintenance is to be performed on valve 1020A (EP-249).
- 4) Completed PT-9.1 RCP lubricate 2437 gpm
- 5) 1530 hours lined up A charging pump for operation. PT-15.2 not performed in air program; normal lineup + RCP pressure + parameter had low + unstable respectively.
- 6) 1512 hours started B RCP in air program; pressure and ST-29A.
- 7) 1522 hours started C RCP in air program; pressure and ST-29A.
- 8) Reviewed load of liquid nitrogen
- 9) Isolated generator by busbar.
- 10) Transferred 2 batches of hair cream to B primary storage tank. B RCP 2433 gpm
- 11) Lined charging line and gave hold down line in service; isolated other known valves below from service.
- 12) Completed work on B water tank. Take notes - noted remaining in program; open and closed, closed those low level in station and left them in the closed position; that was complete prior to starting B or C RCP's
- 13) Completed PT-262
- 14) Condition unit returned for maintenance; RCP at 484°F + 1800 psi; 11-21 pump 11-22 2000 gpm


15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100

T_{cold}


T_{hot}



TR-408
 T_{avg}/T_{ref}



NR 45 Nuclear Power




Spikes at 10:30

Source Power

Power Drop

Power Drop



7 AM

8 AM


9 AM

Electric Load

MEGAWATTS

LEVEL
FEED
STEAM



STEAM GENERATOR A Level
FEEDWATER FLOW/STEAM FLOW




REVERSE ENGINEERING

11-11-11


Pressurizer Pressure (UR + WR)



PRESSURIZER PRESSURE



P/D LEVEL



Level
Feed
STEAM


STEAM GENERATOR B LEVEL
FEEDWATER FLOW / STEAM FLOW



11/11/77


FEED
STEAM

STEAM GENERATOR C LEVEL
FEEDWATER FLOW / STEAM FLOW




Turbine Governor Valve Position


- 10 -



Low A 21 /
01:27 -
00:10

- 11 -





RCP Seal Leak (NR)

- 13 -




FIGURE 1 (1945) DIAGRAM (continued)

PLANT OPERATING SECTION

PLANT OPERATING SECTION
PLANT OPERATING SECTION
PLANT OPERATING SECTION





FIGURE 2 CONTAINMENT SUMP VOLUME



MODIFICATION NO. 525
REVISION 3