

Attachment 1 IN 92-67 September 10, 1992 Page 1 of 6

P.O. Box 165 • New Hill, N.C. 27562

R. B. RICHEY Vice President Harris Nuclear Project

1.

α

FEB 1 4 1992

Letter Number: H0-920047 (0)

NRC-774

Document Control Desk United States Nuclear Regulatory Commission Washington, DC 20555

> SHEARON HARRIS NUCLEAR POWER PLANT UNIT 1 DOCKET NO. 50-400/LICENSE NO. NPF-63 <u>10CFR PART 21 REPORT</u> MAIN FEEDWATER PREHEATER BYPASS VALVES

Gentlemen:

Attached is our report on the subject item which was deemed reportable per the provisions of 10CFR21, on January 15, 1992. Carolina Power and Light Company considers that the actions taken are adequate for resolution of this item.

If you should have any questions regarding this matter, please contact Mr. Chuck Olexik at (919) 362-2718.

Very truly yours,

R. B. Richey / Vice President Harris Nuclear Project

MGW:kjc

cc: Mr. S. D. Ebneter (NRC-RII) Ms. B. L. Mozafari (NRR) Mr. J. E. Tedrow (NRC-SHNPP)

180051 MEM /H0.920047 0/1/051 7202200037 720214 PDR ADDCK 05000400 PDR ADDCK 05000400

TEIA

Page 2 of 6

CAROLINA POWER & LIGHT COMPANY SHEARON HARRIS NUCLEAR POWER PLANT

FINAL REPORT

POTENTIAL FAILURE OF MAIN FEEDWATER PREHEATER BYPASS VALVES

.

FEBRUARY 12, 1992

.

REPORTABLE UNDER 10CFR21

MEM/HO-920047.0/2/0S1

SUBJECT:

ITEM:

Shearon Harris Nuclear Power Plant, 10CFR21 reportable deficiency. Potential failure of Main Feedwater Preheater Bypass Isolation Valves.

Deficiency in the actuator (Hiller Model No. 12 SA-A029) for the Main Feedwater Preheater Bypass Isolation Valves.

> Plant identification numbers: 2AF-V156 SAB-1 2AF-V157 SAB-1 2AF-V158 SAB-1

The Harris Plant (3 loop Westinghouse NSSS) has model D-4 steam generators (SGs). These SGs have a split feed arrangement where at 100% full power, approximately 82% of the needed SG feed flow is directed to the SG preheater section located immediately above the SG tube sheet, and the remaining 18% is directed to the SG upper U-tube region via the same line used for auxiliary feedwater (AFW) flow. The containment isolation valve for the 18% feed flow path is the Main Feedwater Preheater Bypass Isolation Valve.

<u>SUPPLIED BY</u>: Anchor Darling Valve Company, Williamsport, Pa., supplied valve and actuator package.

NATURE OF DEFICIENCY: The valve and actuator for the three Main Feedwater Preheater Bypass Isolation Valves were specified, purchased, and installed for a Q Class application. During review of a proposed plant modification, it was determined that several actuator components were in fact non-Q.

A potential failure mechanism existed where the failure of a non-Q component could result in the inability of a Q-class component to perform as designed. Specifically, a postulated failure of the air pump (item 6 on attached drawing), could cause a situation where normal leakage of the accumulator (item 1) from its normal 150 psig pressure would go undetected by redundant pressure switches (PS A and B). These switches provide the valves an auto close signal when pressure drops to 66 psig in the input air header.

The values are containment isclation values and are required to close within 10 seconds of a feedwater isolation signal. If accumulator pressure drops from its normal 150 psig to below 122 psig, it may not close within the required time. If accumulator pressure drops to approximately 20 psig, there may not be sufficient force to reposition the value and maintain it closed against maximum differential pressure.

DATE PROBLEM WAS CONFIRMED TO EXIST:

CP&L discovered the potential deficiency during review of a proposed modification on January 7, 1992. Subsequent review and evaluation by CP&L engineers and the Harris Plant Nuclear Safety Committee determined this item to be reportable per 10CFR21 on January 15, 1992. PROBLEM REPORTED: Page 4 of 6

~

C. S. Hinnant notified the NRC Operations Center that this item was reportable under 10CFR21 on January 16, 1992.

<u>SAFETY</u> <u>IMPLICATIONS</u>:

This design deficiency could have compromised the containment boundaries capability to prevent or mitigate the consequences of accidents resulting in offsite exposures.

CORRECTIVE ACTION:

Upon discovery of this condition on January 7, 1992 a two hour surveillance interval was commenced to verify the actuators' components were functioning properly and the accumulators were fully pressurized. On January 12, 1992 a plant change request (PCR 06158) was implemented which replaced the non-Q components with suitable components. Testing was completed satisfactorily and the two hour surveillance interval was suspended.



Page 6 of 6

Ţ	TEM	DECOUDTION
	t	BASIC ACTUATOR - 12 BORE X 0 % STRUKE WITH ACCUMULATOR
	2	1/2 - 4 WAY VALVE NORGREN VALVE MODEL NO. FOOISA
	3	1/4" EXHAUST BREATHER MOSIER MODEL NO. EM-2
	4	1/2" EXHAUST MUFFLER QUIETAIRE MODEL 88-4
	5	V2" FLOW CONTROL VALVE REPUBLIC MODEL NO. M 4113C -8528-6
	6	AIR PUMP HASKEL MODEL NO. AAD-5
•	78	V2" AIR REGULATOR NORGREN MODEL NO 11-002-061
Z	8	CONOFLON SCHLATOR
18	•	1/4" - 3 WAY SOLENOID OPERATED WALVE ASCO MODEL NO. NP-8320ANSEV 125 V.D.C. NORMALLY CLOSED
	10 A	0-160 PSIG GAUGE NORGAEN # /8-0/3-206 TTEM 104 MTG. TO ITEM TA.
		0-160 PSIG GAUGE -MIL TO ITEM B NORGEEN# 18-018-209
	12	W RELIEF VALVE - NORGREN # 16-001-035
	13	A-300 PSIA GAUGE -MIL TO ACCUM. HEAD MARSH # 21/2 - 10FM-1/2 CBM-300
	11	1/2" NEEDLE VALVE -
_		WENTHOL WILVE
M	10	KEPNER # 1582
	B.	WE S-MAY WILVE - MORCREN COOOTF
KI KC		WE EXA, BREATHER MESSIER + EM-G
		I. AR CIRCUIT SHOWN WITH THE ACTUATOR IN ITS NORMAL, POSITION (RETRACTED) SOLENOID (A) ((B) ENERGIZED. 2. O INDICATES PORT DESIGNATION AS STAMPED ON , VALVES.
		RALPH A. HILLER COMPANY
		AIR CIRCUIT & WIRING DIAGRAM
		12 SA-A029 Ides 3