

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
WASHINGTON, D.C. 20555

July 14, 1986

IE INFORMATION NOTICE NO. 86-59: INCREASED MONITORING OF CERTAIN PATIENTS
WITH IMPLANTED CORATOMIC, INC. MODEL C-100
AND C-101 NUCLEAR-POWERED CARDIAC PACEMAKERS

Addressees:

All NRC licensees authorized to use nuclear-powered cardiac pacemakers.

Purpose:

This notice is to alert users of Coratomic, Inc. Model C-100 and C-101 nuclear-powered cardiac pacemakers of the manufacturer's recent warning of possible problems with certain units. The manufacturer recommends increased monitoring of patients with these units implanted. It is expected that licensees will review this information for applicability to their patients and consider actions, if appropriate. However, suggestions contained in this information notice do not constitute NRC requirements; therefore, no specific action or written response is required.

Description of Circumstances:

By letter dated March 14, 1986, the manufacturer, Coratomic, Inc., notified applicable attending physicians of possible problems with Model C-100 and C-101 plutonium-powered pacemakers that were manufactured between September 1974 and October 1977. During that time, "2CN potting material," a glue-like substance, was used in the construction of the pacers. The reversion of the 2CN potting material to a viscous form in some units has led to a rate drop and to a higher-than-anticipated random transformer failure rate. Accordingly, Coratomic recommends that the monitoring of affected patients be increased to once every 3 months. The March 14 letter included a listing of affected patients.

Discussion:

There is no radiological hazard associated with the problem described in Coratomic's March 14, 1986 letter. However, this notice serves as a reminder that, as a condition of their license, licensees are required to follow the manufacturer's protocol and to notify the NRC within 10 days of loss of contact with a nuclear pacemaker patient. If you have any difficulty locating or contacting any affected patient, the NRC suggests you contact the manufacturer for assistance. However, since the Coratomic protocol, dated either August 1, 1974 or November 1, 1975, specifies in-person followup visits every 6 months for patients with Coratomic Model C-100 or C-101 pacemakers implanted for more than 6 months, you should have no difficulty in contacting affected patients.

8607090442

860714

T & E NOTICE 86-059

IN 86-59
July 14, 1996
Page 2 of 2

No specific action or written response is required by this information notice. If you have any questions regarding this matter, please contact the Regional Administrator of the appropriate NRC regional office or this office.

J. G. Partlow

James G. Partlow, Director
Division of Inspection Programs
Office of Inspection and Enforcement

Technical Contact: J. R. Metzger, IE
(301) 492-4947

Attachment: List of Recently Issued IE Information Notices

LIST OF RECENTLY ISSUED
IE INFORMATION NOTICES

Information Notice No.	Subject	Date of Issue	Issued to
86-58	Dropped Fuel Assembly	7/11/86	All power reactor facilities holding an OL or CP
86-57	Operating Problems With Solenoid Operated Valves At Nuclear Power Plants	7/11/86	All power reactor facilities holding an OL or CP
36-56	Reliability Of Main Steam Safety Valves	7/10/86	All PWR facilities holding an OL or CP
86-55	Delayed Access To Safety-Related Areas And Equipment During Plant Emergencies	7/10/86	All power reactor facilities holding an OL or CP
86-54	Criminal Prosecution Of A Former Radiation Safety Officer Who Willfully Directed An Unqualified Individual To Perform Radiography	6/27/86	All holders of by-product, source, or special nuclear material
86-53	Improper Use Of Heat Shrinkable Tubing	6/26/86	All power reactor facilities holding an OL or CP
86-52	Conductor Insulation Degradation On Foxboro Model E Controllers	6/26/86	All power reactor facilities holding an OL or CP
86-51	Excessive Pneumatic Leakage In The Automatic Depressurization System	6/18/86	All BWR facilities holding an OL or CP
86-50	Inadequate Testing To Detect Failures Of Safety-Related Pneumatic Components Or Systems	6/18/86	All power reactor facilities holding an OL or CP
86-49	Age/Environment Induced Electrical Cable Failures	6/16/86	All power reactor facilities holding an OL or CP

OL = Operating License
CP = Construction Permit