

#### **DEPARTMENT OF ENERGY**

Office of Civilian Radioactive Waste Management Office of Geologic Disposal Yucca Mountain Site Characterization Project Office P.O. Box 98608 Las Vegas, NV 89193-8608

WBS 1.2.11 QA: N/A

## FEB 0 7 1994

Robert F. Pritchett Technical Project Officer for Yucca Mountain Site Characterization Project Reynolds Electrical & Engineering Co., Inc. P.O. Box 98521 Las Vegas, NV 89193-8521

EVALUATION OF AMENDED RESPONSE TO CORRECTIVE ACTION REQUEST (CAR) YM-93-061 RESULTING FROM YUCCA MOUNTAIN QUALITY ASSURANCE DIVISION (YMQAD) AUDIT YMP-93-12 OF REYNOLDS ELECTRICAL & ENGINEERING CO., INC. (SCP: N/A)

The YMQAD staff has evaluated the amended response to CAR YM-93-061. The amended response has been determined to be satisfactory. Verification of completion of the corrective action will be performed after the effective date provided. Any extension to this date must be requested in writing, with appropriate justification, prior to the date. Please send a copy of extension requests to Nita J. Brogan, YMQAD/QATSS, 101 Convention Center Drive, Suite 640, Las Vegas, Nevada 89109.

If you have any questions, please contact either Robert B. Constable at 794-7945 or Raul A. Hinojosa at 794-7991.

C. Spence

Richard E. Spence, Director Yucca Mountain Quality Assurance Division


YMQAD: RBC-1904

Enclosure: CAR YM-93-061

cc w/encl: K. **A**. Hooks, NRC, Washington, DC S. W. Zimmerman, NWPO, Carson City, NV W. J. Glasser, REECo, Las Vegas, NV

cc w/o encl: J. W. Gilray, NRC, Las Vegas, NV N. J. Brogan, YMQAD/QATSS, Las Vegas, NV

## 140020



Add: Ken Hacken Ster End NHOB: 11 WM-11 102.7

 . V			THIS IS A RED STAMP
RADIOACTIV U.S. DEP	FICE OF CIVILIAN /E WASTE MANAGEM ARTMENT OF ENERG SHINGTON, D.C.		CAR NO.: <u>YM-93-061</u> DATE: <u>07/02/93</u> SHEET: <u>1</u> OF <u>1</u> QA
CORRECT	TIVE ACTION REQUES	ST	
1 Controlling Document Specification XMP-025-1-SP09		2 Related R YMP-93-1	•
3 Responsible Organization REECo QC	4 Discussed With P. Bryant		
5 Requirement: Specification YMP-025-1-SP09, Section 03 Paragraph 3.10.B.3.d states in part, "W specified requirements and was taken fro shall be taken from the area of work in tested for conformance to the specificat	m a test panel, additional	samples	and
6 Adverse Condition:			
Contrary to the above, Field Quality Con take additional samples when two test pa failed. Refer to test results for shotcrete plac	ed on 4/23/93 and on 5/10/		
adverse to quality exist? YesNo <u>x</u> Yes	es a stop work condition exist? sNo <u>X_;</u> if Yes - Attach cop /es, Circle One: A_B_C_D	by of SWO	11 Response Due Date: 20 Working Days from Issuance
<sup>12</sup> Required Actions: X Remedial Extent of		currence	Root Cause Determination
<ul> <li>13 Recommended Actions:</li> <li>1) Ensure the two failed test results a</li> </ul>	are appropriately documents	ed.	
7 Initiator Gerard Heaney	21-93 QADDUDY	intritivo	) \$50 Date07.0703
15 Response Accepted QAR Served Heavergate 8	16 Response Accept	Ded Julia	selistor?
QAR Deand Heanengate 1 17 Amended Response Accepted 4, 14, 14, 14, 14, 14, 14, 14, 14, 14,	U 3/14 LE Artiended Response	Accepte	Date 0//7/25 d RC. Joine 1/14/94 Date 1/14/97
19 Corrective Actions Verified	20 Closure Approve	d by:	D-to
QAR Date	QADD	<u>_</u>	Date

.

.

-

ENCLO	SURF	REV

/. 08/91

۰.

· .	· · · ·		
	RADIOACTIVE WAS U.S. DEPARTME	F CIVILIAN STE MANAGEMENT ENT OF ENERGY TON, D.C.	CAR NO. YM-93-061 DATE: 08/04/93 PAGE: OF QA
	CORRECTIVE ACTION REC	QUEST (Continuation F	Page)
C	ORRECTIVE ACTION RESPONSE for CAR #	<u>YM-93-061</u>	
A	. Remedial Action:		
•.	REECo YMP Quality Control (QC) Se panel failures and has determined included in the area addressed by Number 93-014. Further evaluatio shotcrete records with 28 day tes is completed, all failing panels. Architect/Engineer disposition.	that the failure o Project Nonconform n indicates that a t results is needed	n April 23, 1993, is ance Report (NCR) full review of all . When this review
	<u>Responsible Individual:</u> Estimated completion date		<u>93</u>
C. Root Cause Determination:			
	Positive controls to ensure appro not in place.	priate actions for	test failures were
D	. Corrective Action to Preclude Rec	urrence:	
	As a positive control, a log syst timely receipt of test data and t test results and any action requi appropriate Inspection Report.	o clearly indicate	test status. The
	<u>Responsible Individual:</u> Estimated completion date	<u>E. P. Bryant</u> : September 15, 19	<u>93</u>
, R	esponse Approved: 127 Price	Theat	Date: <u>8/4/93</u>
1			
St	n dtd 8/4/93 - 580-01-	587	

د.

8

OFFICE OF CIVILIAN RADIOACTIVE WASTE MANAGEMENT U.S. DEPARTMENT OF ENERGY WASHINGTON, D.C.         CORRECTIVE ACTION REQUEST (Continuation Page)         CORRECTIVE ACTION RESPONSE FOR CAR # YM-93-061         Supplemental CAR response on Remedial Actions:         During a recent review of documentation for inclusion in the final Design Package IA records package, REECo identified additional information concerning the status of shotcrete test panels and results. REECo Quality Control Section had originally determined that the panel identified as occurring on April 23, 1993, was included in the area addressed by Project Nonconformance Report (NCR) 93-014. Further evaluation showed that, although the failure apparently occurred in the first 33 feet of the tunne the date of failure was after the time frame covered by the NCR.         Based upon this new information, it has been determined that additional evaluation is necessary to ensure that frequired test panels have been take test reports have been received, and test results (including test results for placed shotcrete on April 23, 1993, and May 10, 1993) have been adequately reviewed for inclusion on Project NCR(s), as necessary.         Net, therefore, r		<u> </u>	
CORRECTIVE ACTION RESPONSE FOR CAR # YM-93-061 Supplemental CAR response on Remedial Actions: During a recent review of documentation for inclusion in the final Design Package 1A records package, REECo identified additional information concerning the status of shotcrete test panels and results. REECo Quality Control Section had originally determined that the panel identified as occurring on April 23, 1993, was included in the area addressed by Project Nonconformance Report (NCR) 93-014. Further evaluation showed that, although the failure apparently occurred in the first 33 feet of the tunner the date of failure was after the time frame covered by the NCR. Based upon this new information, it has been determined that additional evaluation is necessary to ensure that required test panels have been taken test reports have been received, and test results (including test results for placed shotcrete on April 23, 1993, and May 10, 1993) have been adequately reviewed for inclusion on Project NCR(s), as necessary. We, therefore, request an extension until November 19, 1993, to complete the additional evaluation and initiate the necessary NCR(s). <u>Responsible Individual: E. P. Bryant</u> <u>Estimated completion date: November 19, 1993</u>		RADIOACTIVE WASTE MANAGEMENT U.S. DEPARTMENT OF ENERGY	DATE: 10/19/93 PAGE:OF
Supplemental CAR response on Remedial Actions: During a recent review of documentation for inclusion in the final Design Package 1A records package, REECo identified additional information concerning the status of shotcrete test panels and results. REECo Quality Control Section had originally determined that the panel identified as occurring on April 23, 1993, was included in the area addressed by Project Nonconformance Report (NCR) 93-014. Further evaluation showed that, although the failure apparently occurred in the first 33 feet of the tunne the date of failure was after the time frame covered by the NCR. Based upon this new information, it has been determined that additional evaluation is necessary to ensure that required test panels have been take test reports have been received, and test results (including test results for placed shotcrete on April 23, 1993, and May 10, 1993) have been adequately reviewed for inclusion on Project NCR(s), as necessary. We, therefore, request an extension until November 19, 1993, to complete t additional evaluation and initiate the necessary NCR(s). <u>Responsible Individual: E. P. Bryant</u> <u>Estimated completion date: November 19, 1993</u>	CORR	ECTIVE ACTION REQUEST (Continuatio	n Page)
During a recent review of documentation for inclusion in the final Design Package 1A records package, REECo identified additional information concerning the status of shotcrete test panels and results. REECo Quality Control Section had originally determined that the panel identified as occurring on April 23, 1993, was included in the area addressed by Project Nonconformance Report (NCR) 93-014. Further evaluation showed that, although the failure apparently occurred in the first 33 feet of the tunne the date of failure was after the time frame covered by the NCR. Based upon this new information, it has been determined that additional evaluation is necessary to ensure that required test panels have been take test reports have been received, and test results (including test results for placed shotcrete on April 23, 1993, and May 10, 1993) have been adequately reviewed for inclusion on Project NCR(s), as necessary. We, therefore, request an extension until November 19, 1993, to complete t additional evaluation and initiate the necessary NCR(s). <u>Responsible Individual: E. P. Bryant Estimated completion date: November 19, 1993</u>	". CORRECTIVE ACTION RES	PONSE FOR CAR # <u>YM-93-061</u>	
Package 1A records package, REECo identified additional information concerning the status of shotcrete test panels and results. REECo Quality Control Section had originally determined that the panel identified as occurring on April 23, 1993, was included in the area addressed by Project Nonconformance Report (NCR) 93-014. Further evaluation showed that, although the failure apparently occurred in the first 33 feet of the tunne the date of failure was after the time frame covered by the NCR. Based upon this new information, it has been determined that additional evaluation is necessary to ensure that required test panels have been take test reports have been received, and test results (including test results for placed shotcrete on April 23, 1993, and May 10, 1993) have been adequately reviewed for inclusion on Project NCR(s), as necessary. We, therefore, request an extension until November 19, 1993, to complete t additional evaluation and initiate the necessary NCR(s). <u>Responsible Individual: E. P. Bryant Estimated completion date: November 19, 1993</u>	Supplemental CAR resp	onse on Remedial Actions:	
<pre>evaluation is necessary to ensure that required test panels have been take test reports have been received, and test results (including test results for placed shotcrete on April 23, 1993, and May 10, 1993) have been adequately reviewed for inclusion on Project NCR(s), as necessary. We, therefore, request an extension until November 19, 1993, to complete t additional evaluation and initiate the necessary NCR(s). <u>Responsible Individual: E. P. Bryant Estimated completion date: November 19, 1993</u></pre>	Package 1A records pac concerning the status Control Section had or occurring on April 23 Nonconformance Report although the failure a	ckage, REECo identified additional of shotcrete test panels and resu riginally determined that the pane , 1993, was included in the area a (NCR) 93-014. Further evaluation apparently occurred in the first 3	information lts. REECo Quality l identified as ddressed by Project showed that, 3 feet of the tunne
additional evaluation and initiate the necessary NCR(s).          Responsible Individual:       E.       P.       Bryant         Estimated completion date:       November 19, 1993	evaluation is necessar test reports have been for placed shotcrete of adequately reviewed for	ry to ensure that required test pa n received, and test results (incl on April 23, 1993, and May 10, 199 or inclusion on Project NCR(s), as	nels have been take uding test results 3) have been necessary.
Estimated completion date: November 19, 1993			
			93
Response Approved: Date: Date:		_	
	Response Approved:		Date:

••

, ;





.

#### **Department of Energy**

Yucca Mountain Site Characterization Project Office P. O. Box 98608 Las Vegas, NV 89193-8608

WBS 1.2.11 QA: N/A

#### NOV 0 4 1993

Robert F. Pritchett Technical Project Officer for Yucca Mountain Site Characterization Project Reynolds Electrical & Engineering Co., Inc. P.O. Box 98521 Las Vegas, NV 89193-8521

VERIFICATION OF CORRECTIVE ACTION REQUEST (CAR) YM-93-061 RESULTING FROM YUCCA MOUNTAIN QUALITY ASSURANCE DIVISION (YMQAD) AUDIT YMP-93-12 OF REYNOLDS ELECTRICAL & ENGINEERING CO., INC. (REECO) AND EVALUATION OF AMENDED RESPONSE AND REQUEST FOR EXTENSION DATED OCTOBER 19, 1993, FROM REECO (REECO LETTER 580-01-38) (SCP: N/A)

The YMQAD staff has verified the corrective action to CAR YM-93-061 and determined the verification results to be unsatisfactory.

The response stated that the failure of the shotcrete test panels tested on April 23, 1993 and May 10, 1993 is addressed by Project Nonconformance Report (NCR) 93-014. Furthermore, a full review of all shotcrete records with 28-day results would be conducted and completed by September 15, 1993. Contrary to this response, the cited nonconformance report does not address test panels which failed, and the review of all shotcrete records with 28-day results had not been completed as of October 12, 1993.

All other corrective action described in the accepted response was found to be satisfactory. In addition, REECo amended response and request for extension of corrective action completion date (REECo letter 580-01-038 dated October 19, 1993) has been received and approved.

Based on the above verification results and evaluation of the amended response received, an extension of corrective action completion to November 19, 1993, is granted. Verification of completion of corrective actions will be performed after the effective dates provided.

If you have any questions, please contact Robert B. Constable at (702) 794-7945.

P.C. Spince

Richard E. Spence, Director Yucca Mountain Quality Assurance Division

YMOAD: RBC-447

Enclosure: CAR YM-93-061 -2-

0

Robert F. Pritchett

2

cc w/encl: K. R. Hooks, NRC, Washington, DC S. W. Zimmerman, NWPO, Carson City, NV W. J. Glasser, REECo, Las Vegas, NV cc w/o encl: J. W. Gilray, NRC, Las Vegas, NV N. J. Brogan, YMQAD/QATSS, Las Vegas, NV



#### DEPARTMENT OF ENERGY

Office of Civilian Radioactive Waste Management Office of Geologic Disposal Yucca Mountain Site Characterization Project Office P.O. Box 98608 Las Vegas, NV 89193-8608

WBS 1.2.11 QA: N/A

### DEC 1 4 1993

Robert F. Pritchett
Technical Project Officer
for Yucca Mountain
Site Characterization Project
Reynolds Electrical & Engineering Co., Inc.
P.O. Box 98521
Las Vegas, NV 89193-8521

VERIFICATION OF CORRECTIVE ACTION OF CORRECTIVE ACTION REQUEST (CAR) YM-93-061 RESULTING FROM YUCCA MOUNTAIN QUALITY ASSURANCE DIVISION (YMQAD) AUDIT YMP-93-12 OF REYNOLDS ELECTRICAL & ENGINEERING CO., INC. (SCP: N/A)

The YMQAD staff has verified the corrective action to CAR YM-93-061 and determined the results to be unsatisfactory because of the following:

The amended response stated that additional evaluation of all shotcrete test panels including the panels tested April 23, 1993 and May 10, 1993, would be completed, and necessary nonconformance reports (NCRs) would be issued by November 19, 1993.

A verification of completion of the above-committed corrective actions revealed that the evaluation is not complete, and the necessary NCRs have not been issued.

Your response is requested within ten working days of the date of this letter stating the revised corrective action and expected completion date. The response should address the following:

- 1. A complete listing of all shotcrete test panels since initiation of shotcrete application by date.
- 2. An annotation on the Materials Test Laboratory (MTL) log of the acceptance or rejection of the test panels based on all available test results. Nonconformance reports must be issued for test results that do not meet minimum requirements.
- 3. Inspection records that were signed off as acceptable where the 7-day test results and/or the 28-day test results were below required minimums must be corrected to reflect that the results were unacceptable and the appropriate NCR number annotated thereon.
- 4. Nonconformance reports must be issued for lost test panels or test panels not tested because of delayed delivery to the MTL.

Verification of completion of the required corrective action will be performed after the date provided.

Robert F. Pritchett

۳

-2-

If you have any questions, please contact either Robert B. Constable at 794-7945 or Raul A. Hinojosa at 794-7991.

Spince

Richard E. Spence, Director Yucca Mountain Quality Assurance Division

YMQAD:RBC-1193

Enclosure: CAR YM-93-061

cc w/encl: K. R. Hooks, NRC, Washington, DC S. W. Zimmerman, NWPO, Carson City, NV W. J. Glasser, REECo, Las Vegas, NV

cc w/o encl: J. W. Gilray, NRC, Las Vegas, NV N. J. Brogan, YMQAD/QATSS, Las Vegas, NV

	. 🔾	93-105609
OFFICE OF C RADIOACTIVE WASTE U.S. DEPARTMENT WASHINGTO	MANAGEMENT OF ENERGY	CAR NO.: <u>YM-93-061</u> DATE: <u>12-29-93</u> SHEET: <u>OF</u>
CORRECTIVE ACTI (continuation		
REVISED CORRECTIVE ACTION RESPONSE FOR CAP	R YM-93-061	
<ol> <li>A complete listing of all shotcrete pa compiled and validated. The final lis January 28, 1994.</li> </ol>	nels is in the prod ting will be submit	cess of being tted by
2. The Material Test Request Log was impletest data and to indicate test status. corrective action to preclude recurrent not as remedial action which might record prior to its inception in August 1993. Indicated for test results received af planned corrective action dated August "The test results and any action requires appropriate Inspection Report." Furth Test Laboratory (MTL) is a tracking to received as expected. Once the result useful purpose since results are on the reason that the MTL procedure is not a records.	The log was imple the of the identifie puire backfitting of Although accept of ter inception of the 4, 1993 to the CAN red will be document of only to ensure the s are received, the per Inspection Report	emented as ed deficiency and f information or reject is he log, our R clearly states: nted on the oted the Materials results are e log serves no t. It is for this
3. Evaluation of existing test results have verification and a subsequent NCR has review, REECo considers all actions to with the DOE QA representative indicat proper use of specification for evalua. REECo will seek an interpretation concand if necessary, issue additional NCR REECo methodology is not as required. be provided by January 28, 1994.	since been issued. be complete. Howe es a potential disa tion of shotcrete t erning the applicat c's if it is determine	Based on this ever, discussion agreement in the test results. ble specification, ined that the
<ol> <li>The need for any additional NCR's for tested because of delayed delivery to determined as a result of compiling th 1, above.</li> </ol>	the MTL, if require	ed, will be
Responsible individual: W. J. Estimated Completion Date: Ja		nard
Response Approved: <u>N7 Pritched</u>	Date: <u>/2</u>	2/29/93

Str ded 12/29/93- 580-01-176

٦

÷

	•	OFFICE OF CIVILIAN RADIOACTIVE WASTE MANAGEMENT U.S. DEPARTMENT OF ENERGY WASHINGTON, D.C.
		CORRECTIVE ACTION REQUEST (Continuation Page)
••		
		RECTIVE ACTION RESPONSE AND EXTENSION REQUEST for CAR <u>YM-93-061</u>
D.	Remed	lial Actions:
	1.	The listing of shotcrete panels has been compiled and is being validated. The final listing will be submitted by February 28, 1994.
	2.	As a result of a written request to the Subsurface A/E, the A/E has responded and agrees with REECo that 28 day break test results evaluated in accordance with ACI 506.2-90, paragraph 1.6.3.3 (i.e., $f'_{e} = 5000 \text{ psi}$ ), is a correct application of Project specifications. REECo is seeking A/E concurrence that 7 day break tests are for information and that acceptance is based upon product achieving design strength at 28 days. A copy of the REECo and A/E correspondence is attached for your information.
	<b>3.</b>	The need for any additional NCR's for lost test panels or test panels not tested because of delayed delivery to the Material Test Laboratory, if required, will be determined as a result of compiling the information requested by item no. 1, above.
		<u>Responsible Individuals: T. M. Leonard/E. P. Bryant</u> Estimated completion date: February 28, 1994
Respo	onse Ap	oproved: Date: 1/28/94
_		
Ja a	t.	1/28/94-580-01-238

1

۰.

 $\cup$ 



94-000139

## Reynolds Electrical & Engineering Co., Inc.

Post Office Box 98521 • Las Vegas, NV 89193-8521

IN REPLY REFER TO. 580-01-182

January 5, 1994

WBS 1.2.11.4 QA

M. L. Renegar Construction Manager Morrison Knudsen Management & Operating Contractor 101 Convention Center Drive Mail Stop 423 Las Vegas, NV 89109

EVALUATION OF COMPRESSIVE STRENGTH TEST RESULTS (SCP: N/A)

As a result of Reynolds Electrical & Engineering Co., Inc. (REECo's) efforts to resolve a U.S. Department of Energy (DOE) Corrective Action Request (CAR) (YM-93-061) concerning the reporting of shotcrete test core compressive strengths below specified requirements, a question has been raised by DOE Quality Assurance concerning the utilization of specified criteria which requires Architect/Engineer (A/E) resolution. Based on DOE QA's discussion with A/E personnel, DOE QA has indicated that REECo may have misinterpreted the requirements. However, REECo's discussions with the A/E in the field have an interpretation consistent with REECo's practice. The purpose of this request is to resolve any differences. Requirements which require either agreements with REECo's actions or clarifying direction are noted below.

Disposition of shotcrete compressive test results of test panel cores are given in Project Specification YMP-025-1-SP09, Revision 3, Section 03361. Applicable requirements are as follows:

- Paragraph 3.10.B.3.b, "One core shall be tested at 7 days and 2 cores tested at 28 days in accordance with Section 2.02B."
- Paragraph 2.02B (third paragraph), "The mixes (dry or wet) shall be designed to provide an unconfined compressive strength of 5000 pounds per square inch at 28 days when tested in accordance with ACI 506.2-90."
- Attachment A requires in paragraph 2.1.b, "Construction samples shall be taken and tested as outlined in ACI 506.2 Section 1.6.3."
- ACI 506.2-90 states in paragraph 1.6.3.3 (second paragraph), "The average compressive strength of 3 cores taken from the structure or test panel, representing a shift or 50 cubic yards (38 mm<sup>3</sup>) of shotcrete, must equal or exceed 0.85  $f_c$  with no individual core less than 0.75  $f_c$ .

REECO



M. L. Renegar 580-01-182 Page 2 January 5, 1994

- ACI 506.2  $\P$  2.5 states " Specified strength of the shotcrete,  $f_e$ ', for each portion of the structure."
- ACI 318 identifies in Chapter 5, Section 5.0, that  $f_c'$  = specified compressive strength of concrete, psi.

Based on the above information, REECo has evaluated shotcrete cores using the provisions of ACI 506.2-90, paragraph 1.6.3.3 in that REECo has considered the project specified compressive strength of 5000 psi to be the  $f_c$  value. This evaluation criteria has allowed REECo to accept test results with an average compressive strength as low as 4250 psi which is 0.85  $f_c$ .

REECo requests concurrence with the above described application of Project specifications or clarification as to how cores are to be evaluated.

A formal response is requested by January 14, 1994, so that your decision may be included as part of REECo's required response to DOE CAR YM-93-061. Should you have any questions, please contact William J. Glasser at (702) 794-7562.

E. P. Bryant, Section Chief YMP Quality Assurance Department

EPB:as

- cy: Information Services Center, M/S 408

  - T. I. Fortner, DOE/YMP, M/S 523 W. J. Glasser, REECo, M/S 408
  - D. L. Koss, REECo, M/S 408
  - T. M. Leonard, REECo, M/S 408
  - R. F. Pritchett, REECo, M/S 408

94-000372

# **INFORMATION COPY**

TRW Environmental Safety Systems Inc. 101 Convention Center Drive, Suite 527 Las Vegas, NV 89109 702.794.1800 WBS: 1.2.6 QA: N/A

JAN 10 1991

٤.

Contract #: DE-AC01-91RW00134 LV.YM.MLR.1/94-003

January 11, 1994

E. P. Bryant, Section Chief
YMP Quality Assurance Department
Reynolds Electrical & Engineering Co, Inc.
PO Box 98521
Las Vegas, NV 89193-8521

Reference: Your letter, 580-01-182, Evaluation of Compressive Strength Test Results (SCP: N/A), dated January 5, 1994

Dear Mr. Bryant:

Pursuant to the above referenced letter, the Subsurface A/E has determined that we are in agreement with your described application of the project specification as stated. It is the A/E's intention to further clarify the shotcrete specification for the next phase and declare  $f'_c$  as 34.4738 MPa (5000psi).

Should you require further information on this subject, please contact A. Watkins at 702/295-4068.

M. L. Renegar Construction Manager Management and Operating Contractor

cc: T. I. Fortner, DOE/YMP

W. J. Glasser, REECo D. L. Koss, REECo T. M. Leonard, REECo J. L. Naaf, M&O J. H. Pye, M&O R. M. Sandifer, M&O

MLR:lg