

July 23, 2003

Mr. Mark E. Warner, Site Vice President  
c/o James M. Peschel  
Seabrook Station  
FPL Energy Seabrook, LLC  
P.O. Box 300  
Seabrook, NH 03874

SUBJECT: SUMMARY OF PRE-OUTAGE CONFERENCE CALL WITH FPL ENERGY SEABROOK, LLC REGARDING THE INSPECTION SCOPE FOR THE UPCOMING STEAM GENERATOR INSPECTIONS AT THE SEABROOK STATION, UNIT NO. 1 (TAC NO. MB8928)

Dear Mr. Warner:

On June 16, 2003, the U. S. Nuclear Regulatory Commission held a conference call with FPL Energy Seabrook, LLC, the licensee for the Seabrook Station, Unit No.1 (Seabrook), to discuss the inspection scope for the scheduled upcoming steam generator inspections at Seabrook during the next refueling outage. Currently, the planned scope includes inspection of 100% of the tubes in all four steam generators using a bobbin coil, with supplementary inspections using a rotating coil in tube locations with increased susceptibility to degradation.

Enclosed is a summary of the conference call.

Sincerely,

*/RA/*

Victor Nerses, Senior Project Manager, Section 2  
Project Directorate I  
Division of Licensing Project Management  
Office of Nuclear Reactor Regulation

Docket No. 50-443

Enclosure: Summary of Pre-Outage Conference Call

cc w/encl: See next page

July 23, 2003

Mr. Mark E. Warner, Site Vice President  
c/o James M. Peschel  
Seabrook Station  
FPL Energy Seabrook, LLC  
P.O. Box 300  
Seabrook, NH 03874

SUBJECT: SUMMARY OF PRE-OUTAGE CONFERENCE CALL WITH FPL ENERGY SEABROOK, LLC REGARDING THE INSPECTION SCOPE FOR THE UPCOMING STEAM GENERATOR INSPECTIONS AT THE SEABROOK STATION, UNIT NO. 1 (TAC NO. MB8928)

Dear Mr. Warner:

On June 16, 2003, the U. S. Nuclear Regulatory Commission held a conference call with FPL Energy Seabrook, LLC, the licensee for the Seabrook Station, Unit No.1 (Seabrook), to discuss the inspection scope for the scheduled upcoming steam generator inspections at Seabrook during the next refueling outage. Currently, the planned scope includes inspection of 100% of the tubes in all four steam generators using a bobbin coil, with supplementary inspections using a rotating coil in tube locations with increased susceptibility to degradation.

Enclosed is a summary of the conference call.

Sincerely,

*/RA/*

Victor Nerses, Senior Project Manager, Section 2  
Project Directorate I  
Division of Licensing Project Management  
Office of Nuclear Reactor Regulation

Docket No. 50-443

Enclosure: Summary of Pre-Outage Conference Call

cc w/encl: See next page

DISTRIBUTION:

PUBLIC PDI-2 Rdg. CHolden JClifford VNerses CRaynor  
OGC ACRS GHill(2) BMcDermott, RGN-I  
ADAMS Accession Number: ML031970605

OFFICE	PDI-2/PM	PDI-2/LA	EMCB/SC	PDI-2/SC
NAME	VNerses	CRaynor	LLund	JClifford
DATE	7/21/03	7/21/03	7/21/03	7/23/03

**OFFICIAL RECORD COPY**

## SUMMARY OF PRE-OUTAGE CONFERENCE CALL REGARDING THE INSPECTION

### SCOPE FOR THE UPCOMING STEAM GENERATOR INSPECTION AT THE

#### SEABROOK STATION, UNIT NO. 1

As part of a U.S. Nuclear Regulatory Commission (NRC) normal oversight activity with plants that have steam generator issues (SG), the NRC, on June 16, 2003, held a conference call with FPL Energy Seabrook, the licensee for the Seabrook Station, Unit No. 1 (Seabrook). The purpose of the call was to discuss the planned SG inspection scope at Seabrook during the upcoming refueling outage. The scope is preliminary as the plant's SG tube degradation assessment is not yet complete.

Seabrook uses four Westinghouse Model F steam generators with thermally-treated Alloy 600 tubing, and is the first domestic plant to identify axial outside-diameter stress corrosion cracking (ODSCC) of SG tubes fabricated from this material. This degradation was identified during the Spring 2002 refueling outage and was attributed to non-optimal tube processing during the fabrication of the SG. Additional details are contained in NRC Information Notice (IN) 2002-21, "Axial Outside-Diameter Cracking Affecting Thermally Treated Alloy 600 Steam Generator Tubing" (Agencywide Document Access and Management System (ADAMS) Accession No. ML021770094); IN 2002-21, Supplement 1, "Axial Outside-Diameter Cracking Affecting Thermally Treated Alloy 600 Steam Generator Tubing" (ADAMS Accession No. ML030900517); and in the licensee's root cause analysis report (ADAMS Accession Nos. ML023300457 and ML023240524). The planned inspection scope consists of:

- inspection of 100% of the active tubes in all four SGs with a bobbin probe
- inspection of 50% of the tubes in all four SGs with a rotating probe in the hot leg top-of-tubesheet region (i.e., inspection from 3 inches above to 3 inches below the top-of-tubesheet region)
- inspection of 50% of the row 1 and 2 tubes in the U-bend region in all four SGs with a rotating probe
- inspection of 50% of dents and dings greater than 5 volts in the hot leg tubes in all four SGs with a rotating probe
- inspection of indications with a rotating probe that are identified as "I Codes," based on examination with a bobbin probe

Six tubes displaying an eddy current signal offset, characteristic of the tubes with axial ODSCC, will be plugged during the next refueling outage. These six tubes were determined to display the offset after completion of the 2002 refueling outage and exhibited no ODSCC crack-like indications during the 2002 SG inspection. Eddy current testing will be performed on these tubes prior to plugging, in order to assess their condition. Refer to ADAMS Accession No. ML023170187, "Summary of Conference Call With North Atlantic Energy Service Corporation Regarding The Seabrook Steam Generator Laboratory Examination Results," for additional information regarding the eddy current signal offset.

Eddy current analysis of site-specific orientation and testing will incorporate samples from the thermally-treated Alloy 600 tubing with ODSCC. The licensee indicated this was an enhancement to their training program, since the previous level of training had been sufficient to detect the ODSCC flaws in the previous outage.

Enclosure

Seabrook Station, Unit No. 1  
cc:

Mr. J. A. Stall  
Senior Vice President, Nuclear and  
Chief Nuclear Officer  
Florida Power & Light Company  
P.O. Box 14000  
Juno Beach, FL 33408-0420

Mr. Peter Brann  
Assistant Attorney General  
State House, Station #6  
Augusta, ME 04333

Resident Inspector  
U.S. Nuclear Regulatory Commission  
Seabrook Nuclear Power Station  
P.O. Box 1149  
Seabrook, NH 03874

Town of Exeter  
10 Front Street  
Exeter, NH 03823

Regional Administrator, Region I  
U.S. Nuclear Regulatory Commission  
475 Allendale Road  
King of Prussia, PA 19406

Office of the Attorney General  
One Ashburton Place, 20th Floor  
Boston, MA 02108

Board of Selectmen  
Town of Amesbury  
Town Hall  
Amesbury, MA 01913

Mr. Dan McElhinney  
Federal Emergency Management Agency  
Region I  
J.W. McCormack P.O. &  
Courthouse Building, Room 401  
Boston, MA 02109

Mr. Jack Devine  
Polestar Applied Technology  
One First Street, Suite 4  
Los Altos, CA 94019

Mr. Stephen McGrail, Director  
ATTN: James Muckerheide  
Massachusetts Emergency Management Agency  
400 Worcester Road  
Framingham, MA 01702-5399

Philip T. McLaughlin, Attorney General  
Steven M. Houran, Deputy Attorney  
General  
33 Capitol Street  
Concord, NH 03301

Mr. Donald Bliss, Director  
New Hampshire Office of Emergency  
Management  
State Office Park South  
107 Pleasant Street  
Concord, NH 03301

Mr. Daniel G. Roy  
Nuclear Training Manager  
Seabrook Station  
FPL Energy Seabrook, LLC  
P.O. Box 300  
Seabrook, NH 03874

Mr. Gene F. St. Pierre  
Station Director  
Seabrook Station  
FPL Energy Seabrook, LLC  
P.O. Box 300  
Seabrook, NH 03874

Mr. M. S. Ross, Attorney  
Florida Power & Light Company  
P.O. Box 14000  
Juno Beach, FL 33408-0420

Mr. Rajiv S. Kundalkar  
Vice President - Nuclear Engineering  
Florida Power & Light Company  
P.O. Box 14000  
Juno Beach, FL 33408-0420