

Draft Submittal

(Risk Based)

**VOGTLE OP RETAKE EXAM
50-424 & 50-425/2003-301**

MAY 8, 2003

1. Operating Test Simulator Scenarios

Facility: Vogtle Electric Generating Plant Scenario No.: 1 Op-Test No.: 301-2003

Examiners: _____ Operators: _____

Initial Conditions:


Rx Power 100%, EOL, Rod Operability Testing in progress with CB C and D left to do.

Turnover:

1A MDAFW out of service

Event No.	Malf. No.	Event Type*	Event Description
1	GE05	R (RO, SRO)	Abnormal H₂ Pressure - leaking causes crew to rampdown. At approximately 95% power, fix leak.
2		N (RO)	Complete Rod Operability Test
3	RD09 Rod stick	C (RO, SRO)	Control Rod Urgent Failure - On CB D, Gp 2 when pulling bank D. Tech Spec for SRO
4	Needs development	I (RO)	Failure of 1-PT-0131 high - Causes Letdown High Pressure alarm and fails open 1-PV-0131, Letdown Pressure Control Valve. Causes pressure to go low and a high flowrate.
5	EL10	C (SRO)	480VAC Switchgear Fault- Fault switchgear that feeds HV-8801A (BIT valve) Tech Spec for SRO. Begin to slowly ramp in RCS leak at Examiners discretion.
6	TU02	C (BOP)	Main turbine vibration which leads to the requirement to lower turbine load. Will continue until crew is forced to use rods which, at this point will not drive CB D. This should lead to a manual Rx trip.
7	ES02/1 & RC04	MT	ATWS followed by Small Break LOCA
POST MT			1A HHSI pump fails to start, HV-8801B fails to open.

* (N)ormal, (R)eactivity, (I)nstrument, (C)omponent, (M)ajor

Approved By R. L. Mansfield	Vogtle Electric Generating Plant 	Procedure Number Rev 17007-1 20
Date Approved 2/25/02	ANNUNCIATOR RESPONSE PROCEDURES FOR ALB 07 ON PANEL 1A2 ON MCB	Page Number 28 of 37

ORIGIN

1-PT-0131

SETPOINT

425 psig

LTDN HX OUT
 HI PRESS

WINDOW E03

1.0 PROBABLE CAUSE

1. 1-PV-0131 malfunction.
2. All three Letdown Orifice Isolation Valves open.

2.0 AUTOMATIC ACTIONS

NONE

3.0 INITIAL OPERATOR ACTIONS

1. CHECK letdown pressure and flow using 1-PI-0131A and 1-FI-0132 on the QMCB.
2. GO to 18007-C, "Chemical And Volume Control System Malfunction" if letdown is lost.

4.0 SUBSEQUENT OPERATOR ACTIONS

NONE

5.0 COMPENSATORY OPERATOR ACTIONS

NONE

END OF SUB-PROCEDURE

REFERENCES: 1X4DB115, PLS

INSTRUCTOR STATION NO: RD09 .

DESCRIPTION: Control Rod Urgent Failure

CAUSE: Bank D, Group 2 power cabinet multiplexing
thyristor failure

SOFTWARE NAME(s): Logicals Severitys

YP:XMFTB(84)

PLANT STATUS: 100% power

EFFECTS:

The control rod urgent failure inhibits automatic control rod motion.

Control banks A, B & C can be positioned in manual individual control. CNTL BK D GP 2 D motion is blocked in manual and auto due to the failure in bank D.

Malfunction removal will restore the control rod system to normal.

INSTRUCTOR STATION NO: GE05

DESCRIPTION: Abnormal Generator H₂ Pressure

Variable: 100% severity equals a leakrate that will result in a pressure reduction of approximately 10 psig/minute at a generator hydrogen pressure of 75 psig.

SOFTWARE NAME(s): Logicals Severitys

YP:XMFTB(378) YPXSVRTY(98)

CAUSE: Hydrogen leakage through a faulty relief valve

PLANT STATUS: 100%

EFFECTS:

The hydrogen pressure will decrease at a rate designated by the malfunction severity. The rate of change of pressure will decrease as the hydrogen pressure decreases.

A reduction in hydrogen pressure will reduce the hydrogen Heat transfer coefficient; this will result in an increase in the generator field temperature. The increase in generator field temperature will in turn increase the hydrogen outlet temperature. This will cause TIC-7097 to open TV-7097 which will increase turbine plant cooling water to the hydrogen coolers. As the hydrogen pressure continues to decrease, the hydrogen will no longer be capable of removing the Heat generated in the generator field. If the generator load is not reduced, high generator field. If the generator load is not reduced, high generator field temperature will result in internal insulation breakdown. This will be indicated on the generator core monitor. Continued operation in this condition will result in grounding the generator field and generator neutral ground overcurrent lockout trip.

Upon malfunction removal the relief valve will re-seat stopping the leak and hydrogen pressure reduction. The hydrogen pressure can be returned to normal by using remote function GE05 which will open the hydrogen supply isolation valve. The pressurization rate for remote function GE05 will be 0.1 psig/minute at 75 psig hydrogen pressure. Remote function GE05 may also be used to increase the hydrogen pressure to 100 psig.

INSTRUCTOR STATION NO: RD09

DESCRIPTION: Control Rod Urgent Failure

CAUSE: Bank D, Group 2 power cabinet multiplexing
thyristor failure

SOFTWARE NAME(s): Logicals Severitys

YP:XMFTB(84)

PLANT STATUS: 100% power

EFFECTS:

The control rod urgent failure inhibits automatic control rod motion.

Control banks A, B & C can be positioned in manual individual control. CNTL BK D GP 2 D motion is blocked in manual and auto due to the failure in bank D.

Malfunction removal will restore the control rod system to normal.

3.1 REACTIVITY CONTROL SYSTEMS

3.1.4 Rod Group Alignment Limits

LCO 3.1.4 All shutdown and control rods shall be OPERABLE, with all individual indicated rod positions within 12 steps of their group step counter demand position.

APPLICABILITY: MODES 1 and 2.

ACTIONS

CONDITION	REQUIRED ACTION	COMPLETION TIME
A. One or more rod(s) untrippable.	A.1.1 Verify SDM is \geq the limit specified in the COLR.	1 hour
	<u>OR</u>	
	A.1.2 Initiate boration to restore SDM to within limit.	1 hour
	<u>AND</u>	
	A.2 Be in MODE 3.	6 hours
B. One rod not within alignment limits.	B.1.1 Verify SDM is \geq the limit specified in the COLR.	1 hour
	<u>OR</u>	
		(continued)

ACTIONS

CONDITION	REQUIRED ACTION	COMPLETION TIME
B. (continued)	B.1.2 Initiate boration to restore SDM to within limit.	1 hour
	<u>AND</u>	
	B.2 Reduce THERMAL POWER to $\leq 75\%$ RTP.	2 hours
	<u>AND</u>	
	B.3 Verify SDM is \geq the limit specified in the COLR.	Once per 12 hours
	<u>AND</u>	
	B.4 Perform SR 3.2.1.1.	72 hours
	<u>AND</u>	
	B.5 Perform SR 3.2.2.1.	72 hours
	<u>AND</u>	
	B.6 Reevaluate safety analyses and confirm results remain valid for duration of operation under these conditions.	5 days

(continued)

ACTIONS (continued)

CONDITION	REQUIRED ACTION	COMPLETION TIME
C. Required Action and associated Completion Time of Condition B not met.	C.1 Be in MODE 3	6 hours
D. More than one rod not within alignment limit.	D.1.1 Verify SDM is \geq the limit specified in the COLR.	1 hour
	<u>OR</u>	
	D.1.2 Initiate boration to restore required SDM to within limit.	1 hour
	<u>AND</u>	
	D.2 Be in MODE 3.	6 hours

SURVEILLANCE REQUIREMENTS

SURVEILLANCE	FREQUENCY
SR 3.1.4.1 Verify individual rod positions within alignment limit.	12 hours <u>AND</u> Once within 4 hours and every 4 hours thereafter when the rod position deviation monitor is inoperable

(continued)

SURVEILLANCE REQUIREMENTS (continued)

SURVEILLANCE		FREQUENCY
SR 3.1.4.2	Verify rod freedom of movement by moving each rod not fully inserted in the core ≥ 10 steps in either direction.	92 days
SR 3.1.4.3	<p>Verify rod drop time of each rod, from the physical fully withdrawn position, is ≤ 2.7 seconds from the beginning of decay of stationary gripper coil voltage to dashpot entry, with:</p> <p>a. $T_{avg} \geq 551^{\circ}\text{F}$; and</p> <p>b. All reactor coolant pumps operating.</p>	Prior to reactor criticality after each removal of the reactor head

Facility: <u>Vogtle Electric Generating Plant</u>		Scenario No.: <u>2</u>		Op-Test No.: <u>301-2003</u>	
Examiners: _____		Operators: _____			
_____		_____			
_____		_____			
Initial Conditions:					
Rx Power 47% ¹⁰⁰ and increasing, EOL, Procedure 12004-C in progress <i>Rads in data</i>					
Turnover:					
1A MDAPFW out of service for lube schedule					
Event No.	Malf. No.	Event Type*	Event Description		
1		R (RO, BOP)	Ramp up unit by approximately 5% per procedure		
2	CV12	I (RO)	VCT LT 185 Fails Hi		
3	FW02G	C (BOP)	1G Main Feed Reg valve oscillates, requiring manual control		
4	CV04	C (RO)	Loss of cooling to the Letdown Hx, requiring manual control		
5	GE09 <i>PT-505</i>	C (BOP)	Load Rejection <i>with impulse pressure XMTOR</i> (May trip Turbine or Rx manually per AOP) <i>Pressure high.</i>		
6	FW06	MT	Feed break inside containment		
Post MT			Automatic Feedwater isolation fails, HV 8801B thermals out when being closed, 1BMDAPFW fails to auto start		
			Scenario ends when primary and secondary plant are stable.		

* (N)ormal, (R)eactivity, (I)nstrument, (C)omponent, (M)ajor

INSTRUCTOR STATION NO: FW06

DESCRIPTION: Feedwater Line Rupture Inside Containment

Variable: 100% = 9,460,00 lbm/hr (25,000 gpm)

FW06a - FWL1

FW06c - FWL3

FW06c - FWL2

FW06d - FWL4

SOFTWARE NAME(s): Logicals Severitys

FWL 1: JMLCFW1 (1) SMLCFW1 (1)

FWL 2: JMLCFW1 (2) SMLCFW1 (2)

FWL 3: JMLCFW1 (3) SMLCFW1 (3)

FWL 4: JMLCFW1 (4) SMLCFW1 (4)

CAUSE: Pipe break between S/G and temp element TE-15205

PLANT STATUS: 100% power

EFFECTS:

Use the following chart to insert the malfunction:

<u>SEVERITY</u>	<u>FLOW TO CTMT FROM SG</u>	<u>FLOW TO CTMT FROM FEED LINE</u>	<u>FEED FLOW TO AFFECTED SG</u>
100%	5.76E6 lbm/hr	all FW	0 lbm/hr
80%	4.5E6	all FW	0
60%	3.4E6	2.3E6 lbm/hr	1.6E6
50%	2.8E6	1.9E6	1.9E6
40%	0	1.5E6	2.3E6
20%	0	7.6E5	3E6
10%	0	3.8E5	3.44E6
0%	0	0	all FW

At 100% power, the malfunction can be inserted at 21% severity and still maintain the plant on line. This is with the FRV 100% open, three condensate pumps, and the SGFPT's in manual at maximum speed.

Indicated feed flow to the steam generator increases. A feedwater line rupture causes a reduction in feed flow to the

affected steam generator. This reduced feed flow causes the affected steam generator level to decrease. The steam generator level control system responds to maintain level. With maximum severity inserted, the affected steam generator blowsdown rapidly and causes a reactor trip/turbine trip.

The reduced feedwater flow causes a decrease in subcooling of the affected steam generator. This causes an increase in T_{avg} . Pressurizer level and pressure correspondingly increase. The pressurizer pressure and level control systems respond to this transient.

Once a reactor trip occurs, the affected steam generator and the other steam generators continue to blowdown through the rupture. This leads to a low steamline pressure condition and initiates safety injection steamline and feedwater isolation.

When the SLI & FWI isolations occur, blowdown of the unaffected steam generators stops. The affected loop boils dry due to the location of the rupture. Auxiliary feedwater restores level in the unaffected loops.

Containment pressure and humidity increase dependent on break size. The sump levels increase, initiating sump pump starts.

Malfunction removal will stop the leak.

INSTRUCTOR STATION NO: CV04

DESCRIPTION: Loss of Cooling to Letdown Heat Exchanger

SOFTWARE NAME(s): Logicals Severitys

YP:XMFTB(299)

CAUSE: Temperature Element TE 130 Fails Low Causing Temp
Control Valve TV-130 to Fully Close

PLANT STATUS: 100% power

EFFECTS:

V-130 going closed will cause ACCW flow to the letdown Heat exchanger to go to minimum. This will cause an increase in letdown temperature downstream of the letdown Heat exchanger to approximately that at the outlet of the regenerative heat exchanger.

When the letdown temperature exceeds the setpoint for the high temperature diversion valve, it will shift letdown directly to the volume control tank and bypass the demineralizers. Volume control tank temperature will increase and annunciate a high temperature alarm when its setpoint is exceeded.

The operator can take manual control of TV-130 and control letdown temperature.

Malfunction removal will return the failed temperature element to normal.

INSTRUCTOR STATION NO: FW02

DESCRIPTION: Feed Flow Transmitter Fails (Cont)

Variable: 0-100% of Scale

FW02a - FT 510
FW02b - FT 520

FW02c - FT 530
FW02d - FT 540

SOFTWARE NAME(s): Logicals Severitys

510	:YP:XMFTB(443)	YPXSVRTY(106)
520	:YP:XMFTB(444)	YPXSVRTY(107)
530	:YP:XMFTB(445)	YPXSVRTY(108)
540	:YP:XMFTB(446)	YPXSVRTY(109)

CAUSE: Transmitter failure

PLANT STATUS: 100% power (assume failed channel selected for control)

EFFECTS:

This feed flow transmitter failing high or low will generate a steam flow-feed flow mismatch condition and alarm.

As transmitter output goes high, the associated feedwater control valve will modulate closed to bring steam and feed flows together. the reduced feedwater flow will cause actual steam generator level to decrease. This level decrease will continue until it either offsets the feed flow error or until a steam generator low low level generates a reactor trip and auxiliary feedwater pumps start. The time required for this to occur will depend on the severity selected.

If this transmitter fails low, just the opposite of the above stated reactions will occur, except that the turbine trip/reactor trip and feedwater isolation will occur if the hi-hi steam generator level is reached.

The operator can take manual feedwater control to stabilize steam generator level at program level or select the other channel for control.

Malfunction removal will cause transmitter output to return to normal.

INSTRUCTOR STATION NO: GE09

DESCRIPTION: Load Rejection

Variable: Percent Entered will Equal Percent
Decrease in Load Set Setpoint

SOFTWARE NAME(s): Logicals Severitys

YP:XMFTB(382) YPXSVRTY(102)

CAUSE: Electrical failure in EHC system


PLANT STATUS: 100% power, control rods in auto

EFFECTS:

This malfunction will decrease the load set setpoint at 133% per minute until the percent decrease is equal to the malfunction severity. The control valves will close at the maximum rate allowed by the EHC hydraulic system.

The decrease in turbine impulse pressure causes control rods to insert and will arm the steam dumps. The steam dumps will modulate open or if the Tavg-Tref error is large enough they will quick open. The system accepts a load reduction of 50% without opening the atmospheric relief valve or a reactor trip. Larger load reduction may result in a reactor trip, dependent upon the pressurizer pressure and level control system response.

Malfunction removal will stop the decrease in the load set setpoint.

Approval J. T. Gasser	Vogtle Electric Generating Plant NUCLEAR OPERATIONS  Unit <u>COMMON</u>	Procedure No. 18012-C
Date 12/6/99		Revision No. 11
		Page No. 1 of 5

Abnormal Operating Procedures

TURBINE RUNBACK

PURPOSE

PRB REVIEW REQUIRED

This procedure provides instructions for validating a turbine **runback**, stabilizing plant conditions following a **runback** and terminating an invalid **runback**.

SYMPTOMS

- **OVERTEMP** DELTA-T ROD STOP TURBINE **RUNBACK** C3 ON BPLB.
- **OVERPWR** DELTA-T ROD STOP TURBINE **RUNBACK** C4 ON BPLB.
- OVERPOWER AT ROD BLOCK AND **RUNBACK** ALERT Annunciator
- **OVERTEMP** AT ROD BLOCK AND **RUNBACK** ALERT Annunciator
- **OVERTEMP** DELTA-T ALERT Annunciator.
- OVERPOWER DELTA-T ALERT Annunciator.
- Unexplained loss of generator **MW**.
- Unexplained insertion of control **rods** while in auto.

PROCEDURE NO.	REVISION NO.	PAGE NO.
VEGP 18012-C	11	2 of 5

<u>ACTION/EXPECTED RESPONSE</u>	<u>RESPONSE NOT OBTAINED</u>
<u>IMMEDIATE OPERATOR ACTIONS</u>	
1. Verify that a turbine runback is - REQUIRED: Any 2 out of 4 runback bistable status lights energized: • OT DELTA-T • OP DELTA-T	1. Go to 8.
2. Ensure Rod Control System 'in AUTO and inserting rods to 'restore Tavg/Tref.	2. Manually insert control rods as required.
3. Verify that a runback has initiated: • Turbine control valves-SHUTTING . • Generator load - LOWERING. • LOSS OF TURB LOAD INTLK C7 Status Light - ENERGIZED.	3. Reduce load manually by depressing LOAD DECREASE pushbutton UNTIL: • OT DELTA-T or OP DELTA-T runback bistable status lights extinguish.
<u>SUBSEQUENT OPERATOR ACTIONS</u>	
4. Verify Steam Dump System - ARMED AND RESPONDING TO TAVG/TREF DEVIATION.	4. Verify SG ARVs are in AUTO.
5. Verify PRZR Pressure Control System - RESTORING PRESSURE TO 2235 PSIG.	5. Take manual control of PRZR spray and heaters to restore pressure.
6. Verify SGWLC System - RESTORING SG LEVELS TO PROGRAMMED BAND.	6. Take manual control of FRVs and restore level.

PROCEDURE NO. VEGP	REVISION NO. 11	PAGE NO. 3 of 5
-----------------------	--------------------	--------------------

ACTION/EXPECTED RESPONSE

7. IF the runback condition has cleared,
THEN continue operation in accordance with 12004-C,
POWER OPERATION (MODE 1).

RESPONSE NOT OBTAINED

7. IF less than 50% power,
THEN trip the turbine and go to 18011-C, TURBINE TRIP
BELOW P-9,

-OR-

Trip the reactor and go to 19000-C, E-O REACTOR TRIP OR SAFETY INJECTION.

NOTE:

The following steps will place the turbine in Standby Mode to facilitate recovery. These steps may be used, if necessary, to stabilize turbine load, and may be used in conjunction with 12004-C, POWER OPERATION (MODE 1).

8. Stabilize turbine loads using STANDBY SIGNAL MATCH controls:

- a. Match CV SIGNAL and IV SIGNAL using STANDBY LOAD SET potentiometer.
- b. Simultaneously depress ON and BYPASS pushbuttons on STANDBY SIGNAL MATCH.

9. Check that turbine load stabilizes.

9. IF less than 50% power,
THEN trip the turbine and go to 18011-C, TURBINE TRIP
BELOW P-9.

-OR-

IF runback continues,
THEN trip the reactor and go to 19000-C, E-O REACTOR TRIP OR SAFETY INJECTION.

PROCEDURE NO. VEGP	18012-C	REVISION NO. 11	PAGE NO. 4 of 5
-----------------------	---------	--------------------	--------------------

ACTION/EXPECTED RESPONSE

RESPONSE NOT OBTAINED

CAUTION:

Turbine loading rates in Standby Mode are not restricted by the EHC System and are totally under control of the operator.

10. Control load using the
STANDBY LOAD SET
potentiometer.

NOTE:

Chemistry should be notified every time reactor power is changed by 15% or more in a one-hour period so iodine activity can be determined per Tech Spec SR 3.4.16.2.

11. IF C-7 present,
THEN reset C-7.
12. Perform 14286, TURBINE TRIP
DEVICE OPERABILITY TEST,
Section 5.1 and 5.2.
13. Continue operation in
accordance with the UOP
currently in effect.
14. IF the load reduction was
unplanned or unexplained,
THEN initiate a Condition
Report per 00150-C,
Condition reporting and
Tracking System.
15. WHEN the cause of the
runback has been corrected,
THEN initiate 13800, TURBINE
OPERATION to restore EHC to
normal,

PROCEDURE NO. JEGP 18012-C	REVISION NO. 11	PAGE NO. 5 of 5						
<table><tr><td><u>ACTION/EXPECTED RESPONSE</u></td><td><u>RESPONSE NOT OBTAINED</u></td></tr><tr><td>16. Power ascension may commence after review of event cause and corrective action.</td><td></td></tr><tr><td colspan="2">END OF PROCEDURE TEXT</td></tr></table>			<u>ACTION/EXPECTED RESPONSE</u>	<u>RESPONSE NOT OBTAINED</u>	16. Power ascension may commence after review of event cause and corrective action.		END OF PROCEDURE TEXT	
<u>ACTION/EXPECTED RESPONSE</u>	<u>RESPONSE NOT OBTAINED</u>							
16. Power ascension may commence after review of event cause and corrective action.								
END OF PROCEDURE TEXT								