



INPO-NRC Materials Meeting



INPO Materials Group


Steve Johnson
August 21, 2003




Meeting Purpose




- **Exchange information with NRC about materials-related programs**
- **Answer questions on INPO materials activities**




INPO Materials Group



- **New group formed July 2002**
- **Align with industry materials management improvement initiative**
- **Implement a boric acid leakage and corrosion management review visit program (now expanded to primary systems integrity)**
- **A key INPO initiative for 2003 and 2004**




Focus Areas




Materials Review Visit Programs


- **Steam Generator Program – '95**
- **BWR Vessel and Internals Program – '01**
- **PWR Primary Systems Integrity – '03**
- **Future material review programs**



Review Visit Methodology



- **Separate from INPO evaluation process**
- **Use best industry experts**
- **Focused, detailed review**
- **Review visit guidelines**
- **Standard of excellence for safety and reliability issues – not minimum compliance**




Review Visit Purpose




Big Picture

- **Ensure stations have material programs in place and being used to promote safe and reliable operation**

- **Ensure consistent interpretation and application of industry guidelines**




Review Visit Purpose




But also,


- Identify outliers
- Make industry guidelines a living program – identify and promote changes to industry guidelines
- Resolve technical disagreements
- Promote best practices available
- Share results widely




What does INPO add?



- **Team leaders are experienced evaluators**
- **Formal, structured, proven evaluative process**
- **Senior management attention**
- **Continuous follow-up on important issues (boric acid programs being looked at on every INPO evaluation)**




Depth of Review



On-site review includes:


- > **NDE review (eddy current, videotapes, UT scans)**
- > **Interviews (technician level to site management)**
- > **Walkdowns and observations**
- > **Documentation (process and results)**




Review Visit Results




- Strengths and recommendations for improvement are discussed with site management**
- **Results are reviewed by INPO management and provided in a report to the site vice president**
 - **Issues impacting safety and reliability require a written utility response and follow-up during next INPO evaluation**




Program Scope




- Visit every station
- Targeted second round of visits
- Add to existing programs or implement new review programs based on industry needs and operating experience
- What additional material areas are of most concern to the NRC?




Program Trends



- **Most steam generator programs mature**
- **BWR vessel and internals programs – good foundation of industry guidelines**
- **PWR primary system integrity – most programs in a state of change**




Industry Materials Initiative




**Roles and responsibilities of INPO as defined in NEI
03-08:**


- > On-site evaluation of industry guidelines**
- > Analysis of operating experience for emerging material issues**
- > Communicate identified trends or emerging issues to industry**
- > Participating at all levels of industry materials management initiative**




INPO Materials Group



Questions/comments?




INPO-NRC Materials Meeting




INPO Steam Generator Review Visits

Jeff Ewin


August 21, 2003




INPO Steam Generator Review Visits




- **Began mid-1995 at industry request**
- **Review visit guidance written with industry input**
- **NEI 97-06 and EPRI guidelines used as technical basis**




INPO Steam Generator Review Visits




- **63 domestic visits**
- **3 international visits**
- **All PWRs have had at least one visit**
- **18 PWRs have had second visit**




Team Composition




- **INPO Team Lead**
- **Chemistry Evaluator**
- **Steam generator program manager or engineer**
- **Eddy-current Level III/QDA**




Review Visit Scope and Structure




- Program management, self-assessment, and corrective actions
- Degradation assessments and inspection plans for tubing and secondary-side structures
- Integrity assessments – condition monitoring and operational assessments
- Response to inspection results – repairs or alternate repair criteria



Review Visit Scope and Structure



- **NDE analyst and technique qualification**
- **NDE data acquisition, analysis, management**
- **Operations and chemistry procedures and practices for primary-to-secondary leakage monitoring and response**
- **Primary and secondary chemistry control**




Typical Strengths



Management support of program


- Knowledge and experience of personnel
- Participation in industry groups
- Long-term strategies for steam generator health
- Robust program procedures
- Improved quality of degradation, condition monitoring and operational assessments




Typical Recommendations




- **Implementation of industry guideline requirements**
- **Deviation justifications and level of approval**
- **Inspection scope (critical areas/buffer zones)**



Typical Recommendations




- **Primary-to-secondary leak monitoring and response**
- **Evaluation and response to industry operating experience**
- **Accuracy of program procedures and documents**




INPO Steam Generator Review Visits



Questions/comments?




INPO-NRC Materials Meeting




INPO BWRVIP Review Visits


David Berko
August 21, 2003




INPO BWRVIP Review Visits




- **Began July 2001 at industry request**
- **Modeled after steam generator review program**
- **BWRVIP guidelines provide technical basis**
- **18 of 23 sites visited to date**
- **Complete all U.S. plants by 2003**




Team Composition




- **INPO Team Lead**
- **Chemistry Evaluator**
- **Level III NDE (Visual and UT)**
- **1-2 Program Owners**
- **EPRI team member**




Review Visit Scope and Structure




- **Weld-by-weld review all 12 BWRVIP components**
- **2-3 components per day**
- **For dual-unit sites, focus on unit with upcoming outage, but review aspects of alternate unit as well**
- **Two sets of eyes on major components**
- **Look beyond BWRVIP components (steam dryer, head bolts, dry-tubes, foreign material)**




Review Visit Scope and Structure




- Peers selection based on station history
- Review visit information sources:
 - > Vendor inspection reports (baseline and re-exams)
 - > Program guidelines
 - > Nondestructive evaluation data (UT, visual)
 - > Chemistry trends and parameters
 - > Operating parameters (jet pumps, etc.)
 - > Interviews




Typical Strengths



- **Proactive towards understanding material condition of vessel internals**
 - > UT applications, aggressive scope, inspection coverage
- **Plant-specific applications**
 - > Fluence profile, analysis, labyrinth seals, NDE remote viewing
- **Program Elements**
 - > Implementation plan, self-assessment




Typical Recommendations



- **Guideline requirements**
 - > Management oversight, quality of technical justifications

- **Bow-wave effect for inspections**


- **Component-specific vulnerabilities**
 - > Shroud, core spray, jet pumps, steam dryer




Typical Recommendations




- **Effects of power uprate**
- **Quality of nondestructive evaluation (visual, UT)**
- **Mitigation (+/Δ)**
 - > Hydrogen availability, aggressive ion intrusion events
- **Operational considerations**
 - > Jet pump performance monitoring, drywell leakage detection




INPO BWR VIP Review Visits



Questions/comments?




INPO-NRC Materials Meeting




INPO Primary System Integrity Review Visits

John Makar, Russ Warren


August 21, 2003




Primary Systems Integrity Review Visits




- MRP and industry recognized need for independent review
- Decision to begin INPO review visits 2002
- Several meetings held with industry peers
- INPO guideline developed with industry input




Primary Systems Integrity Review Visits




- Modeled after Steam Generator and BWRVIP review visit programs
- Industry peers provide technical expertise
- EPRI and WCAP guidelines provide technical basis
- Review to standards of excellence




Primary Systems Integrity Review Visits




- First two pilots completed 2002
- Ten visits complete October 2002 - July 2003
- Seven more visits scheduled August - December 2003 - schedule to complete all US plants by end of 2005




Team Composition




- INPO Team Leader
- 2-3 peers knowledgeable of guidelines, selected based on plant-specific needs
- ISI / NDE expertise




Review Visit Scope and Structure




- Scope includes:
 - Management Oversight and Involvement
 - Program Scope
 - Implementation
 - Interfaces with Other Programs
 - Training and Qualification




Review Visit Scope and Structure




- Review all Alloy 600 components
- Thorough Auxiliary Building walkdown
- Review of containment conditions, potential indications of leakage over several years
- Strong focus on vessel penetrations, condition of upper head and vessel bottom
- Interviews with station personnel (Program Owners, Engineering, Maintenance, Operations, Chemistry, and Health Physics)




Typical Strengths




- Commitment to vessel upper head exams
- Comprehensive Alloy 600 program plans
- Sensitivity to minor leakage
- Eddy Current Testing techniques




Typical Recommendations




- Program implementation
- Vessel lower head exams
- Alloy 600 susceptibility analysis and bare metal examination
- Threshold for reporting leakage




Typical Recommendations




- Carbon steel component replacement
- Shutdown inspections
- Reactor Coolant System leakage indicators




Primary Systems Integrity Review Visits



Questions/comments?




INPO-NRC Materials Meeting




International Operating Experience

Francois
Chapelier


August 21, 2003




Materials Group Interaction with EDF




- **January 2003 meeting between INPO, US industry and EDF focused on operating experience feedback and identification of potential industry issues**
- **Share operating experience**
- **INPO/EDF have established a framework for future meetings on shared materials issues**




Key Material Issues



- **BMI**
- **CVCS charging line nozzle**
- **Boric acid injection nozzle**
- **Surge line nozzle**
- **Tee upstream of RHR pump**
- **Tee connecting feed flow and AFW**
- **CCW**



International Operating Experience



Questions/comments?

**NRC
DOCUMENTS**

RECENT STEAM GENERATOR ISSUES



NRC/INPO Meeting

August 21, 2003

Louise Lund

U.S. Nuclear Regulatory Commission

(301) 415-3248

SG PERFORMANCE

- **Forced Outages**
 - **Wolf Creek – no leakage - primary side loose part**
 - **Byron 2 – 75 to 80 gpd leak – secondary side loose part**
 - **Comanche Peak 1 – 50 gpd leak – SCC in U-bend**
- **Most forced outages in a single year since 1994**
- **Performance criteria not met**
 - **Comanche Peak 1 – Structural / Accident Leakage**
 - **Oconee 2 – Structural**
- **Meeting performance criteria is another measure of plant performance**

COMANCHE PEAK 1

- **Axial ODSCC at dinged location in U-bend**
- **Accident and structural performance criteria not met**
- **Issues:**
 - **Overly restrictive phase angle response reporting criteria**
 - **Presence of artifact signals (dents , dings, probe wobble, etc.)**
 - **Automated data screening threshold criteria**
 - **Detecting long freespan indications**
 - **Use of “Judas” tube**

OCONEE 2

- **Flaw coincident with 2 volt dent (industry calibration) and a manufacturing burnish mark which caused the tube to not meet structural performance criteria**
- **Dent and MBM in close proximity are precursor and masking combination that affects flaw detectability**
- **Observations**
 - Inspect dents and MBMs with qualified techniques**
 - Certain artifact types, or combinations thereof, may pose significant challenge for detection of flaws**

OTHER SG ISSUES

- **Diablo Canyon – degradation in unexpected location/unexpected high voltage indications**
- **Seabrook – first domestic incident of cracking in thermally treated Alloy 600 tubing**
- **Beaver Valley 2 – implementation of GL 95-05**
- **Tubesheet Inspections – inspections to evaluate circumferential cracking in lower tubesheet regions**

DIABLO CANYON 2

- **Secondary side pressure test performed based on operational leakage**
- **Circumferential cracks (ID initiated) in U-bend – Rows 1 through 10**
 - **Met performance criteria**
 - **Cracking may not progress sequentially row by row**
 - **Experience should be factored into degradation assessments**

DIABLO CANYON 2 (cont'd)

- **Axial ODSCC at tube supports (GL 95-05)**
- **Large voltage indication – 19.5 volt increase in one cycle**
 - **NDE indicated flaw nearly through-wall during previous inspection**
 - **Review rotating probe profiles for indications less than repair limits**
 - **Unexpected number of large voltage indications**
 - **Voltage dependent growth rate methodology should result in conservative estimates of voltage growth**

SEABROOK

- **First domestic incident of confirmed ODSCC at tube support plate elevations in 15 Alloy 600 thermally treated tubes**
- **Cracking unexpected based on tube material, plant age, and operating conditions at plant (e.g., temperature)**
- **Observations:**
 - **Manufacturing/fabrication anomalies can lead to unanticipated degradation mechanisms**
 - **Abnormal trends in eddy current data may indicate potential problem**
 - **ISI programs – intended to manage known degradation as well as promptly detect unanticipated degradation**

BEAVER VALLEY 2

- **Spring 2003 outage – licensee may not be following Generic Letter 95-05 (voltage based repair limit) guidance concerning large mix residuals**
- **Technical Issue: Mix residuals can mask indications and may affect the bobbin voltage response of the indications**
- **Observations/Issues**
 - **Critical evaluation of inspection results is important**
 - **Is criteria for identifying large mix residuals supported by inspection results (i.e., finding >1.0 volt flaws near lower range of screening criteria may question adequacy of screening criteria)**
 - **Are large mix residuals consistently called from outage-to-outage?**

TUBESHEET INSPECTIONS

- **Draft generic letter issued for public comment**
- **Staff position and expectations discussed**
- **Questions developed based on review of licensee's technical basis (ADAMS Accession Numbers: ML031270287, ML030350719, and ML022980486)**
- **Licensee submittals should address these issues**

RECENT NRC GENERIC COMMUNICATIONS ON SG OPERATING EXPERIENCE

- Information Notice (IN) 2002-02 - Experience with Plugged Steam Generator (SG) Tubes
- IN 2002-21 - Cracking Affecting Thermally Treated Alloy 600 Steam Generator Tubes
- IN 2003-05 - Failure to Detect Freespan Cracks in SG Tubes - Comanche Peak 1
- Draft GL, Requirements for Steam Generator Tube Inspections – May 14th Federal Register, Pages 25909-25912 (ML031270171)
- SECY-03-0080, SG Tube Integrity (SGTI) - Plans for Revising the Associated Regulatory Framework
- NUREG-1771, U.S. Operating Experience with Thermally Treated Alloy 600 SG Tubes
- Plan to issue an IN on Diablo Canyon 2

RECENT STEAM GENERATOR ISSUES



NRC/INPO Meeting

August 21, 2003

Louise Lund

U.S. Nuclear Regulatory Commission

(301) 415-3248

SG PERFORMANCE

- **Forced Outages**
 - **Wolf Creek – no leakage - primary side loose part**
 - **Byron 2 – 75 to 80 gpd leak – secondary side loose part**
 - **Comanche Peak 1 – 50 gpd leak – SCC in U-bend**
- **Most forced outages in a single year since 1994**
- **Performance criteria not met**
 - **Comanche Peak 1 – Structural / Accident Leakage**
 - **Oconee 2 – Structural**
- **Meeting performance criteria is another measure of plant performance**

COMANCHE PEAK 1

- **Axial ODSCC at dinged location in U-bend**
- **Accident and structural performance criteria not met**
- **Issues:**
 - **Overly restrictive phase angle response reporting criteria**
 - **Presence of artifact signals (dents , dings, probe wobble, etc.)**
 - **Automated data screening threshold criteria**
 - **Detecting long freespan indications**
 - **Use of “Judas” tube**

OCONEE 2

- **Flaw coincident with 2 volt dent (industry calibration) and a manufacturing burnish mark which caused the tube to not meet structural performance criteria**
- **Dent and MBM in close proximity are precursor and masking combination that affects flaw detectability**
- **Observations**
 - Inspect dents and MBMs with qualified techniques**
 - Certain artifact types, or combinations thereof, may pose significant challenge for detection of flaws**

OTHER SG ISSUES

- **Diablo Canyon – degradation in unexpected location/unexpected high voltage indications**
- **Seabrook – first domestic incident of cracking in thermally treated Alloy 600 tubing**
- **Beaver Valley 2 – implementation of GL 95-05**
- **Tubesheet Inspections – inspections to evaluate circumferential cracking in lower tubesheet regions**

DIABLO CANYON 2

- **Secondary side pressure test performed based on operational leakage**
- **Circumferential cracks (ID initiated) in U-bend – Rows 1 through 10**
 - **Met performance criteria**
 - **Cracking may not progress sequentially row by row**
 - **Experience should be factored into degradation assessments**

DIABLO CANYON 2 (cont'd)

- **Axial ODSCC at tube supports (GL 95-05)**
- **Large voltage indication – 19.5 volt increase in one cycle**
 - **NDE indicated flaw nearly through-wall during previous inspection**
 - **Review rotating probe profiles for indications less than repair limits**
 - **Unexpected number of large voltage indications**
 - **Voltage dependent growth rate methodology should result in conservative estimates of voltage growth**

SEABROOK

- **First domestic incident of confirmed ODSCC at tube support plate elevations in 15 Alloy 600 thermally treated tubes**
- **Cracking unexpected based on tube material, plant age, and operating conditions at plant (e.g., temperature)**
- **Observations:**
 - **Manufacturing/fabrication anomalies can lead to unanticipated degradation mechanisms**
 - **Abnormal trends in eddy current data may indicate potential problem**
 - **ISI programs – intended to manage known degradation as well as promptly detect unanticipated degradation**

BEAVER VALLEY 2

- **Spring 2003 outage – licensee may not be following Generic Letter 95-05 (voltage based repair limit) guidance concerning large mix residuals**
- **Technical Issue: Mix residuals can mask indications and may affect the bobbin voltage response of the indications**
- **Observations/Issues**
 - **Critical evaluation of inspection results is important**
 - **Is criteria for identifying large mix residuals supported by inspection results (i.e., finding >1.0 volt flaws near lower range of screening criteria may question adequacy of screening criteria)**
 - **Are large mix residuals consistently called from outage-to-outage?**

TUBESHEET INSPECTIONS

- **Draft generic letter issued for public comment**
- **Staff position and expectations discussed**
- **Questions developed based on review of licensee's technical basis (ADAMS Accession Numbers: ML031270287, ML030350719, and ML022980486)**
- **Licensee submittals should address these issues**

RECENT NRC GENERIC COMMUNICATIONS ON SG OPERATING EXPERIENCE

- Information Notice (IN) 2002-02 - Experience with Plugged Steam Generator (SG) Tubes
- IN 2002-21 - Cracking Affecting Thermally Treated Alloy 600 Steam Generator Tubes
- IN 2003-05 - Failure to Detect Freespan Cracks in SG Tubes - Comanche Peak 1
- Draft GL, Requirements for Steam Generator Tube Inspections – May 14th Federal Register, Pages 25909-25912 (ML031270171)
- SECY-03-0080, SG Tube Integrity (SGTI) - Plans for Revising the Associated Regulatory Framework
- NUREG-1771, U.S. Operating Experience with Thermally Treated Alloy 600 SG Tubes
- Plan to issue an IN on Diablo Canyon 2