

William R. Kanda
Vice President - Nuclear

440-280-5579
Fax: 440-280-8029

October 20, 2003
PY-CEI/NRR-2738L

United States Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555


Perry Nuclear Power Plant
Docket No. 50-440
LER 2003-003-00

Ladies and Gentlemen:

Enclosed is Licensee Event Report (LER) 2003-003, Unrecognized Diesel Generator Inoperability During Mode Changes. This event is being reported in accordance with 10CFR50.73(a)(2)(i)(B), as an operation, or condition prohibited by Technical Specifications. There are no regulatory commitments contained in this letter. Any actions discussed in this document that represent intended or planned actions, are described for the NRC's information, and are not regulatory commitments.

If you have questions or require additional information, please contact Mr. Vernon K. Higaki, Manager-Regulatory Affairs, at (440) 280-5294.

Very truly yours



Enclosure: LER 2003-003

cc: NRC Project Manager
NRC Resident Inspector
NRC Region III

IE22

LICENSEE EVENT REPORT (LER)

(See reverse for required number of digits/characters for each block)

Estimated burden per response to comply with this mandatory information collection request: 50 hrs. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records Management Branch (T-6 E6), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to bjs1@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME Perry Nuclear Power Plant	2. DOCKET NUMBER 05000 440	3. PAGE 1 OF 5
---	-------------------------------	-------------------

4. TITLE
Unrecognized Diesel Generator Inoperability During Mode Changes

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MO	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO	MO	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
08	20	2003	2003	-- 003 --	00	10	20	2003	FACILITY NAME	DOCKET NUMBER

9. OPERATING MODE 2	10. POWER LEVEL 000	11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)							
		20.2201(b)	20.2203(a)(3)(ii)	50.73(a)(2)(ii)(B)	50.73(a)(2)(ix)(A)				
		20.2201(d)	20.2203(a)(4)	50.73(a)(2)(iii)	50.73(a)(2)(x)				
		20.2203(a)(1)	50.36(c)(1)(i)(A)	50.73(a)(2)(iv)(A)	73.71(a)(4)				
		20.2203(a)(2)(i)	50.36(c)(1)(ii)(A)	50.73(a)(2)(v)(A)	73.71(a)(5)				
		20.2203(a)(2)(ii)	50.36(c)(2)	50.73(a)(2)(v)(B)		OTHER Specify in Abstract below or in NRC Form 366A			
		20.2203(a)(2)(iii)	50.46(a)(3)(ii)	50.73(a)(2)(v)(C)					
		20.2203(a)(2)(iv)	50.73(a)(2)(i)(A)	50.73(a)(2)(v)(D)					
		20.2203(a)(2)(v)	X	50.73(a)(2)(i)(B)	50.73(a)(2)(vii)				
20.2203(a)(2)(vi)		50.73(a)(2)(i)(C)	50.73(a)(2)(viii)(A)						
20.2203(a)(3)(i)		50.73(a)(2)(ii)(A)	50.73(a)(2)(viii)(B)						

12. LICENSEE CONTACT FOR THIS LER

NAME David A. Bowen – Compliance Engineer	TELEPHONE NUMBER (Include Area Code) (440) 280-5597
--	--

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX

14. SUPPLEMENTAL REPORT EXPECTED				15. EXPECTED SUBMISSION DATE			MONTH	DAY	YEAR
YES (If yes, complete EXPECTED SUBMISSION DATE).				X	NO				

16. ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

At 1206, August 21, 2003, with the reactor in MODE 1 at approximately 13 percent power, the monthly "Diesel Generator Start and Load" surveillance was performed and the starting output voltage was discovered to be set at approximately 4534 volts. This value was greater than the Technical Specification acceptance criteria band of 3900 to 4400 volts AC and resulted in the Division 1 diesel generator [DG] being declared inoperable.

The conditions initiating this event were traced to the reverse power trip of the Division 1 diesel generator and its output breaker at 1813, August 14, 2003, while restoring the Division 1, Class 1E, 4160 volt AC electrical bus to its offsite power supply. Subsequently, the plant changed MODES two times on 8/20/03 with an inoperable diesel generator. The two MODE changes were made in violation of Technical Specifications, i.e. one at 0150 to MODE 2 at 0 percent power and the second at 2146 to MODE 1 at approximately 8 percent power. This condition is reportable per 10CFR50.73(a)(2)(i)(B).

The root causes of this event are a less than adequate questioning attitude concerning the operability of the Division 1 diesel generator including the need to restart the diesel generator to verify proper voltage adjustment; and a deficient procedure that neither addresses operation outside normal bands nor contains sufficient guidance to recover a tripped diesel and ensure voltage is properly adjusted prior to restoring the diesel to an operable status.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
Perry Nuclear Power Plant	05000440	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 OF 5
		2003	-- 003 --	00	

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

I. DESCRIPTION OF OCCURRENCE:

At 1206, August 21, 2003, with the reactor in MODE 1 at approximately 13 percent power, the monthly "Diesel Generator Start and Load" surveillance was being performed and the starting output voltage was found to be approximately 4534 volts. This value is outside of the Technical Specification (TS) acceptance criteria band of 3900 to 4400 volts AC.

A root cause investigation traced the initiating event of this condition to a reverse power trip of the Division 1 diesel generator [DG] and its output breaker [BKR] that occurred at 1813, August 14, 2003.

On August 14, 2003, the Perry Nuclear Power Plant was recovering from a loss of offsite power condition (Perry LER 2003-002). The Division 1, Class 1E (nuclear safety related), 4160 volt electrical bus [ED] was being powered from the Division 1 diesel generator. As part of this recovery, the diesel generator was being paralleled with the Division 1 preferred power supply, the offsite source [JX], in preparation for transferring the safety bus from the diesel generator to the offsite source per the system operating instruction (SOI).

The offsite source was at a higher than normal voltage. The Division 1 diesel generator was prepared for paralleling with the offsite source. During the restoration, the Division 1 diesel generator output voltage was matched to the preferred source voltage. The syncroscope [SYN] was adjusted to rotate "slowly in the clockwise direction" as directed in the SOI, and then the preferred source breaker was closed at approximately 12 o'clock on the syncroscope. The diesel generator began to immediately lose load as the breaker was closed, which is expected due to the diesel generator speed and voltage control reverting from the isochronous to the droop mode of operation.

At 1813, August 14, 2003, the Division 1 diesel generator and its output breaker tripped on reverse power, and the Division 1 electrical bus remained energized by the offsite source.

This diesel generator reverse power trip occurred prior to the completion of the SOI steps that would have shutdown the diesel. As such, the diesel generator shutdown step that has the operator adjust the voltage regulator to between 4100 and 4200 volts prior to shutdown was marked "not applicable" by the control room staff as it could not be performed with the diesel generator already shutdown. The diesel generator trip was reset and the diesel generator was placed in standby readiness at 1835, August 14, 2003.

At 1152, August 21, 2003, the Division 1 diesel generator was started for the performance of the "Diesel Generator Start and Load" monthly surveillance. At 1206, it was found that the starting voltage stabilized at approximately 4534 volts, which is above the maximum allowed 4400 volts, and the diesel was declared inoperable. During the shutdown to standby readiness of the diesel generator, the step of the SOI that instructs the operator to adjust the voltage regulator [RG] between 4100 and 4200 volts was performed by the control room staff, which restored the Division 1 diesel generator to the desired voltage band. The diesel generator was stopped at 1227 and shutdown to standby readiness at 1246, per the SOI.

The system engineer recognized that there was a connection between the reverse power trip on August 14 and the starting voltage being high on August 21. Computer traces of the reverse power trip were obtained. These traces indicated that the bus voltage was at this high level when the diesel generator tripped on reverse power on August 14, 2003. Since the Division 1 diesel generator voltage was not properly restored on August 14, 2003, the Division 1 DG voltage remained high outside of TS limits and unrecognized by the plant operators until its discovery on August 21, 2003.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Perry Nuclear Power Plant	05000440	2003	-- 003 --	00	3 OF 5

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

DESCRIPTION OF OCCURRENCE: (Continued)

Between August 14 and 21 of 2003, the Division 2 diesel generator was operable except for a period of one hour seventeen minutes for the performance of a post-shutdown engine roll (8/16/2003). The plant was in mode 4 at the time of the post-shutdown roll and plant personnel did not know that the Division 1 diesel generator was inoperable.

TS 3.8.2, AC Sources-Shutdown, is applicable in MODE 4 and specifies that one diesel generator capable of supplying one division of the Division 1 or 2 onsite Class 1E AC electrical power distribution subsystem(s) is required. If the aforementioned cannot be met, required action B.4 states to initiate action to restore a required DG to operable status with a COMPLETION TIME of "Immediately." Since it was unknown that the Division 1 diesel generator was inoperable, the Division 2 diesel generator was declared operable at the completion of the post-shutdown engine roll instead of "Immediately." The Division 3 diesel generator was operable during this time.

On 8/20/03 the plant changed MODES from 4 to 2 and 2 to 1 making TS 3.8.1, AC Sources-Operating, applicable. TS 3.8.1 requires that two qualified circuits between the offsite transmission network and the onsite Class 1E AC Electrical Power Distribution system; and three diesel generators be operable when in MODES 1, 2, and 3. TS 3.8.1 does not have an exception to TS 3.0.4 to allow a MODE change with an inoperable diesel generator.

TS 3.0.4 states that when an LCO is not met, entry into a MODE or other specified condition in the Applicability shall not be made except when the associated ACTIONS to be entered permit continued operation in the MODE or other specified condition in the Applicability for an unlimited period of time. Since Division 1 diesel generator was inoperable, the plant made the following MODE changes in violation of TS 3.0.4: from MODE 4 to MODE 2 at 0150 on 08/20/2003 at 0 percent power; and from MODE 2 to MODE 1 at 2146, on 08/20/2003 at approximately 8 percent power.

II. CAUSE OF EVENT

Two root causes were identified for this event:

A less than adequate questioning attitude by the control room staff of the operability of the Division 1 diesel generator after tripping including a less than adequate response to the need to restart the diesel generator to verify proper voltage adjustment.

The Division 1 and 2 diesel generator SOI content was found to be deficient in that it does not anticipate operation outside of normal bands. The SOI does not verify that bus parameters will be within limits prior to paralleling between sources; however, the Systems Operations section of the SOI does specify voltage to be maintained between 3900 to 4400 volts. Additionally, the SOI does not contain sufficient guidance to recover a diesel generator from a tripped condition and to ensure that the voltage is adjusted within limits prior to restoring the diesel generator to an operable status.

Contributing causes were identified as the Division 1 and 2 diesel generator SOI section for transferring to the preferred or alternate preferred source from the diesel generator is not written in the correct sequence and does not have a specific step to adjust the diesel generator speed to prevent a reverse power trip situation; however, a note in the SOI states, upon closing the Preferred Source Breaker the indicated diesel generator load will decrease (sometimes less than zero) and it may be necessary to raise load with the Diesel Generator Governor to prevent a reverse power condition. Also identified was a less than adequate questioning attitude in response to the reverse power trip by the responsible system engineer and technical support center personnel.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
Perry Nuclear Power Plant	05000440	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	4 OF 5
		2003	-- 003 --	00	

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

III. SAFETY ANALYSIS

To assess the impact of the inoperable condition of the Division 1 diesel generator from August 14, 2003 through August 21, 2003 a Probabilistic Safety Assessment (PSA) Risk Impact was performed.

Although the Division 1 diesel generator was inoperable from 1813, on August 14, until 1624, August 21, 2003, an engineering evaluation was performed and concluded the diesel generator would meet its design function. Since the diesel generator was fully expected to meet its design function, there was no significant increase in risk during the time it was inoperable.

Additionally, if the diesel generator had started in this condition, the operator would have recognized the voltage was outside the operating band and adjusted it in band. Therefore, there would have been negligible effect on the equipment supplied due to the temporary high voltage condition. The contribution due to the failure mechanism of the diesel generator to fulfill its function (to run for its mission time) would be several orders of magnitude below the existing equipment failure probabilities. This is because operation of the diesel is directed by procedure, the operators are trained to the procedure, a Perry plant operator is dispatched to the diesel generator and monitors the operating limits, the control room operators walk down the panels periodically and verify parameters on operating equipment, and ample time would exist to identify an over-voltage condition while still maintaining a negligible effect on connected equipment.

IV. CORRECTIVE ACTIONS:

Immediate Actions Taken

The Division 1 diesel generator voltage was adjusted, per the SOI, during the shutdown following the failed surveillance test. Subsequent testing using monthly "Diesel Generator Start and Load" surveillance verified operability of the Division 1 diesel generator.

The system operating instructions were changed to provide additional direction, through an added precaution and limitation and note (in applicable sections), to ensure that Division 1, 2, and 3 diesel generators are not declared operable until their voltage settings are adjusted correctly during the shutdown steps of the SOI.

Preventive Actions

The following actions in aggregate represent the Preventative Actions for this condition report:

A lessons learned discussion of this event is to be conducted with plant operation section control room personnel.

The system operating instructions for Division 1, 2, and 3 Diesel Generators will be revised to provide guidance to recover a diesel generator from a tripped condition and to ensure that the diesel generator voltage is adjusted within limits prior to restoring the diesel generator to an operable status.

The system operating instructions for Division 1, 2, and 3 Diesel Generators will be revised to provide the correct sequence and specific steps to adjust the diesel generator speed to prevent a reverse power trip situation and verify grid voltage within acceptable band prior to paralleling evolutions. Other sections of the system operating instructions for the Division 1 and 2 Diesel Generator System and Division 3 Diesel Generator will be reviewed for similar corrections.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
Perry Nuclear Power Plant	05000440	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	5 OF 5
		2003	-- 003 --	00	

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

CORRECTIVE ACTIONS: (continued)

Remedial Actions

A lessons learned discussion of this event was conducted on October 9, 2003 with the diesel generator responsible system engineers and other plant engineering section engineers.

V. PREVIOUS SIMILAR EVENTS

A review of plant operating experience did not reveal any past events where diesel generator output voltage was left out of Technical Specification allowable band as a result of a reverse power trip.

A review of Perry's corrective action program from January 1, 2000 through September 9, 2003 revealed one condition report documenting a 2001 reverse power trip of the Division 1 diesel generator (condition report # 01-1099, Division 1 Diesel Generator Reverse Power Trip). This condition occurred during a post maintenance run used to vent the governor hydraulics after a new governor actuator was installed on the diesel generator. A corrective action for that event provided for the control room operators to review the investigation for sensitivity of governor control issues.

Additionally, it was identified that another reverse power trip of the Division 1 diesel generator occurred during testing in refueling outage 9 (RFO9). This occurrence was not logged in a condition report, but it was documented in the responsible system engineer's RFO9 logbook. This second reverse power trip also occurred during tuning and testing of the diesel generator governor when it was inoperable for maintenance.

DG operability was not an issue in either case since both trips occurred while the DG was inoperable for maintenance under conditions where DG voltage had been within the acceptable band prior to the trip.

A similar condition was documented in Perry Licensee Event Report (LER) 2001-005-01 (CR 01-4350). This documented that as a result of normal surveillance testing, the high pressure core spray (HPCS) diesel [DG] was found to have been improperly shutdown during the recovery from a Level 2 reactor protection system actuation and subsequent HPCS diesel start. The cause of this event was attributed to the operator over-adjusting the governor prior to opening the generator output breaker. The over-adjustment resulted in the diesel generator failing to meet Technical Specification 3.8.1 surveillance allowable value for rated speed and frequency start time. The system operating instruction for the Division 3 diesel generator was changed to include steps to verify the diesel generator speed prior to stopping the diesel.

VI. Component Failure

There were no structures, systems, or components that were inoperable at the start of this event and contributed to the event.

Energy Industry Identification System (EIIS) codes are identified in the text as [XX].