

South Texas Project Electric Generating Station P.O. Box 289 Wadsworth, Texas 77483

February 9, 2004 NOC-AE-04001677 10CFR50.73 10CFR50.72

U. S. Nuclear Regulatory Commission Attention: Document Control Desk One White Flint North 11555 Rockville Pike Rockville, MD 20852

> South Texas Project Unit 1 Docket Nos. STN 50-498 Licensee Event Report 1-03-006 Unanalyzed Condition That Significantly Degraded Plant Safety Regarding the Natural Circulation Cool Down Rate

Pursuant to 10CFR50.73, the South Texas Project submits the attached Unit 1 Licensee Event Report 1-03-006 regarding an unanalyzed condition that significantly degraded plant safety regarding the natural circulation cool down rate for Unit 1 and Unit 2. This event did not have an adverse effect on the health and safety of the public.

There are no commitments contained in this event report. Resulting corrective actions will be handled in accordance with STP Corrective Action Program.

If there are any questions on this submittal, please contact S. M. Head at (361) 972-7136 or me at (361) 972-7849.

E. D. Halpin Plant General Manager

KJT/

Attachment: LER 1-03-006 (South Texas, Unit 1)

F77

LER 1-03-006 (natural circulation cooldown).doc

STI: 31695780

NOC-AE-04001677 Page 2 of 2

cc: (paper copy)

Bruce S. Mallett Regional Administrator, Region IV U. S. Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 400 Arlington, Texas 76011-8064

U. S. Nuclear Regulatory Commission Attention: Document Control Desk One White Flint North 11555 Rockville Pike Rockville, MD 20852

Richard A. Ratliff Bureau of Radiation Control Texas Department of Health 1100 West 49th Street Austin, TX 78756-3189

Jeffrey Cruz U. S. Nuclear Regulatory Commission P. O. Box 289, Mail Code: MN116 Wadsworth, TX 77483

C. M. Canady City of Austin Electric Utility Department 721 Barton Springs Road Austin, TX 78704 (electronic copy)

A. H. Gutterman, Esquire Morgan, Lewis & Bockius LLP

L. D. Blaylock City Public Service

David H. Jaffe U. S. Nuclear Regulatory Commission

R. L. Balcom Texas Genco, LP

A. Ramirez City of Austin

C. A. Johnson AEP Texas Central Company

Jon C. Wood Matthews & Branscomb

						· .	(\sim, \circ)	80 20 11								
NRC ⁺ FORM 366 U.S. NUCLEAR REGULATORY (7-2001) COMMISSION						Y I. APPROVED BY OMB NO. 3150-0104 EXPIRES 7-31-2004 Estimated burden per response to comply with this mandatory information collection request: 50 hours.										
R •							Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records Management Branch (T-6 E6), U.S. Nuclear									
LICENSEE EVENT REPORT (LER) (See reverse for required number of digits/characters for each block) (See reverse for required number of digits/characters for each block)																
				· - ·			2 00			ity valid ONB Con	notional allo	2 0			sponsor, and a	
South Texa	s Unit 1						2.00		00	0 108		3. P	AGE	1 05	Λ	
4. TITLE							03000 498									
I Inanalyzed condition that significantly degraded plant safety regarding the natural circulation cool down rate																
5. EVENT DATE 6. LER NUMBER 7.							REPOR	T DATE	Γ	<u>ng ng ng ng</u>	OTHER I	FACIL	ITIES IN	VOLVED		
		[SEQUENTIAL	DEV			1	FA	FACILITY NAME		DOCKET NUMBER				
MONTH	DAY	YEAR	R YEAR NUMBER		NO	MO	DAY	YEAR	South Texas Unit 2				05000	499		
12	09	2003	20	03 - 06 -	00	02	09	9 2004		FACILITY NAME			DOCKET NUMBER			
			11.	THIS REPORT IS	SUBMI		RSUAN			UIREMENTS OF	10 CFR '	05000				
9. OPERATING	G MODE	1	H	20 2201/b)		20.220	3(a)(3))/ii)	× 50 73/9//2//ii)		(B)		50,73(a)(2)(ix)(A)			
		100		20.2201(d)		20.220	03(a)(4)		Ĺ.	50.73(a)(2)(i	i)		50.73(a)(2)(x)		
10. POWER LI	EVEL	100		20.2203(a)(1)		50.360	D(1)(i)(A)		50.73(a)(2)(i	v)(A)	Ē	73.71(a)(4)			
			\square	20.2203(a)(2)(i)		50.360	©(1)(ii)	(A)	<u> </u>	50.73(a)(2)(v	/)(A)	 ·	73.71(a)(5)			
			Ц	20.2203(a)(2)(ii)		50.360	D(2)			50.73(a)(2)(v)(B)			OTHEF	t Part	21	
			┝─┤	20.2203(a)(2)(iii)	50.46	a)(3)(ii)		50.73(a)(2)(v	<u>/)(C)</u>		Specify in Abstract below or in			
			\vdash	20.2203(a)(2)(IV 20.2203(a)(2)(IV	<u>/ </u> -	50.73	a)(2)(1)	<u>)(A)</u>		50.73(a)(2)(\	<u>/)(U)</u>	12.00	INC Form 366A			
			\vdash	20.2203(a)(2)(vi	$\frac{20.2203(a)(2)(v)}{20.2203(a)(2)(v)} = \frac{50.73(a)(2)(i)(B)}{50.73(a)(2)(i)(C)}$				<u>50.73(a)(2)(viii)(A)</u>							
20.2203(a)(3)(i) 50.73(a)(2)(ii)(A) 50.73(a)(2)(viii)(B)																
		_		1:	2. LICE	NSEE	CONT	ACT FOR T	HIS	SLER						
NAME									TE	ELEPHONE NUM	IBER (Incl	ude A	rea Code	e)		
Ken Taplett 361-972-8416																
[<u></u> .	<u>13. CO</u>								DESCRIBEL		KEF				
CAUSE	CAUSE SYSTEM COL					PORTABI	E CAUSE		SYSTEM C		СОМРО	NENT	MANU	FACTURER	REPORTABLE TO EPIX	
14. SUPPLEMENTAL REPORT EXPECTED					ED			-1	15. EXPECTED			IONTH	DAY	YEAR		
YES (If yes, complete EXP			ECTED SUBMISSION DATE)			 E)	X	NO	SUBMISSION DATE		SION E					
16. ABSTRAC	T (Limit to	1400 sp	aces,	, i.e., approximat	ely 15	single-s	paced	typewritten	line	 es)			_	•		
	hor 0 2	002 11	loit ·	1 and Linit 2			otina	of 1000	/		ing the	0.01	forme	nnon of	o firo	
hazards re	actor co	olant s	uni. svsti	em (RCS) c	noi d	own a	nalve	sis itwa	e c o h	liscovered	that th	e ci hei	irrent	nroced		
down rate	of 50°F/	br doe	s nr	nt satisfy the	desi	ian ha	isis re	equirem	o c >nt	is when les	s than	4 s	team	neneral	ors are	
available d	urina na	atural c	ircu	lation cool c	lown	condi	tions	. This c	on	dition place	ed both	י ער ו	it 1 a	nd Unit	2 in an	
unanalyzed	d condit	ion tha	t sic	nificantly de	egrac	led pla	ant s	afety.	- · ·							
-				-	0	•		•								
The root ca	auses of	f this e	ven	t were the fa	ilure	of the	e We	stinghou	se	Owner's C	Group t	o fu	lly ad	dress R	CS loop	
stagnation	conditio	ons for	nati	ural circulati	on co	ool do	wn a	nd the fa	ailu	ire to re-an	alyze f	he r	natura	al circula	ation cool	
down cases when a change was made to increase the cool down rate to 50°F/hr.																
Corrective actions were taken to limit the natural circulation cool down rate and to complete long-term cooling																
analyses to validate the revised rate.																
I his event resulted in no personnel injuries, no offsite radiological releases, and no damage to safety-related																
equipment. There were no challenges to plant salety.																
NRC FORM	366 (7-:	2001)														
	- (.								_		<u> </u>					

;

NRC FORM (1-2001)	366A U.S. NUCLEAR REGULATORY COMM	ISSION		<u></u>			****	· · · · ·			
LIUEI	NSEE EVENT REPORT (LER)										
	1. FACILITY NAME	2. DOCKET	E	5. LER NUMBER			3. PAGE	3. PAGE			
South Te:	xas Unit 1	05000 498	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2	OF	4			
			2003	06	00						
NARRATIVE	(If more space is required, use additional copies	s of NRC Form 366.	A) (17)								
I. DESC	RIPTION OF EVENT										
A.	REPORTABLE EVENT CLASSIF	FICATION									
	This event is reportable pursuant in the nuclear power plant being safety.	t to 10CFR50.3 in an unanalyz	73(a)(2)(ii) zed condit)(B), any eve ion that signi	nt or con ificantly d	dition legrad	that res ed plan	sulted 1t			
В.	PLANT OPERATING CONDITIONS PRIOR TO EVENT										
	STP Unit 1 and Unit 2 were in Mode 1 operating at 100% power.										
C.	STATUS OF STRUCTURES, SYS THE START OF THE EVENT AN	STEMS OR CO	omponei Tributei	NTS THAT V D TO THE E	VERE INC VENT	OPER	ABLE A	AT .			
	All structures, systems and compo event.	onents were de	etermined	to be OPER	ABLE at	the sta	art of th	10			
D.	NARRATIVE SUMMARY OF THE	EVENT, INCI	LUDING E	ATES AND	APPROX	(IMAT	E TIME	ES			
	During the performance of a fire h discovered that the current proceed requirements when less than 4 ste conditions. The analysis demons residual heat removal (RHR) syst to steam. Therefore, controlled c	azards reactor dural cool dow eam generator trated that the em cut-in temp cool down could	r coolant s n rate of 5 rs are avai active RC perature o d not be p	ystem (RCS i0°F/hr does ilable during S loop coulc f 350°F; but erformed.) cool do not satisf natural c l be coole the inacti	wn an fy the irculati ed dow ve looj	alysis, i design ion coo vn to th p would	it was basis Il down e d flash			
	STP was originally designed as a number of steam generator tubes through the core increased. In or reactor vessel lower internal flang The increase in bypass flow to the	reactor vesse when the stea der to reduce to ge were modifie e upper head o	I head (RN am genera the fuel up ed to allow classified \$	/H) T _{HOT} plar Itors were rep Itift forces, th It for more flo STP as a T _{cc}	nt. With t placed, th le flow by lw to the l pLD plant.	he inc te net pass r upper	rease ii RCS file nozzles head a	n the ow in the irea.			
	Westinghouse performed an evaluand determined the change to be for other T_{COLD} plants. The change the cool down rate from 25°F/hr to Emergency Operating Procedure	uation for char acceptable ba je of the reacto o 50°F/hr for n Background d	nging the c ised on W or vessel h atural circ locuments	cool down rat estinghouse lead from T _H ulation cool (te from 29 Owner's or to T _{COI} Jown in a	5°F/hr Group LD allov	to 50°F o guidel wed cha ance wi	^{-/hr} lines anging ith			
	While performing a natural circula could not achieve cool down with rate.	ition cool dowr only two avail:	ı analysis able stean	at STP, it wa n generators	us discove with a 50	ered th)°F/hr	nat the cool dc	plant own			

Water in the tube side of the two steam generators that were not receiving auxiliary feedwater (AFW) would stagnate with hot water and flash to steam during the depressurization process. This would result in filling the pressurizer and causing a loss of RCS pressure control. Cool down and

LICENSEE EVENT REPORT (LEF	र)										
1. FACILITY NAME	2. DOCKET	(5. LER NUMBER	3. PAGE							
South Texas Unit 1	05000 498	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3	OF	4				
NADDATIVE /// mom opposis proving two officiants		2003	06	00							
depressurization of the RCS in assumed in the current analyse storage tank inventory prior to to plant design requirements.	this configuration es. A long cool d reaching the resi	n would ta own time dual heat	ke substanti could result removal (RF	ially longer in depletio IR) cut-in c	r than n of t condil	that he AFV lions co	V ontrary				
Although there is adequate con existing design basis and not s The evaluation affects safe shu AFW flow to one or more stear	re cooling, the pla specifically addres utdown for fire an m generators.	ant would I ssed by th Id long terr	be in a cond e Emergenc m cooling ar	ition that is by Operatir nalyses tha	s outs ng Pro nt resu	ide the ocedure ult in los	es. ss of				
Following discovery of the even reduced. Long-term cooling an successfully meet the function	Following discovery of the event, the natural circulation cool down rate was conservatively reduced. Long-term cooling analyses are being performed to validate the cool down rate to successfully meet the functional objective of bringing the plant to cold shutdown conditions.										
This event was discovered at 1 Regulatory Commission at 173	This event was discovered at 1538 on December 9, 2003. Notification was made to the Nuclear Regulatory Commission at 1732 on December 9, 2003.										
E. METHOD OF DISCOVERY OF ERROR	F EACH COMPO	ONENT, S	YSTEM FA	ILURE, O	r pr	OCED	URAL				
This condition was identified (RCS) cool down analysis.	during the perfo	rmance of	a fire haza	ards reacto	or co	olant s	ystem				
II. EVENT DRIVEN INFORMATION							•				
A. SAFETY SYSTEMS THAT RE	SPONDED										
Not Applicable.											
B. DURATION OF SAFETY SYS	TEM INOPERAB	ILITY									
Not Applicable.											
C. SAFETY CONSEQUENCES A	ND IMPLICATIO	NS OF TH	IE EVENT								
This event did not result in per releases nor damage to import acceptable with forced circula the plant down with less than a condition that could have pr ability of the AFW storage tan conditions.	rsonnel injuries, r rtant safety relate tion in all the stea 100% steam gen evented fulfillmer k to provide suffic	adiation e d equipme am genera erator ava nt of a safe cient inver	xposure, on ent. The high itors. South ilability. Ho ety function. itory to cool	site or offs her cool do Texas has wever, this The safet the RCS d	ite rae own ra not h s ever y fund lown f	diologic ate is ad to c nt resul ction is to RHR	cal cool ted in the t cut-ir				
There is no impact or change acceptable for the plant condi	in core damage f tions at the time (frequency (i.e., all fou	since the higur steam ger	gher cool o nerators w	down ere av	rate wa vailable	as e for				

cool down).

•

.

NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION (1-2001)

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	e	6. LER NUMBER	3. PAGE			
South Texas Unit 1	05000 498	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	4	OF	4
		2003	06	00			

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

III. CAUSE OF THE EVENT

- 1. Failure of the Westinghouse Owner's Group (WOG) to identify all limiting scenarios in the WOG Guidelines for Natural Circulation Cool down. Specifically, the WOG Guidelines addressed upper head cooling and did not fully address loop stagnation.
- 2. Failure to re-analyze the natural circulation cool down cases when a change was made increase the cool down rate to 50°F/hr.

IV. CORRECTIVE ACTIONS

- A. Administrative requirements were put in place to limit the natural circulation cool down rate.
- B. Complete long-term cooling analyses to validate and change the natural circulation cool down rate.
- C. Prepare a design change package to revise the EOP Set Point Document to change the natural circulation cool down rate.
- D. Revise plant operations procedures that require the operators to use a plant cool down rate.

V. PREVIOUS SIMILAR EVENTS

- A. The Westinghouse methodology that was used to determine the worth of the highest worth stuck rod in the STP analysis could result in a non-conservative shutdown boron concentration.
- B. The Westinghouse methodology for the STP loss of normal feedwater/loss of offsite power analysis did not include the zero per cent steam generator tube plugging case that resulted in filling of the pressurizer.

VI. ADDITIONAL INFORMATION

The inability to cool down during natural circulation with less than all Steam Generators available could impact other plants that have used the WOG Guidelines. Westinghouse is currently investigating the need to notify specific plants of the natural circulation cool down unanalyzed condition. [Reference: CAPs-ACA-03-351-M007, Rev. 0, Inactive Loop Flow Stagnation During Natural Circulation Cooldown (Westinghouse internal document)] In addition, STP is developing a direct work request for the WOG to address the ability of plants to cool down to RHR cut-in conditions with a dry steam generator.