



South Texas Project Electric Generating Station P.O. Box 289 Wadsworth, Texas 77483

March 4, 2004
NOC-AE-04001684
10CFR50.73

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
One White Flint North
11555 Rockville Pike
Rockville, MD 20852

South Texas Project
Unit 2
Docket No. STN 50-499
Errata Sheet

The South Texas Project submits the attached erratum for the Licensee Event Report addressing the recent Standby Diesel Generator 22 failure. The Licensee Event Report was misidentified as 2-03-004, and should have been 2-03-003. Attached is a corrected version of the Licensee Event Report. There are no other changes.

Note that the attached Licensee Event Report has been re-signed under the date of the original and is provided as a replacement for Licensee Event Report 02-03-004. Please destroy the first submittal.

If there are any questions, please contact me at (361) 972-7136.

A handwritten signature in black ink, appearing to read "Scott M. Head".

Scott M. Head
Manager, Licensing

PLW

STI: 31699392

IE22

cc:

(paper copy)

Bruce S. Mallett
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 400
Arlington, Texas 76011-8064

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
One White Flint North
11555 Rockville Pike
Rockville, MD 20852

Richard A. Ratliff
Bureau of Radiation Control
Texas Department of Health
1100 West 49th Street
Austin, TX 78756-3189

Jeffrey Cruz
U. S. Nuclear Regulatory Commission
P. O. Box 289, Mail Code: MN116
Wadsworth, TX 77483

C. M. Canady
City of Austin
Electric Utility Department
721 Barton Springs Road
Austin, TX 78704

(electronic copy)

A. H. Gutterman, Esquire
Morgan, Lewis & Bockius LLP

L. D. Blaylock
City Public Service

David H. Jaffe
U. S. Nuclear Regulatory Commission

R. L. Balcom
Texas Genco, LP

A. Ramirez
City of Austin

C. A. Johnson
AEP Texas Central Company

Jon C. Wood
Matthews & Branscomb



South Texas Project Electric Generating Station P.O. Box 289 Wadsworth, Texas 77483

February 5, 2004
NOC-AE-04001674
10CFR50.73

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
One White Flint North
11555 Rockville Pike
Rockville, MD 20852

South Texas Project
Unit 2
Docket No. STN 50-499
Licensee Event Report 2-03-003
Standby Diesel Generator 22 Failure

Pursuant to 10CFR50.73, the South Texas Project submits the attached Unit 2 Licensee Event Report 2-03-003 regarding the failure of Standby Diesel Generator 22. This event did not have an adverse effect on the health and safety of the public.

Commitments are listed in the Corrective Actions section of the attached report.

If there are any questions on this submittal, please contact either P. L. Walker at (361) 972-8392 or me at (361) 972-7849.

A handwritten signature in black ink, appearing to read "E. D. Halpin".

E. D. Halpin
Plant General Manager

PLW
Attachment: LER 2-03-003

cc:

(paper copy)

Bruce S. Mallett
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 400
Arlington, Texas 76011-8064

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
One White Flint North
11555 Rockville Pike
Rockville, MD 20852

Richard A. Ratliff
Bureau of Radiation Control
Texas Department of Health
1100 West 49th Street
Austin, TX 78756-3189

Jeffrey Cruz
U. S. Nuclear Regulatory Commission
P. O. Box 289, Mail Code: MN116
Wadsworth, TX 77483

C. M. Canady
City of Austin
Electric Utility Department
721 Barton Springs Road
Austin, TX 78704

(electronic copy)

A. H. Gutterman, Esquire
Morgan, Lewis & Bockius LLP

L. D. Blaylock
City Public Service

David H. Jaffe
U. S. Nuclear Regulatory Commission

R. L. Balcom
Texas Genco, LP

A. Ramirez
City of Austin

C. A. Johnson
AEP Texas Central Company

Jon C. Wood
Matthews & Branscomb

LICENSEE EVENT REPORT (LER)

(See reverse for required number of
digits/characters for each block)

Estimated burden per response to comply with this mandatory information collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records Management Branch (T-6 E6), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to bjs1@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose information collection does not display a currently valid OMB control number, the NRC may not

1. FACILITY NAME South Texas Unit 2				2. DOCKET NUMBER 05000 499				3. PAGE 1 OF 7			
4. TITLE Standby Diesel Generator 22 Failure											
5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO	MO	DAY	YEAR	FACILITY NAME	DOCKET NUMBER	
12	09	2003	2003	03	00	2	05	2004	FACILITY NAME	DOCKET NUMBER	
									05000		
									05000		
9. OPERATING MODE		1		11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR : (Check all that apply)							
10. POWER LEVEL		100		20.2201(b)		20.2203(a)(3)(ii)		50.73(a)(2)(ii)(B)		50.73(a)(2)(ix)(A)	
				20.2201(d)		20.2203(a)(4)		50.73(a)(2)(iii)		50.73(a)(2)(x)	
				20.2203(a)(1)		50.36(c)(1)(i)(A)		50.73(a)(2)(iv)(A)		73.71(a)(4)	
				20.2203(a)(2)(i)		50.36(c)(1)(ii)(A)		50.73(a)(2)(v)(A)		73.71(a)(5)	
				20.2203(a)(2)(ii)		50.36(c)(2)		50.73(a)(2)(v)(B)		X OTHER - 10 CFR 21	
				20.2203(a)(2)(iii)		50.46(a)(3)(ii)		50.73(a)(2)(v)(C)		Specify in Abstract below or in NRC Form 366A	
				20.2203(a)(2)(iv)		50.73(a)(2)(i)(A)		50.73(a)(2)(v)(D)			
				20.2203(a)(2)(v)		X 50.73(a)(2)(i)(B)		50.73(a)(2)(vii)			
20.2203(a)(2)(vi)		50.73(a)(2)(i)(C)		50.73(a)(2)(viii)(A)							
20.2203(a)(3)(i)		50.73(a)(2)(ii)(A)		50.73(a)(2)(viii)(B)							
12. LICENSEE CONTACT FOR THIS LER											
NAME P. L. Walker						TELEPHONE NUMBER (Include Area Code) 361-972-8392					
13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT											
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX		
B	EK	ENG	C634	Y							
14. SUPPLEMENTAL REPORT EXPECTED								15. EXPECTED SUBMISSION DATE		MONTH	DAY
YES (If yes, complete EXPECTED SUBMISSION DATE)								X NO			
16. ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)											
<p>On Tuesday, December 9, 2003, a monthly surveillance test was being performed on Standby Diesel Generator 22. Unit 2 was operating in Mode 1 at 100% power. At approximately 1038, Standby Diesel Generator 22 experienced a mechanical failure in which the position 9 Master Connecting Rod fractured. This occurred approximately 18 minutes after the diesel generator was loaded to 100% during the surveillance. The failure caused significant peripheral damage to the cylinders, pistons, frame, control systems, lubrication system, crankshaft, and bearings on the engine, as well as the starting air system components located adjacent to the engine.</p> <p>The root cause of the failure is microcracks that developed on the position 9 Master Connecting Rod during the manufacturing process. The microcracks later propagated due to high cycle fatigue until the master connecting rod failed.</p> <p>Corrective actions include inspection of the master connecting rods of all Standby Diesel Generators to ensure that similar cracking had not occurred elsewhere.</p> <p>This event resulted in no personnel injuries, no offsite radiological releases, and no damage to other safety-related equipment. Unit 2 continued to operate at 100% power after the event.</p>											
NRC FORM 366 (7-2001)											

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
South Texas Unit 2	05000 499	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 OF 7
		2003	03	00	

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

I. DESCRIPTION OF EVENT

A. REPORTABLE EVENT CLASSIFICATION

This event is reportable pursuant to 10CFR50.73(a)(2)(i)(B). The South Texas Project has determined, based on metallurgical analysis of the failed parts, that Standby Diesel Generator 22 was inoperable for an undetermined period of time and could not have satisfied Technical Specification requirements for operability in the times specified under Technical Specification 3.8.1.1, Action b.

B. PLANT OPERATING CONDITIONS PRIOR TO EVENT

South Texas Project Unit 2 was in Mode 1 operating at 100% power.

C. STATUS OF STRUCTURES, SYSTEMS, AND COMPONENTS THAT WERE INOPERABLE AT THE START OF THE EVENT AND THAT CONTRIBUTED TO THE EVENT

Standby Diesel Generator 22 was the only component affected by this event.

D. NARRATIVE SUMMARY OF THE EVENT, INCLUDING DATES AND APPROXIMATE TIMES

On December 9, 2003, an operability test of Standby Diesel Generator 22 was performed in accordance with surveillance procedures. Standby Diesel Generator 22 was started at 0942 and initially loaded at 0947. The generator load was increased to 25% at 0950, 50% at 1000, 75% at 1010, and 100% at 1020. At 1038, the 9R master connecting rod and associated parts failed. The engine continued to run until the fuel racks were manually closed approximately six minutes later.

At the time of the engine failure, the Plant Operator monitoring the diesel locally was taking the first set of diesel logs as directed by the surveillance procedure. The Plant Operator was standing at the northwest corner of the engine recording the crankcase differential pressure reading when a loud noise came from the engine. The local Plant Operator immediately left the diesel engine area and returned to the local control panel area where multiple alarms were indicated. At the same time that the noise occurred, the Main Control Room received a diesel trouble alarm. The licensed operator in the Main Control Room observed indication of no electrical load and no engine oil pressure for Standby Diesel Generator 22. The Main Control Room Operator put the diesel control switch in "Pull-To-Stop," but the engine continued to run.

The local Plant Operator notified the Main Control Room of the alarms, that no oil or jacket water pressure was indicated, and that the diesel was still running at approximately 600 rpm. The local Plant Operator was instructed by the Main Control Room to locally push the two emergency stop buttons. The buttons were pushed immediately, but the diesel engine continued to run. A second licensed Operator left the Main Control Room and went to the Standby Diesel Generator 22 bay to aid in tripping the diesel engine locally. The local Plant Operator and he both tried the emergency stop push buttons, again with no response, and then went to the remote trip location for the air intake butterfly valve. The licensed Operator was unable to trip the air intake butterfly valve at the overspeed governor. Seeing some of the engine damage and significant amounts of smoke-like oil fumes in the area, the licensed Operator directed the local Plant Operator to leave the area for safety reasons. The local Plant Operator then went to the fuel oil storage tank room and closed the fuel isolation valve to the engine. The licensed Operator returned to the butterfly remote trip to try again to isolate it. At

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
South Texas Unit 2	05000 499	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3 OF 7
		2003	03	00	

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

about the same time, a second licensed Operator and several other Plant Operators entered the diesel area. The second licensed Operator concurred with the arriving Plant Operators that the fuel racks needed to be closed. The engine was stopped at approximately 1044 by manually closing the fuel racks. The air intake butterfly valve was then successfully closed at the valve.

At about the same time the engine was stopped, the second licensed Operator recommended to the Shift Supervisor in the Main Control Room that the fire brigade be called out. The Fire Brigade was dispatched at 1044 under the procedure for Fire/Explosion. When the fire brigade arrived at Standby Diesel Generator 22, no smoke or flames were found, but there was a significant amount of fuel/lubrication oil fumes in the air and oil on the floor which could have posed a fire hazard. At 1048, the Fire Brigade confirmed that no flames were present. After a short period with maximum ventilation, the Fire Brigade Leader notified the Main Control Room that there was no fire. The Fire/Explosion procedure was exited at 1112.

See Attachment 1 for a diagram showing the master and articulated rods.

Damage Assessment and Investigation

Following the incident, the Standby Diesel Generator 22 room was cordoned off and access was controlled to protect the integrity of fractured surfaces for future metallurgical analysis. Pictures were taken of the damaged diesel and the ejected components on the floor prior to anything being moved or touched. All Operations personnel on duty and involved in the incident were interviewed and data collected before the end of shift.

Initial examination of the engine revealed destruction of the 9-Right (9R) and 9-Left (9L) cylinders and corresponding moving parts. Portions of the engine center frame with several major components were ejected out of the right (east) side of the engine. The ejected parts included:

- The 9L articulated rod,
- The 9R piston,
- A piece of the end of the position 9 master rod that attaches to the articulated rod and crankshaft,
- A crankshaft counterweight,
- A center frame inspection door, and
- Pieces of the center frame itself.

The 9L piston crown was lodged in its cylinder. The major part of the position 9 master rod and other parts and debris were found in the crankcase.

Shutdown air is needed to trip the diesel engine from the Main Control Room switch and from the local emergency stop pushbuttons. However, ejected parts severely damaged the diesel control air and shutdown air lines, which is why the trip attempts from those two stations were unsuccessful. When the Operators attempted to trip the air intake butterfly valve at the overspeed governor, the plunger could not be pulled out. The reason why the butterfly valve could not be tripped will be addressed as part of replacing the damaged turbocharger.

The crack initiated on the master connecting rod in the area (ligament) between the crankshaft

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
South Texas Unit 2	05000 499	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	4 OF 7
		2003	03	00	

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

bearing bore and the articulating rod bushing bore. The crack propagated through the section thickness (approximately 1") and then propagated across the width of the bore. One side of the fracture essentially extended across the width of the fracture face with only a small corner section showing overload. The other side of the fracture extended approximately 3.5" angled toward the articulating rod bushing surface, followed by failure due to overload.

Visible "beach marks", which indicate that a crack was propagated by cyclic stresses, were found on a fracture surface on the position 9 master rod at the common ligament area between the master rod crankshaft bearing bore and the articulated rod pin bore. The articulated rod, a piece of the master rod, and several other damaged pieces were sent to a metallurgical lab for analysis. Lab results confirmed that there was a high cycle fatigue crack on the master connecting rod.

Inertial loads as the master rod piston approaches top dead center on the exhaust stroke cause the peak tensile stress in the vicinity of the fracture. Fatigue cracking is propagated by tensile stresses. Since the firing stroke imposes compressive stresses, it does not cause fatigue cracking. Because of this, the stress in the region of the fracture is independent of engine load and crack propagation is related only to the number of master rod piston exhaust strokes.

Summary of Root Cause

The root cause of the diesel engine failure was microcracks created on the position 9 master connecting rod during the manufacturing process. The microcracks propagated due to high cycle fatigue until the master connecting rod failed.

The crack began in a region of microcracks at the surface of the master rod bearing bore. The crack initiation area was at the bottom of a small indentation made after the master rod failure (the area was struck during the failure). The indentation was a smooth, high energy impact zone with directional lines, and partially overlapped the fracture surface. The surface features in the bottom of the indentation and next to the indentation at the fracture surface were examined and the indentation was found to not be the stress riser that initiated the crack. The surface features in both areas are comparable. Both areas exhibit surface microcracking. The microcracking orientation is parallel to the failure fracture surface.

Based on the Scanning Electron Microscope inspection of the high cycle fatigue crack initiation site and based on inspection of the upper connecting rod bearing shell, there is no evidence of foreign material entrapped between the bearing shell and the connecting rod crankshaft bearing bore. There is also no evidence of fretting fatigue, large inclusions, or foreign material at the crack initiation site. The crack actually initiated from two sites. The two crack fronts grew together over a short distance, indicating they were very close in proximity and very similar in initiation time (simultaneous).

The ligament sees alternating stresses and these stresses allowed the microcracks to slowly propagate through the master rod until critical crack size was reached. The surface features and microcracking are consistent with damage produced during manufacture (such as from tool chatter) followed by the honing that is normally done as part of the manufacturing process. The force required to produce the microcracks would only be seen during machining operations.

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE		
South Texas Unit 2	05000 499	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	5	OF	7
		2003	03	00			

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

No human performance issues were noted with respect to this event.

E. METHOD OF DISCOVERY OF EACH COMPONENT FAILURE, SYSTEM FAILURE, OR PROCEDURAL ERROR

This condition was identified during a routine surveillance test of Standby Diesel Generator 22.

II. EVENT-DRIVEN INFORMATION

A. SAFETY SYSTEMS THAT RESPONDED

The failure of Standby Diesel Generator 22 caused no other safety systems to start or change state.

B. DURATION OF SAFETY SYSTEM INOPERABILITY

Technical Specification action 3.8.1.1.b requires that an inoperable standby diesel generator be returned to operable status within 14 days or be in at least hot shutdown within the next 12 hours and in cold shutdown within the following 24 hours. Considering the extent of damage done to Standby Diesel Generator 22 and supporting equipment, the South Texas Project anticipated that shutdown of Unit 2 would be required under the Technical Specifications as written. Consequently, an emergency Technical Specification change was proposed to the NRC to increase the allowed outage time to 113 days, allowing Unit 2 to continue operation until the next scheduled refueling outage while Standby Diesel Generator 22 is repaired. The request used both deterministic and probabilistic arguments in support of this one-time change. NRC approval of the increase in allowed outage time was given on December 30, 2003.

C. SAFETY CONSEQUENCES AND IMPLICATIONS OF THE EVENT

The Onsite Standby Power Supply Systems of Units 1 and 2 each consist of three independent, physically separated, standby diesel generators supplying power to three associated load groups designated Train A, Train B, and Train C. Each load group consists of a 4.16 kV ESF bus and the electrical loads connected to that bus. The Onsite Standby Power Supply Systems of Units 1 and 2 operate independently of each other. Each standby diesel generator and load group of a particular unit is also physically separated and electrically independent from the other two standby diesel generators and their load groups. Each train (i.e., Load Group) is independent but is not totally redundant; two trains are necessary to mitigate the consequences of a design basis accident.

The South Texas Project has no indications that potential for a common-mode failure may be present.

The deterministic component of the basis for the extended allowed outage time provides assurance that the plant retains a substantial capability to mitigate design basis events with the reduced capability resulting from the inoperable diesel. Design margin is sufficient when:

- Postulating a design basis accident and a single failure while the plant is in the extended allowed outage time, or
- Postulating an accident (with no single failure) in the 24 hours allowed by Technical Specifications for inoperability of required equipment in one of the other trains.

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
South Texas Unit 2	05000 499	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	6 OF 7
		2003	03	00	

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

This evaluation shows that a single operable ESF train can mitigate (at a reduced capacity in certain cases) the design basis accidents except for a large break LOCA where the break is located in the RCS loop associated with the operating train of safety injection.

The current average core damage frequency for the South Texas Project is 9.08E-06/year and the current large early release frequency is 5.18E-07/year.

RG 1.174 requires that the total core damage frequency and large early release frequency be less than 1E-04/year and 1E-05/year, respectively. The values associated with the diesel outage time extension are well within the criteria established in RG 1.174.

Reactor power was reduced while waiting for NRC approval to extend the allowed outage time for Standby Diesel Generator 22. Power output was reduced to approximately 33% before approval was received.

III. CAUSE OF THE EVENT

The root cause of the diesel engine failure was microcracks created on the position 9 master connecting rod during the manufacturing process. The microcracks propagated due to high cycle fatigue until the master connecting rod failed.

IV. CORRECTIVE ACTIONS

1. Repair Standby Diesel Generator 22 and associated damaged equipment.
2. Phased array ultrasonic testing of all standby diesel generator master connecting rods in Unit 1 and Unit 2 has been completed. Similar areas of cracking have not been found.

V. PREVIOUS SIMILAR EVENTS

Failures of Cooper Bessemer KSV diesel engine connecting rods have occurred at other nuclear facilities, as well as at the South Texas Project. However, no other failures have occurred for the same reason as this event. There have also been instances of connecting rod failures in non-nuclear applications and in non-KSV engines, but none had the same cause as the recent South Texas Project diesel failure.

VI. ADDITIONAL INFORMATION

Visual examination of the bearing bores of the ten master connecting rods from Standby Diesel Generator 22 identified some areas of surface disturbance on the bore surfaces. These were generally small areas, 1/8" to 5/16" across, with a roughened appearance. Fluorescent magnetic particle technique (MT) examination of these features in mid-January, 2004, found small crack-like linear indications within the boundaries of a subset of these features.


Metallurgical and metallographic evidence shows that the small anomalies seen in the nine non-ejected connecting rods from SDG 22 are consequences of the incident. They do not represent conditions present in the connecting rods prior to the fracture of master connecting rod #9. Accordingly, there is no reason to suspect that similar features are present in the connecting rods in the other Cooper-Bessemer KSV-20 standby diesels at STP.

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
South Texas Unit 2	05000 499	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	7 OF 7
		2003	03	00	

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

Attachment 1 Diagram of Connecting Rods



Site of crack initiation (on the master rod under the bearing shell)

- | | |
|-------------------|---|
| 1. Piston Pin | 13. Bearing Shell, Top |
| 2. Oil Passage | 14. Dowel (2) |
| 3. Dowel (3) | 15. Rod Cap |
| 4. Washer (4) | 16. Locknut (4) |
| 5. Bolt Lock (4) | 17. Stud (4) |
| 6. Pin Bolt (4) | 18. Bearing Shell Bottom |
| 7. Drake Nut (4) | 19. Art. Rod Pin |
| 8. Bolt Lock (2) | 20. Rod Pin Bolt |
| 9. Washer (2) | 21. Bearing Cap (Nut Tightening Sequence) |
| 10. Oil Passage | 22. Washer |
| 11. Bushing | |
| 12. Dowel Pin (4) | |