



MAR 24 2003

L-2003-062  
10 CFR 50.36

Luis A. Reyes  
Regional Administrator  
U. S. Nuclear Regulatory Commission  
Atlanta Federal Center  
61 Forsyth Street, S. W., Suite 23T85  
Atlanta, GA 30303

Dear Mr. Reyes:

Re: Turkey Point Unit 3  
Docket No. 50-250  
Steam Generator Tube Plugging 15-Day Report

In accordance with Turkey Point Technical Specification 4.4.5.5.a, the subject Special Report is submitted pursuant to Technical Specification 6.9.2 for Turkey Point Unit 3, as a result of the End of Cycle 19 inservice inspection of steam generator tubes.

The Turkey Point Unit 3 steam generators were inspected from March 9, 2003, through March 13, 2003. A total of 3 tubes were plugged as a result of this examination. One tube was preventively plugged in steam generator 3A, based on a manufacturing indication that was determined to be present on the preservice inspection. Two tubes were plugged in steam generator 3B. One tube in steam generator 3B was preventively plugged due to mechanical wear at an anti-vibration bar in the u-bend region. The second tube would not permit inspection by Plus Point technique in the u-bend region due to a restriction, and was preventively plugged. There were no tubes plugged in steam generator 3C.

TUBES PLUGGED THIS OUTAGE


SG 3A  
1

SG 3B  
2

SG 3C  
0

Should there be any questions, please contact Walter Parker at 305-246-6632.

Very truly yours,

  
William Jefferson, Jr.  
Vice President  
Turkey Point Plant

OIH

cc: USNRC, Document Control Desk, Washington, D.C.  
Senior Resident Inspector, USNRC, Turkey Point Plant