

South Texas Project Electric Generating Station P.O. Box 289 Wadsworth, Texas 77483

May 17, 2004 NOC-AE-04001724 STI: 31743778 10CFR50.73

U. S. Nuclear Regulatory Commission Attention: Document Control Desk One White Flint North 11555 Rockville Pike Rockville, MD 20852

South Texas Project Units 1 & 2 Docket Nos. STN 50-498, STN 50-499 Licensee Event Report LER 1-04-002 Inoperable Control Room Makeup and Cleanup Filtration Systems

Pursuant to 10CFR50.73, the South Texas Project submits the attached Licensee Event Report 1-04-002 regarding failure to complete a Limiting Condition for Operation (LCO). This event did not have an adverse effect on the health and safety of the public.

On March 17, 2004, with Units 1 and 2 operating in Mode 1, the South Texas Project declared all three trains of Control Room Makeup and Cleanup Filtration Systems (CRMCFS) inoperable in both units. The basis for this conclusion was the fact that the CRMCFS did not maintain the Control Room Envelope (CRE) at sufficient positive pressure relative to adjacent areas during tests performed in March 2003 for Unit 2 and early March 2004 for Unit 1, as required by a surveillance requirement. This event is reportable as a condition prohibited by the Technical Specifications.

There are no commitments contained in this event report. Resulting corrective actions will be handled in accordance with the South Texas Project Corrective Action Program.

If there are any questions on this submittal, please contact S. M. Head at (361) 972-7136 or me at (361) 972-7849.

5.0h

E. D. Halpin Plant General Manager

jal/

Attachment: LER 1-04-002



NOC-AE-04001724 Page 2 of 3

cc: (paper copy)

Bruce S. Mallett Regional Administrator, Region IV U. S. Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 400 Arlington, Texas 76011-8064

U. S. Nuclear Regulatory Commission Attention: Document Control Desk One White Flint North 11555 Rockville Pike Rockville, MD 20852

Richard A. Ratliff Bureau of Radiation Control Texas Department of Health 1100 West 49th Street Austin, TX 78756-3189

Jeffrey Cruz U. S. Nuclear Regulatory Commission P. O. Box 289, Mail Code: MN116 Wadsworth, TX 77483

C. M. Canady City of Austin Electric Utility Department 721 Barton Springs Road Austin, TX 78704 (electronic copy)

A. H. Gutterman, Esquire Morgan, Lewis & Bockius LLP

L. D. Blaylock City Public Service

Michael K. Webb U. S. Nuclear Regulatory Commission

R. L. Balcom Texas Genco, LP

A. Ramirez City of Austin

C. A. Johnson AEP Texas Central Company

Jon C. Wood Matthews & Branscomb

					_										
NRC FORM 3	56		U.S. N	UCLEAR RE	EGUL/	ATORY	I. APPROVED BY OMB NO. 3150-0104 EXPIRES 7-31-2004								
LICENSEE EVENT REPORT (LER) (See reverse for required number of digits/characters for each block)					551UN	Estimated burden per response to comply with this mandatory information collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records Management Branch (T-6 E6), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to bis1@nrc.goV, and to the Desk Officer, Office of Information and Regulatory Atlairs, NEOB-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to									
							Impose	Information c	ollect	tion does not displa	ay a current	ly valid i	DMB con	Irol number, 1	he NRC may not
1. FACILITY NAME South Text	ME AS						2. DOU	SKET NUME	ET NUMBER 3. PAGE						
							<u> </u>			<u> </u>		L			
4. 111LE		Inc	operab	le Contro	I Roc	om Ma	keup	and Cle	an	up Filtratio	n Syste	ems			
5. EV	ENT DATE		6.	LER NUMBEF	3	7.F	EPORT	DATE	<u> </u>	8	. OTHER F	FACILI	TIES IN	VOLVED	
HONTH		VEAD	VEAD	SEQUENTIAL	REV				FA	CILITY NAME		DOCI	KET NU	MBER	
		TEAN	TEAN	NUMBER	NO					outh Texas	3) <u>500(</u>) 499	
03	17	2004	2004	- 02 -	00	05	17	2004	FA	CILITY NAME	ł	DOCKET NUMBER			
		<u>├</u>	11. THIS	REPORT IS S	SUBM Г	TTED PU	RSUAN	T TO THE R	EQL	UIREMENTS OF	10 CFR *:	: (Che	ck all th	at apply)	
9. OPERATING	3 MODE	1	20.2	2201(b)	\square	20.220)3(a)(3)	/(ii)	\Box	50.73(a)(2)(ii	i)(B)	5	0.73(a))(2)(ix)(A)	
10 POWER L	EVEL	100	20.2	2201(d)		20.220)3(a)(4)	·	_	50.73(a)(2)(ii	i)	5	0.73(a))(2) <u>(</u> x)	
			20.2	2203(a)(1)	<u>_</u> _	50.360	<u>)(i)(/</u>	<u>4)</u>	_	50.73(a)(2)(in	v)(A)	<u> 7</u>	73.71(a)(4)		
			20.2	2203(a)(2)(i)		50.360	<u>»(1)(ii)(</u> /	A)	_	50.73(a)(2)(v	<u>')(A)</u>	┞┼┚	<u>3.71(a</u>))(5)	
			20.2	2203(a)(2)(ii)		50.36	<u>)(2)</u>			50.73(a)(2)(v	<u>/)(B)</u>				
			20.2	2203(a)(2)(III)	<u>-</u>	50.46(<u>a)(3)(ii)</u>		╂—	50.73(a)(2)(v	<u>()(C)</u>				
	7		20.2	$\frac{1}{20.2203(a)(2)(iv)} = 50.73$		50.73	$\frac{a}{2}(2)(0)$	<u>(A)</u>	50.73(a)(2)(v)(D)		/)(D)				
	د او او او او او او مرد مرد و هو و ا		20.	2203(a)(2)(vi	, ^	50.730	<u>a)(2)(i)</u> a)(2)(i)	(<u>)</u>	$\frac{50.73(a)(2)(Vii)}{50.73(a)(2)(yiii)(\Delta)}$		<u>'U)</u> /iii\/∆\				
			20.2203(a)(3)(i) 50.73		50.73(a)(2)(ii)	<u></u> i(A)	50.73(a)(2)(viii)(A)		/iii)(B)	- [25명 : 24.27 이가 아주가 가 가 가 가 가 가 가 가 가 가 가 가 가 가 가 가 가				
		·	<u> </u>	1:	2. LICF	ENSEE	CONTA	ACT FOR T							
NAME								<u> </u>	TE	LEPHONE NUN	BER (Incli	ude Ar	ea Code)	
J. A. Loya									361-972-7922						
		<u>13. CON</u>	<u>IPLETE (</u>	ONE LINE F	OR E/	<u>ACH CO</u>	MPON	ENT FAILI	JLURE DESCRIBED IN THIS REPORT						
					RE	EPORTABL	E			-					REPORTABLE
CAUSE	SYSTEM		PONENT	MANUFACTURE	<u>-</u>	to epix		CAUSE	-+	SYSTEM	COMPOI	NENT_	MANU	FACTURER	TO EPIX
								. <u></u>	_	. <u> </u>					
	1	14. SUPPL	.EMENTA	L REPORT E	(PECT)	ED	r		-1	15. EXPECTED MONTH SUBMISSION			DAY	YEAR	
YES (If y	/es, compl	lete EXPI	ECTED S	SUBMISSION	N DAT	E)		10		DAT	Ē				
16. ABSTRAC	T (Limit to	1400 spr	aces, i.e.	, approximate	ely 15	single-s	paced t	typewritten	line	es)					
At 1242 on 3 the Control I conclusion v pressure rel required by	At 1242 on 3/17/04, with Units 1 and 2 operating in Mode 1, the South Texas Project (STP) declared all three trains of the Control Room Makeup and Cleanup Filtration Systems (CRMCFS) inoperable in both Units. The basis for this conclusion was the fact that the CRMCFS did not maintain the Control Room Envelope (CRE) at sufficient positive pressure relative to adjacent areas during tests performed in March 2003 for Unit 2 and early March 2004 for Unit 1, as required by a surveillance requirement.														
Pursuant to each unit as	10CFR50 a conditi	0.73, ST ion proł	۲ P subr hibited '	nits this Lic by the Tec	cense chnica	e Ever al Spec	nt Rep cificati	ort regar ons.	rdin	g the inoper	ability o	of all t	hree (CRMCF	S trains of
The direct c conservative CRMCFS w body.	he direct causes of this condition were degraded Unit 1 and Unit 2 CRE system health, coupled with the station's non- onservative interpretation regarding the applicability of the surveillance requirement to certain adjacent areas. The RMCFS was capable of performing its safety function of limiting control room operator doses to less than 5 rem whole ody.														
This conditi	his condition resulted in no personnel injuries, no offsite radiological releases, and no damage to safety-related														

equipment. There were no challenges to plant safety.

NRC FORM 366 (7-2001)

NR (1-20	C FORM ⁽⁰¹⁾ LICE	A 366A U.S. NUCLEAR REGULATO	RY COMMISSION									
		1. FACILITY NAME	2. DOCKET		6. LER NUMBER	3. PAGE						
Sc	outh T	exas	05000 498	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2	OF	5			
				2004	02	00						
NAR	RATIVI	E (If more space is required, use addit	tional copies of NRC Form 36	6A) (17)			-					
I. DESCRIPTION OF EVENT												
	A.	REPORTABLE EVENT CLASSIFICATION										
		This event is reportable puby Technical Specification	irsuant to 10CFR50.7 s.	'3(a)(2)(i)(f	3) as an oper	ation or c	onditi	ion prol	hibited			
	B.	PLANT OPERATING CON	NDITIONS PRIOR TO	EVENT								
		Both South Texas Project Units 1 and 2 were in Mode 1 operating at 100% power.										
	C.	C. STATUS OF STRUCTURES, SYSTEMS, AND COMPONENTS THAT WERE INOPERABLE AT THE START OF THE EVENT AND THAT CONTRIBUTED TO THE EVENT										
		All three trains of CRMCF	S were inoperable in	both Units	1 and 2.							
	D.	NARRATIVE SUMMARY	OF THE EVENT, INC	LUDING E	DATES AND	APPROX	IMAT	Е ТІМЕ	S			
		From 3/1 - 3/6/04, STP per accordance with commitm Habitability." The Compor Guidance," was utilized for method in lieu of Tracer G	rformed testing to mea ents made in respons nent Test method desc r this purpose in order as Testing, which was	asure unfilt e to Gener cribed in NI to gather o considere	ered in-leaka ic Letter 2003 El 99-03, "Co data that wou d a less desin	ge into the 3-01, "Cor ntrol Roor Id support rable optic	e Unit Itrol R m Hat futur on.	1 CRE loom pitability e use o	in / f this			
		During the test, several test OPEP05-HE-0002, "Contro- was unsuccessful in restor Manager and Component efforts despite the fact that this conclusion was that th Letter 2003-01, and no in- This supported the underst did not impact operability, that relied on measuring the made when concluding Co- remaining outside of the ar	at points measured less of Room Envelope Diff ring affected test point Test Project Manager t six test points did not re purpose of the testin leakage was detected tanding that the failed and a correlation to th re same parameter was component Testing in U cceptance criteria.	es than the rerential Pro- s above the subseque t meet the mg was to r by virtue of points, wh e Technica as not mad lnit 2 in Ma	acceptance of essure Test." e acceptance ntly decided t test acceptan neasure in-le of all measure ile representi al Specification e. The same rch 2003 with	criteria spo Extensive criteria. to termina ace criteria akage pur ed points b ng degrad on surveilla determin n seven te	ecified e air I The T te bal . The suan being ded co ance r ation st poi	d in balancing est ancing basis t to Ger positive pondition requirer had be nts	ng for heric e. is, ment en			
		On 3/7/04, the NRC Resid measurements on CRMCF failures did not affect opera with the NRC Regional Off paper detailing the station discussions. Several days	ent Inspectors inquire -S operability. After b ability, the Resident In fice. The following da position and forwarde s of frequent, intensive	d on the po eing briefe spectors e y, the STP d it to the I e interaction	otential impac d regarding the xpressed the Project Mana NRC Residen hs between th	et of the fa he station ir intent to ager deve at Inspecto ne NRC at	iled 's pos raise loped ors to nd ST	ition the the iss a white facilitat P follov	at the sue e e wed.			

NRC	FORM	1 366A U.S. NUCLEAR REGULATORY	COMMISSION							
(1-200	LICE	NSEE EVENT REPORT (LI	ER)							
		1. FACILITY NAME	2. DOCKET	[6. LER NUMBER			3. PAG	E	
So	uth T	exas	05000 498	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3	OF	5	
				2004	02	00				
NARF	ATIVE	E (If more space is required, use additional	I copies of NRC Form 360	;A) (17)	 .				· •. •	
		On 3/17/04, the NRC informed were not in compliance with T acknowledged that the non-co reevaluating the station's posi requirement, STP conservative 1242. This placed both units station then submitted a reque significance of the condition. which Units 1 and 2 exited the TS 3.7.7.c requires that the un- within 12 hours following iden hours after the failed surveilla with respect to the Unit 2 CRI Technical Specifications and On 4/15/04, the NRC approve evaluating and taking comper pressure surveillance require subsequently declared all thre	d STP of their interp S surveillance required ompliance did not re- ition in light of the N rely declared all thre in a 12-hour shutdo est for enforcement The NRC granted t eir respective LCO and hit be shut down or tification of the faile ince test in early Ma E in March, 2003. This therefore reportance ed an exigent changes insatory actions for the ment of $\geq 1/8$ " Wate ee trains in both Un	pretation the irement 4. present a IRC's interpeter trains of which is constant the CRMC d test point arch, 2004 This represe ble under ge to TS 3. pest areas per Gauge (its operab	hat all three tr .7.7.e.3. The nuclear safe rpretation of the f CRMCFS in action statements the basis for of Enforcements. CFS be restor nts. Unit 1 wa Additionally sents a condi- 10CFR50.73 /4.7.7 that inc or point(s) while way was not in le and exited	ains of C NRC add ty concern he surveil ioperable ent (TS 3. ir which w ent Discre red to ope as not shu /, a simila tion prohil (a)(2)(i)(B corporated here the c met. The the LCO.	RMCF ditiona n. Wh llance in boti .7.7.c). vas the tion at erable ut dow r cond bited b b). d a prc lifferer statio	S in Ui lly ile h Units . The low sa t 1946, status n within lition ex by the ovision ntial	nit 1 s at afety after n 12 xisted	
	E.	METHOD OF DISCOVERY OF EACH COMPONENT FAILURE, SYSTEM FAILURE, OR PROCEDURAL ERROR This condition was identified during an in-leakage test of the CRMCES								
			-							
11.	EV	/ENT-DRIVEN INFORMATION								
	Α.	SAFETY SYSTEMS THAT R	ESPONDED							
		N/A								
	В.	DURATION OF SAFETY SY	STEM INOPERABI	LITY						
		All three CRMCFS trains for 2004. All three CRMCFS trai 2004.	Unit 1 were inopera ns for Unit 2 were i	able from noperable	at least Marc from at leas	h 6, 2004 t March 2	⊧ to Ap 2003 tc	əril 15, ə April	15,	
	C.	SAFETY CONSEQUENCES		NS OF TH		NC				
		 This condition posed no in Frequency. All test point in relation to adjacent ar 	mpact to Core Dan ts not meeting surv eas thereby prever	hage Freq reillance re	uency or Lar equirement 4 ered leakage	ge Early I .7.7.e.3 r	Releas emain CRE.	se Ied pos	sitive	

NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION (1-2001)

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET		6. LER NUMBER	3. PAGE				
South Texas	05000 498	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	4	OF	5	
		2004	02	00				

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

- All trains of CRMCFS in both Units remained capable of fulfilling their design function of limiting control room operator dose to less than 5 rem whole body, as required by 10CFR50, Appendix A - General Design Criterion (GDC) 19.
- 3). This condition did not affect radiological safety, the safety of station personnel, or the general public.

Therefore, this event is <u>NOT</u> considered a Safety System Functional Failure in accordance with 10CFR50.73(a)(2)(v).

III. CAUSE OF THE EVENT

A. The Root Cause of the degraded condition of the CRE in both Units was:

The station exhibited an inadequate, compliance-based approach to identifying and resolving CRE system health concerns.

Prior to the advent of Component Testing, the station had based its conclusions regarding the health of the CRE primarily on its ability to pass its differential pressure surveillance tests and by evidence of positive pressure across doors to adjacent areas, as indicated by smoke tests. Test results that were in some cases only marginally acceptable were not viewed with concern primarily because, despite the identified condition, the CRE continued to meet its safety function. Component Testing, first implemented in Unit 2 in early 2003 and including significantly more test points, provided the station with its first comprehensive picture of overall system condition. Unit 2 test results revealed test points at or below the acceptance criteria. Subsequent testing in Unit 1 in June 2003 resulted in all points passing (though marginally in some cases). The station placed low priority on resolving these conditions, and did not formally investigate their technical causes until after the station recognized that Component Test failures were equivalent to surveillance point failures and affected operability. In contrast, the station had aggressively resolved failures of test points formally included in the surveillance test. A more appropriate station response to these system health issues would have, at a minimum, resulted in timely restoration of failed points.

B. The Root Cause of the station's non-conservative interpretation of the applicable TS surveillance requirement was:

STP inappropriately based a TS interpretation primarily on assumptions of an equivalent NRC position gleaned from informal verbal communications with the NRC.

The non-conservative position in regards to application of the TS surveillance requirement was based on interpretations of comments in a series of meetings and other dialog with NRC and the industry between 2000 and 2002. These interactions were inappropriately accepted by STP as a basis that testing additional portions of the CRE boundary did not introduce compliance issues placing plant operation in jeopardy.

NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT (LER)

								_		
1. FACILITY NAME	2. DOCKET	KET 6. LER NUMBER					3. PAGE			
South Texas	05000 498	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	5	OF	5			
		2004	02	00						

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

IV. CORRECTIVE ACTIONS

- A. Develop and implement measures that ensure the optimal system health of the Control Room Envelope. The measures adopted shall consider the overall condition of the CRE, as opposed to narrow measures primarily focused on satisfying associated technical specification surveillance requirements.
- B. Revise the Control Room Emergency Air Cleanup System Function Test Procedure to incorporate Component Testing, such that the operability impact of any points that fail to meet minimum differential pressure requirements is clear to the user.
- C. Develop and communicate expectations that STP personnel will not assume NRC concurrence with a station position based upon verbal communications.

V. PREVIOUS SIMILAR EVENTS

LER 1-02-001: CRE HVAC failed to maintain a positive pressure in the Control Room due to the failure of a fire damper. The causes were cited as inadequate communications between operators and engineers, as well as knowledge issues regarding CRE failure modes and appropriate compensatory actions.

VI. ADDITIONAL INFORMATION

None.