

GARY R. PETERSON Vice President McGuire Nuclear Station

Duke Power MG01VP / 12700 Hagers Ferry Road Huntersville, NC 28078-9340

704 875 5333 704 875 4809 fax grpeters@duke-energy.com

June 22, 2004

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555-0001

Subject:

McGuire Nuclear Station

Docket Nos. 50-369

Steam Generator In-Service Inspection Report

Unit 1, End of Cycle (EOC) 16

Pursuant to ASME Section XI, Paragraph IWA-6230, Duke Energy Corporation hereby submits the attached Inservice Inspection (ISI) Outage Summary report for McGuire Unit 1 EOC 16.

Questions regarding this submittal should be directed to Kay Crane, McGuire Regulatory Compliance (704) 875-4306.

Gary R. Peterson

Attachment

A047

U. S. Nuclear Regulatory Commission Document Control Desk June 22, 2004 Page 2

cc: L. A. Reyes

U. S. Nuclear Regulatory Commission Regional Administrator, Region II Atlanta Federal Center 61 Forsyth St. Suite 23T85 Atlanta, GA 30303

J. J. Shea NRC Senior Project Manager (MNS) U. S. Nuclear Regulatory Commission Washington, DC 20555-0001

Joe Brady Senior Resident Inspector (MNS) U. S. Nuclear Regulatory Commission

# Steam Generator Outage Summary Report

# McGuire Unit 1 2004 Outage EOC 16

Location: Hwy. 73, Cowans Ford, North Carolina 28216

NRC Docket No. 50-369

National Board No. 44

Commercial Service Date: December 1, 1981

Owner: Duke Energy Corporation 526 South Church St. Charlotte, N.C. 28201-1006

Revision 0

Prepared By:	Mouth	<u> </u>	Date:	6-17-04
Reviewed By:	Duny & b	(ma)	Date:	6.17.04
Approved By:	Rich Bran	<u></u>	Date:	6-17-04
Copy No.	1	Assigned To	o:	NRC BOCUMENT CONTROL
Controlled:	<u>✓</u>	Uncontrolle	d:	

# Controlled Distribution

Copy No. Assigned To

Original McGuire Nuclear Station

**Document Control** 

Master File MC 1201.35

1 NRC Document Control

## **Uncontrolled Distribution**

Hartford Steam Boiler
Inspection and Insurance
Corporation (AIA)

3 State of North Carolina Department of Labor C/o J. M. Givens, Jr.

# FORM NIS-1 OWNER'S DATA REPORT FOR INSERVICE INSPECTIONS As required by the Provisions of the ASME Code Rules

1. Owner: <u>Duke Energy Corporation</u>, 526 S. Church St.. Charlotte, NC 28201-1006 (Name and Address of Owner)

 Plant: McGuire Nuclear Station, Highway 73, Cowans Ford, N. C. 28216 (Name and Address of Plant)

3. Plant Unit: 1

4. Owner Certificate of Authorization (if required) N/A

5. Commercial Service Date: December 1, 1981

National Board Number for Unit 44

7. Components Inspected:

Component	Manufacturer	Manufacturer Serial No.	State or Province No.	National Board No.
Steam Generator 1A	BWI	. 7701-04	NC-302668	157
Steam Generator 1B	BWI	7693-01	NC-302669	146
Steam Generator 1C	BWI	7701-03	NC-302670	155
Steam Generator 1D	BWI	7701-02	NC-302671	154

Note: Supplemental sheets in form of lists, sketches, or drawings may be used provided (1) size is  $8^{1}/2$  in. x 11 in., (2) information in items 1 through 6 on this data report is included on each sheet, and (3) each sheet is numbered and the number of sheets is recorded at the top of this form.

FORM	1 NIS-1 (Back)
8. Examination Dates Oct. 11, 2002	. to April 12, 2004
9. Inspection Period Identification:	First Period
10. Inspection Interval Identification:	Third Interval
11. Applicable Edition of Section XI	1995 Addenda 1996
12. Date/Revision of Inspection Plan:	Tech Spec 5.5.9
4/19/99.  15. Abstract of Corrective Measures. Reference a  We certify that a) the statements made in this a	attached NRC Inspection Report dated 4/19/99.  The report are correct b) the examinations and tests meet the Section XI, and c) corrective measures taken conform to  NA Expiration Date NA
Date <u>6-17-</u> 20 <u>04</u> Signed	Duke Energy Corp. By Leek Beaul
CERTIFICATE OF	INSERVICE INSPECTION
Inspectors and the State of Province ofNO	sued by the National Board of Boiler and Pressure Vessel  —————————————————————————————————

Atlanta, GA. 30338

0440 0 (010000)

<u></u>		20440-9 (2/2002
A FRAMAT	ENGIN OME ANP	EERING INFORMATION RECORD
Docume Title	nt Identifier 51 - 5044677-00  McGuire Nuclear Station Unit 1 EOC 16 Eddy	y Current Examination Technical Summary
	PREPARED BY:	REVIEWED BY:
Signature	pennis Greene  Date 5-12-04  per Statement: Initials	Name Kyle Rogers  Signature Kur Rogers  Date @5/12/04
Reviewer is Inde	pendent.	
Remarks:		
This report sumn Power Company	narizes the results of the eddy current examinarizes the Nuclear Station Unit 1 during the 1	ations performed on the tubes in four steam generators at Duk 6 <sup>th</sup> refueling outage (EOC 16).

#### 1.0 Introduction

Eddy current examinations were performed on the 0.688" OD x 0.040" wall Inconel 690 tubing in all four steam generators during McGuire Nuclear Station's Unit 1 Refueling Outage sixteen (16).

#### 2.0 Technical Summary

This section provides a technical summary of the eddy current examinations performed at Duke Energy's McGuire Nuclear Station Unit 1 Refueling Outage sixteen (16).

McGuire Unit 1 has the following design characteristics: 1,180 MW Pressurized Water Reactor (PWR) Westinghouse 4 loop Nuclear Steam Supply System (NSSS). The steam generators are Babcock & Wilcox International (BWI) CFR 80 vertical U-bend type generally containing 6,633 tubes each. Personnel from FANP performed the examinations during the 16th refueling outage.

A .560" diameter tuned bobbin coil full length examination was performed on 6,632 tubes in steam generator A, 3,649 tubes in steam generator B, 3,743 tubes in steam generator C and 6,629 tubes in steam generator D. A .540" diameter 3 coil .115" Pancake/.080" Pancake/Plus-Point motorized rotating coil MRPC® probe was used to examine 1327 top of tubesheets (+2" to -8") and special interest locations in the straight sections in each steam generator. A .520" diameter 2 coil .115" Pancake/Plus-Point motorized rotating coil MRPC® was utilized to inspect u-bend special interest locations in all four steam generators. All existing plugs were visually inspected. One (1) tube was removed from service in steam generators B, C and D. The Tube was Removed From service by

Plugging - CBC ANTHEN COCCURTAGE 6-17-04

### 2.1 Summary

The following summarizes the results of eddy current examinations for all four steam generators.

Note: Attachment 1 contains a list of all three-letter codes and acronyms used throughout this report. Attachment 2 contains the eddy current results from all four CFR80 steam generators for McGuire Unit 1 Refueling Outage 16.

#### A S/G:

- Eddy current examinations began on 3/15/04 @ 2000 and were completed on 3/27/04 @ 2300.
- 6,632 tubes were examined with a bobbin coil probe.
- 0 tubes were reported to have indications of 40% TW or greater with the bobbin coil probe examination.
- 0 tubes were reported to have indications of 20-39% TW with the bobbin coil probe examination.
- 41 tubes were reported to have 46 indications of 0-19% TW with the bobbin coil probe.
- 43 tubes were examined for Special Interest Locations.
- 1327 Hotleg top-of-tubesheets were examined.
- 1 tube was removed from service by plugging.
- See Attachment 2 for details.

#### B S/G:

- Eddy current examinations began on 3/15/04 @ 1200 and were completed on 3/22/04 @ 1800.
- 3,649 tubes were examined with a bobbin coil probe.
- 0 tubes were reported to have indications of 40% TW or greater with the bobbin coil probe examination.
- 2 tubes were reported to have 3 indications of 20-39% TW with the bobbin coil probe examination.
- 20 tubes were reported to have 21 indications of 0-19% TW with the bobbin coil probe examination.
- 80 tubes were examined for Special Interest Locations.
- 1327 Hotleg top-of-tubesheets were examined.
- No tubes were removed from service.
- See Attachment 2 for details.

#### C S/G:

- Eddy current examinations began on 3/15/04 @ 1400 and were completed on 3/25/04 @ 2300.
- 3,743 tubes were examined with a bobbin coil probe.
- 0 tubes were reported to have indications of 40% TW or greater with the bobbin coil probe examination.
- 0 tubes were reported to have indications of 20-39% TW with the bobbin coil probe examination.
- 29 tubes were reported to have 29 indications of 0-19% TW with the bobbin coil probe examination.
- 103 tubes were examined for Special Interest Locations.
- 1327 Hotleg top-of-tubesheets were examined.
- No tubes were removed from service.
- See Attachment 2 for details.

#### D S/G:

- Eddy current examinations began on 3/16/04 @ 0000 and were completed on 3/26/04 @ 1700.
- 6,629 tubes were examined with a bobbin coil probe.
- 0 tubes were reported to have indications of 40% TW or greater with the bobbin coil probe examination.
- 0 tubes were reported to have indications of 20-39% TW with the bobbin coil probe examination.
- 14 tubes were reported to have 15 indications of 0-19% TW with the bobbin coil probe examination.
- 22 tubes were examined for Special Interest Locations.
- 1327 Hotleg top-of-tubesheets were examined.
- No tubes were removed from service.
- See Attachment 2 for details.

#### 2.2 Examinations

The examination, analysis, equipment and personnel were in compliance with the requirements of the FANP Multi-Frequency Eddy Current Examination of Tubing (ISI-400) latest revision, Written Practice for Personnel Qualification in Eddy Current Examination (ISI-24) latest revision, Eddy Current Acquisition Guidelines for Duke Power Company's CFR80 Steam Generators and Eddy Current Analysis Guidelines for Duke Power Company's CFR80 Steam Generators.

The steam generator tubing examinations were performed by technicians qualified to Level II, or Level I under direct supervision of personnel qualified to Level II in accordance with FANP procedure ISI-24 (latest revision). The data was evaluated by personnel qualified to a minimum of Level IIA in accordance with FANP procedure ISI-24 (latest revision). The examination and evaluation procedures used during the eddy current examinations were approved by personnel qualified to Level III in accordance with FANP procedure ISI-24 (latest revision). All inspection frequencies were generated using a Zetec MIZ<sup>®</sup>-30 remote data acquisition unit.

The bobbin coil examinations were performed with .560 inch diameter probes. The inspection frequencies used were 650, 320, 170 and 35 kHz operating in both differential and absolute modes. A 650/170 kHz differential tube support plate suppression mix was used to enhance the detection of indications occurring at TSP intersections.

The special interest examinations were performed with .540" and .520" diameter motorized rotating coil MRPC® probes. The inspection frequencies used were 300, 200, 100 and 15 kHz. A 300/100 kHz TSP suppression mix on the pancake coil was used to enhance the detection of indications occurring at TSP intersections.

Official results of the data analysis were recorded on optical disks and verified by two Eddy Current Data Management systems: Framatome Data Management System, (FDMS) and EddyNet<sup>®</sup> Inspection Management System, (EIMS). These systems are used to check the data for invalid analysis entries, perform data sorting routines, ensure all the proper tubes were examined and to printout final data sheets.

#### 2.3 Areas of Concern

Eddy current examinations cannot, in all cases, determine the actual cause of damage. The signal recorded during the eddy current examination can be used to estimate the physical size of any tube damage detected (i.e., penetration into the wall, axial extent), however, the actual type of degradation and its cause can only be determined by tube removal and metallurgical studies.

- a) Loose Parts Loose parts, or damage attributed to loose parts impact or fretting, may be present adjacent to tubes in the periphery. Indications of loose parts and damage associated with loose parts have been detected in the CFR80 SG's.
- b) Mechanical Wear Indications indicative of TSP or FB wear have been indentified and reported in the CFR80 steam generators. Analysts shall be aware of the possibility of wear type indications and report any indication indicative of wear in accordance the Analysis guidelines.
- c) <u>Tube-to-Tube Contact</u> Tube-to-tube contact/proximity has been identified as an area of concern for the CFR80 replacement steam generators. A number of tubes in the CFR80 design generators have been identified as representative of tubes that are touching or in close proximity. The area of concern is the entire U-bend area and shall be monitored for indications indicative of degradation. Any indications indicative of tube-to-tube contact wear shall be reported in accordance the Analysis guidelines.

#### 2.4 Results

A number of indications within all four steam generators were given a nonquantifiable (NQI) code in the percent through-wall column. This code was used during the bobbin examinations for indications where an accurate depth determination could not be made.

Additionally, a number of indications within all four generators were reported as an Absolute Drift Indication (ADI) in the percent through-wall column. These are indications that could not be accurately quantified on differential channels.

#### 2.5 RSG A, B, C, and D results

Attachment 2 details the results of the various eddy current examinations performed in RSG A, B, C, and D. A total of 1 tube was removed from service in CFR80 steam generator "A" during refueling outage 16. This tube was removed from service due to an SVI above the cold leg top of tubesheet. This was a special interest exam following an indication reported from bobbin data.

## Attachment 1

<u>co</u>	DDE	DESCRIPTION
AD	t	Absolute Drift Indication
AX		Axial Indication
BLO		Bulge
BO		Boron
CH		Chatter
CH		
CH	G	Historical comparison has been performed and indication has
	NID	Changed based on the criteria
FAI		Framatome ANP
DN		Dent  Dent With Indication
DW		Dent With Indication
FC		Final Calibration
FC		Final Calibration Late
HN	ı	Historical comparison has been performed and indication has not
10		Changed based on criteria
IC		Incomplete Roll
IV	214	Independent Verification of tube identification
IDC	JK	Tube ID verified; This code shall be used to identify tubes acquired
		More than once during the current outage. Use of this requires tube
18.15	-	to tube comparison or fingerprinting of the affected tube(s)
INF		Indication Not Found
INF		Indication Not Reportable
IRF		Irregular Roll
IDI		Inside Diameter Indication
L3F		Level III Review
MS		Analyst Message
MA		Multiple Axial Indication
MC		Multiple Circumferential Indication
MM		Mix Mode Indication
MV		Multiple Volumetric Indication
MR		Motorized Rotating Pancake Coil
ND		No Degradation Detected
NE: NF		No Expansion No Final Calibration
NS		Needs SGME Review
, NQ		Non-Quantifiable Indication
		Obstructed
OD	-	Outside Diameter
OD		Outside Diameter Outside Diameter Indication
OV		Over Roll
OX		Over Expansion
PID		Positive Indentification
PL(		
PLF		Possible Loose Part
		COSSIDIE LOUSE I AIL
* NQ.	5	Plugged Tube Possible Loose Part  NON-QUANTIFIABLE SIGNAL (FRAMATOME OMITTED FROM REPORT)  NON-QUANTIFIABLE SIGNAL (FRAMATOME OMITTED FROM REPORT)
		1/1 / 11-04
		(1) com

Permeability PVN

**PWSCC** Primary Water Stress-Corrosion Cracking

**Quality Assurance** QA RBD Retest - Bad Data

RFB Retest- Fan Bar using a wear standard for sizing

Retest - Incomplete RIC Retest - Number Check **RNC** ROB Retest - Obstructed SAL Single Axial Indication

SCI Single Circumferential Indication

SI Special Interest

Single Volumetric Indication Tube End Anomalies SVI

TEA TSP **Tube Support Plate** 

TW Through Wall

Through Wall Depth **TWD** 

UTP Upper Tubesheet Primary face Upper Tubesheet Secondary face Volumetric indication UTS

VOL

WAR Wear

Wetting/Leaking WTG

## Attachment 2

# MNS 1 EOC 16 CFR80 A, B, C, and D Eddy Current Results.

## **Bobbin Examinations**

	Steam Generator "A" Tubes Tested: 6632		Steam Generator "B" Tubes Tested: 3649	
	Tubes With Indications	Number of Indications	Tubes With Indications	Number of Indications
TWD > 40%	0	0	0	0
TWD 20-39%	0	0	2	3
TWD < 20%	41	46	19	20
Fan Bar Wear	41	46	20	21
ADI	3	3	13	13
DNT	95	95	96	96
HNI	38	45	50	58
INF	0	0	1	1
INR	_9	11	5	5
NQI	2	4	1	1
PVN	0	0	0	0

	Steam Generator "C" Tubes Tested: 3743		Steam Generator "D" Tubes Tested: 6629		
	Tubes With Indications	Number of Indications	Tubes With Indications	Number of Indications	
TWD > 40%	0	0	0	0	
TWD 20-39%	0	0	0	0	
TWD < 20%	29	29	15	16	
Fan Bar Wear	28	28	14	15	
ADI	10	10	7	7	
DNT	124	124	57	57	
HNI	63	76	49	64	
INF	1	1	2	2	
INR	16	16	13	14	
NQI	8	12	2	2	
PVN	1	1	0	0	

Special Interest Examinations including PLP bounding RPC and HL-TTS RPC retests with wear standard)

	Steam Generator "A" Tubes Tested: 43/1327		Steam Generator "B" Tubes Tested: 80/1327	
	Tubes With Number of Indications Indications		Tubes With Indications	Number of Indications
Wear	38	43	9	9
NQS	0	0	0	0
VOL	2	2	3	3
SAI	0	0	0	0
MAI	0	0	0	0
SCI	0	0	0	0
MCI	0	0	0	0
MMI	0	0	0	0
SVI	1	3	0	0
MVI	0	0	0	0
DNT	0	0	0	0
PLP	0	0	4	5

	Steam Generator "C"		Steam Generator "D"	
	Tubes Tested: 103/1327		Tubes Tested: 22/1327	
	Tubes With	Number of	Tubes With	Number of
	Indications	Indications	Indications	Indications
Wear	25	31	12	13
NQS	0	0	0	0
VOL	2	2	1	1
SAI	0	0	0	0
MAI	0	0	0	0
SCI	0	0	0	0
MCI	0	0	0	0
MMI	O	0	0	0
SVI	0	0	0	0
MVI	0	0	0	0
DNT	O	0	0	0
PI.P	0	0	Ú	Û