

Exelon Generation Company, LLC www.exeloncorp.com
Dresden Nuclear Power Station
6500 North Dresden Road
Morris, IL 60450-9765

10 CFR 50.73

June 28, 2004

SVPLTR: #04-0040

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-0001


Dresden Nuclear Power Station, Units 2 and 3
Facility Operating License Nos. DRP-19 and DRP-25
NRC Docket Nos. 50-237 and 50-249

Subject: Licensee Event Report 2004-003-00, "Units 2 and 3 Control Room Emergency Ventilation System Inoperable Due To Damper Failure To Close"

Enclosed is Licensee Event Report 2004-003-00, "Units 2 and 3 Control Room Emergency Ventilation System Inoperable Due To Damper Failure To Close," for Dresden Nuclear Power Station. This event is being reported in accordance with 10 CFR 50.73(a)(2)(i)(B), "Any operation or condition which was prohibited by the plant's Technical Specifications," and 10 CFR 50.73(a)(2)(v)(D), "Any event or condition that could have prevented the fulfillment of the safety function of structures or systems that are needed to mitigate the consequences of an accident."

Should you have any questions concerning this report, please contact Jeff Hansen, Regulatory Assurance Manager, at (815) 416-2800.

Respectfully,



Danny G. Bost
Site Vice President
Dresden Nuclear Power Station

Enclosure

cc: Regional Administrator – NRC Region III
NRC Senior Resident Inspector – Dresden Nuclear Power Station

JE22

NRC FORM 366 (7-2001)		U.S. NUCLEAR REGULATORY COMMISSION			APPROVED BY OBM NO. 3150-0104 EXP 7-31-2004						
LICENSEE EVENT REPORT (LER)					Estimated burden per response to comply with this mandatory information collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records Management Branch (T-6 E6), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to: bjs1@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.						
1. FACILITY NAME Dresden Nuclear Power Station Unit 2				2. DOCKET NUMBER 05000237			3. PAGE 1 of 4				
4. TITLE Units 2 and 3 Control Room Emergency Ventilation System Inoperable Due To Damper Failure To Close											
5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED		
MO	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO	MO	DAY	YEAR	FACILITY NAME	DOCKET NUMBER	
04	28	2004	2004	- 003	- 00	06	28	2004	Dresden Unit 3	05000249	
									FACILITY NAME	DOCKET NUMBER	
									N/A	N/A	
9. OPERATING MODE		1		11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)							
10. POWER LEVEL		052		20.2201(b)		20.2203(a)(3)(ii)		50.73(a)(2)(ii)(B)		50.73(a)(2)(ix)(A)	
				20.2201(d)		20.2203(a)(4)		50.73(a)(2)(iii)		50.73(a)(2)(x)	
				20.2203(a)(1)		50.36(c)(1)(i)(A)		50.73(a)(2)(iv)(A)		73.71(e)(4)	
				20.2203(a)(2)(i)		50.36(c)(1)(ii)(A)		50.73(a)(2)(v)(A)		73.71(e)(5)	
				20.2203(a)(2)(ii)		50.36(c)(2)		50.73(a)(2)(v)(B)		OTHER Specify in Abstract below or in NRC Form 366A	
				20.2203(a)(2)(iii)		50.46(a)(3)(ii)		50.73(a)(2)(v)(C)			
				20.2203(a)(2)(iv)		50.73(a)(2)(i)(A)	X	50.73(a)(2)(v)(D)			
				20.2203(a)(2)(v)	X	50.73(a)(2)(i)(B)		50.73(a)(2)(vii)			
				20.2203(a)(2)(vi)		50.73(a)(2)(i)(C)		50.73(a)(2)(viii)(A)			
				20.2203(a)(3)(i)		50.73(a)(2)(ii)(A)		50.73(a)(2)(viii)(B)			
12. LICENSEE CONTACT FOR THIS LER											
NAME George Papanic Jr.					TELEPHONE NUMBER (Include Area Code) (815) 416-2815						
13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT											
CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX		
14. SUPPLEMENTAL REPORT EXPECTED							15. EXPECTED SUBMISSION DATE		MONTH	DAY	YEAR
YES (if yes, complete EXPECTED SUBMISSION DATE)							X	NO			

16. ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On April 28, 2004, with Unit 2 at 52 percent power in Mode 1, it was discovered during routine realignment of the Units 2 and 3 Control Room Heating, Ventilation and Air Conditioning System from Train A to Train B, that damper 2/3-5741-053B failed to close. The Control Room Emergency Ventilation System utilizes this Control Room Heating, Ventilation and Air Conditioning System damper and requires this damper to be capable of closure during a postulated Design Basis Accident. The Control Room Emergency Ventilation System was declared inoperable at 1209 hours (CDT).

The root cause of the damper 2/3-5741-053B failure to close was determined to be inadequate instructions in procedure DOA 5750-01, "Ventilation System Failure," and no signoff for the pipe plugs in the Work Order. The corrective actions to prevent reoccurrence are to revise procedures DOA 5750-01 and MA-AA-716-010, "Maintenance Planning."

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET NUMBER	6. LER NUMBER			3. PAGE
Dresden Nuclear Power Station Unit 2	05000237	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 of 4
		2004	003	00	

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

Dresden Nuclear Power Station Units 2 and 3 are General Electric Company Boiling Water Reactors with a licensed maximum power level of 2957 megawatts thermal. The Energy Industry Identification System codes used in the text are identified as [XX].

A. Plant Conditions Prior to Event:

Unit: 02	Event Date: 4-28-2004	Event Time: 1209 CDT
Reactor Mode: 1	Mode Name: Power Operation	Power Level: 52 percent
Reactor Coolant System Pressure: 1000 psig		

B. Description of Event:

The Units 2 and 3 Control Room Heating, Ventilation and Air Conditioning System (HVAC) has two trains, Train A and B. The Control Room Emergency Ventilation System (CREV) provides a radiologically controlled environment to the Control Room from which the unit can be safely operated following a postulated Design Basis Accident (DBA). The CREV utilizes components in Control Room HVAC Train B.

On April 19, 2004, Control Room HVAC Train B was removed from service and CREV declared inoperable to allow temporary modifications to be made to air damper solenoids to allow work to be performed on a Motor Control Center breaker. The temporary air damper solenoid modifications required the installation of tubing, fittings and pipe plugs that effected the operation of a CREV required damper. On April 22, 2004, the temporary modifications were removed from the air damper solenoids. Control Room HVAC Train B was tested and CREV declared operable.

On April 28, 2004, with Unit 2 at 52 percent power in Mode 1, it was discovered during routine realignment of the Control Room HVAC from Train A to Train B, that dampers 2/3-5741-053B, 2/3-5741-054A, 2/3-5741-054B, and 2/3-5741-054C [DMP] failed to close. CREV requires damper 2/3-5741-053B to be capable of closure during a postulated DBA. CREV was declared inoperable at 1209 hours (CDT).

An ENS call was made on April 28, 2004, at 1750 hours (CDT) for the above-described event. The assigned ENS event number was 40712.

Damper 2/3-5741-053B was restored and CREV declared operable at 1201 hours (CDT) on April 29, 2004.

This event is being reported in accordance with:

- 10 CFR 50.73(a)(2)(i)(B), "Any operation or condition which was prohibited by the plant's Technical Specifications." Technical Specification 3.7.4, "Control Room Emergency Ventilation (CREV) System," requires that an inoperable CREV be restored to operable status within 7 days. The CREV was inoperable from April 19, 2004 to April 29, 2004.
- 10 CFR 50.73(a)(2)(v)(D), "Any event or condition that could have prevented the fulfillment of the safety function of structures or systems that are needed to mitigate the consequences of an accident." CREV is a single train system and damper 2/3-5741-053B is required to be capable of closure during a postulated DBA.

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET NUMBER	6. LER NUMBER			3. PAGE
Dresden Nuclear Power Station Unit 2	05000237	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3 of 4
		2004	003	00	

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

C. Cause of Event:

The root cause of the damper 2/3-5741-053B failure to close was determined to be inadequate instructions in procedure DOA 5750-01, "Ventilation System Failure."

On April 19, 2004, the work order associated with the temporary modifications to the air damper solenoids used a Figure contained in procedure DOA 5750-01, "Ventilation System Failure," to describe a temporary modification and the materials needed for the work. The installation of the temporary modifications was successful. However, during the installation an Instrument Maintenance (IM) Technician became concerned that the information contained on the Figure and in the work order might not adequately address the removal of temporary piping plugs installed in the air damper solenoids. The IM Technician flagged the temporary piping plugs with a red flag and the words "Take Out."

On April 22, 2004, different IM Technicians removed the temporary air damper modifications. The IM Technicians used the Figure to remove the temporary modifications, however the Figure did not have a specific step to remove the piping plugs. The IM Technicians noticed the red flagged piping plugs but interpreted it to be an aid in finding the location of the temporary modifications and not a requirement to remove the piping plugs. As a result, the piping plugs were left in the air damper solenoids after the removal of all other components of the temporary modification. The post maintenance testing verified that the Control Room HVAC Train B could operate and the Control Room HVAC was realigned to Train A operation. CREV was declared operable

The effect of the installed piping plugs in the Control Room HVAC air damper solenoids was: (1) if the Control Room HVAC was started in Train B the dampers would be correctly aligned, (2) the Control Room HVAC could be realigned from Train B to Train A, and (3) the Control Room HVAC could not be successfully realigned from Train A to Train B. The installed piping plugs were discovered as a result of attempting to transfer the Control Room HVAC from Train A to B on April 28, 2004.

The corrective actions to prevent reoccurrence are to revise procedures (1) DOA 5750-01 to include pipe plug installation as a note on Figure 3 and in the body of the procedure, and (2) MA-AA-716-010, "Maintenance Planning," to require signoffs within work orders when attached non-maintenance procedures do not have adequate details for the work to be performed.

D. Safety Analysis:

The CREV is required to be manually initiated within 40 minutes of a DBA. Procedure DOA 5750-01 is used by operations personnel to respond to failures in needed plant ventilation systems including CREV. The temporary air damper modifications performed on April 19, 2004, used a temporary damper modification described in procedure DOA 5750-01 to respond to a failure of CREV to operate. The failure on April 22, 2004, to remove the piping plugs would not have prevented operations personnel from implementing the procedural requirements of DOA 5750-01 in reinstalling the air damper modifications. Thus, there is reasonable assurance that plant operations personnel could have successfully implemented the procedural response to a failure of CREV to operate during a postulated DBA. Therefore, the consequences of this event had minimal impact on the health and safety of the public and reactor safety.

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET NUMBER	6. LER NUMBER			3. PAGE
Dresden Nuclear Power Station Unit 2	05000237	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	4 of 4
		2004	003	00	

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

E. Corrective Actions:

Damper 2/3-5741-053B was restored to operable.

Procedure DOA 5750-01 was revised to include pipe plug installation as a note on Figure 3 and in the body of the procedure.

Procedure MA-AA-716-010 will be revised to require signoffs within work orders when attached non-maintenance procedures do not have adequate details for the work to be performed.

F. Previous Occurrences:

A review of recent Dresden Nuclear Power Station Licensee Event Reports (LERs) identified the following occurrence.

Unit 2 LER 2002-002, "Smoke Purge Mode Operation Prevents the Fulfillment of the Safety Function of the Control Room Emergency Ventilation System," describes an April 10, 2002 event in which a design error rendered the CREV inoperable when the Control Room HVAC was operated in the smoke purge mode.

G. Component Failure Data:

NA