

July 27, 2004

Mr. Christopher M. Crane, President
and Chief Nuclear Officer
Exelon Generation Company, LLC
4300 Winfield Road
Warrenville, IL 60555

SUBJECT: EVALUATION OF STEAM GENERATOR INSERVICE INSPECTION SUMMARY
REPORT, BRAIDWOOD, UNIT 1 (TAC NO. MC1894)

Dear Mr. Crane:

By letters dated May 7, 2003 (ML031360617), July 29, 2003 (ML032190155), July 31, 2003 (ML032170925), and April 16, 2004 (ML041140380) Exelon Generation Company, LLC (Exelon) submitted reports summarizing the steam generator tube inspections performed during the tenth refueling outage (April 2003) at Braidwood Station, Unit 1. Additional information pertaining to the 2003 steam generator tube inspections was summarized by the NRC staff in a telephone conference call summary dated June 18, 2003 (ML031570110).

As discussed in the enclosed evaluation, the staff concludes that Exelon provided the information required by their technical specifications. In addition, the NRC staff did not identify any technical issues that warranted follow up action at this time. The staff did note, however, that 132 tubes were classified as having tube-to-tube contact. Exelon indicated that it would continue to monitor the condition and perform inspections of the affected tubes during each scheduled steam generator inspection. The staff believes that continued monitoring is important especially if a new mechanism (i.e., not related to fabrication) is causing tube-to-tube contact since a new mechanism may result in different wear/corrosion rates than assumed in the original tube integrity analysis.

Please contact me if you have questions.

Sincerely,

/RA/

George F. Dick, Jr., Project Manager, Section 2
Project Directorate III
Division of Licensing Project Management
Office of Nuclear Reactor Regulation

July 27, 2004

Mr. Christopher M. Crane, President
and Chief Nuclear Officer
Exelon Generation Company, LLC
4300 Winfield Road
Warrenville, IL 60555

SUBJECT: EVALUATION OF STEAM GENERATOR INSERVICE INSPECTION SUMMARY
REPORT, BRAIDWOOD, UNIT 1 (TAC NO. MC1894)

Dear Mr. Crane:

By letters dated May 7, 2003 (ML031360617), July 29, 2003 (ML032190155), July 31, 2003 (ML032170925), and April 16, 2004 (ML041140380) Exelon Generation Company, LLC (Exelon) submitted reports summarizing the steam generator tube inspections performed during the tenth refueling outage (April 2003) at Braidwood Station, Unit 1. Additional information pertaining to the 2003 steam generator tube inspections was summarized by the NRC staff in a telephone conference call summary dated June 18, 2003 (ML031570110).

As discussed in the enclosed evaluation, the staff concludes that Exelon provided the information required by their technical specifications. In addition, the NRC staff did not identify any technical issues that warranted follow up action at this time. The staff did note, however, that 132 tubes were classified as having tube-to-tube contact. Exelon indicated that it would continue to monitor the condition and perform inspections of the affected tubes during each scheduled steam generator inspection. The staff believes that continued monitoring is important especially if a new mechanism (i.e., not related to fabrication) is causing tube-to-tube contact since a new mechanism may result in different wear/corrosion rates than assumed in the original tube integrity analysis.

Please contact me if you have questions.

Sincerely,

/RA/

George F. Dick, Jr., Project Manager, Section 2
Project Directorate III
Division of Licensing Project Management
Office of Nuclear Reactor Regulation

DISTRIBUTION:

PUBLIC	PDIII-2 R/F	AMendiola	PCoates
GDick	OGC	ACRS	KKarwoski
LLund	MMurphy	EMurphy	SReynolds, RIII
AStone, RIII			

ADAMS Accession Number: ML042020262

OFFICE	PM:PDIII-2	LA:PDIII-2	SC:PDIII-2
NAME	GDick	PCoates	AMendiola
DATE	07/22/04	7/22/04	7/27/04

OFFICIAL RECORD COPY

Braidwood Station Units 1 and 2

cc:

Regional Administrator, Region III
U.S. Nuclear Regulatory Commission
801 Warrenville Road
Lisle, IL 60532-4351

Document Control Desk - Licensing
Exelon Generation Company, LLC
4300 Winfield Road
Warrenville, IL 60555

Ms. C. Sue Hauser, Project Manager
Westinghouse Electric Corporation
Energy Systems Business Unit
Post Office Box 355
Pittsburgh, PA 15230

Joseph Gallo
Gallo & Ross
1025 Connecticut Ave., NW, Suite 1014
Washington, DC 20036

Ms. Bridget Little Rorem
Appleseed Coordinator
117 N. Linden Street
Essex, IL 60935

Howard A. Learner
Environmental Law and Policy
Center of the Midwest
35 East Wacker Dr., Suite 1300
Chicago, IL 60601-2110

U.S. Nuclear Regulatory Commission
Braidwood Resident Inspectors Office
35100 S. Rt. 53, Suite 79
Braceville, IL 60407

Ms. Lorraine Creek
RR 1, Box 182
Manteno, IL 60950

Illinois Emergency Management
Agency
Division of Disaster Assistance &
Preparedness
110 East Adams Street
Springfield, IL 62701-1109

Chairman
Will County Board of Supervisors
Will County Board Courthouse
Joliet, IL 60434

Attorney General
500 S. Second Street
Springfield, IL 62701

George L. Edgar
Morgan, Lewis and Bockius
1111 Pennsylvania Ave, NW
Washington, DC 20004

Braidwood Station Plant Manager
Exelon Generation Company, LLC
35100 S. Rt. 53, Suite 84
Braceville, IL 60407-9619

Site Vice President - Braidwood
Exelon Generation Company, LLC
35100 S. Rt. 53, Suite 84
Braceville, IL 60407-9619

Senior Vice President, Nuclear Services
Exelon Generation Company, LLC
4300 Winfield Road
Warrenville, IL 60555

Vice President of Operations - Mid-West
Pressurized Water Reactors
Exelon Generation Company, LLC
4300 Winfield Road
Warrenville, IL 60555

Chairman, Ogle County Board
Post Office Box 357
Oregon, IL 61061

Regulatory Assurance Manager - Braidwood
Exelon Generation Company, LLC
35100 S. Rt. 53, Suite 84
Braceville, IL 60407-9619

Director - Licensing and Regulatory Affairs
Exelon Generation Company, LLC
4300 Winfield Road
Warrenville, IL 60555

Associate General Counsel
Exelon Generation Company, LLC
4300 Winfield Road
Warrenville, IL 60555

Vice President - Licensing and Regulatory Affairs
Exelon Generation Company, LLC
4300 Winfield Road
Warrenville, IL 60555

Manager Licensing - Braidwood, Byron and LaSalle
Exelon Generation Company, LLC
4300 Winfield Road
Warrenville, IL 60555

SAFETY EVALUATION BY THE OFFICE OF NUCLEAR REACTOR REGULATION

RELATED TO THE EVALUATION OF TENTH REFUELING OUTAGE

STEAM GENERATOR TUBE INSPECTION RESULTS

EXELON GENERATION COMPANY, LLC

BRAIDWOOD STATION, UNIT 1

DOCKET NO. STN 50-456

By letters dated May 7, 2003 (ML031360617), July 29, 2003 (ML032190155), July 31, 2003 (ML032170925), and April 16, 2004 (ML041140380), Exelon Generation Company, LLC (the licensee) submitted reports summarizing the steam generator tube inspections performed during the tenth refueling outage (April 2003) at Braidwood Station, Unit 1. Additional information pertaining to the 2003 steam generator tube inspections was summarized by the Nuclear Regulatory Commission staff in a telephone conference call summary dated June 18, 2003 (ML031570110).

The four steam generators at Braidwood, Unit 1 were replaced in 1998 with steam generators fabricated by Babcock and Wilcox International. Each steam generator contains 6633 thermally treated Alloy 690 tubes. Each tube has a nominal outside diameter of 0.6875-inch and a nominal wall thickness of 0.040-inch. The tubes were hydraulically expanded at both ends for the full length of the tubesheet and are supported by a number of stainless steel tube supports (lattice grid). The tubes installed in rows 1 through 21 were thermally stress relieved after bending.

The scope and results of the licensee's inspections are contained in the documents referenced above. Based on a review of the above documents, the staff concludes that the licensee provided the information required by their technical specifications. In addition, the staff did not identify any technical issues that warranted follow-up action at this time; however, the staff did have the following observation regarding the results of the licensee's inspection and assessments.

During fabrication of the steam generators, tube-to-tube contact was identified. This condition was expected to naturally correct itself after one or two cycles of operation in the vertical position (licensee's license amendment application of February 9, 2001, ML010470080). During the preservice inspection, 508 tubes were identified as being in contact. The number of tubes in contact dropped to 85 when examined during the 2000 outage. Reinspection of these 85 tubes during the 2003 outage showed 67 remained in contact; however, 65 additional tubes, which had not been in contact in the past, were classified as being in contact during the 2003 outage. The licensee previously assessed tube integrity given the tube-to-tube contact condition and concluded that there were no structural integrity concerns for the life of the steam generators. In addition, the

licensee indicating they would continue to monitor the condition and perform inspections of the affected tubes during each scheduled steam generator inspection. The staff notes that continued monitoring is important especially if a new mechanism (i.e., not related to fabrication) is causing tube-to-tube contact since a new mechanism may result in different wear/corrosion rates than assumed in the original tube integrity analysis.

Principal Contributor: K. Karwoski

Date: July 27, 2004