C* Update

September 20, 2004

Revised C* Report

- To be Completed in October.
- Provides Tubesheet Region Inspection Lengths for CE-designed Units
- Based on Conservative Methodology Previously Submitted to NRC by SCE/APS
- Addresses NRC RAIs on CE-designed Units
- C* Participants Available to Meet with NRC Staff in early November



FLORIDA POWER & LIGHT ST. LUCIE UNIT 2 STEAM GENERATOR INSPECTION PLANNING

NRR - WHITE FLINT SEPTEMBER 20, 2004



AGENDA

- Purpose of Meeting
- Background
- SL2-15 Inspection Scope
- Projected Tube Plugging
- Operating Experience
- Contingency Planning
- Generic Letter 2004-01
- Summary & Closing

1



STEAM GENERATOR INSPECTION PLANNING SL2-15 NOVEMBER 2004 - NRR, WHITE FLINT

Purpose of Meeting


- Review SL2 S/G Condition
- Review SL2-15 Inspection Plans
- GL 2004-01 Response
- Address Staff Concerns



Background

S/G Design

- CE Model 3410
- 8411 Tubes / SG
- ▶ ~18.3 EFPY @ SL2-15
- A-600 HTMA Tubing
- ► CS Lattice Support System
- Tubesheet Joint Explosive
- > Total Tubes Plugged SG A - 671 (8.0%) SG B - 872 (10.4%)
- T-Hot ~600°F



7



STEAM GENERATOR INSPECTION PLANNING SL2-15 NOVEMBER 2004 - NRR, WHITE FLINT

Background

FPL Steam Generator Program

- Committed to Safe Operation
- Full Implementation of NEI 97-06, S/G Program Guidelines
 - Inspection
 - Chemistry
 - Leak Monitoring
- Incorporate Industry Experience
- Extensive Examination History at Unit 2
- Conservative Approach
 - In Situ Pressure Test at Last 5 Inspections



Background

- Last Inspection SL2-14 in April 2003
- Results Discussed with NRR During Outage
 - ▶ Most Damage Mechanisms as Expected
 - ▶ No ODSCC in Dings
 - ▶ PWSCC in Tubesheet Limited and Confined to Upper 2"
 - ▶ Increase in Axial ODSCC at Eggcrate Supports
 - Degradation Trend Typical for Unit with A-600 MA Tubing

5



STEAM GENERATOR INSPECTION PLANNING SL2-15 NOVEMBER 2004 - NRR, WHITE FLINT

Background

Summary of PSL-2 Indication Counts (April 2003)

Mechanism	Number of Indicators			
	S/G A	S/G B	Total	
Axial ODSCC at Eggcrates	222	441	663	
Axial ODSCC at Diagonal Straps (1)	0	2	2	
Axial ODSCC at Dings	0_	0	0	
Axial ODSCC in Freespans (2)	1	0	1	
Axial ODSCC at Tubesheet (Hot)	17	14	31	
Axial IDSCC below Tubesheet (Hot)	6	2	8	
Circumferential ODSCC at Tubesheet (Hot)	3_	7	10	
Circumferential Indications below Expansion Transition	0	0	00	
OD Volumetric at Tubesheet (Hot) (3)	0	2	2	
Wear at Tubesheet (Cold)	5_	1	6	
Wear at Diagonal/Vertical and Eggcrate Supports	695	478	1173	

Notes:

- Two Indicators detected at bat wing supports were evaluated in combination with eggcrate indications.
- Single indication detected in freespan was evaluated in combination with eggcrate indications.
 Volumetric indications are attributed to loose part wear. These indications were evaluated in combination with top-of-tubesheet wear indications.



Background

Tube Plugging by Mechanism (1)	4/00	<u>11/01</u>	4/03
ODSCC at Eggcrates	14	259	482(2)
Wear at Tube Supports	18	11	
ODSCC at Top of Tubesheet	16	19	27
Preservice, FO Wear, Preventative	••	51	6
Circ. ODSCC at Top of Tubesheet	5	13	10
OD Volumetric - Various		2	
IDSCC Below Top of Tubesheet	1	1	4
ODSCC at Dings		5	
ODSCC in Freespan	<u></u>		1
	54	361	530
Cumulative Plugging	652	1013	1543
Cumulative Percent	3.9%	6.0%	9.2%

(1) Axial unless noted otherwise. (2) Includes 2 Indications at Diagonal Strap.

7



STEAM GENERATOR INSPECTION PLANNING SL2-15 NOVEMBER 2004 - NRR, WHITE FLINT

Background

In Situ Pressure Testing Through SL2-14

- 54 Total Indications
- Mechanisms Include
 - Axial ODSCC at Eggcrates
 - ▶ Axial ODSCC at Dings
 - Axial ODSCC at TTS
 - Axial IDSCC below TTS
 - ▶ Circ ODSCC at TTS
 - OD Volumetric TTS

No Leakage or Burst

В



SL2-15 Inspection Scope

- **■**Visual Examination of All Tube Plugs
- ■Bobbin Probe All Active Tubes
 - Screen Dings <5 Volts in Straight Sections</p>
 - Full Length Row 3-140, Straight Length Row 1-2
- ■Plus Point Probe
 - ▶ 100% Hot Leg Top of Tubesheet (+3"/- WCAP Value)
 - Cold Leg Periphery Tubes for FO Damage (+3"/-2")
 - 35% Row 1-2 U-bends (~40/SG)
 - ▶ 100% Wear Scars at Eggcrates & HL Diagonal (A-118, B-84)
 - 20% Wear Scars at U-bends & CL Diagonal (A-111, B-73)
 - All Tubes with No Tube Expansion (A-22, B-1)

q



STEAM GENERATOR INSPECTION PLANNING SL2-15 NOVEMBER 2004 - NRR, WHITE FLINT

SL2-15 Inspection Scope (con't)

	Plus	Po	int	Pro	be ·	for	Dings
--	------	----	-----	-----	------	-----	-------

	<u>SGA</u>	<u>SGB</u>
All Dings Hot Leg Tubesheet to 1st Support	43	24
All Dings >5 volts 1st Support to HL Bend	98	77
All Dings in HL & CL Square Bends Row 19-140	68	54
All Dings >5 volts in Horizontal Run Row 19-140	97	107
All Dings in Rows 1-18 U-Bends	140	104
20% Dings >5 volts CL Tubesheet to CL Bend	26	_23
	472	389

■ In Situ Testing Based on Industry Screening Guidance



Projected Tube Plugging

	Predicted Number
Mechanism/Location	<u>SL2-15</u>
Axial ODSOC at Eggcrate Supports	700-1100
Axial ODSOC at Top of Tubesheet	30-50
Circumferential ODSCC at Expansion Transitions	10-20
Axial ODSCC at Dings	5-10
Axial IDSOC Below Secondary Face of Tubesheet	5-10
TOTAL PROJECTED	750-1190

11



STEAM GENERATOR INSPECTION PLANNING SL2-15 NOVEMBER 2004 - NRR, WHITE FLINT

Operating Experience

- Continue Emphasis on Dings/Dents & Anomalous Indications
- Foreign Object Damage
- U-Bend Cracking
- Coverage of Auto Analysis
- Tube to Tube Wear (Tube Sever Potential)
 - Wear Progression Analysis Completed for Plugged Tubes
 - 49 Locations Susceptible to Tube-to-Tube Contact <SL2-17
 - Susceptible Locations to be Reviewed by Lead Analysts



Contingency Planning

<u>Issue or Inspection Item</u> <u>Contingency Action</u>

Leaking Plug Replace as Necessary

Crack in Row 1&2 U-bend Test 100% Affected Rows

& 20% Row 3, etc.

Crack in U-bend Wear Scar Test All (A~450, B~300)

Crack in Cold Leg Ding Test All (A~104, B~92)

Foreign Object Wear Bound FO Wear

CL Expansion Transition Cracking Test 100% in Affected SG

Freespan Cracking Validate Bobbin POD

13



STEAM GENERATOR INSPECTION PLANNING SL2-15 NOVEMBER 2004 - NRR, WHITE FLINT

Generic Letter 2004-01

FPL Program Complied with NEI 97-06 and Tech Specs for All Past Inspections

- Tubesheet Inspection Depth Not Challenged
 - Cracking Limited to 2" Below Top of Tubesheet
 - Inspections to 5" and 8" Below Top of Tubesheet
- Frequency & Extent of Cracking is Limited
- LAR to Redefine Inspection Depth Submitted Prior to SL2-14
 - Withdrawn Based on Inspection Results and Discussions with NRC



Generic Letter 2004-01

ID Axial Cracks Below Expansion Transition (1)

RFO Date	Exam Scope	Exam Depth	No. <u>IND</u>	Maximum Depth Into Tubesheet
04-97	100%	~2"	1	-1.10"
11-98	100%	~2"	0	
04-00	100%	2"	1	-0.17"
11-01	100%	5"	2(2)	-2.10"
04-03	100%	8"	8(3)	-1.89"

- (1) No ID circumferential indications reported below transition
- (2) Only one tube affected (3) Only four tubes affected



STEAM GENERATOR INSPECTION PLANNING SL2-15 NOVEMBER 2004 - NRR, WHITE FLINT

Generic Letter 2004-01

- Planning for SL2-15 Inspection
 - Assumptions on Distribution of Degradation in Tubesheet Challenged by Recent Inspection Results
 - Need to Redefine Tube Inspection Depth and Plugging Limit
 - ▶ Submit License Amendment Request
 - Follow Guidance in GL 2004-01
 - Tube Inspection & Plugging Limit Definitions
 - Inspection Depth Based on WCAP
 - New WCAP to Address NRC Comments
- May Request Expedited License Amendment Approval



Summary & Closing

- FPL Program Meets Industry Guidance
- Reasonable Assurance of Tube Integrity
- Compliance with Tech Spec & NRC Position
- Amend License Consistent with GL 2004-01
- Identify & Address Staff Concerns