

Exelon Nuclear Peach Bottom Atomic Power Station 1848 Lay Road Delta, PA 17314-9032 Telephone 717.456.7014 www.exeloncorp.com Nuclear

10CFR 73.71

December 10, 2004

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555-0001

Peach Bottom Atomic Power Station (PBAPS) Unit 2 and Unit 3 Facility Operating License Nos. DPR-44, DPR-56

NDO D. J. L. L. CO. 027 FO. 020

NRC Docket No. 50-277, 50-278

Subject:

60 Day Security Event Report 2-04-S01

Enclosed is a report concerning an event involving an inadequately compensated posting of a security perimeter zone. In accordance with NEI 99-04, the regulatory commitment contained in this correspondence is to restore compliance with the regulations. The specific methods that are planned to restore and maintain compliance are discussed in the report. If you have any questions or require additional information, please do not hesitate to contact us.

Sincerely.

Joseph P. Grimes Plant Manager

Peach Bottom Atomic Power Station

JPG/dwm/CR263823 Attachment

CC:

PSE&G, Financial Controls and Co-owner Affairs

R. R. Janati, Commonwealth of Pennsylvania

INPO Records Center

H. J. Miller, US NRC, Administrator, Region I

R. I. McLean, State of Maryland

US NRC, Senior Resident Inspector

Glenn M. Tracy, Director, Division of Nuclear Security, Office of Nuclear Security and

Incident Response.

CCN 04- 14099

SUMMARY OF EXELON NUCLEAR COMMITMENTS

The following table identifies commitments made in this document by Exelon Nuclear. (Any other actions discussed in the submittal represent intended or planned actions by Exelon Nuclear. They are described to the NRC for the NRC's information and are not regulatory commitments.)

Commitment	Committed Date or "Outage"						
In accordance with NEI 99-04, the regulatory commitment contained in this correspondence is to restore compliance with the regulations. The specific methods that are planned to restore and maintain compliance are discussed in the LER.	In accordance with the Corrective Action Program						

NRC FO	RM 366			U.S.	NUCLI	AR R	EGULATO	RY COMM	ISSION	ı			3: NO. 3150-01			RES: 06/30/2007
LICENSEE EVENT REPORT (LER) (See reverse for required number of digits/characters for each block)								Estimated burden per response to comply with this mandatory collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or reporter and a page of the response to the								
1. FACILITY NAME								not conduct or sponsor, and a person is not required to respond to, the information collection. 2. DOCKET NUMBER 3. PAGE								
Peach Bottom Atomic Power Station, Unit 2 4. TITLE								05000 277 1 OF 3								
Inadeo	quate									e to	o inac		human per			
							EPORT D	ATE	-	ACILITY		OTHER FAC	ILITIES INV		ET NUMBER	
MONTH	DAY	YEAR			REV NO.	MONTH	DAY YEA					Atomic Powe	ower St –Unit3		05000 278	
10	13	04	04 - S01 - 00		00	12	10	04	ľ	ACILITY	' NAME				DOCKET NUMBER 05000	
9. OPER	ATING	MODE	11	. THIS	REPO	RT IS	SUBMITTE	D PURSI	UANT T	ОΤ	HE RE	QUIREM	ENTS OF 10	CFR§: (Che	ck all th	at apply)
1 20.2201(b) 20.2203(a)(3)(i) 20.2203(a)(3)(ii) 20.2203(a)(1) 20.2203(a)(3)(ii) 20.2203(a)(1) 20.2203(a)(4) 20.2203(a)(2)(ii) 50.36(c)(1)(i)(A) 20.2203(a)(2)(ii) 50.36(c)(1)(ii)(A) 20.2203(a)(2)(iii) 50.36(c)(2) 20.2203(a)(2)(iii) 50.36(c)(2) 20.2203(a)(2)(iv) 50.46(a)(3)(ii) 20.2203(a)(2)(v) 50.73(a)(2)(i)(A) 20.2203(a)(2)(vi) 50.73(a)(2)(i)(B)							(3)(ii) (4) (i)(A) (ii)(A) (ii) (ii)	□ 50.73(a)(2)(i)(C) □ 50.73(a)(2)(vii) □ 50.73(a)(2)(ii)(A) □ 50.73(a)(2)(viii)(A) □ 50.73(a)(2)(ii)(B) □ 50.73(a)(2)(viii)(B) □ 50.73(a)(2)(iii) □ 50.73(a)(2)(ix)(A) □ 50.73(a)(2)(iv)(A) □ 50.73(a)(2)(x) □ 50.73(a)(2)(v)(A) □ 73.71(a)(4) □ 50.73(a)(2)(v)(B) □ 73.71(a)(5) □ 50.73(a)(2)(v)(C) □ OTHER □ 50.73(a)(2)(v)(D) Specify in Abstract below						viii)(A) viii)(B) ix)(A) x)		
						1:	2. LICENS	EE CONT	ACT FO)R	THIS L	.ER		OF II	NRC FOR	m 300A
	12. LICENSEE CONTACT FOR THIS LER ACILITY NAME JAMES Mallon, Regulatory Assurance Manager (717) 456-3351															
James	ivialior													7) 456-33	<u> </u>	
CAUSE SYSTEM COMPONENT MANU-FACTURER TO EPIX												EPORTABLE TO EPIX				

14. SUPPLEMENTAL REPORT EXPECTED						<u> </u>				(PECTED	MONTH	DAY	YEAR			
☐ YES (If yes, complete 15. EXPECTED SUBMISSION DATE)							\boxtimes	NO	SUBMISSION DATE							
ABSTRA	CT (Lim	it to 1400	spaces, i	.e., apj	oroxima	tely 15	5 single-sp	aced type	written li	ines	;)					
	secur position in deg comp requir inade discov vital a	ity super oned surgradation ensatory ed, per quate hu	rvisor d ch that n in the measu the site uman po securit	iscover he was safegures was ares was erform y office reas was	ered thas una guard were noticely produced to the contraction of the c	hat the system of adolan, during s imr	ne nucleand adequate of the term of the policy and the policy and the policy and the policy and and the term of term o	ar securi ately obsould allow employ is event osting of y assign	ity offices serve sow una yed. Coccurrent the coceut to the company of the total servers and the company of the	er sec uth om ed omp	assigurity incrized appending the company of the co	ined to a zone 13 d acces satory m e cause o atory me pensator	era walk-do a compensa in its entire s to the pro easures for of this even asures for by post. A s areas was	atory post ety. This of tected are zone 13 of was due zone 13.	was resulted ea whe were e to When reep of	ere all

NRC FORM 366AU.S. NUCLEAR REGULATORY COMMISSION

(1-2001)

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	L	ER NUMBER (6)	PAGE (3)			
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Peach Bottom Atomic Power Station, Unit 2	05000 277	04	- S01 -	00	2	OF	3

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

Unit Conditions Prior to the Event

Both Unit 2 and Unit 3 were in Mode 1 operating at approximately 80% and 100% rated thermal power respectively when the event occurred. There were no structures, systems, or components out of service that contributed to this event.

Description of Event

On 10/15/04, at approximately 0144 hours, while conducting a security camera walk-down, a nuclear security supervisor discovered that the contract nuclear security officer assigned to a compensatory post was positioned such that he was unable to adequately observe security zone 13 in its entirety. On 10/13/04, two compensatory security posts were in place on security zones 13 and 14 due to construction activities associated with the design bases threat (DBT) project. Post 1 was assigned as a compensatory measure for zone 14 and zone 13 east. Post 2 was assigned as compensatory measure for zone 13 west and two other compensatory measures previously established. Construction activities were secured on security zone 14 for the day and the nuclear security supervisor secured Post 1 on security zone 14, which was no longer required. The nuclear security supervisor verbally (via hand held radio) notified Post 2 that compensatory measures would be expanded to cover all of zone 13. There was inadequate communications between the nuclear security supervisor and the contract nuclear security officer at Post 2, to clearly communicate specific compensatory requirements. This resulted in a portion of security zone 13 to be inadequately compensated for in accordance with the approved site Nuclear Security Plan.

This event resulted in degradation in the safeguard system that could allow unauthorized access to the protected area where compensatory measures were not adequately employed. Compensatory measures for security zone 13 were required, per the site's security plan, when this event occurred. The cause of this event was due to inadequate human performance during the posting of the compensatory measures for security zone 13. When discovered, a nuclear security officer was immediately assigned to the compensatory post for zone 13. A search/sweep of all vital and protected areas was performed and a review of the security alarm areas was conducted yielding no security areas of concern in either case.

Analysis of the Event

There were no actual safety consequences associated with this event.

The Site Physical Security Plan requires compensatory measures be employed when there is a degradation of the physical security measures for the site. In this event, zone 13 was inadequately compensated from 10/13/04 at approximately 1807 hours to 10/15/04 at approximately 0144 hours. During this time routine roving contract nuclear security officers and other posted compensatory measures were in place that would detect and respond to an intrusion. Additionally, other physical security systems were available to detect entry into the vital areas of the plant.

This event is not considered to be risk significant.

NRC FORM 366AU.S. NUCLEAR REGULATORY COMMISSION

(1-2001)

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	L	ER NUMBER (6)	PAGE (3)			
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Peach Bottom Atomic Power Station, Unit 2	05000 277	04	- S01 -	00	3	OF	3

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

Cause of the Event

The cause of this event was due to inadequate human performance during the posting of the compensatory measures for zone 13.

Corrective Actions

A contract nuclear security officer was immediately assigned to the compensatory post and properly positioned and instructed for security zone 13.

Additional corrective actions, including the creation of additional procedural guidance for establishing and securing compensatory posts, is being evaluated in accordance with the corrective action program.

Previous Similar Occurrences

There were no previous similar occurrences identified involving a failure adequately post for compensatory measures due to inadequate human performance.