N	RC FORM 591M PART 3		U.S	S. NUCLEAR REGULATORY COMMISSION	
•	0-2003)	Docket File	Information		
10	O CFR 2.201 SAFETY INSPECTION REPORT				
	SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION				
1.	LICENSEE		2. NRC/REGIONAL OFFICE		
Department of the Army			LICARC Pagion IV		
RE	PORT NUMBER(S) 2004-001		USNRC Region IV		
_	DOCKET NUMBER(S)	4. LICENSE NUMBER(S)		5. DATE(S) OF INSPECTION	
	030-03368	46-02645-03		December 7, 2004	
6.	INSPECTION PROCEDURES USED	7. INSPECTION FOCUS A	REAS		
	87131	All areas 1-7			
H			ECTION INFORMATION		
Ļ			ECTION INFORMATION	A TELEPHONE NUMBER	
1.	PROGRAM CODE(S) 2. PRIORITY 2	3. LICENSEE CONTACT David Rynders	, RSO	4. TELEPHONE NUMBER 253 968-4300	
	X Main Office Inspection		Next Inspection Date:	December 2006	
	Field Office				
	Temporary Job Site				
PROOPAN COORE					
PROGRAM SCOPE					
	This licensee was last inspected in July 1999, and subsequent inspections were delayed due to changes to the inspection frequencies during the revision of NRC Manual Chapter 2800.				
	changes to the inspection frequencies during the revision of NRC Manual Chapter 2800. Additionally, the licensee's primary use code was changed from Program Code 2120 to Program.				
	Additionally, the licensee's primary use code was changed from Program Code 2120 to Program Code 2240 (Medical Therapy-Other Emerging Technology) with a two-year inspection interval.				
	This licensee's use of licensed material has decreased significantly over the past three years. Particularly, the use of brachytherapy has diminished since CY 2001. The licensee's radiation				
	Particularly, the use of brachytherapy has diminished since CY 2001. The licensee's radiation safety program continues to be organized under three areas of licensed material use: Nuclear Medicine, Radiation Therapy, and Department of Clinical Investigations (DCI).				
	Medičine, Radiation Therapy, and Department of Clinical Investigations (DCI).				
	The oversight of radiation safety is by the Health Physics Office, consisting of Chief (RSO) Health				
	Physics Service, MAJ David Ryr Physics Service is located remo	iders; HP 1Lt. Ma	rgaret Myers; and tw	o HP Techs. The Health	
	Physics Service is located remo	te from the hospi	ital in Building 9909 C	Health Physics Office	
	Wińg.				
	The Nuclear medicine program is still very active with the use of a weekly 3.0 curie Mo-99 generator. The licensee maintains in-hospital radiopharmacy using a single ANP, Jane Besich-Carter and several NMT for nuclear medicine procedures.				
	generator. The licensee maintains in-hospital radiopharmacy using a single ANP, Jane Besich-				
	Carter and Several Mill for nuclear medicine procedures.				
	The licensee's radiation therapy department sent its Novoste IVP therapy units back to the				
	supplier back in the 1 st quarter CY 2003, and do not plan on continual use of IVB for therapies.				
	A review of radiation therapy us	e showed that the	e licensee has provid	ed consistent therapies	
	using I-131, Pd-103, Cs-137, Ir-1	92, and 1-125. A	review of Written Dire	ectives (WD) for therapy	
	use showed that WD(s) had bee	n prepared as rec	quired and had been	maintained as required.	
	noted that all therapy performar	nces had been be	rformed and docume	nted as required.	
	A review of radiation therapy use showed that the licensee has provided consistent therapies using I-131, Pd-103, Cs-137, Ir-192, and 1-125. A review of Written Directives (WD) for therapy use showed that WD(s) had been prepared as required and had been maintained as required. During discussions with licensee staff and the review of radiation therapy records the inspector noted that all therapy performances had been performed and documented as required. No Medical Events were reported by the licensee and the inspector did not identify any Medical				
	No Medical Events were reporte Events .	a by the licensee	and the inspector di	a not identify any Medical	
	Surveys of restricted and unrestlimits.	tricted areas reve	ealed that radiation le	vels were within regulatory	
	minto.				