

Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION

1. LICENSEE Cardinal Health REPORT NUMBER(S) 2005-004		2. NRC/REGIONAL OFFICE US Nuclear Regulatory Commission Region IV	
3. DOCKET NUMBER(S) 030-33224	4. LICENSE NUMBER(S) 04-26507-01MD	5. DATE(S) OF INSPECTION December 15-29, 2004	
6. INSPECTION PROCEDURES IP 87127	7. INSPECTION FOCUS AREAS 03.01-.07		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM 2500	2. PRIORITY 2	3. LICENSEE CONTACT Samuel E. Leveritt, site RSO	4. TELEPHONE NUMBER 417-831-5190
<input type="checkbox"/> Main Office Inspection		Next Inspection Date: Normal: 12/15/2006	
<input checked="" type="checkbox"/> Field Office 3040 East Elm Street, Springfield, Missouri			
<input type="checkbox"/> Temporary Job Site			

PROGRAM SCOPE

This facility was a nuclear pharmacy located in Springfield, Missouri. Licensee staff consisted of three pharmacists, two technologists, and five drivers. The pharmacy manufactured and distributed approximately 200-250 unit doses and bulk technetium-99m vials daily Monday through Friday. Most of the unit doses were technetium-99m compounds, with occasional thallium-201, gallium-67, yttrium-90, and indium-111 doses. Licensee operated two shifts from around 1:00 AM until 4:30 PM on weekdays, with limited hours on weekends. The first run started at 3:30 AM and the second at 8:00 AM, with additional runs as needed throughout the day. The pharmacy received three 3-Curie technetium-99m generators weekly, delivered Mondays, Tuesdays, and Thursdays. Licensee compounded iodine-131 and iodine-123 capsules in a dedicated hood. Licensee received and redistributed xenon-133 vials. The licensee's corporate office performed independent safety audits on the radiation safety program three times annually. Licensee had addressed all concerns raised by these audits.

Performance Observations

During this inspection, the inspector observed generator milking and molybdenum test procedures, kit preparation and quality assurance, dose preparations, iodine-131 compounding, dose packaging, package surveys, dose calibrator constancy, survey meter tests, package transport, shipping paper preparation, package transport, returned package receipt, personnel bioassays, and daily surveys of radiation use areas. No issues were identified with these practices. Interviews with licensee staff indicated adequate knowledge of radiation safety procedures and policies. Surveys indicated radiation levels consistent with licensee records and postings.

The inspector closed a violation from the previous inspection regarding leak tests of sealed sources. Licensee had previously failed to leak test reference sources. The leak tests on those sources were current, and had been done consistently since the previous inspection.