



Entergy Nuclear Northeast
Indian Point Energy Center
450 Broadway, GSB
P.O. Box 249
Buchanan, NY 10511-0249
Tel 914 734 6700

Fred Dacimo
Site Vice President
Administration

January 6, 2005
Indian Point Unit No. 2
Docket Nos. 50-247
NL-05-003

Document Control Desk
U.S. Nuclear Regulatory Commission
Mail Stop O-P1-17
Washington, DC 20555-0001

Subject: Licensee Event Report # 2004-004-00, "Emergency Diesel Generator Actuation from 480 VAC Safety Bus Undervoltage/Blackout Signal Due to Missing Tie Breaker Contact Fingers."

Dear Sir:

The attached Licensee Event Report (LER) 2004-004-00 is the follow-up written report submitted in accordance with 10 CFR 50.73. This event is of the type defined in 10 CFR 50.73(a)(2)(iv)(A) for an event recorded in the Entergy corrective action process as Condition Report CR-IP2-2004-05927.

There are no commitments made by the Licensee in the attached LER. Should you or your staff have any questions regarding this matter, please contact Mr. Patric W. Conroy, Manager, Licensing, Indian Point Energy Center at (914) 734-6668.

Sincerely,

A handwritten signature in black ink, appearing to read "Fred R. Dacimo".

Fred R. Dacimo
Site Vice President
Indian Point Energy Center

IE22

Attachment: LER-2004-004-00

cc:

Mr. Samuel J. Collins
Regional Administrator – Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406-1415

Resident Inspector's Office
U.S. Nuclear Regulatory Commission
Indian Point Unit 2
P.O. Box 59
Buchanan, NY 10511-0059

Mr. Paul Eddy
State of New York Public Service Commission
3 Empire Plaza
Albany, NY 12223-1350

INPO Record Center
700 Galleria Parkway
Atlanta, Georgia 30339-5957

LICENSEE EVENT REPORT (LER)

Estimated burden per response to comply with this mandatory collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME INDIAN POINT 2	2. DOCKET NUMBER 05000-247	3. PAGE 1 OF 6
---	--------------------------------------	--------------------------

4. TITLE Emergency Diesel Generator Actuation from 480 VAC Safety Bus Undervoltage/Blackout Signal Due to Missing Tie Breaker Contact Fingers

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV. NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
11	09	2004	2004	004	00	1	06	2005		05000
									FACILITY NAME	DOCKET NUMBER
										05000

9. OPERATING MODE 6	11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: <i>(Check all that apply)</i>																																				
10. POWER LEVEL 0%	<table style="width:100%; border: none;"> <tr> <td><input type="checkbox"/> 20.2201(b)</td> <td><input type="checkbox"/> 20.2203(a)(3)(i)</td> <td><input type="checkbox"/> 50.73(a)(2)(i)(C)</td> <td><input type="checkbox"/> 50.73(a)(2)(vii)</td> </tr> <tr> <td><input type="checkbox"/> 20.2201(d)</td> <td><input type="checkbox"/> 20.2203(a)(3)(ii)</td> <td><input type="checkbox"/> 50.73(a)(2)(ii)(A)</td> <td><input type="checkbox"/> 50.73(a)(2)(viii)(A)</td> </tr> <tr> <td><input type="checkbox"/> 20.2203(a)(1)</td> <td><input type="checkbox"/> 20.2203(a)(4)</td> <td><input type="checkbox"/> 50.73(a)(2)(ii)(B)</td> <td><input type="checkbox"/> 50.73(a)(2)(viii)(B)</td> </tr> <tr> <td><input type="checkbox"/> 20.2203(a)(2)(i)</td> <td><input type="checkbox"/> 50.36(c)(1)(i)(A)</td> <td><input type="checkbox"/> 50.73(a)(2)(iii)</td> <td><input type="checkbox"/> 50.73(a)(2)(ix)(A)</td> </tr> <tr> <td><input type="checkbox"/> 20.2203(a)(2)(ii)</td> <td><input type="checkbox"/> 50.36(c)(1)(ii)(A)</td> <td><input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A)</td> <td><input type="checkbox"/> 50.73(a)(2)(x)</td> </tr> <tr> <td><input type="checkbox"/> 20.2203(a)(2)(iii)</td> <td><input type="checkbox"/> 50.36(c)(2)</td> <td><input type="checkbox"/> 50.73(a)(2)(v)(A)</td> <td><input type="checkbox"/> 73.71(a)(4)</td> </tr> <tr> <td><input type="checkbox"/> 20.2203(a)(2)(iv)</td> <td><input type="checkbox"/> 50.46(a)(3)(ii)</td> <td><input type="checkbox"/> 50.73(a)(2)(v)(B)</td> <td><input type="checkbox"/> 73.71(a)(5)</td> </tr> <tr> <td><input type="checkbox"/> 20.2203(a)(2)(v)</td> <td><input type="checkbox"/> 50.73(a)(2)(i)(A)</td> <td><input type="checkbox"/> 50.73(a)(2)(v)(C)</td> <td><input type="checkbox"/> OTHER</td> </tr> <tr> <td><input type="checkbox"/> 20.2203(a)(2)(vi)</td> <td><input type="checkbox"/> 50.73(A)(2)(I)(B)</td> <td><input type="checkbox"/> 50.73(a)(2)(v)(D)</td> <td style="font-size: small;">Specify in Abstract below or in NRC Form 366A</td> </tr> </table>	<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)	<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER	<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(A)(2)(I)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	Specify in Abstract below or in NRC Form 366A
<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)																																		
<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)																																		
<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)																																		
<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)																																		
<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)																																		
<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)																																		
<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)																																		
<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER																																		
<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(A)(2)(I)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	Specify in Abstract below or in NRC Form 366A																																		

12. LICENSEE CONTACT FOR THIS LER

NAME Richard Schmitt, Maintenance Superintendent - Electrical	TELEPHONE NUMBER (Include Area Code) (914) 844-8476
---	---

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX
A	EB	BKR	W120	Y					

14. SUPPLEMENTAL REPORT EXPECTED <input type="checkbox"/> YES <i>(If yes, complete 15. EXPECTED SUBMISSION DATE)</i> <input checked="" type="checkbox"/> NO	15. EXPECTED SUBMISSION DATE						
	<table style="width:100%; border: none;"> <tr> <td style="font-size: small;">MONTH</td> <td style="font-size: small;">DAY</td> <td style="font-size: small;">YEAR</td> </tr> <tr> <td style="height: 20px;"></td> <td style="height: 20px;"></td> <td style="height: 20px;"></td> </tr> </table>	MONTH	DAY	YEAR			
MONTH	DAY	YEAR					

16. ABSTRACT *(Limit to 1400 spaces, i.e., approximately 15 single-spaced type written lines)*

On November 9, 2004, two of three emergency diesel generators (EDG) actuated during a refueling outage planned evolution to tie 480 VAC safety bus 3A to 480 VAC safety bus 6A. When the normal supply breaker to bus 6A was opened, an unexpected loss of power to 480 VAC safety bus 6A occurred. The de-energized bus 6A caused an undervoltage/blackout signal to be generated that automatically actuated 2 of 3 EDGs which started and powered their assigned safety buses (2A/3A, 5A). The EDG for bus 6A was out of service for planned maintenance and therefore remained de-energized. The 22 Residual Heat Removal (RHR) pump and 22 Spent Fuel Pool (SFP) pump were in service on bus 6A and were de-energized by the event. RHR cooling was restored in approximately 5 minutes and SFP cooling restored in approximately 39 minutes. All fuel assemblies were installed in the core but the reactor vessel head and upper internals were removed. Offsite power remained available. The cause of the event was missing primary disconnect contacts due to a failure to install them on bus tie breaker 52/3AT6A during preventive maintenance in March 2003 as a result of human performance (HP) error/inadequate work practices. Significant corrective actions included breaker removal, repair, reinstallation and testing; conducted a meeting with maintenance staff to review the event, discuss lessons learned and reinforce management's expectations on use of HP tools (i.e., self-checking, verification, questioning attitude, place keeping). Applicable procedures will be revised. The event had no effect on public health and safety.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Indian Point Unit 2	05000-247	2004	004	00	2 OF 6

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

Note: The Energy Industry Identification System Codes are identified within brackets { }

DESCRIPTION OF EVENT

On November 9, 2004, at 2339 hours, with the plant in a refueling condition and no core alterations in progress, two of three emergency diesel generators (EDG) of the emergency AC electrical power system {EK} actuated during a planned evolution, after a tie breaker {BKR} was used to tie two of three 480 VAC safety buses {ED} (bus 2A/3A, 5A, 6A) together. At 2338 hours, 480 VAC tie breaker 52/3AT6A was operated to tie 480 VAC safety bus 3A to 480 VAC safety bus 6A. When the normal supply breaker (fed from 138 KV offsite power) to bus 6A was opened at approximately 2339 hours, an unexpected loss of power to 480 VAC safety bus 6A occurred. The de-energized bus 6A caused an undervoltage/blackout signal to be generated which actuated the start and automatic loading of two of three EDGs (EDG-21 and EDG-22) in accordance with plant design. EDG 21 and 22 automatically started and powered 480 VAC safety buses. The EDG-23 for bus 6A was out of service for planned maintenance therefore bus 6A remained de-energized. At the time of the event, the 22 Residual Heat Removal (RHR) {BP} pump and 22 Spent Fuel Pool (SFP) {DA} pump were in service on bus 6A and were de-energized by the event. RHR cooling was restored in approximately 5 minutes and SFP cooling was restored in approximately 39 minutes. The redundant RHR and SFP pumps (21 RHR and 21 SFP pumps) were placed in service. RHR pump 21 was manually started because it only automatically connects with the 480 VAC safety bus on a Safety Injection signal. The SFP pump 21 was also manually started as the SFP pumps have no automatic start features. All fuel assemblies were installed in the core but the reactor vessel head and upper internals were removed and the reactor cavity was filled with water. On November 10, 2004, at 0058 hours, the plant was returned to its normal 480 VAC lineup. On November 10, at 0405 hours, an 8-hour non-emergency notification was made to the NRC for a valid actuation of the emergency AC electric power system under 10CFR50.72(b)(3)(iv)(A) (Event Log # 41187). The event was recorded in the IPEC corrective action program (CAP) as CR-IP2-2004-05927.

Tie breaker 52/3AT6A is a 480 VAC electrical bus tie breaker Model DB-75, manufactured by Westinghouse {W120}. An investigation into the cause of the event identified the following chronology of activities that resulted in the event:

March 19, 2003: maintenance performs breaker closeout section of Preventive Maintenance (PM) procedure (BRK-P-003-A) which includes 8 major steps including reinstallation of the primary disconnects with 4 of the 8 steps requiring QC verification. However, the primary disconnect installation step is the only major step in this section of the procedure that does not require a "perform" signature or "verification" signature. The maintenance mechanic fails to install the primary disconnects as required by procedure BRK-P-003-A, step 8.7.2. A final inspection is conducted and the breaker covered prior to returning it to operations for installation in the breaker cubicle.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Indian Point Unit 2	05000-247	2004	004	00	3 OF 6

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

March 20, 2003: Maintenance Supervisor signs procedure step 8.8.1 to indicate that the procedure is complete and all data recorded even though the breaker cleaning and breaker lubrication sections had not been signed.
 April 17-18, 2003: Operations removed the tag out for the tie breaker (52/3AT6A) and installs the breaker into the breaker cubicle. Operations installation procedure (OAP-037) check list contains an "as-found" inspection of the breaker cubicle, a visual inspection of the breaker and requires the breaker to be cycled. Under this check list, all DB-50 and DB-75 breakers, except for tie breakers, are required to be racked-in and its associated load started or energized. Operations backed the covered cart-mounted breaker into position in front of the breaker cubicle opening, removed the FME cover and failed to notice the missing primary disconnect contacts prior to inserting the breaker into the switchgear cubicle.

An extent of condition review was performed. Maintenance and Component Engineering determined that the condition only applies to 480 V tie breakers. Except for tie breakers, failures of this type are self-revealing as a result of energizing the connected load during post-maintenance testing. The remaining two Unit 2 480 VAC tie breakers were inspected and verified to have their primary disconnects installed. Unit 2 spare breakers staged for installation in the 480 V Switchgear Room were inspected to verify the presence of the primary disconnects. No discrepancies were identified.

CAUSE OF EVENT

The direct cause of EDG-21 and EDG-22 actuation and start was an undervoltage/blackout signal on 480 VAC safety bus 6A due to missing tie breaker 52/3AT6A primary disconnects when 480 VAC bus 3A was tied to 480 VAC bus 6A and normal bus 6A supply power was removed in a planned evolution. The absence of the primary disconnects for the breaker prevented the electrical circuit from energizing bus 6A from bus 3A when the tie breaker was closed.
 The root cause of the event was human performance (HP) errors/inadequate work practices. The HP errors were mainly due to the overconfidence of personnel performing repetitive tasks that resulted in ineffective application of error prevention tools to ensure attention to detail. The verification tools of self check, peer check, independent verification were not effective. The maintenance mechanic failed to verify the breaker maintenance was complete and that the primary disconnects were installed. The maintenance supervisor failed to verify that all steps in the work package were complete. Operations personnel failed to identify the missing breaker primary disconnects when the breaker was installed into the cubicle. Procedure place keeping techniques were not used. Maintenance mechanics did not use the recommended place keeping convention or any other equivalent method while using the breaker procedure. Questioning attitude challenges were not effective. The mechanics and supervisor failed to take appropriate actions to check the status of the assembled tie breaker when the primary disconnect parts were left over following completion of the breaker PM.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Indian Point Unit 2	05000-247	2004	004	00	4 of 6

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

A primary contributing cause was inadequate procedures. DB-75 Breaker PM procedure BRK-P-003-A does not contain appropriate verification hold points (e.g., verify that all breaker deficiencies have been resolved and that the breaker has been reassembled, verify that all steps have been completed and that the breaker is complete and ready to be placed in service). In addition, the procedure does not have good procedure place keeping features (i.e., signoff provisions at each step). Maintenance procedure BRK-P-003-A and Operations procedure OAP-037, "Operations Electrical Equipment Operating Guidelines," do not include specific precautions or additional enhancements for the tie breakers that may be appropriate because they cannot be retested in the conventional manner as all breakers.

CORRECTIVE ACTIONS

The following corrective actions have been or will be performed under the CAP to address the causes of this event and prevent recurrence.

- Tie breaker 52/3AT6A was removed from the cubicle and the missing primary disconnects reinstalled, an inspection was performed and the breaker reinstalled and tested.
- Maintenance performed a stand down meeting with maintenance staff to discuss the event and lessons learned and to reinforce management's expectations on use of HP tools (i.e., self-checking, verification, questioning attitude, place keeping). The Maintenance Superintendent and Human Performance Manager interviewed the individuals responsible for the breaker task to review the human performance factors associated with the event and reinforce management's expectations by reminding the individuals of the importance of situational awareness, effective communication, and a questioning attitude. The Station Event-Free Clock was reset and an Entergy Red Memo issued to provide site wide notification of the event and the lessons learned.
- Operations prepared a Shift Order discussing the lessons learned from the event with Operations crews emphasizing the role of the Nuclear Plant Operator (NPO) as the last line of defense in catching anomalies prior to breaker installation.
- The Breaker Procedure involved in this event (BRK-P-003-A) was revised to include proper place keeping provisions for each step and signoff verification based on EPRI recommendations, including installation of the primary disconnects. The revision also recognized the inability to fully test the tie breakers and provides additional appropriate precautions and reference to the lessons learned from this event. The procedure revision was completed on December 29, 2004.
- The appropriate breaker procedures will be revised to upgrade their format according to the latest procedure Writer's Guide. Procedure enhancement will include appropriate place keeping and verification features, incorporate lessons learned from the event and steps to verify installation of primary disconnects. Procedure revisions are scheduled to be complete by March 15, 2005.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
Indian Point Unit 2	05000-247	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	5 of 6
		2004	004	00	

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

- Operation's procedure OAP-037, "Operations Electrical Equipment Operating Guidelines," will be revised to provide inspection of primary disconnects for proper installation, a visual check for missing parts, and a note to remind the NPO that a visual pre-installation inspection is critical for tie breakers since they can not be re-tested. Procedure revisions are scheduled to be complete by March 15, 2005.

EVENT ANALYSIS

The event is reportable under 10CFR50.73 (a) (2) (iv) (A). The licensee shall report any event or condition that resulted in manual or automatic actuation of any of the systems listed under 10CFR50.73 (a) (2) (iv) (B). Systems to which the requirements of 10CFR50.73 (a) (2) (iv) (A) apply include the emergency AC electrical power systems (EDGs). This event meets the reporting criteria because two of three EDGs actuated from a undervoltage/blackout signal on 480 VAC safety bus 6A and energized their associated buses.

PAST SIMILAR EVENTS

A review of the previous two years of Licensee Event Reports (LERs) for events that involved an actuation of the EDGs due to undervoltage as a result of human error (HE) did not identify any applicable LERs. LER-2002-006 reported a TS prohibited condition caused by two inoperable EDGs due to EDG component failure. Component failures were not a direct result of HE. LER-2002-003 reported a loss of 138 KV preferred offsite power that de-energized 480 V safety buses 5A and 6A. Two of three EDGs started as EDG-21 was inoperable for maintenance. Cause of event was a HE for a worker performing unauthorized activities that resulted in grounding of the 138 KV C-phase conductor for normal off-site power. Corrective actions for these events would not have prevented this event.

SAFETY SIGNIFICANCE

This event had no effect on the health and safety of the public. There were no actual safety consequences for the event because two of three EDGs were operable in accordance with plant Technical Specifications and automatically started per plant design and energized their assigned safety buses (480 VAC buses 5A and 2A/3A). Redundant safety components for forced core cooling and SFP cooling (21 RHR and 21 SFP pumps) were placed in service using their assigned safety power source. In addition, the decay heat load in the reactor core was reduced and the heat sink for core cooling increased as the reactor cavity was filled with water for refueling activities. The reactor core had approximately a third of the core with new fuel assemblies which have no heat load and with the reactor vessel head still removed, the core had a large reactor cavity water inventory thereby increasing the time available to respond to the event. RCS forced core cooling was restored in approximately 5 minutes and SFP cooling was restored in approximately 39 minutes.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Indian Point Unit 2	05000-247	2004	002	00	6 of 6

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

The event occurred at 2339 hours, on November 9, 2004, and RHR pump 21 placed in service at approximately 2345 hours. Reactor cavity water temperature was approximately 94 degrees F. On November 10, 2004, at 0018 hours, the 21 SFP pump was placed in service. The SFP temperature was 99 degrees. At the time of the event, approximate time to boil for the reactor coolant system (RCS) was 12 hours, and for the SFP approximately 25 hours. This event is well below the temperature and time limits for restoring cooling to the RCS and SFP. The time that RCS cooling was restored (approximately 5 minutes) was well within the available time to restore forced RCS cooling (12 hours). FSAR Section 9.3.3.2.3, discusses the loss of SFP heat removal at a maximum SFP water temperature of 180 degrees, and concludes the time to rise to 212 degrees is 1.8 hours. This FSAR time (1.8 hours) and the time to boil (25 hours) bound the actual time the SFP was without cooling (approximately 39 minutes). Adequate operator response time was available to mitigate the event.

There were no significant potential safety consequences of this event under reasonable and credible alternative conditions. The loss of power to 480 VAC safety bus 6A would be bounded by a loss of off-site power (LOOP) event as analyzed in FSAR Section 14.1.12, "Loss of all AC Power to the Station Auxiliaries." The plant is designed for a LOOP and has safety related emergency AC power by EDGs to start on a 480 VAC safety bus undervoltage/blackout signal and power the 480 VAC safety buses (2A/3A, 5A, 6A). Plant operation in accordance with Technical Specification (TS) 3.8.1, AC Sources Operating (Modes 1, 2, 3 and 4), Limiting Condition for Operation (LCO) require two offsite AC sources and three operable EDGs, any two EDGs of which can supply power to one minimum required set of safeguards equipment (e.g., RHR pump). TS 3.8.9 Basis (Distribution Systems-Operating) requires tie breakers between redundant safety related AC, DC and 118 VAC instrument bus power distribution subsystems to be open (Modes 1,2, 3 and 4). A single failure is considered when evaluating the ability to meet the design of electrical power systems. The inability to power safeguards bus 6A is bounded by the single failure and therefore adequate power remained available for postulation of this type of event. During plant shutdown (Modes 5 and 6), TS 3.8.2 (AC Sources-Shutdown) requires one offsite AC power source and two EDGs to be operable. TS 3.8.2 Basis states it is acceptable for safeguards power trains to be cross tied during shutdown conditions and notes for the shutdown/refueling condition (Modes 5 and 6), that assuming a single failure and concurrent loss of all offsite or all onsite power is not required. One EDG has sufficient capacity to support required actions that may be needed in response to any event that might occur during refueling operations. For this event, the plant retained adequate emergency AC power with two operable EDGs and one offsite power supply.