


Nuclear Fuel Update

Palo Verde Nuclear Generating Station

December 9, 2004
Meeting with US NRC



NUCLEAR FUEL MANAGEMENT 2004



Review of 2003-4

- ◆ **March 2003 Meeting with NRR**
- ◆ **CENTS Implementation**
- ◆ **Steam Generator Replacement**
- ◆ **Power Uprate**
- ◆ **CPC Replacement**
- ◆ **Dry Cask Storage in Production**



Agenda Today

- ◆ **Fuel Performance**
- ◆ **Considering Dual LTA Program**
- ◆ **CEA Replacement**
- ◆ **Planned License Submittals**
- ◆ **Dry Cask Storage Update**



Palo Verde Fuel Performance



Fuel & Clad Performance

Clad Performance
Uprate Conditions
High Burnup Leakers
Fabrication Issues



Integrated Fuel Performance

- ◆ **Clad Performance Strategy:**
 - Advanced Clad Alloys
 - Primary Chemistry
 - CRUD/Oxide Software
 - Low Duty Core Designs
- ◆ **Multi Phase Performance Program**
 - 3876 MW and 3990 MW Conditions
- ◆ **Long Range Fuel Inspection Plan**




Early Learnings in Fuel Performance

- ◆ **Evolution of Core Design Strategies**
 - Low Leakage Checkerboards
 - Feed-Face-Feed Strategies
 - Modified Checkerboards
- ◆ **Unit 2 Cycle 9**
 - Axial Offset Anomaly (CIPS)
 - Fuel Failures
- ◆ **Cause of CRUD and Oxidation**
 - Different Fuel Duty Cycles
 - Different Solutions




Clad CRUD in Unit 2 Cycle 9

P2L5xx Assembly Face



The Two Duty Cycles

Typical (U2C13) Core Design



Fuel Performance in Uprate Conditions

- ◆ **3% Power and $\sim 2^{\circ}\text{F}$ Inlet Temperature**
- ◆ **New Steam Generators**
- ◆ **Increased Clad Oxidation**
 - Spallation Risk
- ◆ **Increased Steaming Rate**
 - Each 1°F or 1% Power is Worth 10% Steaming Rate
 - Higher Source Term from New Steam Generators
 - CRUD & AOA Risk



ZIRLO™ Clad


- ◆ **Westinghouse Low Tin Zirconium Based Alloy**
- ◆ **First Implementation in Unit 2 Cycle 11**
 - **Protect High Duty 2 Cycle Assemblies**
- ◆ **Licensing Limitation**
 - **Fuel Duty Index**
 - **Maximum Oxide Thickness**
- ◆ **2R11 Inspection Results**
 - **Performance as Expected**







New Lattice Design

- ◆ **First Implementation in Unit 2 Cycle 12**
 - Protect High Duty First Burn Assemblies
- ◆ **Design Concept – Balance Power & Flow**
 - In-House Designed Based on APS CRUD Model
 - Three Enrichments, Four Pin Types
- ◆ **Extensive Design Review**
 - In-House, Westinghouse, URA


Crud Model Development



Crud Model Results



Crud Model Results




Revised Lattice Design Objectives

- ◆ **Smallest Change Possible**
- ◆ **Change Only Well Understood Lattice Feature(s)**
- ◆ **No Operational, Licensing, Manufacturing Impact**
- ◆ **Minimal Safety Analysis Impact**




Sample Lattice Comparison



Previous - 64 Er


- 4.05 w/o
- 3.75 w/o
- 3.75 w/o Er




New - 64 Er

- 4.29 w/o
- 3.99 w/o
- 3.79 w/o
- 3.79 w/o Er


Pin Power Comparison



New Lattice CRUD Impact



Comparison of Average Crud Thickness - Predicted



Long Term Fuel Inspection Program

- ◆ **Proof of Design Concept**
 - Davis-Besse: “I know because I looked”
- ◆ **Zirlo**
- ◆ **New Lattice**
- ◆ **Other Planned Inspections**
 - Assembly Bow
 - Top Grid



Flawless Fuel

- ◆ **New Agreement with Westinghouse**
 - Identify and Investigate All Failures
 - Incentive for Flawless Fuel
 - Reconstitute Failed Assemblies
- ◆ **Sipping in Containment**
- ◆ **UT in Spent Fuel Pool**



High Burnup Fuel Performance

High Burnup Fuel Failure Trend

Loose Top Grid Cells

Top Grid Re-Design




High Burnup Fuel Failure Trend

- ◆ Mid 90's, Clean Cores Cycle After Cycle
- ◆ Ten Failed First Burn Pins in U2C9
- ◆ One Failed End Cap Weld (U1C9)
- ◆ Nine Indications Starting with U2C9
- ◆ Five of Nine Cycles with 1 or 2 Indications
- ◆ UT Has Failed Repeatedly to Locate Rods
- ◆ Three Identified Grid-Rod Fretting Failures



Figure 4.5.9 Assembly P2L108, Rod I10 – Through-Wall Spring (top) and Back-Up Arch (bottom) Wear Scars on 90° Face at Grid 10




Loose Top Grid Cells

- ◆ **PV1P Fabrication Campaign**
- ◆ **Description of Rod Support Features**
- ◆ **Root Causes**
 - **Bias in Grid Construction Tolerances**
 - **Force-Fit of 20 mil Oversize Guide Tube**
 - **Rod Pushing Table Mis-Alignment**
 - **Weaknesses in Inspection/QA Process**




Loose Grid Cells & Grid-Rod Fretting

Current Zircaloy Top Grid



Current Zircaloy Top Grid




Top Grid Re-Design

- ◆ **Zirc-4 to Inconel 625**
- ◆ **Wavy strip to Straight Strip**
- ◆ **Cantilever Spring Cut-out**
- ◆ **Double Back-up Arch**
- ◆ **Accommodation of Expanded Guide Tube**
- ◆ **Grid to Guide Tube Attachment**
- ◆ **Change to “Top Nozzle” (UEF)**
 - **Assembly Length Measurements Spring 2005**



Proposed Inconel Top Grid



Dual LTA Program



Long Term Fuel Design Strategy

- ◆ **Fuel Contract Timeline**
 - 12 Years on Westinghouse Contract
- ◆ **LTAs Needed to Demonstrate New Design**
 - 8 Assembly, 3 Cycle LTA Programs
- ◆ **AREVA and Westinghouse Designs**
 - No Current Disaster Back-up to Columbia
 - More Options Lead to Better Designs
- ◆ **Starts 2005**



Specific Fuel Design Goals

- ◆ **Materials for Higher Burnup/Duty**
 - Cladding Oxidation
 - Dimensional Stability
- ◆ **“Mixing” Grids**
 - Minimize CRUD
 - Increase Thermal Margin
- ◆ **Preserving/Increasing Operating Margins**
- ◆ **Improve Fuel Utilization**
- ◆ **Overall Robust Design for Flawless Fuel**



CEA Replacement



CEA Replacement

- ◆ **Review CEA History**
- ◆ **Determination of New, Conservative Lifetime**
- ◆ **Design of New Replacement CEAs**
- ◆ **Replacement of PLCEAs**




Review of CEA History

- ◆ **CEA Clad Failures Observed - 2001**
 - Cracks in High Fluence CEA Tips
 - Root Cause - IASCC, Inadequate Testing
 - U2/U3 With Small Pellet Less Severe
- ◆ **All Full Length CEAs Replaced**
 - Replaced by Design with Smallest Pellet
- ◆ **Lifetime Software Abandoned**

Control Element Assemblies

- ◆ 89 CEAs in 8 groups
 - 148 inches of B_4C poison
- ◆ 4-finger and 12-finger assemblies
 - B_4C wrapped in “Feltmetal” at bottom 8%
 - 12-finger CEAs span 5 assemblies
 - 688 total fingers



Determination of New Lifetime

- ◆ Investigated Various Options
 - ◆ Monitored YGN Inspections
 - ◆ Vendor Adjusted Software
 - ◆ Inconel IASCC Threshold
 - ◆ Observed Crack in U2C8 CEA
- ⇒ **5 Cycle Lifetime**
- ⇒ **Need New CEAs for Fall 2008**

Design of Future CEAs

- ◆ **Now: Unique Feltmetal Design**
- ◆ **Want:**
 - Industry Standard AgInCd
 - Extended Tip Region
- ◆ **CEDM Weight Restrictions**
 - AgInCd Tip Region
 - Boron Carbide for Remainder
- ◆ **Lifetime Issues Remain**
 - 20 EFPY Design Lifetime
 - ~12 EFPY Experience Base


Replacement of PLCEAs

- ◆ **Original Equipment**
 - Part Length, Part Strength
 - Not Subject to Same Failure Mode
 - Replacing Now for Prudence
- ◆ **Replacements**
 - Full Length, Part Strength
 - Transparent to Safety Analysis
 - Tech Spec Change Approved
- ◆ **U1 Done -- U3 Done -- U2 Spring 2005**



New Design PSCEAs

Comparison of Part Strength CEAs



Planned License Submittals



2005 License Submittals

- ◆ (U1 & U3 Power Up-Rate in Review)
- ◆ TS 3.1.6
Shutdown CEA Insertion Limits
- ◆ TS 5.6.5
Core Operating Limits Report



Shutdown CEA Insertion Limits

- ◆ **Current T.S. allows insertion to 144.75" withdrawn**
 - 6.2" into active fuel
- ◆ **Safety Analysis only covers insertion to 147.75"**
 - 3.2" into active fuel
- ◆ **Shutdown Margin is monitored per Core Data Book**
 - 147.75" withdrawn, forces higher boron concentration
- ◆ **T.S. 3.1.6 rewritten to reference COLR**
 - Shutdown CEA COLR based on 147.75



Core Operating Limits Report

- ◆ **One Inconsistent Reference**
 - CEA Drop Methodology Reference
- ◆ **Currently Evaluating Changes**
 - Update CEA Drop Reference
 - Remove CESSAR References
 - Update to Power Uprate SER

