1650 Calvert Cliffs Parkway Lusby, Maryland 20657



March 31, 2005

U.S. Nuclear Regulatory Commission Washington, DC 20555

ATTENTION: Document Control Desk

 SUBJECT:
 Calvert Cliffs Nuclear Power Plant

 Unit No. 1; Docket No. 50-317; License No. DPR 53
 Licensee Event Report 2005-001

 Main Feedwater Isolation Valve Inoperability Due to Handswitch Wiring

The attached report is being sent to you as required under 10 CFR 50.73 guidelines. The condition was discovered on April 10, 2004, but not identified as a reportable condition until February 2, 2005. Should you have questions regarding this report, we will be pleased to discuss them with you.

Very truly yours,

for David A. Holm Plant General Manager

DAH/MJY/bjd

Attachment: As stated

cc: R. V. Guzman, NRC S. J. Collins, NRC Resident Inspector, NRC R. I. McLean, DNR

TEDD

NRC FORM 366 U.S. NUCLEAR REGULATORY COMMISSION					APPROVED BY OMB: NO. 3150-0104 EXPIRES: 06/30/2007										
(See reverse for required number of					Estimated burden per response to comply with this mandatory collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the										
1 FACU		ME	13/01/212						Information collection.						
Calve	ert Cli	ffs Nucl	ear Pow	ver Plant, U	nit 1				05	5000 317		1	OF 00	5	
4. TITLE Main	4. TITLE Main Feedwater Isolation Valve Inoperability Due to Handswitch Wiring														
5. E	VENT D	ATE	6. 1	ER NUMBER		7. R	EPORT	DATE		8.	OTHER FAC	CILITIES INV	DLVED		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	rev No.	MONTH	DAY	YEAR	FACILIT				DOCKET	NUMBER 00	
04	10	2004	2005	- 001 -	00	03	31	2005	FACILIT	YNAME			DOCKET	NUMBER 00	
9. OPER	ATING	MODE	11	THIS REPOR	RT IS	SUBMITTI	ED PURS	UANT T	O THE R	EQUIREM	ENTS OF 10	CFR§: (Che	ck all that	apply)	
5 20.2201 5 20.2203 20.2203 10. POWER LEVEL 20.2203 20.203			201(b) 201(d) 203(a)(1) 203(a)(2)(i) 203(a)(2)(ii) 203(a)(2)(iii) 203(a)(2)(iv) 203(a)(2)(v) 203(a)(2)(vi)	 20.2203(a)(3)(i) 20.2203(a)(3)(ii) 20.2203(a)(4) 50.36(c)(1)(i)(A) 50.36(c)(2) 50.46(a)(3)(ii) 50.73(a)(2)(i)(A) 50.73(a)(2)(i)(B))(3)(i))(3)(ii))(4))(i)(A))(ii)(A))(ii))(ii))(i)(A))(i)(B)		□ 50.73(a)(2)(i)(C) □ 50.73 □ 50.73(a)(2)(ii)(A) □ 50.73 □ 50.73(a)(2)(ii)(B) □ 50.73 □ 50.73(a)(2)(ii)(B) □ 50.73 □ 50.73(a)(2)(ii)(A) □ 50.73 □ 50.73(a)(2)(iv)(A) □ 50.73 □ 50.73(a)(2)(v)(A) □ 73.71 □ 50.73(a)(2)(v)(C) □ OTHI □ 50.73(a)(2)(v)(C) □ OTHI □ 50.73(a)(2)(v)(D) Specitor or in N			3(a)(2)(vii) 3(a)(2)(vii) 3(a)(2)(vii) 3(a)(2)(ix) 3(a)(2)(ix) 3(a)(2)(x) 1(a)(2)(x) 1(a)(4) 1(a)(5) IER ify in Abstra NRC Form	(a)(2)(vii) (a)(2)(viii)(A) (a)(2)(viii)(B) (a)(2)(ix)(A) (a)(2)(x) (a)(4) (a)(5) :R y in Abstract below RC Form 366A		
					1	2. LICENS	SEE CON	TACT FO	DR THIS	LER					
FACILITY N. Michae	ame I J. Yo	ox, Senie	or Engi	neering Ana	alyst						TEL 41	ерноне нимве 0-495-6652	R (Include Ar 2	ea Code)	
			13. COM	PLETE ONE I	INE F	OR EACH	I COMPC	NENT F	AILURE	DESCRIB	ED IN THIS I	REPORT			
CAUS	SE	SYSTEM	COMPO	NENT MAN FACTU	U- RER	REPOR TO E	RTABLE EPIX	C4	USE	SYSTEM	COMPONEN	T MANU- FACTURER	REPO	ORTABLE DEPIX	
А		SJ	ISV	7 V08	35	Ŋ	{								
	14. SUPPLEMENTAL REPORT EXPECTED					NO	15. E SUB	XPECTED MISSION DATE	MONTH	DAY	YEAR				
ABSTRA	CT (Lin	it to 1400	spaces, i	.e., approxima	tely 1	5 single-sp	paced typ	ewritten l	ines)						
On April 10, 2004, with Unit 1 shutdown in Mode 5, the 12 Main Feedwater Isolation Valve,															

1-FW-4517-MOV, failed to shut on Steam Generator Isolation Signals (SGIS) during performance of surveillance test procedures. Additional surveillance testing revealed the valve also would not operate upon receipt of a Containment Spray Actuation Signal (CSAS). Investigation and troubleshooting into the cause of the malfunction determined that a lead was terminated at the wrong location on the handswitch for 1-FW-4517-MOV. The handswitch, 1HS4517, is located on Control Panel 1C03 in the Control Room. The improperly wired handswitch caused an open electrical circuit for the 1-FW-4517-MOV SGIS/CSAS functions. The lead was relocated to the proper terminal and subsequent testing of 1-FW-4517-MOV was satisfactorily performed on April 10, 2004.

The improperly wired handswitch termination was the result of Human Performance errors, which directly challenged the operability of 1-FW-4517-MOV. Calvert Cliffs Nuclear Power Plant addressed an overall weakness in Human Performance with a site-wide initiative. Procedure changes have also been implemented to allow the use of ring-tongue lugs when performing wire terminations on new or re-worked wiring during maintenance in control panels.

NRC FORM 366AU.S. NUCLEAR REGULATORY COMMISSION (1-2001) LICENSEE EVENT REPORT (LER)							
1. FACILITY NAME	1. FACILITY NAME 2. DOCKET 6. LER			ER NUMBER			E
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
CALVERT CLIFFS, UNIT 1	05000 317	2005	- 001 -	00	02	0 F	005

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

I. DESCRIPTION OF EVENT

On April 10, 2004, with Unit 1 shutdown in Mode 5, the 12 Main Feedwater Isolation Valve, 1-FW-4517-MOV, failed to shut on the "A" Steam Generator Isolation Signal (SGIS) during performance of Surveillance Test Procedure STP-O-56A-1. The valve also failed to shut on the "B" SGIS during the subsequent performance of STP-O-56B-1. Surveillance testing under STP-O-69-1 also revealed that the valve would not operate on receipt of a Containment Spray Actuation Signal (CSAS). Investigation and troubleshooting into the cause of the malfunction determined that a lead was terminated at the wrong location on the handswitch for 1-FW-4517-MOV. The handswitch for 1-FW-4517-MOV, 1HS4517, is located on Control Panel 1C03 in the Control Room. The improperly wired handswitch caused an open electrical circuit for the 1-FW-4517-MOV SGIS/CSAS functions. Manual operation of 1-FW-4517-MOV via handswitch 1HS4517 was not compromised by this condition. The lead was relocated to the proper terminal and subsequent testing of 1-FW-4517-MOV was satisfactorily performed on April 10, 2004.

Further investigation determined that 1-FW-4517-MOV was last tested successfully on February 19, 2002, during the previous Unit 1 Refueling Outage. No other structures, components, or systems were inoperable at the start of this event that would have contributed to or influenced the event.

The main feedwater isolation valves (MFIVs) function, upon receipt of an SGIS or CSAS, to limit the inventory added to the steam generator following a high energy line break (HELB). Limiting the inventory to the steam generator provides protection by limiting the energy released to the Containment Building, thereby limiting containment pressure after an HELB. Closure of the MFIVs effectively terminates the addition of feedwater to an affected steam generator, limiting the mass and energy release for feedwater line or steam line breaks inside the Containment Building, and reducing cooldown effects for steam line breaks. The MFIVs close on receipt of an SGIS generated by low steam generator pressure and upon receipt of a CSAS. The wiring deficiency identified in this event challenged this safety function.

This was a self-revealing issue that was identified through required surveillance testing. Unit 2 was not impacted by this event, as evidenced by the last successful completion of STP-O-56A-2 and STP-O-56B-2 on February 15, 2003.

NRC FORM 366AU.S. NUCLEAR REGULATORY COMMISSION (1-2001) LICENSEE EVENT REPORT (LER)								
1. FACILITY NAME	2. DOCKET	6. LER NUMBER				3. PAGE		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		_		
CALVERT CLIFFS, UNIT 1	05000 317	2005	- 001 -	00	03	O F	005	

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

II. CAUSE OF EVENT

The root cause of the improperly wired handswitch termination was Human Performance errors, which directly challenged the operability of 1-FW-4517-MOV. Specific contributors to the Human Performance aspect of this event are as follows:

- 1. A lack of proper application of Human Performance Event Free Tools ("Stop, Think, Act, and Review" Method, Peer Checks, and Independent Verification) prevented identification and restoration of the improperly wired lead in the correct location.
- 2. Supervision was not informed of the potential problem when the wire in question came out of the compression termination during earlier maintenance. This failure prevented supervision from providing direction or guidance at the time the error was first identified.
- 3. The initial error in the wiring was not detected because the Post-Maintenance Operational Test did not verify the CSAS/SGIS isolation function prior to returning the valve to service after the 2002 refueling outage.
- 4. The cluttered and congested layout of the wiring underneath Control Room Panel 1C03 resulted in challenges to error free preventive and corrective maintenance when work was performed inside the panel.

III. ANALYSIS OF EVENT

This event is reportable in accordance with the following:

10 CFR 50.73(a)(2)(i)(B); "Any operation or condition which was prohibited by the plant's Technical Specifications."

Technical Specification 3.7.15, Main Feedwater Isolation Valves (MFIVs), Limiting Condition for Operation (LCO) states, "Two MFIVs shall be OPERABLE." Condition A of this Technical Specification allows one or more MFIVs to be inoperable for up to 72 hours while in Modes 1, 2, or 3. Condition B then requires action to reach Mode 3 within 6 hours and Mode 4 within 12 hours. The inability of 1-FW-4517-MOV to close on a SGIS caused the valve to be inoperable from June 16, 2002 until Unit 1 was shutdown and entered Mode 4 on April 10, 2004 for refueling. Unit 1 exceeded the LCO for inoperable MFIVs 72 hours after entering Mode 3 on June 16, 2002 at 0021 hours.

The safety function of the MFIVs is to provide isolation of the main feedwater flow in the event of a HELB upstream of the main steam isolation valves or downstream of the MFIVs. This function can still be maintained by other components in the Main Feedwater System in the event of a challenge to MFIV operability. While these components are not typically credited in the Updated

NRC FORM 366AU.S. NUCLEAR REGULATORY COMMISSION (1-2001) LICENSEE EVENT REPORT (LER)								
1. FACILITY NAME	2. DOCKET	6. LER NUMBER				3. PAGE		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER				
CALVERT CLIFFS, UNIT 1	05000 317	2005	- 001 -	00	_04	0 F	005	

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

Final Safety Analysis accident analyses, they can be credited when considering safety function operability. Specifically, the main feedwater regulating valves will ramp closed upon a reactor trip signal. The main feedwater bypass valves will open and allow a small (approximately 3.8% of full flow) amount of flow. Additionally, the steam generator feed pumps will be isolated from steam pressure by the main steam isolation valves and will receive a trip signal from SGIS. This combination of additional valve operation and the loss of motive force to the steam generator feed pumps ensures that the safety function of main feedwater flow isolation is maintained. A probabilistic risk assessment of this event determined that the failed automatic closure of 1-FW-4517-MOV would increase the Unit 1 core damage frequency approximately 1.5E-08 per year (very low safety significance).

No significant safety consequences resulted from this event. At no time during the period of inoperability did the lack of automatic closure of 1-FW-4517 result in a challenge to plant operations or safety limits.

IV. CORRECTIVE ACTIONS

- A. Calvert Cliffs Nuclear Power Plant addressed an overall weakness in Human Performance with a site-wide initiative. This initiative included the creation of a group of interdepartmental procedures addressing specific Human Performance attributes. Specific tools and verification practices were put in place in an effort to reverse the declining trend observed site wide in Human Performance. Additional controls and expectations were implemented to improve pre-job briefings and post-job critiques. A direct result of these initiatives has been a site wide improvement in human performance, as noted by both NRC and Institute of Nuclear Power Operations evaluation results.
- B. The Human Performance Procedures also have established the expectation that workers stop and notify supervision when off-normal or unexpected conditions arise.
- C. Industry best practices have been benchmarked and incorporated into site procedures for functional testing.
- D. Procedure changes have been implemented to allow the use of ring-tongue lugs when performing wire terminations on new or re-worked wiring during maintenance in control panels.

NRC FORM 366AU.S. NUCLEAR REGULATORY COMMISSION (1-2001) LICENSEE EVENT REPORT (LER)								
1. FACILITY NAME	2. DOCKET	6. LER NUMBER	3. PAGE					
		YEAR SEQUENTIAL REVISION						
CALVERT CLIFFS, UNIT 1	05000 317	2005 - 001 - 00	05 F 005					

r.

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

V. ADDITIONAL INFORMATION

A. Component Identification

ъ **ў**

Component	IEEE 803 EIIS Function	IEEE 805 System ID
Main Feedwater Isolation Valve (1-FW-4517-MOV)	ISV	SJ
Main Feedwater Header Check Valve (1-CKVFW-130)	VLV	SJ
12 Feedwater to Steam Generator Isolation Valve Handswitch (1HS4517)	HS	SJ
Condensate and Feedwater Control Panel (1C03)	PL	JL
Main Steam Isolation Valve	ISV	SB
Steam Generator Feed Regulating Valve	FCV	SJ
Steam Generator Feed Regulating Bypass Valve	FCV	SJ
Steam Generator Feedwater Pump	Р	SJ

B. Previous Occurrences

No other previous similar events have occurred within the past three years.