

Final Precursor Analysis

Accident Sequence Precursor Program --- Office of Nuclear Regulatory Research

Nine Mile Point Unit 1	Degraded Piping in Reactor Building Closed Loop Cooling System	
Event Date: 03/07/2003	NRC Special Inspection Report 220/03-003	Importance = 4.2E-06

March 14, 2005

Condition Summary

Description. From February 10, 2003, to March 7, 2003, the NRC conducted a special inspection of the Nine Mile Point Nuclear Station - Unit 1, with regard to degraded piping in the reactor building closed loop cooling (RBCLC) system (Reference 1). This special inspection followed three shutdowns from power operation to repair leaks in the RBCLC system within an 8-month period. The shutdowns for piping repair occurred as follows:

May 14-19, 2002	Repaired two RBCLC leaks
Dec 5-11, 2002	Repaired one RBCLC leak
Dec 13-24, 2002	Repaired one RBCLC leak

The RBCLC system is a safety-related, risk-significant system that is required to operate during normal plant operation and accident conditions. The loss of the RBCLC system would result in the loss of cooling to several other systems and their subsequent failure. Major components supplied by the RBCLC system include the instrument air compressors (2 out of 3), the high- pressure injection system (i.e., feedwater pumps, feedwater booster pumps, and condensate pumps), control room air conditioning equipment, shutdown cooling heat exchangers, reactor recirculation pump coolers, drywell air coolers, reactor building equipment drain tank cooler, and fuel pool heat exchangers.

The NRC special inspection team determined that degraded piping in the RBCLC system was extensive. For example: the special inspection team learned that a full section of RBCLC piping was able to be manually broken apart following removal by maintenance personnel. Also, during the numerous repairs of piping during shutdowns, the licensee had discovered notable and widespread wall thinning in RBCLC piping sections, which were most severe at threaded mechanical connections. The NRC team determined that the licensee's structural analysis did not provide evidence that the as-found condition of the degraded piping in the RBCLC system retained sufficient strength. Consequently, the structural integrity of the affected RBCLC system piping may not have been maintained when subjected to design loading conditions. The special inspection team concluded that the initiating event frequency for a loss of RBCLC had been increased over its nominal value and that other initiating events [loss-of-coolant accidents (LOCAs) and loss of all electrical ac power], if they occurred, would induce piping failures in the RBCLC system.

Cause. The NRC special inspection team's review of the events determined that the root and contributing causes for the degraded piping included inadequate system design, inadequate corrective actions, and degraded RBCLC system water chemistry.

Time period/condition duration. This event was analyzed as a condition assessment.

The degraded condition of the RBCLC piping existed over a period of years. Prior to 2002, there had been numerous small bore piping leaks within the RBCLC system at threaded mechanical joints. Also, around May 2000, chloride and sulfate concentrations in the RBCLC system were found to be elevated. Near the same time, RBCLC system oxygen levels were found to be significantly below normal levels, and iron particulate levels were high. These parameters indicated an increased corrosion rate; however, efforts to identify the cause and correct the abnormal chemistry parameters were unsuccessful.

Per accident sequence precursor guidelines, the maximum time for evaluation of a condition assessment is 1 year. Therefore, the time period from March 7, 2002, to March 7, 2003, was used for this condition assessment. The total time for the condition assessment was assumed to be 8760 hours even though the unit was shut down for approximately 29 days during the time period.

There were three times during the 1-year period that overlapping unavailabilities occurred with respect to other equipment.

Period 1

From September 24, 2002, to October 19, 2002 (390 hours), the #12 control rod drive (CRD) pump was unavailable as described in LER 220/02-002, "Loss of One Control Rod Drive Pump due to Circuit Breaker Failure," (Reference 2) and NRC Integrated Inspection Report 05000220/2003004 (Reference 3).

Period 2

On November 1, 2002, for an 8-hour period, the potential existed for any trip of the reactor to cause a loss of offsite power (LOOP) as described in LER 220/02-001, "115 kilovolt Offsite Power Inoperable Due to Low Voltage on Line 4 and Line 1 Out of Service" (Reference 4).

Period 3

For the entire period, no credit could be taken for the condensate system following failure of the high-pressure injection system. In Reference 5, the NRC discovered that EOP-2 did not address a hardware interlock and the steps necessary to bypass the interlock in order to be able to use the condensate system should no feedwater pumps be available.

Recovery opportunities. No recovery of the RBCLC system following a postulated break in RBCLC piping was assumed in the condition assessment. The basis for this assumption comes from Reference 1, in the section *Risk Significance and Analysis of the Event*.

"Assumption #5: Failure of the RBCLC piping would result in system leakage in excess of the automatic makeup capability for the system. Consequently, the RBCLC expansion tank level would be lost and the operating RBCLC pumps would fail due to inadequate net positive suction head (NPSH).

The team did not credit recovery of the RBCLC system because under certain entry conditions, Annunciator Response Procedure N1-ARP-H1, 'Control Room Panel H1,' directed the starting of the standby RBCLC pump; and Annunciator Response Procedure N1-ARP-H1, Special Operating Procedure N1-SOP-8, 'RBCLC Failure,' and Operating Procedure N1-OP-11, 'Reactor Building Closed Loop Cooling System,' did not provide guidance to secure the operating RBCLC pumps when inadequate NPSH existed. Also, no procedural guidance existed to isolate an RBCLC leak and recover the RBCLC system."

Assuming no recovery of the RBCLC system leads to assuming no recovery of any of the equipment cooled by the RBCLC system.

Analysis Results

! Importance¹

The total importance was calculated to be 4.2×10^{-6} .

A summary of the calculation for importance is shown in the table below:

	Condition assessment
Conditional core damage probability (CCDP)	4.4×10^{-6}
Nominal core damage probability (CDP)	2.3×10^{-7} (*)
Importance () CDP = CCDP - CDP)	4×10^{-6}

(*) = The reported CDPs are for those initiating events that are affected by the condition, namely IE-LORBC and the LOCA events (SLOCA, MLOCA, and LLOCA).

The Accident Sequence Precursor Program acceptance threshold for condition assessment is an importance () CDP) of 1×10^{-6} . The importance of the condition assessment for this event exceeds the precursor threshold.

! Dominant sequences

Condition assessment: The sequence with the highest importance (3.4×10^{-6} or 81%) is a sequence that starts with a pipe break in the RBCLC system followed by a failure of the reactor recirculation pump seals due to loss of RCP seal cooling. Thus the event proceeds as a small LOCA with the reactor tripped. Power conversion system fails; manual reactor depressurization is successful; core spray is successful, but the long term cooling fails (see Tables 1 and 2). The main failure combination leading to core damage is the failure of instrument air system and failure to recover it in a timely manner. This sequence is depicted in Figure 2, sequence 26.

¹ For the condition assessment, the parameter of interest is the measure of the incremental increase between the conditional probability for the period in which the condition existed and the nominal probability for the same period but with the condition nonexistent and plant equipment available. This incremental increase or "importance" is determined by subtracting the CDP from the CCDP. This measure is used to assess the risk significance of hardware unavailabilities especially for those cases where the nominal CDP is high with respect to the incremental increase of the conditional probability caused by the hardware unavailability.

The following cutset dominates the sequence:

IE-SLOCA	SMALL LOSS OF COOLANT ACCIDENT	2.98E-03
CSS-XHE-XM-ERROR1	OPERATOR FAILS TO RECOVER CSS FOLLOWING LOIAS	1.00E-02
IAS-SYS-FC-LORBC	INSTRUMENT AIR FAILS AS A RESULT OF LOSS OF RBCCW	1.00E-01
IE-SLOCA-NOREC	OPERATOR FAILS TO RECOVER SLOCA IN SHORT TERM	1.00E+00
Cutset CDP =		3.0E-06

! Results tables

- The conditional probabilities of the dominant sequences are shown in Table 1.
- The event tree sequence logic for the dominant sequences are provided in Tables 2a and 2b.
- The conditional cut sets for the dominant sequences are provided in Table 3.
- The definitions for the modified or dominant basic events are shown in Table 4.

Modeling Assumptions

! Assessment summary

This event was modeled as a condition assessment.

The condition assessment was run for 8,760 hours. Only four of the initiating events have an importance value: IE-LORBC, IE-SLOCA, IE-MLOCA, and IE-LLOCA. For all other initiating events, the change case and the base case are the same.

Due to the assumptions used in the analysis, only one of the three periods of overlapping unavailabilities had an impact on the calculations. For the overlapping period where the #12 CRD pump was unavailable (390 hours), the unavailability had a small impact.

For the overlapping period where any reactor trip would cause a LOOP, the time period of 8 hours was not long enough to have a significant impact. For the overlapping period where the condensate system would be unavailable following failure of the reactor feedwater pumps, no credit was taken for the condensate system in any of the change case evaluations, and so the overlapping failure of the condensate system had no additional impact on the analysis.

! Key Modeling Assumptions

It is modeled that there is 0.50 probability of pump seal LOCA if the LORBC event occurs and the RCP seal cooling is lost, leading to SLOCA event. This probability is used in SDP and taken from the licensee PRA (Reference 1). Thus, 50% of the IE-LORBC frequency is taken out of this initiating event frequency and is added to the IE-SLOCA initiating event frequency, both in the base case and in the conditional case.

Credit is given for potential isolation of leaking RCP pump since specific procedures for this purpose exist, namely N1-SOP-1.2 (Recirc Pump Seal Failure).

! **SPAR model used in the analysis**

Nine Mile Point 1 (ASP BWR A), Revision 3.01, February 2003 (Reference 6)

! **Unique system and operational considerations**

A break in the RBCLC piping would result in dependent failure of two of the three instrument air compressors. The SPAR Revision 3.01 model assumes that there is a 0.1 chance that instrument air fails as a result of loss of RBCLC, modeled as the basic event IAS-SYS-FC-LORBC = 0.1 in the IAS fault tree. This assumption has been retained in the analysis.

! **Modifications to event tree and fault tree models**

The SPAR Revision 3.01 event trees and fault trees were used to calculate the base case values for the condition assessment for IE-LORBC, IE-SLOCA, IE-MLOCA, and IE-LLOCA. A modification is made to the IE-LORBC, as discussed below.

! **Initiating event probability changes**

The SPAR model initiating event frequency of IE-LORBC is $9.5\text{E-}07/\text{hr}$ and IE-SLOCA is $5.71\text{E-}08/\text{hr}$. These frequencies are modified as discussed below.

The LORBC initiating event frequency is increased by the following increment to account for the condition that can lead to pipe break:

$$(4 \text{ leaks/year}) \times (1 \text{ year}/8760 \text{ hours}) \times (1/100 \text{ break per leak}) = 4.6 \times 10^{-6} \text{ per hour.}$$

The 4 leaks/year came during the three shutdowns in the year prior to March 7, 2003. The 1/100 break per leak is the value used in Reference 1 in the significance determination process.

Thus, the total IE-LORBC value is:

$$9.5\text{E-}07 + 4.6\text{E-}06 = 5.6\text{E-}06/\text{hr.}$$

In the base SPAR model, RCP seal leakage was not modeled in IE-LORBC; it was only addressed in SBO event. For this ASP analysis, the following modification is made: both in the base case, and the conditional case, 50% of the IE-LORBC frequency is assigned to RCP seal leakage. As discussed later on 90% of these leaks are isolable, 10% are not (see basic event RRS-XHE-ISOLATE, introduced for this purpose). Only the unisolable leaks are assigned to IE-SLOCA. The initiating event frequencies are modified as follows:

Base Case:

IE-LORBC frequency consists of those cases where no leakage has occurred, plus the cases where the leakage is isolated (see the small event tree that illustrates this):

LORBC 9.50E-07	No Seal Leak		IE-LORBC	4.75E-07
	0.5	Isolate Leak	IE-LORBC	4.28E-07
		Seal Leak	IE-SLOCA	4.75E-08
	0.5	No Leak Isol.		
		0.1	Total =	9.50E-07

$$\text{IE-LORBC} = 9.5\text{E-}07 * 0.50 + 9.5\text{E-}7 * 0.5 * 0.90 = 9.03\text{E-}07 \text{ /hr}$$

$$\text{IE-SLOCA} = 5.71\text{E-}08 + 9.5\text{E-}07 * 0.5 * 0.1 = 1.05\text{E-}07 \text{ /hr}$$

Current Case:

$$\text{IE-LORBC} = 5.6\text{E-}06 * 0.50 + 5.6\text{E-}6 * 0.5 * 0.90 = 5.3\text{E-}06 \text{ /hr}$$

$$\text{IE-SLOCA} = 5.71\text{E-}08 + 5.6\text{E-}06 * 0.5 * 0.1 = 3.4\text{E-}07 \text{ /hr}$$

MLOCA and LLOCA initiating event frequencies remained the same. Other initiating event frequencies are set equal to zero, both in the base and the conditional case, since they are not affected by the condition.

! Basic event probability changes

S **Probability of failure of reactor recirculation pump seals following loss of RBCLC).** The probability that the reactor recirculation pump seals would leak following a pipe break in the RBCLC inside the drywell was set to 0.5 based on the evaluation of the licensee pump seal model by the Nine Mile Point 1 NRC special inspection team (Reference 1).

S **Isolation of Leaking Recirc Pump.** This new recovery action (RRS-XHE-ISOLATE) is introduced and used to reduce the initiating event frequency of consequential small LOCA due to RCP seal leakage. The HEP of this basic event is calculated in attachment A.

S Conditional Case Basic events set to failure (TRUE)

The following four basic events are set to failure for the conditional case. These event are taken from the flag file for LORBC, where they are set to TRUE in the base case, affecting only the initiating event IE-LORBC. By putting them explicitly into the change set, they also apply to LOCA events.

run	CDS-MDP-CF-PUMPS	Condensate pumps fail from common cause to
	LORBC	Loss of RBCCW
	PCS-MOV-OC-STEAM	Steam LOOP valves fail to remain open

SDC-HTX-CF-PLUG Common cause plugging of SDC heat exchanger

! Model update and modifications

- ***Probability of one safety relief valve sticks open (PPR-SRV-OO-1VLV).*** This value was changed to 3.7×10^{-3} based on the latest BWR evaluation.

Sequence 36 in the LORBC event tree is transferred to ATWS, rather than left conservatively as is (core damage). Figure 1 shows the modified event tree.

The above calculated initiating event frequencies are used for the base case IE-LORBC and IE-SLOCA.

The base SPAR model is quantified with these changes and is stored as the base case for this analysis.

! Sensitivity analysis

Two parameters are identified as those with potentially large uncertainties, and that would affect the results directly. These are

Increase in frequency of IE-LORBC (0.04 per year).

Seal LOCA probability due to loss of RBC (0.50).

Since the calculated event importance is in less than mid 10^{-6} , an increase of a factor of 2 in either parameter does not change the conclusions of the analysis; higher increases are not realistic. Thus, the uncertainty/sensitivity analyses are not pursued further.

References

1. NRC Special Inspection Report 50-220/03-003, *Preliminary White Finding*, dated April 15, 2003 (ADAMS Accession Number ML031060288).
1. Licensee Event Report LER 220/02-002, *Loss of one Control Rod Drive Pump due to Circuit Breaker Failure*, dated December 26, 2002 (ADAMS Accession Number ML030070698).
2. NRC Integrated Inspection Report 05000220/2003004, dated August 4, 2003 (ADAMS Accession Number ML032160113).
3. Licensee Event Report LER 220/02-001, *115 kilovolt Offsite Power Inoperable Due to Low Voltage on Line 4 and Line 1 Out of Service*, dated December 27, 2002 (ADAMS Accession Number ML030070699).
4. NRC Integrated Inspection Report 05000220/2003005, dated November 5, 2003 (ADAMS Accession Number ML033100273).
5. John A. Schroeder and Richard E. Gregg, *Standardized Plant Analysis Risk Model for Nine Mile Point 1 (ASP BWR A)*, Revision 3.01, February 2003, computer model updated March 6, 2003.

Appendix A. Human Reliability Analysis

A new operator action, RRS-XHE-ISOLATE, isolation of leaking RCP pump(s), is defined. If this action is performed per "Recirc Pump Seal Failure" procedure N1-SOP-1.2.

The performance shaping factors for this action are minimal, except for stress, which is assigned high due to the existence of a rare event. Thus the diagnosis and action HEPs are calculated as 0.02 and 0.002, respectively. There are three valves to be closed per pump. If one is left open, the leak will not be terminated. This is reflected in the estimation of HEP by multiplying the action HEP by 3. The final HEP for the basic event is

$$\text{HEP} = 2.6\text{E-}03 \sim 3\text{E-}02.$$

If multiple RCP seals are leaking (with lesser probabilities), more valves need to be closed. Thus, the action failure may be as high as 5 pumps * 3 valves/pump * 0.002 = 0.03, and the total HEP may be as high as 0.05 (0.02 + 0.03). However, the probability of such a scenario is expected to be lower.

The licensee has provided a HEP of 0.1 which was also used in the SDP analysis. This value is adapted for the current ASP analysis. Thus,

$$\text{HEP (RRS-XHE-ISOLATE)} = 0.1.$$

Table 1. Conditional probabilities associated with the highest probability sequences for the condition assessment.

Event Tree	Sequence	CCDP	CDP	Importance	%
SLOCA	26	3.40E-06	0.00E+00	3.40E-06	81.0%
LORBC	22	6.00E-07	1.00E-07	5.00E-07	11.9%
LORBC	34-20	1.80E-07	3.10E-08	1.50E-07	3.6%
LORBC	35-12	7.50E-08	1.30E-08	6.20E-08	1.5%
MLOCA	15	4.30E-08	0.00E+00	4.30E-08	1.0%
		4.40E-06	2.30E-07	4.20E-06	

Table 2a. Event tree sequence logic for the condition assessment.

Event Tree	Sequence	Logic ("/" denotes success; see Table 2b for top event names)	
SLOCA	26	L PCS /DEP SPC CVS	/RPS MFW /LCS CSS
LORBC	22	/RPS PCS MFW CDS SPC CSS	/SRV ISO /DEP /LCS SDC CVS
LORBC	34-20	/RPS MFW CDS SPC CSS	P1 /DEP /LCS SDC CVS
LORBC	35-12	/RPS CDS SPC CSS	P2 /LCS SDC CVS
MLOCA	15	/RPS MFW /LCS CSS	/VSS /DEP SPC CVS

Table 2b. Definitions of top events listed in Table 2a.

Fault Tree Name	Description
CDS	CONDENSATE INJECTION IS UNAVAILABLE
CSS	CONTAINMENT SPRAY COOLING FAILS
CVS	CONTAINMENT VENTING
DEP	MANUAL DEPRESSURIZATION FAILS
ISO	ISOLATION CONDENSER FAILURE
L	OPERATOR FAILS TO RECOVER SLOCA IN SHORT TERM
LCS	CORE SPRAY SYSTEM IS UNAVAILABLE
MFW	FEEDWATER SYSTEM FAILS
P1	ONE SRV FAILS TO CLOSE
PCS	POWER CONVERSION SYSTEM FAILS
RPS	REACTOR SHUTDOWN FAILS
SDC	SHUTDOWN COOLING SYSTEM IS UNAVAILABLE
SPC	TORUS COOLING FAILS
SRV	SRVS FAIL TO RECLOSE
VA1	ALTERNATE LOW PRESSURE INJECTION IS UNAVAILABLE

Table 3. Conditional cut sets for LORBC.

Event Tree: SLOCA Sequence: 26		CCDF: 3.8E-010	
CCDF	% Cut Set	Cut Set Events	
3.4E-010	87.52	IAS-SYS-FC-LORBC IE-SLOCA-NOREC	CSS-XHE-XM-ERROR1
2.4E-011	6.13	IE-SLOCA-NOREC CVS-XHE-XM-VENT1	CSS-XHE-XM-ERROR
1.7E-011	4.38	IAS-SYS-FC-LORBC CSS-XHE-XM-ERROR	IE-SLOCA-NOREC
Event Tree: LORBC Sequence: 22		CCDF: 6.8E-011	
CCDF	% Cut Set	Cut Set Events	
5.2E-011	76.66	/SRV ISO-XHE-XM-LOIAS	IAS-SYS-FC-LORBC CSS-XHE-XM-ERROR1
5.2E-012	7.67	/SRV IAS-SYS-FC-LORBC	MFW-XHE-XO-ERROR CSS-XHE-XM-ERROR1
5.2E-012	7.67	/SRV CSS-XHE-XM-ERROR1	IAS-SYS-FC-LORBC ISO-XHE-XM-ERROR
2.6E-012	3.83	/SRV ISO-XHE-XM-LOIAS	IAS-SYS-FC-LORBC CSS-XHE-XM-ERROR
Event Tree: LORBC Sequence: 34-20		CCDF: 2.1E-011	
CCDF	% Cut Set	Cut Set Events	
2.0E-011	93.22	PPR-SRV-OO-1VLV CSS-XHE-XM-ERROR1	IAS-SYS-FC-LORBC
9.8E-013	4.66	PPR-SRV-OO-1VLV CSS-XHE-XM-ERROR	IAS-SYS-FC-LORBC
Event Tree: LORBC Sequence: 35-12		CCDF: 8.6E-012	
CCDF	% Cut Set	Cut Set Events	
6.9E-012	79.81	PPR-SRV-OO-2VLVS CSS-XHE-XM-ERROR1	IAS-SYS-FC-LORBC
1.2E-012	13.51	PPR-SRV-OO-3VLVS CSS-XHE-XM-ERROR1	IAS-SYS-FC-LORBC
3.4E-013	3.99	PPR-SRV-OO-2VLVS CSS-XHE-XM-ERROR	IAS-SYS-FC-LORBC
Event Tree: MLOCA Sequence: 15		CCDF: 4.9E-012	
CCDF	% Cut Set	Cut Set Events	
4.6E-012	93.28	IAS-SYS-FC-LORBC	CSS-XHE-XM-ERROR1
2.3E-013	4.66	IAS-SYS-FC-LORBC	CSS-XHE-XM-ERROR

Notes:

1. See Table 4 for definitions and probabilities for the basic events.
2. Total Importance includes all cut sets (including those not shown in this table).

INSPECTION REPORT 220/03-003


Table 4. Definitions and probabilities for modified or dominant basic events.

BASIC EVENT CHANGES					
Event Name	Description	Base Prob	Curr Prob	Type	
CDS-MDP-CF-PUMPS	CONDENSATE PUMPS FAIL FROM C	+0.0E+000	1.0E+000	TRUE	
IE-LORBC	LOSS OF RBCCW	9.0E-007	5.3E-006		
IE-SLOCA	SMALL LOSS OF COOLANT ACCIDE	1.1E-007	3.4E-007		
LORBC	LOSS OF RBCCW	+0.0E+000	1.0E+000	TRUE	
PCS-MOV-OC-STEAM	STEAM LOOP VALVES FAIL TO RE	3.1E-002	1.0E+000	TRUE	
SDC-HTX-CF-PLUG	COMMON CAUSE PLUGGING OF SDC	+0.0E+000	1.0E+000	TRUE	

BASIC EVENT THAT ARE NOT CHANGED					
Event Name	Description	Base Prob	Curr Prob	Type	
CSS-XHE-XM-ERROR	OPERATOR FAILS TO START/CONTROL CONTAINMENT S		5.0E-004		
CSS-XHE-XM-ERROR1	OPERATOR FAILS TO RECOVER CSS FOLLOWING LOIAS		1.0E-002		
CVS-XHE-XM-VENT1	OPERATOR FAILS TO VENT CONTAINMENT		1.4E-001		
IAS-SYS-FC-LORBC	INSTRUMENT AIR FAILS AS A RESULT OF LOSS OF R		1.0E-001		
IE-SLOCA-NOREC	OPERATOR FAILS TO RECOVER SLOCA IN SHORT TERM		1.0E+000		
ISO-XHE-XM-ERROR	OPERATOR FAILS TO CONTROL ISOLATION CONDENSER		1.0E-003		
ISO-XHE-XM-LOIAS	OPERATOR FAILS TO RECOVER ISOLATION CONDENSER		1.0E-002		
MFW-XHE-XO-ERROR	OPERATOR FAILS TO START/CONTROL FEEDWATER INJ		1.0E-003		
PPR-SRV-OO-1VLV	ONE SRV STICKS OPEN		3.7E-003		
PPR-SRV-OO-2VLVS	TWO SRVS STICK OPEN		1.3E-003		
PPR-SRV-OO-3VLVS	THREE OR MORE SRVS STICK OPEN		2.2E-004		
SRV	SRV'S CLOSE		5.2E-003		


INSPECTION REPORT 220/03-003

Figure 1. IE-LORBC Event Tree



INSPECTION REPORT 220/03-003

Figure 2. SLOCA Event Tree



Attachment A Supporting Details for the Analysis

Event Dates: between Jan-01-2002 and Dec-31-2004

Docket: 220

Date of Search: Oct-20-2004

Summary of Plant Status

The reactor building closed loop cooling (RBCLC) system provides cooling for various reactor auxiliary equipment, as well as balance of plant equipment. Major components supplied by the system included the drywell air coolers, reactor recirculation pump coolers, reactor building equipment drain tank cooler, fuel pool heat exchangers, shutdown cooling system, control room air conditioning equipment, instrument air compressors, and the high pressure injection system (i.e., feedwater pumps, feedwater booster pumps, and condensate pumps). The RBCLC system is a safety-related, risk-significant system that is required to operate during normal plant operations and accident conditions.

In May 2002, and again on December 5 and 12, 2002, the licensee experienced substantial leaks in RBCLC small bore (less than 2" diameter) piping. Following evaluation and analysis of these leaks, the licensee discovered notable and widespread wall thinning in RBCLC piping sections, which were most severe at threaded mechanical connections (where piping thickness was the smallest due to the thread roots). This reduction in wall thickness was ultimately attributed to a combination of general corrosion, flow-assisted corrosion, and galvanic corrosion.

Prior to 2002, there had been numerous additional small bore piping leaks within the RBCLC system at threaded mechanical joints. Repair methods for these leaks varied, and included tightening the connection or fittings, replacing components (such as flow switches), seal welding the threaded connections, and replacing affected pipe sections. Around May 2000, chloride and sulfate concentrations in the RBCLC system were found to be elevated. Near the same time, RBCLC system oxygen levels were found to be significantly below normal levels, and iron particulate levels were high. These parameters indicated an increased corrosion rate, however, efforts to identify the cause and correct the abnormal chemistry parameters were unsuccessful. The NRC team's review of the event details determined the root and contributing causes for the degraded RBCLC piping included: inadequate system design, inadequate corrective actions, and degraded RBCLC system water chemistry. Subsequent to the December 12, 2002, leak, several immediate corrective actions were implemented, including extensive RBCLC small bore piping and fitting replacement with improved piping material and design. Longer term similar actions were also in progress for the remaining RBCLC piping sections that had not been replaced. In addition, the licensee was continuing their efforts to determine the cause and corrective actions for the unexpected and unexplained chemistry parameters. The performance deficiency was the failure, prior to December 12, 2002, to determine the cause of a significant condition adverse to quality and implement appropriate corrective actions to prevent further degradation of the RBCLC system. The NRC team determined that the licensee's structural analysis did not provide evidence that the as-found condition of the degraded piping in the RBCLC system retained sufficient strength, and consequently, the structural integrity of the affected RBCLC system piping may not have been maintained when subjected to design loading conditions. The safety significance of the inspection finding, based on the increase in core damage frequency due to internal and external initiating events, was determined to be White, which represents a finding of low to moderate safety significance.

Subject: Nine Mile Point Unit 1, Special Inspection Report 220/03-003

Condition assessment of degraded piping in Reactor Building Closed Loop Cooling (RBCLC).

Treated as condition assessment for 1 year from date of completion (March 7, 2003) of NRC Special Inspection Report 220/03-003.

From March 7, 2002 to March 7, 2003, there were three shutdowns from power operation to repair leaks in the RBCLC piping and this extensive number of shutdowns caused the NRC Special Inspection. Other than these three shutdowns, the unit was operating at power over the entire period – no other shutdowns except for RBCLC leaks.

1. May 14 to May 19. Repaired two RBCLC leaks.
2. Dec 5 to December 11. Repaired one RBCLC leak.
3. Dec 13 to December 24. Repaired one RBCLC leak.

The degradation in piping appears to have been extensive. From the Special Inspection Report – “The removed section of the pipe was visually examined by the inspection team to assess the material condition. The removed section indicated a highly corroded piping section with missing thread root. Even where the material was not missing, a flashlight illumination indicated a material ligament so thin that it appeared nearly translucent. The team also learned that a full section of the pipe was able to be broken apart manually following removal by maintenance personnel.”

Increased frequency for IE-LORBC

From the SERP Worksheet for SDP-Related Finding at Nine Mile Point 1 Degraded RBCLC Piping Issue – “Assumptions: #2 The RBCLC system piping was significantly degraded and lacked adequate structural integrity. Therefore, the dominant failure mode of the RBCLC system involved a passive failure of the piping which resulted in an increase in the likelihood of a loss of RBCLC initiating event. The initiating event frequency was determined by taking into account the existing failure modes of the system (8.3E-3 per year), the lack of structural integrity of the piping, the numerous leaks from the RBCLC piping over the years (between 1 and 5 per year), and the likelihood of a leak before break in the piping (100 to 1).

For the ASP analysis, the increase in the IE-LORBC frequency of pipe break = (4 leaks/year) x (1 year/8760 hours) x (1/100 based on leak before break) = 4.6E-6 breaks per hour.

Induced pipe break

Loss coolant accidents result in drywell temperatures that induce thermal stresses in the RBCLC piping in excess of the structural capability of the piping. Therefore, a conditional failure probability of 1.0 for the RBCLC system is used in these events.”

In effect, LOCAs and SBO would induce a pipe break in the RBCLC system inside containment that would be equivalent to IE-LORBC.

Recovery from pipe break in RBCLC

The Special Inspection Report indicated “Assumptions: #5 “Failure of the RBCLC piping would result in system leakage in excess of the automatic makeup capability for the system. Consequently, the RBCLC expansion tank level would be lost and the operating RBCLC pumps would fail due to inadequate net positive suction head (NPSH).

The ABS analysis did not include any recovery from a pipe break in RBCLC. Recovery of the RBCLC system is not credited because under certain entry conditions, Annunciator Response Procedure N1-ARP-H1, ‘Control Room Panel H1,’ directed the starting of the standby RBCLC pump; and Annunciator Response Procedure N1-ARP-H1, Special Operating Procedure N1-SOP-8, ‘RBCLC Failure,’ and Operating Procedure N1’ -OP-11,

'Reactor Building Closed Loop Cooling System,' did not provide guidance to secure the operating RBCLC pumps when inadequate NPSH existed. Also, no procedural guidance existed to isolate a RBCLC leak and recover the RBCLC system."

Reactor Recirculation Pump Seals

The Special Inspection Report indicated, "Failure of the RBCLC piping would result in the inability to remove heat from the recirculation pump seals. Without cooling, the likelihood of a recirculation pump seal leak increased substantially. Therefore, the team used a seal failure probability of 0.5, which was based on the licensee's recirculation pump seal package test results."

In effect, some initiating events (IE-LORBC, IE-SLOCA, IE-MLOCA, IE-LLOCA) would cause a small LOCA from the reactor recirculation pump seals. The condition assessment made changes to the IE-LORBC analysis to consider the impact of this induced leakage.

The base SPAR Revision 3.01 model sets the following three basic events to 1.0 for IE-LORBC by the use of project rules (see the flag file in Figure 1):

CDS-MDP-CF-PUMPS Condensate pumps fail from common cause to run
PCS-MOV-OC-STEAM Steam LOOP valves fail to remain open
SDC-HTX-CF-PLUG Common cause plugging of shutdown cooling heat exchanger

These three basic events are set to 1.0 for IE-SLOCA, IE-MLOCA, and IE-LOCA.

Moreover, 50% of the IE-LORBC frequency is assigned to RCP seal leak. Then, credit is given for proceduralized RCP seal leakage isolation with 90% success. The failures are assigned to IE-SLOCA frequency (by simply adding it to the IE-SLOCA frequency, to account for the seal LOCAs.)

How the Base and Conditional Runs are made:

The base case is run with all initiating event frequencies set equal to zero, except for LORBC, SLOCA, MLOCA, and LOCA.

The conditional case is run with the same initiating event frequencies, except LORBC and SLOCA frequencies are modified. Moreover, the effect of RORBC in LOCA events is reflected by setting other basic events to failure (true). This is done by defining a change set named IE-BC. The contents of this change set are shown in Figure 2.

Overlapping events during year of the condition assessment

The 12 control rod drive pump failed to start during a routine surveillance test on October 17, 2002. Pump was determined to be unavailable from 9/24/02 to 10/19/03 (390) hours). LER 220/02-002 and NRC Integrated Inspection Report 220/03-004. As a stand-alone event, this event was rejected as a precursor as part of the Accident Sequence Precursor Program.

For a period of 8 hours on 11/1/02, during maintenance on offsite-power lines to Unit 1, it was determined that it was possible that if Unit 1 tripped during these 8 hours, a LOOP would be induced for Unit 1 as a consequence of the trip. LER 220/02-001 and NRC Integrated Inspection Report 220/03-004. As a stand-alone event, this event was rejected as a precursor based on extensive analysis as part of the Accident Sequence Precursor Program.

For the entire year, it was determined that an HPCI interlock would have prevented the use of the condensate pumps as a separate injection source to the reactor following failure of the reactor feedwater pumps. The bypass of the HPCI interlock was not included in the procedures used to inject water into the reactor vessel following failure of the reactor feedwater pumps. NRC Integrated Inspection Report 220/03-005.

INSPECTION REPORT 220/03-003

LER Number Event Date Plant Title

2202002001 11/01/2002 Nine Mile Pt 1 115 Kilovolt Offsite Power Inoperable Due to Low Voltage on Line 4 and Line 1 Out of Service

2202002002 10/17/2002 Nine Mile Pt 1 Loss of One Control Rod Drive Pump Train Due to Circuit Breaker failure

2202002003 12/02/2002 Nine Mile Pt 1 Loss of Power to Reactor Protection System (RPS) Bus 12 While RPS Bus 11 Emergency Power Source Was Inoperable

Search Restrictions:

Status: Active, Canceled, Restricted

Event Dates: between Jan-01-2002 and Mar-08-2003

Docket: 220

Date of Search: Jul-07-2004

LER Search for Windowed Events Nine Mile Pt 1

LER Number	Event Date	Event Description
2202002001	11/01/2002	115 Kilovolt Offsite Power Inoperable Due to Low Voltage on Line 4 and Line 1 Out of Service
2202002002	10/17/2002	Loss of One Control Rod Drive Pump Train Due to Circuit Breaker failure
2202002003	12/02/2002	Loss of Power to Reactor Protection System (RPS) Bus 12 While RPS Bus 11 Emergency Power Source Was Inoperable
2202003001	04/22/2003	Technical Specification Cooldown Rate Exceeded During Required Cooldown for a Failed Solenoid Actuated Pressure Relief Valve
2202003002	08/14/2003	Reactor Scram Due to Electric Grid Disturbance
2202003003	11/13/2003	Automatic Initiation of Emergency Diesel Generator 103 due to Momentary Loss of Offsite Power
2202003004	08/13/2003	Unplanned Inoperability of Emergency Cooling System Caused by Inadequate Review of Clearance for Replacement of Instrumentation Relay
2202004001	05/02/2004	Manual Reactor Scram and Cooldown Rate Exceeding Technical Specification Limits Due to Electromatic Relief Valve Failure to Close
2202004002	05/14/2004	Changes and Errors in the Methodology Used by General Electric and Global Nuclear Fuel to Demonstrate Compliance with Emergency Core Cooling System Performance Requirements
2202004003	02/25/2003	Inadequate Environmental Qualification Barrier Considerations Resulting in an Unanalyzed Condition

Search Restrictions:

Status: Active, Canceled, Restricted

Event Dates: between Jan-01-2002 and Dec-31-2004

Docket: 220

Date of Search: Oct-20-2004

Figure 1 Flag File for LORBC in the Base SPAR Model





Figure 2. Basic events in Change Set LORBC used for Conditional Case



Nine Mile Point ASP Analysis

OERAB ASP ANALYSIS Summary Sheet		
1	Plant	Nine Mile Point 1 (BWR)
2	Docket #	05 000 220
3	Event	Degraded piping in the reactor building closed loop cooling (RBCLC) system. The failure to adequately identify and evaluate equipment problems, and correct deficiencies, resulted in repetitive and continued degraded piping conditions in the RBCLC system. Specifically, a RBCLC system piping leak occurred on May 15, 2002, due to significant pipe corrosion, primarily as a result of inadequate piping design, application and operation. Additionally, numerous RBCLC system leaks occurred during several preceding years. However, the cause for these leaks was not determined and appropriate corrective actions were not implemented. This led to further degradation of the RBCLC system piping such that additional significant leaks occurred on December 5, 2002, and again on December 12, 2002. These significant leaks in December 2002 were accompanied by a significant reduction in the pipe wall which degraded the structural integrity of the affected piping sections.
4	Event Date	May 15, 2002, December 5, 2002, December 12, 2002
5	Auto Reactor Trip	No reactor trip occurred. This is a plant condition with recurrent degraded RBCLC piping. The condition caused plant to shutdown from power operation to repair leaks.
6	LER #	No LER
7	SDP Worksheet	EAW-03-053 March 18, 2003
8	Inspection Report	50-220/2003-003 EA-03-053 April 15, 2003
9	SDP Finding	White
10	Reason for Fast Rejection of Event	There is no reason for fast rejection since multiple safety systems supported by RBCLC may be affected.
11	Preliminary ASP Analysis	ASP analysis by ABS indicated that consequential small LOCA due to pump seal leakage dominates the risk with a event importance in the 10-E-5 range. Also, the SDP analysis uses SPAR models, and considers external, as well as internal events. The results of the SDP analysis for a 1-year exposure time is) CDF = 5.3E-06/year. Since these two results do not match, the ASP analysis is performed and documented in the main body of this document.
12	Contribution from External Events	Studied in SDP. Not a contributor to conclusions.
13	Contribution from Shutdown Events	Not relevant.

Nine Mile Point ASP Analysis

14	LERF Considerations	Not an issue.
15	Windowed Events	<p>3 LERs are found:</p> <p>LER Number Event Date Plant Title</p> <p>2202002001 11/01/2002 Nine Mile Pt 1 115 Kilovolt Offsite Power Inoperable Due to Low Voltage on Line 4 and Line 1 Out of Service</p> <p>2202002002 10/17/2002 Nine Mile Pt 1 Loss of One Control Rod Drive Pump Train Due to Circuit Breaker failure</p> <p>2202002003 12/02/2002 Nine Mile Pt 1 Loss of Power to Reactor Protection System (RPS) Bus 12 While RPS Bus 11 Emergency Power Source Was Inoperable</p> <p>Search Restrictions:</p> <p>Status: Active, Canceled, Restricted</p> <p>Event Dates: between Jan-01-2002 and Mar-08-2003</p> <p>Docket: 220</p> <p>Date of Search: Jul-07-2004</p>
16	Recommendation	Classify event as qualifying for ASP database with a delta CDP in the range of 3E-05.

Attachment B SDP Phase 3 Analysis

Internal Initiating Events:

The NRC's Standardized Plant Analysis Risk (SPAR) model, Revision 3.01, was used to evaluate the significance of this finding. The analyst determined that the SPAR model needed to be revised to link the loss of RBCLC event tree and the anticipated transient without scram (ATWS) event tree and to reflect the possibility of a recirculation pump seal leak following the loss of the RBCLC system. This revision resulted in an increase in the baseline core damage frequency from 7.88E-6 per year to 7.91E-6 per year.

Assumptions:

1. The performance deficiency existed for in excess of a year. Therefore, the analyst used an exposure time of 1 year.
2. The RBCLC system piping was significantly degraded and lacked adequate structural integrity. Therefore, the dominant failure mode of the RBCLC system involved a passive failure of the piping which resulted in an increase in the likelihood of a loss of RBCLC initiating event. The initiating event frequency was determined by taking into account the existing failure modes of the system (8.3E-3 per year), the lack of structural integrity of the piping, the numerous leaks from the RBCLC piping over the years (between 1 and 5 per year), and the likelihood of a leak before break in the piping (100 to 1). Applying engineering judgement, the team concluded that the loss of RBCLC initiating event frequency was approximately 5.0E-2 per year.
3. Loss of coolant accidents and SBO events result in drywell temperatures that induce thermal stresses in the RBCLC piping in excess of the structural capability of the piping. Therefore, the analyst used a conditional failure probability of 1.0 for the RBCLC system in these events.
4. Failure of the RBCLC piping would result in the inability to remove heat from the recirculation pump seals. Without cooling, the likelihood of a recirculation pump seal leak increased substantially. Therefore, the analyst used a seal failure probability of 0.5, which was based on the licensee's recirculation pump seal package test results.
5. Failure of the RBCLC piping would result in system leakage in excess of the automatic makeup capability for the system. Consequently, the RBCLC expansion tank level would be lost and the operating RBCLC pumps would fail due to inadequate net positive suction head (NPSH). The analyst did not credit recovery of the RBCLC system because under certain entry conditions, Annunciator Response Procedure N1-ARP-H1, "Control Room Panel H1," directed the starting of the standby RBCLC pump; and Annunciator Response Procedure N1-ARP-H1, Special Operating Procedure N1-SOP-8, "RBCLC Failure," and Operating Procedure N1-OP-11, "Reactor Building Closed Loop Cooling System," did not provide guidance to secure the operating RBCLC pumps when inadequate NPSH existed. Also, no procedural guidance existed to isolate an RBCLC leak and recover the RBCLC system. In addition, because each of the dominant accident sequences involved the failure of operator actions prior to when RBCLC would have been recovered, the likelihood of the failure of the operators to recover RBCLC would be dependent on those prior failures. Consequently, the analyst considered the likelihood of the operators' failure to recover the RBCLC system too high to credit.

The analyst revised the SPAR model to reflect these assumptions, determined a revised core damage frequency for the exposure period (1.32E-5 per year) and calculated the change in core damage frequency (CDF) for this finding due to internal initiating events.

$$\text{CDF} = [(1.32\text{E-}5 \text{ per year}) - (7.91\text{E-}6 \text{ per year})] = 5.29\text{E-}6 \text{ per year (White)}$$

Nine Mile Point ASP Analysis

Attachment C GEM Output for the Analysis

CONDITION ASSESSMENT

Code Version: 7:24	Model Version : 1998/09/03
Project : NMP1_3I	Duration (hrs) : 8.8E+003
User Name :	Total CCDP : 4.4E-006
Event ID : IE-LORBC	Total CDP : 2.3E-007
	Importance : 4.2E-006

Description : Condition Assessment

BASIC EVENT CHANGES				
Event Name	Description	Base Prob	Curr Prob	Type
CDS-MDP-CF-PUMPS	CONDENSATE PUMPS FAIL FROM C	+0.0E+000	1.0E+000	TRUE
IE-LORBC	LOSS OF RBCCW	9.0E-007	5.3E-006	
IE-SLOCA	SMALL LOSS OF COOLANT ACCIDE	1.1E-007	3.4E-007	
LORBC	LOSS OF RBCCW	+0.0E+000	1.0E+000	TRUE
PCS-MOV-OC-STEAM	STEAM LOOP VALVES FAIL TO RE	3.1E-002	1.0E+000	TRUE
SDC-HTX-CF-PLUG	COMMON CAUSE PLUGGING OF SDC	+0.0E+000	1.0E+000	TRUE

SEQUENCE PROBABILITIES

Truncation : Cumulative : 100.0% Individual : 1.0%

Event Tree Name	Sequence Name	CCDP	CDP	Importance
SLOCA	26	3.4E-006	+0.0E+000	3.4E-006
LORBC	22	6.0E-007	1.0E-007	5.0E-007
LORBC	34-20	1.8E-007	3.1E-008	1.5E-007
LORBC	35-12	7.5E-008	1.3E-008	6.2E-008
MLOCA	15	4.3E-008	+0.0E+000	4.3E-008

NEGATIVE SEQUENCE PROBABILITIES

Truncation : Cumulative : 100.0% Individual : 1.0%

Event Tree Name	Sequence Name	CCDP	CDP	Importance
SLOCA	06	+0.0E+000	6.8E-008	-6.8E-008
SLOCA	05	+0.0E+000	6.3E-009	-6.3E-009
MLOCA	10	+0.0E+000	2.1E-009	-2.1E-009
SLOCA	16	+0.0E+000	2.1E-009	-2.1E-009

NOTE: Percent contribution to total Importance.

SEQUENCE LOGIC

Event Tree	Sequence Name	Logic
SLOCA	26	L /RPS

Nine Mile Point ASP Analysis

		PCS /DEP SPC CVS	MFW /LCS CSS
LORBC	22	/RPS PCS MFW CDS SPC CSS	/SRV ISO /DEP /LCS SDC CVS
LORBC	34-20	/RPS MFW CDS SPC CSS	P1 /DEP /LCS SDC CVS
LORBC	35-12	/RPS CDS SPC CSS	P2 /LCS SDC CVS
MLOCA	15	/RPS MFW /LCS CSS	/VSS /DEP SPC CVS
SLOCA	16	L PCS /LCS CSS	/RPS /MFW SPC CVS
MLOCA	10	/RPS /MFW VA	/VSS LCS
SLOCA	05	L /PCS SPC /CVS	/RPS /LCS CSS VA1
SLOCA	06	L /PCS SPC CVS	/RPS /LCS CSS

Fault Tree Name	Description
CDS	CONDENSATE
CSS	CONTAINMENT SPRAY

2005/03/14

12:25:33

page 2

Nine Mile Point ASP Analysis

CVS	CONTAINMENT VENTING
DEP	MANUAL REACTOR DEPRESS
ISO	ISOLATION CONDENSER
L	OPERATOR FAILS TO RECOVER SLOCA IN SHORT TERM
LCS	CORE SPRAY
MFW	FEEDWATER
P1	ONE SRV FAILS TO CLOSE
P2	TWO SRVS FAIL TO CLOSE
PCS	POWER CONVERSION SYSTEM
RPS	REACTOR PROTECTION SYSTEM
SDC	SHUTDOWN COOLING
SPC	SUPPRESSION POOL (TORUS) COOLING
SRV	SRV'S CLOSE
VA	ALTERNATE LOW PRESS INJECTION
VA1	LONG-TERM LOW PRESS INJECTION
VSS	VAPOR SUPPRESSION

SEQUENCE CUT SETS

Truncation: Cumulative: 100.0% Individual: 1.0%

Event Tree: SLOCA
Sequence: 26

CCDF: 3.8E-010

CCDF	% Cut Set	Cut Set Events	
3.4E-010	87.52	IAS-SYS-FC-LORBC	CSS-XHE-XM-ERROR1
		IE-SLOCA-NOREC	
2.4E-011	6.13	IE-SLOCA-NOREC	CSS-XHE-XM-ERROR
		CVS-XHE-XM-VENT1	
1.7E-011	4.38	IAS-SYS-FC-LORBC	IE-SLOCA-NOREC
		CSS-XHE-XM-ERROR	

Event Tree: LORBC
Sequence: 22

CCDF: 6.8E-011

CCDF	% Cut Set	Cut Set Events	
5.2E-011	76.66	/SRV	IAS-SYS-FC-LORBC
		ISO-XHE-XM-LOIAS	CSS-XHE-XM-ERROR1
5.2E-012	7.67	/SRV	MFW-XHE-XO-ERROR
		IAS-SYS-FC-LORBC	CSS-XHE-XM-ERROR1
5.2E-012	7.67	/SRV	IAS-SYS-FC-LORBC
		CSS-XHE-XM-ERROR1	ISO-XHE-XM-ERROR
2.6E-012	3.83	/SRV	IAS-SYS-FC-LORBC
		ISO-XHE-XM-LOIAS	CSS-XHE-XM-ERROR

Nine Mile Point ASP Analysis

Event Tree: LORBC
Sequence: 34-20

CCDF: 2.1E-011

CCDF	% Cut Set	Cut Set Events	
2.0E-011	93.22	PPR-SRV-OO-1VLV	IAS-SYS-FC-LORBC
		CSS-XHE-XM-ERROR1	
9.8E-013	4.66	PPR-SRV-OO-1VLV	IAS-SYS-FC-LORBC
		CSS-XHE-XM-ERROR	

Event Tree: LORBC
Sequence: 35-12

CCDF: 8.6E-012

CCDF	% Cut Set	Cut Set Events	
6.9E-012	79.81	PPR-SRV-OO-2VLVS	IAS-SYS-FC-LORBC
		CSS-XHE-XM-ERROR1	
1.2E-012	13.51	PPR-SRV-OO-3VLVS	IAS-SYS-FC-LORBC
		CSS-XHE-XM-ERROR1	
3.4E-013	3.99	PPR-SRV-OO-2VLVS	IAS-SYS-FC-LORBC
		CSS-XHE-XM-ERROR	

Event Tree: MLOCA
Sequence: 15

CCDF: 4.9E-012

CCDF	% Cut Set	Cut Set Events	
4.6E-012	93.28	IAS-SYS-FC-LORBC	CSS-XHE-XM-ERROR1
2.3E-013	4.66	IAS-SYS-FC-LORBC	CSS-XHE-XM-ERROR

Event Tree: SLOCA
Sequence: 16

CCDF: +0.0E+000

CCDF	% Cut Set	Cut Set Events	
+0.0E+000	100.00	<FALSE>	

Event Tree: MLOCA
Sequence: 10

CCDF: +0.0E+000

CCDF	% Cut Set	Cut Set Events	
+0.0E+000	100.00	<FALSE>	

Event Tree: SLOCA
Sequence: 05

CCDF: +0.0E+000

CCDF	% Cut Set	Cut Set Events	
+0.0E+000	100.00	<FALSE>	

Nine Mile Point ASP Analysis

Event Tree: SLOCA
Sequence: 06

CCDF: +0.0E+000

CCDF	% Cut Set	Cut Set Events
+0.0E+000	100.00	<FALSE>

BASIC EVENTS (Cut Sets Only)		
Event Name	Description	Curr Prob
<FALSE>	SYSTEM GENERATED SUCCESS EVENT	+0.0E+000
CSS-XHE-XM-ERROR	OPERATOR FAILS TO START/CONTROL CONTAINMENT S	5.0E-004
CSS-XHE-XM-ERROR1	OPERATOR FAILS TO RECOVER CSS FOLLOWING LOIAS	1.0E-002
CVS-XHE-XM-VENT1	OPERATOR FAILS TO VENT CONTAINMENT	1.4E-001
IAS-SYS-FC-LORBC	INSTRUMENT AIR FAILS AS A RESULT OF LOSS OF R	1.0E-001
IE-SLOCA-NOREC	OPERATOR FAILS TO RECOVER SLOCA IN SHORT TERM	1.0E+000
ISO-XHE-XM-ERROR	OPERATOR FAILS TO CONTROL ISOLATION CONDENSER	1.0E-003
ISO-XHE-XM-LOIAS	OPERATOR FAILS TO RECOVER ISOLATION CONDENSER	1.0E-002
MFW-XHE-XO-ERROR	OPERATOR FAILS TO START/CONTROL FEEDWATER INJ	1.0E-003
PPR-SRV-OO-1VLV	ONE SRV STICKS OPEN	3.7E-003
PPR-SRV-OO-2VLVS	TWO SRVS STICK OPEN	1.3E-003
PPR-SRV-OO-3VLVS	THREE OR MORE SRVS STICK OPEN	2.2E-004
SRV	SRV'S CLOSE	5.2E-003