

# RI - DNMS Licensee Event Report Disposition

Licensee: Storigenics

Event Description: Bent Source

License No: 29-20900-01 Docket No: 03022307 MLER-RI: 2005-037

Event Date: 5/23/05 Report Date: 6-1-05 HQ Ops Event #: \_\_\_\_\_

①

### REPORTING REQUIREMENT

<input type="checkbox"/>	10 CFR 20.1906 Package Contamination	<input type="checkbox"/>	10 CFR 30.50 Report
<input type="checkbox"/>	10 CFR 20.2201 Theft or Loss	<input type="checkbox"/>	10 CFR 35.3045 Medical Event
<input type="checkbox"/>	10 CFR 20.2203 30 Day Report	<input type="checkbox"/>	License Condition
<input checked="" type="checkbox"/>	Other <u>Not required to be reported by PART 30 or 36 (no failure of source encapsulation)</u>		

2.

### REGION I RESPONSE

<input type="checkbox"/>	Immediate Site Inspection	Inspector/Date	<input type="text"/>
<input type="checkbox"/>	Special Inspection	Inspector/Date	<input type="text"/>
<input type="checkbox"/>	Telephone Inquiry	Inspector/Date	<input type="text"/>
<input type="checkbox"/>	Preliminary Notification/Report	<input type="checkbox"/>	Daily Report
<input checked="" type="checkbox"/>	Information Entered in RI Log	<input checked="" type="checkbox"/>	Review at Next Inspection
Report Referred To: _____			

③

### REPORT EVALUATION

<input checked="" type="checkbox"/>	Description of Event	<input checked="" type="checkbox"/>	Corrective Actions
<input checked="" type="checkbox"/>	Levels of RAM Involved	<input type="checkbox"/>	Calculations Adequate
<input type="checkbox"/>	Cause of Event	<input type="checkbox"/>	Additional Information Requested from Licensee

④

### MANAGEMENT DIRECTIVE 8.3 EVALUATION

<input type="checkbox"/>	Release w/Exposure > Limits	<input type="checkbox"/>	Deliberate Misuse w/Exposure > Limits
<input type="checkbox"/>	Repeated Inadequate Control	<input type="checkbox"/>	Pkging Failure > 10 rads/hr or Contamination > 1000x Limits
<input type="checkbox"/>	Exposure 5x Limits	<input checked="" type="checkbox"/>	Large# Indivs w/Exp > Limits or Medical Deterministic Effects
<input type="checkbox"/>	Potential Fatality	<input checked="" type="checkbox"/>	Unique Circumstances or Safeguards Concerns
If any of the above are involved:			
<input type="checkbox"/>	Considered Need for IIT	<input type="checkbox"/>	Considered Need for AIT
Decision/Made By/Date: _____			

⑤

### MANAGEMENT DIRECTIVE 8.10 EVALUATION (additional evaluation for medical events only)

<input type="checkbox"/>	Timeliness - Inspection Meets Requirements (5 days for overdose / 10 days for underdose)
<input type="checkbox"/>	Medical Consultant Used-Name of Consultant/Date of Report: _____
<input type="checkbox"/>	Medical Consultant Determined Event Directly Contributed to Fatality
<input type="checkbox"/>	Device Failure with Possible Adverse Generic Implications
<input type="checkbox"/>	HQ or Contractor Support Required to Evaluate Consequences

⑥

### SPECIAL INSTRUCTIONS OR COMMENTS

discuss the bent source with the manufacturer as part of the inspection

Non-Public

Inspector Signature: Joseph A. Jovanov

Date: 6/8/05

Public-SISP REVIEW COMPLETE

Branch Chief Initials: J. Jovanov

Date: 6/16/05



RECEIVED  
REGION 1

2005 JUN -6 PM 1:07

June 1, 2005

Ms. Judith Joustra  
Nuclear Materials Safety Branch  
U. S. Nuclear Regulatory Commission, Region I  
475 Allendale Road  
King of Prussia, PA 19406-1415

Reference: Renewal Application, Material License Number 29-20900-01

Dear Ms. Joustra:

As you are probably aware, a source loading took place at the Sterigenics facility in Salem, New Jersey, last week. During the process of rearranging the sources in the rack to achieve the desired dose distribution patterns, one source was discovered that was significantly bent. The source, serial number 9279EE, was manufactured by Reviss Services, Puridex Irradiation Technologies. Our records indicate that it was originally installed in the irradiator in February 1999, with an initial activity of 10,700 Curies (activity as of May 27, 2005, was 4,692 Ci).

While it is not extremely unusual to observe some curvature to sources after several years of cycling in a wet source storage irradiator, this particular source was bent to such a degree that there was some concern that it might not be held in the source rack securely. The design of the Salem source rack is such that the sources are held in position by channels, approximately one-half inch deep, at the top and bottom of each module and by having the module completely full of either active sources or nonradioactive placeholders that ensure sources are held tightly within the module. Although we did not have specific evidence that this might be a problem, our concern was that the amount of curvature in this source could shorten the effective length of the source to such an extent that the channels in the module would not hold it securely in place, possibly leading to the source becoming dislodged from the rack.

Because the rearrangement of sources within the rack occurred after the shipping containers had already been secured and returned to the source supplier, it was not possible to return the source to the manufacturer at this loading. Instead, the source was removed from the rack and placed in storage at the bottom of the pool. We intend to leave it there until we have a chance to return it to the manufacturer. There was no indication of damage to the source's structural integrity.

If you believe that a license amendment is necessary to authorize this storage, please consider this letter a request for such an amendment. Should you need any further information, please call me.

Sincerely,

A handwritten signature in black ink, appearing to read 'Mark A. Smith'.

Mark A. Smith, CHP  
Vice-President, Radiation Services

cc: S. Ferraro

Sterigenics International, Inc.  
10811 Withers Cove Park Drive  
Charlotte, NC 28278  
Tel 704.588.6877 • Fax 704.588.3667 • www.sterigenics.com