

Oconee Nuclear Station
Unit #1 Steam Generator
Discussion with NRC
Washington, DC
June 22, 2005


C. Thomas Alley

1


Introduction

- Design comparison of the ONS OTSG and ROTSG
- Spring Inspections Results for ONS #1 SGs
- Wear Indications and Probable Causes
- Duke's Response to the Wear Issue
- Future Impact
- Summary

2



Hourglass Broached Hole



Significant Differences in Design between OTSG and ROTSG

Oconee ROTSG
Comparison between Original and Replacement OTSG
with respect to Tube / Tube Support Plate

Description	Original OTSG	Replacement OTSG
Tube diameter	1.800	1.850
Tube pitch	5.8" OD (+0.025, 0, 0.025) Term 0.030" Term	5.8" OD (+0.025, -0, 0.025) Term 0.030" Term
Tube free tube	Yes	No
Tube support plate material	SA-212 B anneal @ SA-515 Gr 70	SA-240 Type 410S
Tube support plate thickness	1.5"	1.5"
Tube support plate spacing	Varying between end cover to -45", between at 35"-40"	45" (25" - 60" @ 22.525") See attached
Plate end hole diameter	0.640" min. 0.640" max. no hole-plate	0.640" min. 0.640" max. No hole-plate. See attached
Tube support plate end length of hole overlap	1.5"	0.75" (from 1" to 1.25" from end-ends)
Structural Hole Limit	concave	flat
Avg. tube to hole distance	0.0150"	0.0150" (non-rectangular), 0.018" (rectangular)
Min. hole clearance	0.021" on corner	0.021" on corner
Off Corner Tube to Lobe Clearance	= 0.022" (from hole, min tube O), = 0.0215" (from hole, min tube O)	0.022" (from hole, min tube O), 0.0215" (from hole, min tube O)
Peripheral gap between tube support plate and shroud	Yes at all points 75% 1 and 1.5	Yes only at - See attached
Location shroud to shroud any connector (above lower pipe)	Beveled cylindrical junction - 4" gap	Circular junction - 5.485" diameter opening
Tube protrusion	4 - 15 lbs. depending on source	4.7 lbs
Tube stress at full power condition	no	See attached
Assembly Technique	Shroud beams inserted into plate - lower beam lower and upper beam top upper end. Tubes installed with manual means inside shroud can providing quality assistance and special phenomena assistance	SPs installed sequentially into shroud from bottom up. Tubes installed with lever force

5

Operational Comparison OTSG to ROTSG, and "A" to "B"

- FDW Flow (ROTSG Limit = 6.0 X 106 #/hr)
 - A FDW Mass Flow (avg): ~ 5.42x106 #/hr
 - B FDW Mass Flow (avg): ~ 5.35x106 #/hr
(compared to previous cycle these values are slightly lower, -0.05 x 106 #/hr)
- MS Outlet Temperature
 - MS Temperature increased from -592F on A side & -582F B side to -595F on both S/Gs
(with cleaner tube surfaces and better heat transfer performance, this was expected)
- RCS
 - Flow Increased ~3% on A side compared with previous cycle
 - Flow Increased ~5% on B side compared with previous cycle
 - Rx Delta T decreased accordingly
(Total RCS performance remained constant from previous cycle)
- Water level
 - Water level was lowered ~180" to ~140" (as expected, better heat transfer)

Other Items Reviewed Did Not Indicate Any Operational Abnormalities
(Final FDW Flow, RCS Press, FDW Pump Press, Aux Fdw Flow, MS Press, Vibrations, etc.)

6

Definition of the Issue

- A significant number of tubes in the ONS ROTSG were found with wear indications after 14 months of operation.
- 100% eddy current inspection of Oconee Unit #1 "A" and "B" steam generators was conducted at the end of the initial operating cycle as recommended by industry guidance. (15,631 tubes per generator)
- Eddy current inspection scope included 100% bobbin inspection, "X" probe inspection of all tubes showing indications ~3250 tubes

7

Oconee Unit 1 EOC-22 Steam Generator Inspection Observations

- Identification of widespread tube wear - confirmed with multiple ECT techniques (bobbin and "X" probe)
- Tube wear statistics
 - 1,800 tubes with wear indications in 1A SG
 - 1,450 tubes with wear indications in 1B SG
 - maximum wear depth observed = 42% TW in the "A" SG
 - 80% wear indications were between 5% and 15% TW
 - wear indications primarily in peripheral regions at 9th, 10th, and 11th TSPs
 - most tubes had single indication; some had indications at multiple locations
 - wear indications were small (generally < 0.5 inch axial, < 35° circumferential)
 - wear indications had a tapered depth profile
 - minimum detectability is 4% TW

8

Oconee Unit 1 EOC 22 Steam Generator Inspection Observations

- Most indications (~95%) appear in the superheated steam region in the periphery of the bundle
- Highest population of indications is at the 10th TSP followed by the 11th and the 9th
- Population of indications in the 12th TSP in the "B" SG is low but in the "A" SG 12th TSP the population is 4th highest
- The 15th TSP shows only a few indications (single side chamfer broached hole on the outer tubes ~10 inches)
- The outermost 4 tubes at the 14th TSP in both SGs has only 2 indications (1st four outer tubes are drilled not broached)
- 11th, 12th and 13th TSP have same broached hourglass holes with ½ inch bypass between the plate and the shroud blocked. The pattern of indications are similar with two exceptions
 - The lack of indications at the 12th TSP of the "B" SG
 - Higher number of large indications at the 11th TSP in the "B" SG
- The 9th TSP is located just below the bleed port has broached single sided chamfer for ~14 outer tube rows. In the "A" SG this TSP has the most significant non-peripheral population of wear indications
- The single sided chamfer pattern for the 15th, 10th, and 9th TSP covers ~10 inches of the periphery. Indications at the 9th, and 10th TSP occur in both the single sided and hourglass broached holes


9

Oconee 1A SG Wear Size Distribution


	Support															Total
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	
%TW<=5					1			4	24	15	21	17	8	13		101
%TW>5<=10	4	5	5		2		9	48	318	384	344	228	110	121	1	1577
%TW>10<=15	1	2	2				1	8	89	157	102	83	49	50	4	548
%TW>15<=20									13	47	31	16	8	14	1	130
%TW>20<=25									1	19	15	3		2		40
%TW>25<=30										15	3	1				19
%TW>30<=35										8	4					12
%TW>35<=40										2	2					4
%TW>40<=45										2						2
%TW>45<=50																0
%TW>50																0
Total/Support	5	7	7	0	3	0	10	58	445	649	522	348	173	200	8	2433

10



Wear Indications "A" Generator



Wear Indications "A" Generator



Wear Indications "A" Generator




13

Ocone 1B SG Wear Size Distribution


	Support															Total
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	
%TW$d=5$		3	2		1		6	13	19	34	11	2	6	17	1	115
%TW>5$d=10$	1	9	6	5	2	1	32	34	254	407	177	6	57	178	10	1179
%TW>10$d=15$	1		1				4		28	131	83	2	5	68	2	325
%TW>15$d=20$									7	40	36			17	1	101
%TW>20$d=25$	1								2	16	14		1	3		37
%TW>25$d=30$										16	6					22
%TW>30$d=35$										5	4					9
%TW>35$d=40$										3	2					5
%TW>40$d=45$											3					3
%TW>45$d=50$																0
%TW>50																0
Total/Support	3	12	9	5	3	1	42	47	310	652	336	10	69	283	14	1795

14


Wear Indications "B" Generator




Wear Indications "B" Generator



Wear Indications "B" Generator



Wear Distribution by Support Location



Excessive Wear Probable Causes

- Tube Vibration Induced by ROSTG Motion
- Excessive Compressive Load in Tubes
- High Wear Rate Coefficient for Inconel 690 with 410 SS TSP
- Acoustically Induced Tube Vibration
- Broached Hole Surface Finish Roughness
- Hourglass Broached Hole Divergent Nozzle

25

Tube Vibration Induced by ROTSG Motion with Primary or Secondary Pipe Flow

- Wide distribution of wear
- Pedestal is less resistant to rocking motion
- Factors to Consider:
 - Upper restraint may have gaps – beyond assembly concerns
 - Flow in the Hot Leg (Candy Cane) can cause ROSTG vibration
 - Main Steam flow restrictor can cause pressure pulsation
- Actions:
 - Verify gap measurements during RSG outage
 - Review loose parts monitoring data
 - Mount accelerometers on ONS Unit #2 during Fall 2005 outage
 - Contingency to mount instrumentation on ONS Unit 1

26

Excessive Compressive Load in Tubes

- Wide distribution of wear
- Wear marks on opposite sides of a tube at different TSPs
- Historical data suggest the OTSG tubes were sensitive to FIV when loads exceeded 300 lbs compression.
- Factors to Consider:
 - Most wear marks are at the periphery, compressive loading is highest in the center
- Actions:
 - MPR to conduct 3rd party review of BWC calculations and assumptions on tube loading both preload and operation state
 - Evaluate feasibility of installing strain gauges in/on a tube prior to pulling during Unit #2 outage
 - Evaluate feasibility of installing strain gauges in a tube in operation – Unit #2 or Unit #3

27

High Wear Rate Inconel 690 Tube to 410 Stainless Steel Support Plate

- Wide distribution of wear
- 410 stainless steel is harder than original carbon steel
- Factors to consider:
 - BWC wear rate coefficients seem conservative compared to values utilized by others
- Actions:
 - BWC / McMaster University is evaluating out wear testing
 - BWC has AECL performing independent wear simulations using VIBIC and H3DMAP
 - BWC review of EC results and development of gap correlations
 - Place accelerometers inside a tube to measure data
 - Duke and EPRI are evaluating wear rate coefficients

28

Acoustically Induced Tube Vibration

- Wide distribution of wear
- Significant amount of wear appears at the aspirator port and above where fluid medium is steam
- Wear did not occur in top span where the acoustic response is likely suppressed
- Factors to consider:
 - Original OTSG top span did not pass current industry guidance for acoustic suppression however no wear was observed
 - No unusual noise was reported
 - Slender structures are not typically prone to acoustic excitation
- Actions:
 - Place microphones or AE listening devices on or around the ROTSG
 - Install accelerometers inside a tube during operation
 - Review loose parts monitor data for vibration response
 - Investigating two mock-ups for laboratory studies

29

Broached Holes Surface Finish Roughness

- The majority of the wear is less than 0.007 inch deep
- Factors to consider:
 - Only a few tubes had wear greater than 40% Thru wall -0.014 inch deep
 - Units 2 and 3 have electro-polished holes which should have smoother surfaces
 - Surface imperfections should rub out without wear reaching the depths reported
- Actions:
 - Perform future inspections which should show decrease in wear rate

30

Hourglass Broached Hole

- Divergent nozzles have inherent flow instabilities due to jet switch from an imperfect configuration - tube is elastic
- Factors to consider:
 - Flow through a divergent cone can cause tube instability – prior worldwide experiences
- Actions:
 - BWC (M. Pettigrew) construct mock-up and perform tests
 - CFD model of tube to TSP interface

31

What We Theorize is Not Causing Wear

- Fluid Elastic Instability
 - No ring wear patterns
 - No mid-span wear
 - Lasted 14 months
- Near Instability Threshold
 - Statistically not valid for 3000 tube to be close with not one tube entering instability
- Classic Vortex Induced Vibration
 - No mid-span wear
 - Wear predominately confined to one location round the circumference at the broached hole
 - Wear noted in interior tubes where vortex shedding is not possible due to very low velocities
- High Turbulence Level
 - Cross flow in aspirator area too low
 - Wear rates are too low unless wear rate coefficient is found in error

32

What We Theorize is Not Causing Wear

- Axial Flow
 - Very little lateral energy in the power spectral density from axial flow
- Cross Flow in the Axial Region
 - Very little energy
- Flow Regime Instability
 - Low probability issue based on cross-flow regime maps

33

Other Possible Causes / Investigations

- Cross flow in the bundle periphery / gaps
 - 2D CFD model completed matches THEDA model fairly well
 - 3D CFD model underway
 - PORTHOS modeling by Areva/Framatome
 - Thermal expansion of the 410 SS TSP when compared to original carbon steel TSP, differential expansion may increase lateral contact load between the tube and TSP

34

Preliminary Conclusions

- No identified design errors – inputs and outputs of models appear reasonable this time
- Expert consensus that the ONS Unit #1 ROTSG are experiencing some flow induced wear – we do not understand excitation force
- Root cause work is continuing

35

Industry Experts Engaged Currently

- BWC design engineering organization
- Duke Technical Services/ ONS Engineering
- Areva / Framatome
- Dr. M K Au-Yang, formerly B&W Areva/Framatome
- Dr. M Pettigrew, Ecole Polytechnique
- Dr. John Luxat, McMaster University
- Dr. N Mureithi, Ecole Polytechnique
- Dr. E. de Langre, Ecole Polytechnique
- E. Blandford, G Srikantiah, EPRI
- M. Rao, Stress Technology – EPRI
- Various EPRI SGMP personnel
- MPR Associates
- N. Fisher, AECL (Chalk River)
- Y. Han, AECL (Chalk River)
- Dr. Alan Bilanin, Continuum Dynamics

36

Plugging Criteria

- Plug and stabilize all tube with wear indications $\geq 28\%$ thru wall - 30 tubes plugged "A" 18 tubes plugged in "B"
 - Wear rate assumed to be linear and based upon the highest rate observed in Unit #1 results 42% (average wear rate approximately 9.8%)
 - Wear rate used in the evaluation was increased based upon the NDE sizing uncertainty of 7.4% thru wall
 - ΔP pressure drop of 3930 psi
 - Material properties were evaluated by Monte Carlo analysis which is industry practice
 - Physical dimension of the flaws were adjusted to take into account linear taper, maximum length of the contact area is 1 inch
 - Allowable EOC maximum depth is 80.6% thru wall for a tapered flaw
 - Plugged tubes were stabilized
 - Plugging criteria was reviewed and accepted by BWC

37

Corrective Actions

Formal Corrective Actions will be detailed in the final root cause report; however, several CAs are evident including:

- Plug tubes on Unit #1 "A" and "B" SG that exceeded that plugging criteria of wear $\geq 28\%$ thru wall
- Refine plugging criteria for Units #2, #3
- Completed installation of the N-16 radiation monitors on each ONS unit
- Review operator actions for N-16 monitors and existing actions for tube leakage and rupture events

38

Corrective Actions

Unit 2 Outage (Oct. 2005)

- Pull two tubes for metallurgical examination
- Determine stress loadings on tubes when pulled
- Install instrumentation (accelerometers, acoustic monitoring)
- Prepare to plug up to 200 tubes

Unit 1 Forced Outage

- Install instrumentation

39

Future Impact

- Duke needs additional EC data to confirm results and validate models and assumptions. ONS will need to accumulate several cycles of data.
- Future inspections and wear rate analyses may result in three possible conclusions:
 - Wear rates higher than expected leading to mid cycle inspection outages
 - Wear rates follow the expected model leading to plugging tubes and more frequent inspections, every outage
 - Wear rates are less than expected and inspection schedule requires more than one additional 100% inspection to accomplish basis for returning to normal inspection frequency
- Possible impact on unit up-rate
- Possible impact on 24 month fuel cycles
- Possible modification to the existing ROTSGS

40

Summary

- Duke and BWC continue to evaluate generator wear using enhanced analysis methods
- BWC will be conducting experiments utilizing mock-ups to prove analysis assumptions, output, and results
- We remain confident the mechanism is fretting wear. We are still searching for the excitation force
- Duke is supplementing in-house expertise with a variety of consultants to ensure that testing plans and analyses are meaningful and lead to corrective actions that will resolve the issue
- This issue is not simple. Considerable effort expended and no "smoking gun" identified
- Expect root cause investigations and research to continue through summer
- Will keep NRC informed of root cause progress and any conclusions