



August 3, 2005

NG-05-0417 10 CFR 50.55a(a)(3)

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555-0001

Duane Arnold Energy Center Docket 50-331 License No. DPR-49 --

Request for Relief Regarding Limited Examination Coverage for Vessel Stabilizer Attachment Welds

In April of 2005, during the Duane Arnold Energy Center's (DAEC's) Refueling Outage (RFO) 19, surface examinations of the reactor vessel stabilizers' attachment welds were performed in accordance with the DAEC Inservice Inspection (ISI) Program. Less than "essentially 100%" coverage was obtained. Accordingly, pursuant to 10 CFR 50.55a(g)(5)(iii), Nuclear Management Company, LLC (NMC) requests relief on the basis that "essentially 100%" coverage is impractical due to physical obstructions.

This letter contains no new commitments and no revisions to existing commitments.

Gary Van Middlesworth

Site Vice President, Duane Arnold Energy Center

Nuclear Management Company, LLC

Enclosures (2)

Administrator, Region III, USNRC

Project Manager, DAEC, USNRC
Resident Inspector, DAEC, USNRC

ENCLOSURE 1 to NG-05-0417

Request Number NDE-R035

Request Number NDE-R035

Relief Request In Accordance with 10 CFR 50.55a(g)(5)(iii) --Inservice Inspection Impracticality--

1. ASME Code Components Affected

Code Class:

Class 1

References:

Subarticle IWB-2500

Table IWB-2500-1

Code Case N-509

Examination Category:

В-К

Item Number:

B10.10

Description:

Surface examination coverage of Reactor Vessel Stabilizers

Component Numbers:

VSW-0AZ, VSW-90AZ, VSW-180AZ, and VSW-270AZ

2. Applicable Code Edition and Addenda

ASME Section XI 1989 Edition, No Addenda.

3. Applicable Code Requirement

Subarticle IWB-2500 states, in part, "Components shall be examined and tested as specified in Table IWB-2500-1." Table IWB-2500-1, Examination Category B-H, (Integral Attachments for Vessels) includes reactor vessel integrally welded attachments as Item No. B8.10 and requires essentially 100% surface examination of these welds.

Code Case N-509, "Alternative Rules for the Selection and Examination of Class 1, 2, and 3 Integrally Welded Attachments, Section XI, Division 1," groups Examination Category B-H and Examination Category B-K-1 (Integral Attachments for Piping, Pumps, and Valves) into Category B-K-(Integral Attachments for Class-1-Vessels, Piping, Pumps, and Valves). The Duane Arnold Energy Center (DAEC) Inservice Inspection (ISI) Program utilizes Code Case N-509, therefore the vessel stabilizer attachment welds are categorized as Category B-K, Item B10.10. Code Case N-509 requires essentially 100% surface examination of these welds.

4. Impracticality of Compliance

Pursuant to 10 CFR 50.55a(g)(5)(iii) relief is requested on the basis that obtaining "essentially 100%" examination coverage is impractical due to physical obstructions and limitations imposed by design.

These welds integrally attach lugs to the vessel. The lugs are used to connect the vessel stabilizers to the vessel. The stabilizers prevent the necessary access to

perform the surface examination of the bottom side of the lug. In addition, the close proximity of the lug to the vessel prevents access.

5. Burden Caused by Compliance

The vessel stabilizers would require disassembly in order to provide the access necessary to complete the examination of 100% of the bottom weld.

6. Proposed Alternative and Basis for Use

Relief is requested from performing a complete coverage examination of the entire volume or area required. Entire volume or area required is defined by ASME Section XI Code Case N-460 titled "Alternative Examination Coverage for Class 1 and Class 2 Welds, Section XI, Division 1." Code Case N-460 states in part, "... when the entire examination volume or area cannot be examined ... a reduction in examination coverage ... may be accepted provided the reduction in coverage for that weld is less than 10%."

During Refueling Outage (RFO) 19, the stabilizer attachment welds received surface examinations to the extent practical with regard to the limited access available. Approximately 60% coverage was obtained for these surface examinations for attachment welds VSW-0AZ, VSW-90AZ, VSW-180AZ, and VSW-270AZ. No indications were identified.

The surface examination of approximately 60% of the vessel stabilizer attachment welds provides reasonable assurance that significant degradation, if present, would have been detected. Disassembly of the vessel stabilizers is impractical; the configuration of the attachment lugs does not provide an alternative examination to expand the coverage. Based on the percentage of examination coverage obtained, and the lack of indications, there is a high level of confidence in the continued structural integrity of the welds. There is no impact upon the overall plant quality and safety, and no adverse impact on the health and safety of the public.

7. Duration of Proposed Alternative


Relief is requested for the Third Ten Year Interval of the Inservice Inspection Program for the DAEC, currently scheduled to end on October 31, 2006.

8. Precedent

By letter dated November 21, 1997, the NRC granted a similar relief (NDE-024) for limited coverage that was obtained for vessel stabilizer attachment welds VSW-0AZ, VSW-90AZ, VSW-180AZ, and VSW-270AZ during the Second Ten Year Interval.


ENCLOSURE 2 to NG-05-0417

SUPPORTING INFORMATION




DAEC INSTRUCE INSPECTION NAME SECTION AT COUNTRIC

ECP NO	<i>//ن</i>	<u> </u>	WO i	NO. 1132948		ISI/P	SI NO I	05158
ECP NO 1/A WO NO. 1132948 ISI/PSI NO IOSISE STABILIZER AR NO 1/A DWG. OR ISO NO 1.1-10 COMPONENT OR SYSTEM VSW - 0° AZ								
PROCEDURE NO 1211.5 REV 6 ACCEPT STD 3.11.6				EQUIPMENT NO. ID QD 024 BU CAL DUE DATE 11/06 AC DC DE AMPERAGE 1/A YOKE/PROD SPACING 6" 70		DRY BLAC WCP	PRY POWDER: RED //A PLACK //A GRAY //A PCP CP-1 9CM RED OZKIZK	
COMP.	TEMP.	89	•F	THICKNESS 3 ½			~ •	·
ITEM		TIAL ECTION	DEFECT CODE*	INITIAL INSPECTION REMARKS	REINSPEC	TION	DEFECT CODE*	REINSPECTION REMARKS
vsw	ACC	REJ		(SIZE/LOCATION)	ACC	REJ		(SIZE/LOCATION)
0.	V			NO INDICATIONS				
		/		////				
						/		
*DEFECT CODE 60 % WELD EXAMINED PREVIOUS INSPECTION DATA REVIEWED								
P - POROSITY, R - ROUNDED, LI - LINEAR INDICATION, LA - LAMINATION, O - OTHER (IDENTIFY)								
O' AZ COMMENTS/SKETCH MT EXAMINATION WAS LIMITED ONLY TO THE TOP WELD. THE BOTTOM WELD IS								
INACESSABLE THE MT COULD ONLY BE								
PER FORMED IN THE LONGITUDINAL PLANE OF THE WELD. SEE PAGE 2 SKETCH. GO'. OF THIS WELD WAS MT EXAMINED IN OUR DIRECTION. Note: For Section XI exams, note indication length, location and component thickness.								
Examiner Level/Date Reviewed By Hundry 4/7/05 Reviewed By 18 4-1905 Reviewed By 18 4-190								




Page 242

ECP NO WO NO	o. 113 2948	ISI/P	SI NO	[05159			
AR NO MA DWG. OR ISO NO	0 1.1-10 COMPONENT						
PROCEDURE NO 1211.5 REV 6 ACCEPT STD 3.11.6	EQUIPMENT NO. ID 90024 CAL DUE DATE 6/11/06 AC DC DRY BLAC AMPERAGE 1/A YOKE/PROD SPACING 6" WCP		POWDER: RED W/A CK W/A GRAY W/A CP-1 9CM RED O2K12K F or 7HF BLACK				
COMP. TEMP. 39 °F THICKNESS 3%"							
INSPECTION DEFECT CODE*	INITIAL INSPECTION REI	INSPECTION	DEFECT CODE*	REINSPECTION REMARKS			
VSW ACC REJ	(SIZE/LOCATION) AC	C REJ		(SIZE/LOCATION)			
180°	NO INDICATIONS	4/					
*DEFECT CODE 60 % WELD EXAMINED PREVIOUS INSPECTION DATA REVIEWED AND PREVIOUS DATA REVIEWED A							
P - POROSITY, R - ROUNDED, LI - LINEAR INDICATION, LA - LAMINATION, O - OTHER (IDENTIFY) 60% OF THIS WELD WAS MT EXAMINED IN ONE OTHER TYPIC TO THE TOTAL OF THIS WELD WAS MT EXAMINED IN ONE OTHER TYPIC TO THE TOTAL OF THE TOT							
SEE PAGE Z SKETCH. THE MT EXAMINATION WAS LIMITED TO THE							
TOP WELD ONLY, DUE TO OBSTRUCTIONS AND BEING INACESSIBLE, THE MT OF THE							
BOTTOM WELD COULD NOT - BE PERFORMED.							
THE MT EXAMINATION COULD ONLY BE PERFORMED IN THE LONGITUDINAL PLANE OF THE WELL. Note: For Section XI exams, note indication length, location and component thickness.							
Examiner July 1/3/05 Reviewed By Much Johnson 4/1/05 Reviewed By 39 4-19-5 Signature/Level/Date Level III Signature/Date ANII Signature/Date NG-1112 REV. 3							



ECP NO WO NO). <u>1132948</u>	ISI/PSI NO 105/60				
AR NO PA DWG. OR ISO NO	O 1.1-10 COMPONENT	RV VESSEL STABILIZER OR SYSTEM VSW-270 AZ				
PROCEDURE NO 1211.5 REV 6 ACCEPT STD 3.11.6	CAL DUE DATE . VII/O6 · AC AMPERAGE VIA YOKE/PROD SPACING 6					
COMP. TEMP. <u>89</u> °F	THICKNESS 3 1/8					
INITIAL INSPECTION DEFECT CODE*	INITIAL INSPECTION REIN REMARKS	REINSPECTION REMARKS DEFECT CODE*				
VSW ACC REJ	(SIZE/LOCATION) ACC	REJ (SIZE/LOCATION)				
270' /	NO INDICATIONS					
+DEFECT CODE 60 % WELD EXAMINED PREVIOUS INSPECTION DATA REVIEWED						
P - POROSITY, R - ROUNDED, LI - LINEAR INDICATION, LA - LAMINATION, O - OTHER (IDENTIFY)						
270° AZ. THE MT EXAMINATION WAS TO THE TOP WELD ONLY DO INACESSIBILITY OF THE BOTTO THE MT EXAMINATION COULD PERFORMED IN THE LONGITU OF THE WELD. SEE PAGE 2	DIM WELD. ONLY BE VILLAGE ONLY SEE VILLAGE ONLY SKETCH.	RPV/wall				
60% OF THIS WELD WAS EXAMINED BY MT IN ONE DEECTION. Note: For Section XI exams, note indication length, location and component thickness.						
Examiner	riewed By Harl Adumen 4/11/0	OF Reviewed By JG 4-1905 Date ANII Signature/Date				



Page 242

ECP NO 4/4 WO NO). <u>//32948</u>	ISI/PSI NO 105	161				
AR NO DWG. OR ISO NO) /./-/O COMPONENT OF	RV VESSEL S R SYSTEM VSW - 90 ·	AZ				
PROCEDURE NO 1211.5 REV 6 ACCEPT STD 3.//. 6	EQUIPMENT NO. ID QD 024 CAL DUE DATE \$/11/0C (AC) E AMPERAGE . 11/A YOKE/PROD SPACING 6"	DRY POWDER: RED BLACK "/A GRA WCP <u>CP-1</u> 9CM	BATCH NO. DRY POWDER: RED */^ BLACK */A GRAY */A WCP CP-1 9CM RED O 2 K 12 K 7C-F or 7HF BLACK */A				
COMP. TEMP89	THICKNESS 3 1/8 *	-					
INITIAL INSPECTION DEFECT CODE*	INITIAL INSPECTION REINSPECTION REINSPECTION	DEFECT CODE*	INSPECTION REMARKS				
VSW ACC REJ	(SIZE/LOCATION) ACC	REJ (SIZ	E/LOCATION)				
90"	NO INDICATIONS						
	/////						
*DEFECT CODE 60 % WELD EXAMINED PREVIOUS INSPECTION DATA REVIEWED JH							
P - POROSITY, R - ROUNDED, LI	I - LINEAR INDICATION, LA - LI	AMINATION, O - OTHER (IDENTIFY)				
90° AZ. COMMENTS/SKETCH THE MT EXAMINATION WAS LIMITED TO THE TOP WELD ONLY, DUE TO THE INACESSABIUTY OF THE BUTTOM WELD. THE MT EXAMINATION COULD ONLY BE							
PERFORMED IN THE LONGITUNIAL PLANE OF THE WELD. SEE PAGE & SKETCH. GO'. OF THIS WELD WAS MT EXAMINED IN ONE DIRECTION. Note: For Section XI exams, note indication length, location and component thickness.							
Examiner I I I I I I I I I I I I I I I I I I I							

VS-01-32

REV.