



U. S. Nuclear Regulatory Commission

Augmented Inspection Team

Inspection of Uranium Hexafluoride
(UF₆) Release at Honeywell Site

December 22, 2003

01-8



U.S. Nuclear Regulatory Commission


- NRC License No. SUB-526
- Convert uranium ore concentrates into uranium hexafluoride (UF_6)
- When UF_6 is released to the atmosphere, it forms uranyl fluoride and hydrofluoric acid
- The hydrofluoric acid presents the greatest hazard




U.S. Nuclear Regulatory Commission


- AIT Team
 - David Hartland, Manuel Crespo, Richard Gibson,
and Nick Baker
- AIT Inspection Objectives
 - determine facts surrounding event
 - assess the licensee's response to event
 - assess the licensee's activities during their
event review and recovery
 - identify root causes
 - assess the public health and safety impact

Simplified Process Drawing





C-minus control valve that began to leak UF₆




← Dust Collector Piping
(Valve on other side)

← C-minus Valve
Removed from here

← C-train System Valve

Dust Collector Exhaust
Point





U.S. Nuclear Regulatory Commission Event Response

- Licensee initial response actions on site were in accordance with emergency response plan
- Declaration of Site Area Emergency done in timely fashion but inadequate information provided to local emergency response personnel
- Room for improvement in some emergency response positions and implementation



U.S. Nuclear Regulatory Commission

Root Causes/Contributing Factors

- The AFO did not place the dust collector valves and the system valves in the correct positions
- The AFO had no procedure or checklist that designated the proper valve positions for the reconfiguration
- No management oversight/review to ensure valves were in correct positions
- Reconfiguration from one to two fluorinator lines performed infrequently



U.S. Nuclear Regulatory Commission

Root Causes/Contributing Factors

- AFO was working a double shift
- System pressure indicators do not have a visible or audible alarm to indicate when pressure is approaching positive
- The boiler/distillation operator was not informed that the vacuum system would be taken off line during the shift
- Pump/motor coupling needed to start the Nash pumps failed, which contributed to the duration of the release



U.S. Nuclear Regulatory Commission Public Health and Safety Impacts

- Impact low based on review and analysis of:
 - Licensee and State of Illinois air, soil and vegetation sample results
 - Worker and members of public bioassays
 - Licensee release calculation (70 pounds)
 - RASCAL assessment of release (42 pounds)
 - Four members of public reported to local hospital; one kept 24 hours for treatment of possible HF exposure



U.S. Nuclear Regulatory Commission

- AIT exited with licensee at public meeting on January 6, 2004
- Approximately 130 members of public present
- Majority of public concerns focused on emergency response actions and communications



U.S. Nuclear Regulatory Commission Licensee Restart Focus Area

- Revise Emergency Response Plan
- Involve local emergency response officials
- Improve emergency response notification
- Improve communications between plant and off-site emergency response personnel
- Public outreach and education
- Conduct emergency drill before re-start



U.S. Nuclear Regulatory Commission

NRC Follow-up Actions

- Frequent communications with licensee, State and local governments and NRC Senior Management
- Management meeting on 2/11 in NRC HQ
- Public meetings on March 18 and April 21
- Restart inspection team on site several weeks during phased restart
- NRC approval before restart of each phase
- Site in full production as of April 26