

Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION



| | | | |
|----------------------------------------|-------------------------------------|----------------------------------------------------------------------------------|--|
| 1. LICENSEE 3 M Company | | 2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road Lisle, IL 60532 | |
| REPORT NUMBER(S) 2005-001 | | | |
| 3. DOCKET NUMBER(S) 03004952 | 4. LICENSE NUMBER(S) 22-00057-07 | 5. DATE(S) OF INSPECTION 8/18/05 | |
| 6. INSPECTION PROCEDURES USED 87126 | | 7. INSPECTION FOCUS AREAS 03.01-03.07 | |

SUPPLEMENTAL INSPECTION INFORMATION

| | | | |
|----------------------------|------------------|---------------------------------------|-------------------------------------|
| 1. PROGRAM CODE(S) 3611 | 2. PRIORITY 5 | 3. LICENSEE CONTACT Fred Entwistle | 4. TELEPHONE NUMBER 651/733-7216 |
|----------------------------|------------------|---------------------------------------|-------------------------------------|

Main Office Inspection Next Inspection Date: 8/2010

Field Office _____

Temporary Job Site _____

PROGRAM SCOPE

Licensee is engaged in research and development of products containing radioactive material. This licensee is located in St. Paul, MN and encompasses a number of locations in the greater twin cities area. Licensee uses radioactive materials in the development of new products and for testing of existing product lines and processes.

Performance Observations

The inspector toured the facilities and interviewed authorized users staff members. Each appeared knowledgeable in radiation safety and isotope handling techniques. Package receipt procedures were demonstrated for the inspector as well as rad waste handling practices were discussed. Independent surveys by the inspector did not detect any abnormal reading and were within the expected range.

The inspector observed the material storage area and found it to be adequate. Records of shipments were reviewed as well as material inventory control procedures. Techniques employed by the staff demonstrated good handling practices as well as adequate knowledge of radiation safety. During the course of the inspection, no abnormalities were noted.