Exelon Nuclear Peach Bottom Atomic Power Station 1848 Lay Road Delta, PA 17314-9032 Telephone 717.456.7014 www.exeloncorp.com



10CFR 50.73

September 2, 2005

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555-0001

> Peach Bottom Atomic Power Station (PBAPS) Unit 2 Facility Operating License No. DPR-44 <u>NRC Docket No. 50-277</u>

Subject: Licensee Event Report (LER) 2-05-01

This LER reports an unplanned automatic scram of Unit 2 during the performance of routine main turbine testing. In accordance with NEI 99-04, the regulatory commitment contained in this correspondence is to restore compliance with the regulations. The specific methods that are planned to restore and maintain compliance are discussed in the LER. If you have any questions or require additional information, please do not hesitate to contact us.

Sincerely,

Joseph P. Grimes Plant Manager Peach Bottom Atomic Power Station

JPG/djf/CR 351609

Attachment

cc: PSE&G, Financial Controls and Co-owner Affairs R. R. Janati, Commonwealth of Pennsylvania INPO Records Center S. Collins, US NRC, Administrator, Region I R. I. McLean, State of Maryland US NRC, Senior Resident Inspector

CCN 05-14074



										ADDO		10		104		EVDIDEO	08/20/0007		
NRC FOR (6-2004)	RC FORM 366 U.S. NUCLEAR REGULATORY COMMISSION -2004)							SSION	APPH(и В :	NO. 3150-0	104		CAPINES:	00/30/2007			
(See reverse for required number of								Estimated burden per response to comply with this mandatory collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and led back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct											
		digit	s/chara	acters	ior ea	ich b	lock)			or spo collecti	nsor, and a	per	son is not	required	to resp	ond to, the	Information		
1. FACIL	ITY NAM	1E								2. DOCKET NUMBER 3. P/				3. PA	. PAGE				
Peach Bottom Atomic Power Station							05000 2771_OF					<u>OF 4</u>							
4. TITLE	0.4				T			h			- Main 7	· · · · · · ·	in a Track						
	2 Auto	omatic S	cram o		Incorr	ect P	Issumpti	ons whe	a TE	orting	a Main 1		one Test	011171					
<u>5. E</u>	VENID		0.				<u>7. R</u>	EPORTD		FAC	ILITY NAME	8. C	THERFA		25 INVC	DOCKET I	NUMBER		
MONTH	DAY	YEAR	YEAR	NUM	BER	NO.	MONTH	DAY	YEAF	1						050	00		
07	10	2005	05	- 0	1 -	0	09	2	200	5							00 00		
9. OPER	ATING I	NODE	1	1. THIS	REPO	RTIS	SUBMITTI	ED PURS	UANT 1	O THE	REQUIRE	MEI	NTS OF 10	CFR§	: (Chec	k all that a	pply)		
1 10. POWER LEVEL 100			□ 20.2201(b) □ 20.2203(a)(1) □ 20.2203(a)(2)(i) □ 20.2203(a)(2)(ii) □ 20.2203(a)(2)(iii) □ 20.2203(a)(2)(iii) □ 20.2203(a)(2)(iv) □ 20.2203(a)(2)(v) □ 20.2203(a)(2)(v) □ 20.2203(a)(2)(v)			 20.2203(a)(3)(i) 20.2203(a)(3)(ii) 20.2203(a)(4) 50.36(c)(1)(i)(A) 50.36(c)(2) 50.36(c)(2) 50.46(a)(3)(ii) 50.73(a)(2)(i)(A) 50.73(a)(2)(i)(B) 		$ \begin{bmatrix} 50.73(a)(2)(i)(C) \\ 50.73(a)(2)(ii)(A) \\ 50.73(a)(2)(ii)(B) \\ 50.73(a)(2)(iii) \\ 50.73(a)(2)(iv)(A) \\ 50.73(a)(2)(v)(A) \\ 50.73(a)(2)(v)(B) \\ 50.73(a)(2)(v)(C) \\ 50.73(a)(2)(v)(D) \\ \end{bmatrix} $		 50.73(a)(2)(vii) 50.73(a)(2)(viii)(50.73(a)(2)(viii)(50.73(a)(2)(ix)(A 50.73(a)(2)(x) 73.71(a)(4) 73.71(a)(5) OTHER Specify In Abstract or In NBC Form 36)(A))(B) A) ct below 366A							
						1	2. LICENS	SEE CON	FACT F	OR TH	IS LER	_		_	01 11				
FACILITY NAME								R (Include Ar	ea Code)										
PBAPS Unit 2, James Mallon, Regulatory Assurance Manager [717-456-3351																			
							FAILUF	IE DESCRI	BEC	D IN THIS	REPOR	<u> </u>							
CAU	CAUSE SYSTEM		COMPC	NENT		JRER	REPOR TO E	EPIX		CAUSE S		:м (NT FA	MANU- CTUREF		DRTABLE DEPIX		
x		IT	RL	Y	G0	80	ר	Č											
		14	. SUPPI	EMENT	TAL RE	EPOR	T EXPECT	ED	_	_	15.	EX	PECTED	м	нтис	DAY	YEAR		
	S (If yes	, complet	e 15. EX	PECTEL	D SUBI	MISSI	ON DATE)		Σ		50	D' NBN	ATE						
ABSTRA	CT (Lim	nit to 1400	spaces,	i.e., app	oroxima	ately 1	5 single-sp	aced type	written	lines)					l		!		
ABSTRA	On 7 Stop gener Turb Main Reac Syste autor conse conce	/10/05, a Valve cl rated du ine trip s Turbing tor Vess om (PCIS natic op equences erning th	spaces, at appro- losure s ring pe signal v e condi el wate 5) Grou eration s assoc ne statu	<i>i.e., app</i> oximat ignal. rforma vas ger tion th r level p II an of the iated s of the	tely 0. The N ance c nerate at req 3 set ad III i e C, 1 with e Mai	318 F Main of the d wh uired solat D, ar this n Tu	5 single-sp nours, a U Turbine weekly en a faile the Mai was reac ions. Als nd E Ma event. T rbine trip	Unit 2 au Stop val Main T ed test w n Turbir ched as e in Stear he Mair o system	utoma urbine vas bei ne to b xpecte ctor V n Safe and n ietion	tic scr ad close Mech ng abo e tripp ed. Th essel f ety Re oine th ot inv	am occur sed as a re hanical T orted and oed. As a is resulted high press elief Valv rip was o olving ad	rred sul rip dic res l in ure ves. caus lditi	as a res t of a Ma Valve re I not refluit ult of the Primary conditio There v sed by i ional per	ult of ain Tu outine ect an e autor Conta n occu were in n corra	a Mai rbine test. ' y actua matic s inmen urred n no act ect ass il while	n Turbin trip signa The Mai al advers cram, th t Isolatio esulting i ual safet sumption	e ll n e e n n y s g		

٠

the routine test. Corrective actions include remediation and re-evaluation of involved personnel and reinforcing management expectations regarding human performance practices.

NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION (1-2001) LICENSEE EVENT REPORT (LER)													
FACILITY NAME (1)	DOCKET (2)		LER NUMBER (6	PAGE (3)									
Peach Bottom Atomic Power Station, Unit 2		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER									
	05000277	_05	- 01	- 00	2	_OF_	4						

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

Unit Conditions Prior to the Event

Unit 2 was in Mode 1 and operating at approximately 100% rated thermal power when the event occurred. There were no structures, systems or components out of service that contributed to this event. Weekly Main Turbine (EIIS: TRB) Mechanical Trip Valve (EIIS: V) testing was in progress.

Description of the Event

On 7/10/05, at approximately 0318 hours, a Unit 2 automatic scram occurred as a result of a Main Turbine Stop Valve closure signal. The Main Turbine Stop valves had closed as a result of a Main Turbine trip signal generated during performance of the weekly Main Turbine Mechanical Trip Valve routine test. The Main Turbine trip signal was generated when a failed test was being aborted and did not reflect any actual adverse Main Turbine condition that required the Main Turbine to be tripped.

As a result of the automatic scram, the Reactor Vessel water level 3 set point was reached as expected. This resulted in Primary Containment Isolation System (PCIS) Group II and III isolations. The PCIS (EIIS: JM) Group II and III isolations resulted in the closure of valves in various systems including the Reactor Building Ventilation system (EIIS: VA), the Containment Atmospheric Control / Containment Atmospheric Dilution systems (EIIS: BB), the Reactor Water Cleanup sytem (EIIS: CE) and other containment penetrating process lines. The Standby Gas Treatment system (EIIS: BH) also actuated as expected on the Group III PCIS isolation. Also, as expected for an automatic scram involving closure of the Main Turbine Stop Valves, a Reactor Vessel high pressure condition occurred resulting in automatic operation of the C, D, and E Main Steam Safety Relief Valves (SRVs) (EIIS: RV) and initiation of Alternate Rod Insertion (EIIS: AA). The Recirculation Pump Motors (EIIS: AD) also tripped as a result of the closure of the Main Turbine Stop Valves as designed. All control rods properly inserted and there were no safety significant anomalies involved with the plant equipment response to the event.

The scram and ARI initiation were reset by approximately 0327 hours. The PCIS Group II and III isolations were reset by approximately 0335 hours and the normal Reactor Building ventilation was restored by approximately 0355 hours.

As required by 10CFR 50.72, NRC prompt notifications were completed on 7/10/05 at approximately 0642 hours to report the automatic scram and PCIS isolations (Event Notification #41832). This report is being submitted pursuant to 10CFR50.73 (a)(2)(iv)(A) due to valid actuations of the Reactor Protection System and the Primary Containment Isolation System.

Analysis of the Event

There were no actual safety consequences associated with this event. The normal heat removal path (i.e. feedwater / condenser) was maintained during the event. All control rods properly inserted and there were no safety significant anomalies involved with safety equipment response to the event. It was determined that safety systems responded appropriately for this event. This event is bounded by the non-limiting event entitled 'Turbine Trip from High Power with Bypass' described in Updated Final Safety Analysis Report (UFSAR) section 14.5.1.2.1. As noted in this UFSAR section, it is expected that the SRVs would open for a short time to relieve the pressure increase caused by the transient.

	DOCKET (2)	<u>l</u>	LER NUMBER (6)			PAGE (3	
	05000277	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			4
Peach Bottom Atomic Power Station, Unit 2		05	- 01 -		3	OF	
ARRATIVE (If more space is required, use additional copie	s of NRC Form 366A) (17)					
Analysis of the Event (continued)							
The Main Turbine trip signal was generat routine test. This test verifies that the M performed weekly with the Main Turbine Turbine emergency trip system hydrauli thereby resulting in a Main Turbine Stop mechanically operated by the Main Turb Final Safety Analysis Report (UFSAR) so could generate missiles. The Main Turbine did not reflect any adverse Main Turbine	ted during perform lain Turbine Mec in service. The p ic pressure in the p and Control Va ine over-speed tri ection 11.4 to min ne trip signal was e condition that a	nance of the chanical Tr rimary pur event of a lve closure p mechani nimize the l generated ctually req	te Main Turbin Tip Valve (MT Tipose of the MT a Main Turbin e (i.e. main Tu ism. The test is likelihood of a l when a failed te puired the Mair	e Mechanic V) is funct IV is to rem e over-spea rbine trip). credited in Main Turbi est was bein n Turbine to	al Trij ioning iove th ed cor The N the U ne fail g abor o be tr	p Valve g and is he Main ndition, MTV is Jpdated ure that ted and ipped.	
This event is not considered as risk sign	ificant.						
Cause of the Event							
The cause of the event is due to shortcom routine test being performed on 07/10/0.	nings in human po 5.	erformance	e when aborting	g the Main	Turbiı	ne MTV	
While performing the test, the test accept indication lights that the MTV had been signal was applied during the test. Whet utility) performing the test received direct test. Because there are two indications of Supervisor (CRS) that the test oil signal actuation did not occur. The CRS did not test. The steps in the routine test involvin and the test was aborted by placing the test MTV had actuated as a result of the test Turbine tripped.	otance criteria ha actuated by the N in the indication ction from the Con of MTV actuation had not been rec t request any addi- ng the resetting of rip system back in a oil signal. Wher	d not been lain Turbir was not re- ntrol Room , it was inc eived by th tional revie the test oil service. H the MTV	met. This was ne over speed n ceived, the Rea Supervisor (lic correctly assum ne over speed r ew concerning t l signal were as Iowever, the ow was placed ba	s a result of nechanism actor Opera- censed, utili- ned by the 0 mechanism the method ssumed to b ver speed m ack into serv	not re when ator (l ty) to a Contro and th of abo be not hechan vice, t	eceiving a test oil icensed, abort the ol Room he MTV rting the required hism and he Main	
	pears to be related	i to a relav	card (General	Electric, 12	25 VD	C Relay	

	DOCKET (2)		LER NUMBER (6)		PAGE (3	<u>8)</u>
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
each Bottom Atomic Power Station, Unit 2	05000277	05	- 01	- 00	4	OF	4
ARRATIVE (If more space is required, use additional cop	ies of NRC Form 366A	4) (17)					
Corrective Actions							
The CRS has been remediated and reevand of full control room duties.	aluated, additiona	l corrective	actions will be	e taken prio	r to res	umption	l
A standing order was issued to licensed performance practices.	operators commu	nicating ma	nagement exp	ectations reg	gardin	g human	l
An assessment of Operations personne behaviors will be performed.	nel concerning th	eir knowle	edge of expec	cted humar	n perfe	ormance	:
A case study was developed covering t	he details of this e	event for us	se in continuir	ig training.			
The relay card and MTV switch were re operation.	eplaced by 7/11/0	5 and MTV	indication wa	as tested to	ensure	reliable	•
Previous Similar Occurrences							
There were no previous LERs identifie	d involving Main	Turbine tr	ips during test	ing.			