



SEP 20 2005

U.S. Nuclear Regulatory Commission
ATTN: NRC Document Control Desk
Washington, DC 20555

Serial: HNP-05-081
10 CFR 50.73

SHEARON HARRIS NUCLEAR POWER PLANT UNIT 1
DOCKET NO. 50-400/LICENSE NO. NPF-63
LICENSEE EVENT REPORT 2002-004-08


Ladies and Gentlemen:

The enclosed Licensee Event Report (LER) 2002-004-08 is submitted in accordance with 10 CFR 50.73. This report is a revision to a previously submitted LER that describes an unanalyzed condition due to inadequate separation of associated circuits. Previous revisions to this report, LER 2002-004-00, submitted on February 18, 2003; LER 2002-004-01, submitted on March 26, 2003; LER 2002-004-02, submitted on September 19, 2003; LER 2002-004-03, submitted on April 12, 2004; LER 2002-004-04, submitted on October 12, 2004; LER 2002-004-05, submitted on November 15, 2004; LER 2002-004-06, submitted on December 20, 2004, and LER 2002-004-07, submitted on March 31, 2005, described similar unanalyzed conditions. The revised information includes additional conditions in previously identified fire areas.

Corrective actions underway in response to the previously identified conditions include a validation of the safe shutdown analysis. This validation is a detailed analysis of the routing of cables affecting equipment credited in response to a fire. The commitments and associated due dates identified in Section VI have been revised to reflect the completion dates for the conditions that have already been corrected and for the remaining conditions in different refueling outages. Compensatory actions, including fire watches, ensure safety pending permanent resolution of the identified conditions.

Please refer any questions regarding this submittal to Mr. Dave Corlett, Supervisor – Licensing/Regulatory Programs, at (919) 362-3137.

Sincerely,



FOR

Eric McCartney
Plant General Manager
Harris Nuclear Plant

EAM/jpy

Enclosure

Progress Energy Carolinas, Inc.
Harris Nuclear Plant
P. O. Box 165
New Hill, NC 27562



Serial: HNP-05-081

Page 2

c: Mr. R. A. Musser (HNP Senior NRC Resident)
Mr. C. P. Patel (NRC-NRR Project Manager)
Dr. W. D. Travers (NRC Regional Administrator, Region II)

NRC FORM 366 (6-2004)	U.S. NUCLEAR REGULATORY COMMISSION	APPROVED BY OMB: NO. 3150-0104	EXPIRES: 06/30/2007
<h2 style="margin: 0;">LICENSEE EVENT REPORT (LER)</h2>		Estimated burden per response to comply with this mandatory collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.	

1. FACILITY NAME Harris Nuclear Plant – Unit 1	2. DOCKET NUMBER 05000400	3. PAGE 1 OF 23
--	-------------------------------------	---------------------------

4. TITLE
 Unanalyzed Condition Due to Inadequate Separation of Associated Circuits

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
07	22	2005	2002	- 004 -	08	09	20	2005	N/A	05000
									N/A	05000

9. OPERATING MODE 1	11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR§: (Check all that apply)			
10. POWER LEVEL 100	<input type="checkbox"/> 20.2201(b) <input type="checkbox"/> 20.2201(d) <input type="checkbox"/> 20.2203(a)(1) <input type="checkbox"/> 20.2203(a)(2)(i) <input type="checkbox"/> 20.2203(a)(2)(ii) <input type="checkbox"/> 20.2203(a)(2)(iii) <input type="checkbox"/> 20.2203(a)(2)(iv) <input type="checkbox"/> 20.2203(a)(2)(v) <input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 20.2203(a)(3)(i) <input type="checkbox"/> 20.2203(a)(3)(ii) <input type="checkbox"/> 20.2203(a)(4) <input type="checkbox"/> 50.36(c)(1)(i)(A) <input type="checkbox"/> 50.36(c)(1)(ii)(A) <input type="checkbox"/> 50.36(c)(2) <input type="checkbox"/> 50.46(a)(3)(ii) <input type="checkbox"/> 50.73(a)(2)(i)(A) <input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(i)(C) <input type="checkbox"/> 50.73(a)(2)(ii)(A) <input checked="" type="checkbox"/> 50.73(a)(2)(ii)(B) <input type="checkbox"/> 50.73(a)(2)(iii) <input type="checkbox"/> 50.73(a)(2)(iv)(A) <input type="checkbox"/> 50.73(a)(2)(v)(A) <input type="checkbox"/> 50.73(a)(2)(v)(B) <input type="checkbox"/> 50.73(a)(2)(v)(C) <input type="checkbox"/> 50.73(a)(2)(v)(D)	<input type="checkbox"/> 50.73(a)(2)(vii) <input type="checkbox"/> 50.73(a)(2)(viii)(A) <input type="checkbox"/> 50.73(a)(2)(viii)(B) <input type="checkbox"/> 50.73(a)(2)(ix)(A) <input type="checkbox"/> 50.73(a)(2)(x) <input type="checkbox"/> 73.71(a)(4) <input type="checkbox"/> 73.71(a)(5) <input type="checkbox"/> OTHER
Specify in Abstract below or in NRC Form 366A				

12. LICENSEE CONTACT FOR THIS LER

FACILITY NAME John Yadusky – Licensing Engineer	TELEPHONE NUMBER (Include Area Code) (919) 362-2020
--	--

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX

14. SUPPLEMENTAL REPORT EXPECTED <input type="checkbox"/> YES (If yes, complete 15. EXPECTED SUBMISSION DATE)	<input checked="" type="checkbox"/> NO
---	--

15. EXPECTED SUBMISSION DATE

MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On December 20, 2002, inspection of the Harris Nuclear Plant (HNP) Safe Shutdown Analysis (SSA) identified that postulated fires could cause spurious actuation of certain valves. Valve actuation in the flowpath for the protected Charging/Safety Injection Pump (CSIP) could result in loss of the pump. Similarly, simultaneous spurious closure of multiple valves in the flowpaths to the Reactor Coolant Pump (RCP) seals could result in the loss of RCP seal cooling. HNP implemented interim compensatory actions upon discovery.

During review and validation, HNP identified other postulated fires could cause spurious actuation of certain valves or components that could also result in the conditions described above and other similar conditions. These additional conditions were discovered on January 29 and July 23, 2003; February 13, August 13, September 14 & 15, October 4, 20, 26 & 29, 2004; and January 18, July 22, and August 4, 2005.

The cause of these conditions is inadequate original Safe Shutdown Analysis of certain conductor-to-conductor interactions or certain operator manual actions. Design changes or other methods approved by the NRC will be used to restore compliance.

NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION
(1-2001)

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Harris Nuclear Plant – Unit 1	05000400	2002	- 004	- 08	2 OF 23

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

I. DESCRIPTION OF EVENT

The Harris Nuclear Plant (HNP) discovered that a condition exists with the lack of separation of cables for redundant components credited by the Safe Shutdown Analysis (SSA). This condition was discovered on December 20, 2002 and reported in LER 2002-004-00, dated February 18, 2003. Revision 1 to this LER describes another condition, which was discovered on January 29, 2003. Revision 2 to this LER describes another condition, which was discovered on July 23, 2003. Revision 3 to this LER describes another condition, which was discovered on February 13, 2004. Revision 4 to this LER describes additional conditions, which were discovered on August 13, September 14, and September 15, 2004. Revision 5 to this LER describes additional conditions, which were discovered on September 15 and October 4, 2004. Revision 6 to this LER describes additional conditions, which were discovered on October 20, October 26, and October 29, 2004. Revision 7 to this LER describes additional conditions, which were discovered on January 18, 2005. Revision 8 to this LER describes additional conditions, which were discovered on July 22 and August 4, 2005.

On December 20, 2002, with the Unit in Mode 1 at 100% power, inspection of the Harris Nuclear Plant (HNP) Safe Shutdown Analysis (SSA) in Case of Fire identified that for postulated fires in three SSA fire areas, the design and compensatory actions credited by the SSA would not ensure a protected train of equipment would remain available. Specifically, the inspection identified that postulated fires could cause spurious actuation of components potentially resulting in loss of the Charging/Safety Injection Pump (CSIP) [CB-P] or loss of Reactor Coolant Pump (RCP) [AB-P] seal cooling credited by the SSA. The fires were postulated to cause spurious closure of valves in the flowpaths for the protected CSIP, prior to implementation of the preplanned actions designed to preserve these flowpaths, resulting in loss of the protected CSIP if it was in service at the time of the postulated fire. Similarly, the fires were postulated to cause spurious closure of valves in the flowpath of Component Cooling Water (CCW) [CC] to the RCP thermal barrier heat exchangers, resulting in loss of flow to RCP thermal barrier heat exchangers credited by the SSA for RCP cooling.

On January 29, 2003, with the Unit in Mode 1 at 100% power, HNP identified that simultaneous spurious opening of multiple valves could result in transferring of Refueling Water Storage Tank (RWST) [BE-, BP-, & BQ-TK] inventory to the containment recirculation sump. A roving fire watch has been posted in fire areas of concern.

On July 23, 2003, with the Unit in Mode 1 at 100% power, HNP identified that spurious opening of certain valves could result in transferring of RWST inventory to the containment recirculation sump. A roving fire watch was already posted in fire areas of concern as interim compensatory actions for other safe shutdown related issues, and the fire watch remains posted. This discovery of an old design issue was made during validation of the HNP safe shutdown analysis. This validation was being performed as a corrective action to the previously reported conditions.

NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION
(1-2001)

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Harris Nuclear Plant – Unit 1	05000400	2002	- 004	- 08	3 OF 23

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

I. DESCRIPTION OF EVENT (Continued)

On February 13, 2004, with the Unit in Mode 1 at 100% power, HNP identified four additional fire areas where spurious actuation of multiple valves could result in loss of the CSIP in service at the time of the postulated fire and in transferring of RWST inventory to the containment recirculation sump. The fire areas of concern are protected by detection and suppression systems, and they are on the path of a roving fire watch already posted as interim compensatory actions for other safe shutdown related issues. The fire watch remains posted. These additional fire areas were inadvertently missed during the investigation for the previously reported conditions (reference December 20, 2002 and July 23, 2003 discoveries). Similar to the previous discoveries, the discovery on February 13, 2004, is an old design issue that was identified during a review of the HNP safe shutdown program. This review and other validations are being performed as corrective actions to the previously reported conditions.

On August 13, September 14, and September 15, 2004, with the Unit in Mode 1 at 100% power, HNP identified that spurious opening of multiple valves could potentially result in the loss of the CSIP in service at the time of the postulated fire. A roving fire watch was already posted in fire areas of concern as interim compensatory actions for other safe shutdown related issues, and the fire watch remains posted. These discoveries are old design issues that were identified during a review of the HNP safe shutdown program. This review and other validations are being performed as corrective actions to the previously reported conditions.

On September 15, 2004, with the Unit in Mode 1 at 100% power, HNP identified that spurious actuation of multiple valves could potentially result in the loss of the CSIP in service at the time of the postulated fire. Additionally, HNP identified that spurious valve opening concurrent with spurious start of a Containment Spray (CT) pump [BE-P] could potentially result in the transfer of the RWST inventory to containment. On October 4, 2004, with the Unit in Mode 1 at 100% power, HNP identified that spurious closure of a certain valve could potentially result in the loss of RCP seal cooling credited by the SSA. Additionally, HNP identified that a postulated fire could result in a loss of indication of both Reactor Coolant System (RCS) wide range pressure transmitters [AB-PT] credited to monitor RCS pressure and level. A roving fire watch was already posted in these fire areas of concern as interim compensatory actions for other safe shutdown related issues, and the fire watch remains posted. These discoveries are old design issues that were identified during a review of the HNP safe shutdown program. This detailed review and other validations are being performed as corrective actions to the previously reported conditions.

On October 20, 26, and 29, 2004, with the Unit in Mode 6 at 0% power, HNP identified discoveries in four additional SSA fire areas and discoveries of components or combinations of components not previously reported in five previously identified SSA fire areas. These discoveries included spurious actuation of multiple components that could potentially result in mal-operation of components similar to previously reported conditions. A roving fire watch was already posted in these fire areas of concern as interim compensatory actions for other safe shutdown related issues, except for fire area 1-C since the containment is closed during normal operations. Additional walkdowns of fire area 1-C in the area of interest were performed to ensure that no in situ ignition sources and no intervening or transient combustibles were in the area. For the other areas, the fire watch remains posted. These discoveries are old design issues that were identified during a review of the HNP safe shutdown program. This detailed review and other validations are being performed as corrective actions to the previously reported conditions.

NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION
(1-2001)**LICENSEE EVENT REPORT (LER)**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Harris Nuclear Plant – Unit 1	05000400	2002	- 004	- 08	4 OF 23

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)**I. DESCRIPTION OF EVENT (Continued)**

On January 18, 2005, with the Unit in Mode 1 at 100% power, HNP identified discoveries in two additional SSA fire areas and discoveries of components or combinations of components not previously reported in eight previously identified SSA fire areas. These discoveries included spurious actuation of multiple components that could potentially result in mal-operation of components similar to previously reported conditions. A roving fire watch was already posted in these fire areas of concern as interim compensatory actions for other safe shutdown related issues, and the fire watch remains posted. These discoveries are old design issues that were identified during a review of the HNP safe shutdown program. This detailed review and other validations are being performed as corrective actions to the previously reported conditions.

On July 22 and August 4, 2005, with the Unit in Mode 1 at 100% power, HNP identified discoveries of components or combinations of components not previously reported in two previously identified SSA fire areas. These discoveries included a potential loss of components resulting from a manual operator action which may not be feasible due to the presence of postulated smoke or resulting from damage under certain conditions by a postulated fire in the area (similar to previously reported conditions). A roving fire watch was already posted in these fire areas of concern as interim compensatory actions for other safe shutdown related issues, and the fire watch remains posted. These discoveries are old design issues that were identified during a review of the HNP safe shutdown program. This detailed review and other validations are being performed as corrective actions to the previously reported conditions.

These findings of unanalyzed conditions are being reported pursuant to 10 CFR 50.73(a)(2)(ii)(B). No systems, structures, or components were inoperable at the time of discovery that significantly contributed to the event.

The previous four SSA fire areas identified included:

1. 1-A-BAL-B, located in the Reactor Auxiliary Building (RAB) Elevations 261' and 286'
2. 1-A-BAL-C, located in the RAB Elevation 286'
3. 1-A-EPA, located in the RAB Electrical Penetration Room "A" Elevation 261'
4. 1-A-EPB, located in the RAB Electrical Penetration Room "B" Elevation 261'

The discoveries on February 13, 2004 identified the following four additional SSA fire areas:

1. 1-A-CSRA, located in the RAB Elevation 286'
2. 1-A-CSR B, located in the RAB Elevation 286'
3. 12-A-CR, located in the RAB Elevation 305'
4. 12-A-CRC1, located in the RAB Elevation 305'

The discoveries on August 13, September 14, and September 15, 2004 included new valves in the following five previously identified SSA fire areas:

1. 1-A-BAL-B, located in the RAB Elevations 261' and 286'
2. 1-A-BAL-C, located in the RAB Elevation 286'
3. 1-A-EPA, located in the RAB Electrical Penetration Room "A" Elevation 261'
4. 1-A-CSRA, located in the RAB Elevation 286'
5. 1-A-CSR B, located in the RAB Elevation 286'

NRC FORM 366AU.S. NUCLEAR REGULATORY COMMISSION
(1-2001)**LICENSEE EVENT REPORT (LER)**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Harris Nuclear Plant – Unit 1	05000400	2002	004	08	5 OF 23

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

I. DESCRIPTION OF EVENT (Continued)

The discoveries on September 15 and October 4, 2004 included new components in the following two previously identified SSA fire areas:

1. 1-A-BAL-B, located in the RAB Elevations 261' and 286'.
2. 1-A-CSRБ, located in the RAB Elevation 286'

The discoveries on October 20 and October 29, 2004 identified the following four additional SSA fire areas:

1. 1-A-BAL-A, located in the RAB Elevations 190', 216', 236', and 261'
2. 1-A-SWGRA, located in the RAB Elevation 286'
3. 1-A-SWGRB, located in the RAB Elevation 286'
4. 1-C, located in the Containment Elevation 261'

The discoveries on October 26 and October 29, 2004 included new components or combinations of components in the following five previously identified SSA fire areas:

1. 1-A-BAL-B, located in the RAB Elevations 261' and 286'
2. 1-A-BAL-C, located in the RAB Elevation 286'
3. 1-A-EPA, located in the RAB Electrical Penetration Room "A" Elevation 261'
4. 1-A-CSRA, located in the RAB Elevation 286'
5. 1-A-CSRБ, located in the RAB Elevation 286'

The discoveries on January 18, 2005 identified the following two additional SSA fire areas:

1. 1-A-ACP, located in the RAB Elevation 286'
2. 12-A-BAL, located in the RAB Elevation 286' and 305'

The discoveries on January 18, 2005 also included new components or combinations of components in the following eight previously identified SSA fire areas:

1. 1-A-BAL-B, located in the RAB Elevations 261' and 286'
2. 1-A-BAL-C, located in the RAB Elevation 286'
3. 1-A-EPA, located in the RAB Elevation 261'
4. 1-A-EPB, located in the RAB Elevation 261'
5. 1-A-CSRA, located in the RAB Elevation 286'
6. 1-A-CSRБ, located in the RAB Elevation 286'
7. 12-A-CR, located in the RAB Elevation 305'
8. 12-A-CRC1, located in the RAB Elevation 305'

The discoveries on July 22 and August 4, 2005 included new components or combinations of components in the following two previously identified SSA fire areas:

1. 1-A-BAL-A, located in the RAB Elevation 236'
2. 1-A-BAL-B, located in the RAB Elevation 261'

NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION
(1-2001)**LICENSEE EVENT REPORT (LER)**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Harris Nuclear Plant – Unit 1	05000400	2002	- 004	- 08	6 OF 23

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

I. DESCRIPTION OF EVENT (Continued)

The specific conditions for each of the fire areas identified above or for a combination of the fire areas identified above, as applicable based on the routing of cables for the various components are detailed below.

For a postulated fire in SSA fire areas 1-A-BAL-B or 1-A-EPA (261' elevation), certain cabling [CBL3] for the two outlet valves (1CS-165 or 1CS-166) of the Volume Control Tank (VCT), the CCW supply valve to RCP thermal barriers (1CC-207), the outlet isolation valve (1SI-4) of the Boron Injection Tank (BIT), and the safety injection to the Reactor Coolant System (RCS) isolation valves (1SI-52 and 1SI-107) are not protected from spurious actuation in accordance with the requirements of NUREG 0800, Attachment 1 (Branch Technical Position CMEB 9.5-1) Section C.5.b. Specifically, the control power cables for charging system Motor Operated Valve (MOV) [20] 1CS-165 and CCW system MOV 1CC-207 are routed through SSA fire areas 1-A-BAL-B and 1-A-EPA with no fire barrier. Similarly, the control power cables for safety injection system MOVs 1SI-4, 1SI-52, and 1SI-107 are routed through SSA fire areas 1-A-BAL-B and 1-A-EPA with no fire barrier. In addition, the control power cable for charging system MOV 1CS-166 is unprotected for about one foot above its Motor Control Center (MCC) [MCC] and inside its MCC in SSA fire area 1-A-BAL-B. Therefore, the unprotected cables for these MOVs are vulnerable to fire-induced hot shorts. The charging system valves are required to remain open to provide CSIP suction from the VCT during a postulated fire in these fire areas. As a result, a fire in any of these areas could result in spurious closure of one of the VCT outlet valves, loss of suction flow to the running CSIP, and subsequent damage to the running CSIP credited by the SSA for charging flow and RCP seal cooling. The CCW system valve is required to remain open to provide CCW flow to RCP thermal barrier heat exchangers. As a result, a postulated fire in this area could result in spurious closure of this valve and loss of flow to RCP thermal barrier heat exchangers credited by the SSA for RCP seal cooling. The safety injection system valves are normally closed, so a postulated fire in this area resulting in spurious opening of multiple valves could result in damage to the running CSIP due to run out conditions. Simultaneous spurious actuation of multiple valves in the charging system and the component cooling water system could result in degradation of the RCP seals, possibly leading to an RCP seal loss of coolant accident (LOCA) without credited CSIPs.

For a postulated fire in SSA fire area 1-A-BAL-C (286' elevation), the control power cables for the CCW return valve from RCP thermal barriers (1CC-251) and the CCW supply valve to RCP seals and motor coolers (1CC-208) are not protected from spurious actuation in accordance with the requirements of NUREG 0800, Attachment 1 (Branch Technical Position CMEB 9.5-1) Section C.5.b. Specifically, the control power cables for the CCW system MOVs 1CC-251 and 1CC-208 are routed through SSA fire area 1-A-BAL-C and into their MCC in this area with no fire barrier. Therefore, the unprotected cables for these MOVs are vulnerable to fire-induced hot shorts. The CCW system valves are required to remain open to provide CCW flow to RCP thermal barrier heat exchangers. As a result, a postulated fire in this area could result in spurious closure of these valves and loss of flow to RCP thermal barrier heat exchangers credited by the SSA for RCP seal cooling. However, RCP seals would still be protected by the normal seal injection function of the redundant charging/safety injection trains.

NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION (1-2001) LICENSEE EVENT REPORT (LER)				
1. FACILITY NAME	2. DOCKET	6. LER NUMBER		3. PAGE
Harris Nuclear Plant – Unit 1	05000400	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER
		2002 - 004 - 08		
17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)				
I. <u>DESCRIPTION OF EVENT (Continued)</u>				
<p>For a postulated fire in SSA fire area 1-A-BAL-B (261' elevation), the control power cables for the CSIP suction cross-connect valves (1CS-168 and 1CS-169), the CSIP mini-flow isolation valve (1CS-214), and the CSIP discharge cross-connect valves (1CS-217, 1CS-218, and 1CS-219) are not protected from spurious actuation in accordance with the requirements of NUREG 0800, Attachment 1 (Branch Technical Position CMEB 9.5-1) Section C.5.b. Specifically, the control power cable for charging system MOVs 1CS-168 and 1CS-217 are unprotected inside their MCC in SSA fire area 1-A-BAL-B. The control power cables for charging system MOVs 1CS-169, 1CS-214, 1CS-218, and 1CS-219 are unprotected for about one foot above their MCC and inside their MCC in the same fire area. Therefore, the unprotected cables for these MOVs are vulnerable to fire-induced hot shorts.</p>				
<p>MOVS 1CS-168 and 1CS-169 valves are required to remain open to provide CSIP suction during a postulated fire in these fire areas. As a result, a fire in this area (1-A-BAL-B, 261' elevation) could result in spurious closure of one of the CSIP suction valves, loss of suction flow to the running CSIP, and subsequent damage to the running CSIP credited by the SSA for charging flow and RCP seal cooling. MOV 1CS-214 provides mini-flow for the CSIPs. As a result, a fire in this area could result in spurious closure of the mini-flow isolation valve and subsequent loss of mini-flow to the CSIPs. However, this loss of function would be recoverable since the CSIPs would not be damaged. MOVs 1CS-217, 1CS-218, and 1CS-219 are required to remain open to provide charging flow from the running CSIP. As a result, a postulated fire in this area could result in spurious closure of one of the CSIP discharge valves, and subsequent loss of flow to charging or high head safety injection credited by the SSA. However, this loss of function would be recoverable since the CSIPs would not be damaged.</p>				
<p>Simultaneous spurious actuation of multiple valves in the charging system (i.e., MOVs 1CS-214, 1CS-217, 1CS-218, and 1CS-219) could result in loss of mini-flow to the CSIPs and loss of flow to charging or high head safety injection, and subsequent damage to the running CSIP.</p>				
<p>Upon discovery, interim compensatory actions were implemented to minimize the impact of the postulated fires. These measures included de-energizing the CSIP suction cross-connect valves to minimize susceptibility to mal-operation of components, and posting a roving fire watch in fire areas of concern.</p>				

NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION
(1-2001)

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Harris Nuclear Plant – Unit 1	05000400	2002	- 004	- 08	8 OF 23

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

I. DESCRIPTION OF EVENT (Continued)

For a postulated fire in SSA fire areas 1-A-BAL-B or 1-A-BAL-C (286' elevation), certain cabling for eight safety injection MOVs, three MOVs in each area, (1SI-300, 1SI-310, and 1SI-322; or 1SI-301, 1SI-311, and 1SI-323, respectively); and two MOV's in both areas, the outlet isolation valve (1SI-3) of the Boron Injection Tank (BIT) and the safety injection to the RCS isolation valve (1SI-86), are not protected from spurious actuation in accordance with the requirements of NUREG 0800, Attachment 1 (Branch Technical Position CMEB 9.5-1) Section C.5.b. Specifically, the control power cables for MOVs 1SI-300, 1SI-310, and 1SI-322 are unprotected inside their MCCs in SSA fire area 1-A-BAL-B. Similarly, the control power cables for MOVs 1SI-301, 1SI-311, and 1SI-323 are routed through SSA fire area 1-A-BAL-C and into their MCCs in this area with no fire barrier. In addition, the control power cables for safety injection system MOVs 1SI-3 and 1SI-86 are routed through SSA fire areas 1-A-BAL-B and 1-A-BAL-C with no fire barrier. Therefore, the unprotected cables for these MOVs are vulnerable to fire-induced hot shorts. These valves are required to shut to prevent transfer of inventory from the RWST to the containment recirculation sump. Simultaneous spurious opening of these multiple valves from a fire in either of these areas could result in inadvertently transferring inventory from the RWST to the containment recirculation sump. If this transfer of inventory were to occur, the water normally used for inventory makeup to the Reactor Coolant System (RCS) would not be available from a suction source (i.e., the RWST) credited by the SSA. The safety injection system MOVs 1SI-3 and 1SI-86 are normally closed, so a postulated fire in these areas resulting in spurious opening of these multiple valves could result in damage to the running CSIP due to run out conditions.

For a postulated fire in SSA fire areas 1-A-EPA, 1A-EPB, or 1-A-BAL-B (261' elevation), certain cabling for two containment spray MOVs (1CT-102 and 1CT-105) are not protected from spurious actuation in accordance with the requirements of NUREG 0800, Attachment 1 (Branch Technical Position CMEB 9.5-1) Section C.5.b. Specifically, the control power cables for MOV 1CT-102 are routed in SSA fire area 1-A-EPB with no fire barrier. Similarly, the control power cables for MOVs 1CT-105 are routed through SSA fire areas 1-A-EPA and 1-A-BAL-B with no fire barrier. Therefore, the unprotected cables for these MOVs are vulnerable to fire-induced hot shorts. These valves are required to remain shut to prevent transfer of inventory from the RWST to the containment recirculation sump. Spurious opening of either of these valves from a fire in any of these fire areas could result in inadvertently transferring inventory from the RWST to the containment recirculation sump. If this transfer of inventory were to occur, the water normally used for inventory makeup to the Reactor Coolant System (RCS) would not be available from a suction source (i.e., the RWST) credited by the SSA. However, back-up sources would be available, and the ability to achieve and maintain cold shutdown would not be affected.

For a postulated fire in SSA fire areas 1-A-CSRA (286' elevation), 1-A-CSR B (286' elevation), 12-A-CR (305' elevation) or 12-A-CRC1 (305' elevation), certain cabling for the two outlet MOVs (1CS-165 or 1CS-166) of the Volume Control Tank (VCT) and for two containment spray MOVs (1CT-102 and 1CT-105) are not protected from spurious actuation in accordance with the requirements of NUREG 0800, Attachment 1 (Branch Technical Position CMEB 9.5-1) Section C.5.b. Specifically, the control power cables for charging system MOVs 1CS-165 and 1CS-166 are routed through SSA fire areas 1-A-CSRA, 1-A-CSR B, 12-A-CR, and 12-A-CRC1 with no fire barrier. Therefore, the unprotected cables for these MOVs are vulnerable to fire-induced hot shorts. The charging system valves are required to remain open to provide CSIP suction from the VCT during a postulated fire in these fire areas. As a result, a fire in any of these areas could result in spurious closure of one of the VCT outlet valves, loss of suction flow to the running CSIP, and subsequent damage to the running CSIP credited by the SSA for charging flow and RCP seal cooling.

NRC FORM 366AU.S. NUCLEAR REGULATORY COMMISSION
(1-2001)**LICENSEE EVENT REPORT (LER)**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Harris Nuclear Plant – Unit 1	05000400	2002	- 004	- 08	9 OF 23

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

I. DESCRIPTION OF EVENT (Continued)

In addition, the control power cables for MOVs 1CT-102 and 1CT-105 are routed through SSA fire areas 1-A-CSRA, 1-A-CSR B, 12-A-CR, and 12-A-CRC1 with no fire barrier. Therefore, the unprotected cables for these MOVs are vulnerable to fire-induced hot shorts. These valves are required to remain shut to prevent transfer of inventory from the RWST to the containment recirculation sump. Spurious opening of either of these valves from a fire in any of these fire areas could result in inadvertently transferring inventory from the RWST to the containment recirculation sump. If this transfer of inventory were to occur, the water normally used for inventory makeup to the Reactor Coolant System (RCS) would not be available from a suction source (i.e., the RWST) credited by the SSA. However, back-up sources would be available, and the ability to achieve and maintain cold shutdown would not be affected.

For a postulated fire in SSA fire areas 1-A-CSRA (286' elevation) or 1-A-CSR B (286' elevation), certain cabling for the four safety injection MOVs (1SI-3, 1SI-4, 1SI-86, and 1SI-107) are not protected from spurious actuation in accordance with the requirements of NUREG 0800, Attachment 1 (Branch Technical Position CMEB 9.5-1) Section C.5.b. Specifically, the control power cables for safety injection MOVs 1SI-4, 1SI-86, and 1SI-107 are routed through SSA fire area 1-A-CSRA with no fire barrier, and the control power cables for safety injection MOVs 1SI-3 and 1SI-86 are routed through SSA fire area 1-A-CSR B with no fire barrier and therefore, are vulnerable to fire-induced hot shorts. These safety injection system valves are normally closed, so a postulated fire in either of these areas resulting in spurious opening of these multiple valves could result in damage to the running CSIP due to run out conditions.

For a postulated fire in SSA fire area 1-A-CSR B (286' elevation), certain cabling is not protected in accordance with the requirements of NUREG 0800, Attachment 1 (Branch Technical Position CMEB 9.5-1) Section C.5.b and therefore is vulnerable to fire-induced hot shorts.

The C CSIP suction cross-connect valve with the A CSIP (1CS-168) is required to remain open to ensure the credited A CSIP is aligned to its suction source. Therefore, a postulated fire resulting in a spurious closure of this valve could result in damage to the running CSIP.

The B CT pump and its associated discharge valve (1CT-88) are required to remain off and shut, respectively, to ensure that the RWST inventory is not discharged to the containment via the containment spray ring header. Therefore, a postulated fire in this area resulting in spurious actuation of these multiple components could result in the water normally used for inventory makeup to the RCS not being available from a suction source (i.e., the RWST) credited by the SSA.

The RCP Thermal Barrier Flow Control Valve (1CC-252) is required to remain open to provide CCW flow to the RCP seals. As a result, a postulated fire in this area could result in spurious closure of this valve and loss of RCP seal cooling credited by the SSA.

The RCS wide range pressure transmitters (PT-402 and PT-403) provide the Operator with an indication of RCS pressure and level. Therefore, a postulated fire in this area could result in the loss of RCS pressure and level indication credited by the SSA.

NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION
(1-2001)

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Harris Nuclear Plant – Unit 1	05000400	2002	- 004	- 08	10 OF 23

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

I. DESCRIPTION OF EVENT (Continued)

For a postulated fire in SSA fire area 1-A-BAL-B (261' and 286' elevations), certain cabling is not protected in accordance with the requirements of NUREG 0800, Attachment 1 (Branch Technical Position CMEB 9.5-1) Section C.5.b and therefore is vulnerable to fire-induced hot shorts. The "A" CT pump is required to remain off and its associated discharge valve (1CT-50) is required to remain shut to ensure that the RWST inventory is not discharged to the containment via the containment spray ring header. Therefore, a postulated fire in this area resulting in spurious actuation of these multiple components could result in the water normally used for inventory makeup to the RCS not being available from a suction source (i.e., the RWST) credited by the SSA.

For a postulated fire in SSA fire area 1-A-SWGRB (286' elevation), certain cabling for the RCP thermal barriers flow control valve (1CC-252) and the CCW supply valve to RCP seals and motor coolers (1CC-208), certain cabling for the Boron Injection Tank outlet isolation valve (1SI-3) and the safety injection to the RCS isolation valve (1SI-86), and certain cabling for the "B" reactor coolant pump (1RC-RCPB) and the pressurizer spray valve loop "B" (1RC-103) is not protected from spurious actuation in accordance with the requirements of NUREG 0800, Attachment 1 (Branch Technical Position CMEB 9.5-1) Section C.5.b. Therefore this cabling is vulnerable to fire-induced hot shorts. The CCW system MOVs 1CC-208 and 1CC-252 are required to remain open to provide CCW flow to the RCP thermal barrier heat exchangers. As a result, a postulated fire in this area could result in spurious closure of either of these valves and loss of flow to RCP thermal barrier heat exchangers credited by the SSA for RCP seal cooling. The safety injection system MOVs 1SI-3 and 1SI-86 are normally closed, so a postulated fire in these areas resulting in spurious opening of these multiple valves could result in damage to the running CSIP due to run out conditions. A postulated fire in this areas resulting in the simultaneous spurious start of the "B" reactor coolant pump (after it had been secured) and the spurious opening of pressurizer spray valve loop "B" valve 1RC-103 could result in an inadvertent pressurizer spray and subsequent depressurization.

For a postulated fire in SSA fire area 1-A-BAL-A (190', 216', 236', and 286' elevations), certain cabling for the Auxiliary Feedwater (AFW) [BA] motor pump "A" discharge valve (1AF-19) and the VCT outlet isolation valve (1CS-166) is not protected from spurious actuation in accordance with the requirements of NUREG 0800, Attachment 1 (Branch Technical Position CMEB 9.5-1) Section C.5.b. Therefore this cabling is vulnerable to fire-induced hot shorts. The AFW valve 1AF-19 is required to remain open while its associated pump is in service. As a result, a fire in this area could result in spurious closure of this valve and therefore the loss of AFW flow to the "A" and "C" steam generators credited by the SSA. The charging system valve is required to remain open to provide CSIP suction from the VCT during a postulated fire in these fire areas. As a result, a fire in this area could result in spurious closure of the VCT outlet valve, loss of suction flow to the running CSIP, and subsequent damage to the running CSIP credited by the SSA for charging flow and RCP seal cooling.

NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION
(1-2001)

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Harris Nuclear Plant – Unit 1	05000400	2002	- 004	- 08	11 OF 23

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

I. DESCRIPTION OF EVENT (Continued)

For a postulated fire in SSA fire area 1-A-CSRA (286' elevation), certain cabling for the charging system flow control valve (1CS-231), for the pressurizer power-operated relief valve (PORV) (1RC-114) and its associated isolation (block) valve (1RC-113), and for the "A" containment spray pump (1CT-E004) and its associated discharge valve (1CT-50) is not protected from spurious actuation in accordance with the requirements of NUREG 0800, Attachment 1 (Branch Technical Position CMEB 9.5-1) Section C.5.b. Therefore this cabling is vulnerable to fire-induced hot shorts. The charging system valve 1CS-231 is required to remain open for RCP seal cooling and as a boration flowpath. As a result, a fire in this area could result in spurious closure of this valve and therefore the loss of RCP seal cooling and a boration flowpath credited by the SSA. The pressurizer PORV 1RC-114 is closed and its associated isolation valve 1RC-113 is open during normal plant operation. As a result, a fire in this area could result in spurious opening of the pressurizer PORV and its associated isolation valve could not be closed resulting in the transfer of some RCS inventory to the Pressurizer Relief Tank (PRT). The "A" CT pump 1CT-E004 is required to remain off and its associated discharge valve (1CT-50) is required to remain shut to ensure that the RWST inventory is not discharged to the containment via the containment spray ring header. Therefore, a postulated fire in this area resulting in spurious actuation of these multiple components could result in the water normally used for inventory makeup to the RCS not being available from a suction source (i.e., the RWST) credited by the SSA.

For a postulated fire in SSA fire area 1-A-ACP (286' elevation), certain control cabling for the normal service water (NSW) [KG] supply valve (1SW-39) to the "A" emergency service water (ESW) [BI] header and the "B" emergency diesel generator (EDG) (1DG-E003) [EK] is not protected from spurious actuation in accordance with the requirements of NUREG 0800, Attachment 1 (Branch Technical Position CMEB 9.5-1) Section C.5.b. Therefore, this cabling is vulnerable to fire-induced hot shorts. The NSW system valve 1SW-39 is required to close to provide isolation between NSW and ESW. A postulated fire in this area resulting in spurious actuation of these multiple components could result in a failure of the "B" EDG with the NSW supply valve (1SW-40) to the "B" ESW header subsequently open. With both NSW supply valves open, the ESW system flow would be split between the "A" and "B" trains. Thus, this diminished cooling capacity could affect the performance of equipment credited in the SSA and subsequently the ability to achieve and maintain safe shutdown.

For a postulated fire in SSA fire area 12-A-BAL (286' and 305' elevation), certain control cabling for the 1FB-8 (seal water injection filter backwash outlet valve), 1NI-107 (seal water injection filter backwash nitrogen supply valve), and 1PM-87 (seal water injection filter backwash primary water supply valve) is not protected from spurious actuation in accordance with the requirements of NUREG 0800, Attachment 1 (Branch Technical Position CMEB 9.5-1) Section C.5.b. Therefore, this cabling is vulnerable to fire-induced hot shorts. If the plant has reached cold shutdown conditions and is depressurized below 200 psig with the charging system seal water injection inlet valve closed, then a postulated fire in this area resulting in spurious actuation of these multiple components could result in an inadvertent dilution or nitrogen injection to the RCS potentially reducing RCS inventory and natural circulation capability.

NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION
(1-2001)**LICENSEE EVENT REPORT (LER)**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Harris Nuclear Plant – Unit 1	05000400	2002	- 004	- 08	12 OF 23

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

I. DESCRIPTION OF EVENT (Continued)

For a postulated fire in SSA fire area 1-A-BAL-A (236' elevation), the SSA credits the use of local operator manual action in lieu of separation or enclosure of certain control cabling for MOV 1CS-291 (CSIP suction valve from the RWST). Access may not be feasible to manually operate 1CS-291 due to the presence of postulated smoke under certain conditions. Therefore, one of the redundant trains credited by the SSA may not be free from fire damage for a postulated fire in accordance with the requirements of NUREG 0800, Attachment 1 (Branch Technical Position CMEB 9.5-1) Section C.5.b. The opening of this valve provides support for normal charging operation for RCS inventory control.

For a postulated fire in SSA fire area 1-A-BAL-B (261' elevation), certain control cabling for the "A" EDG (1DG-E002) is not protected from spurious actuation in accordance with the requirements of NUREG 0800, Attachment 1 (Branch Technical Position CMEB 9.5-1) Section C.5.b. Therefore, this cabling is vulnerable to fire-induced hot shorts. In addition, the SSA credits the use of the "A" train chiller and its associated ventilation system to provide cooling to certain "B" train pumps credited for a postulated fire in SSA fire area 1-A-BAL-B. However, further review has identified that sustained operation of these pumps may not be supported by this configuration. Therefore, a postulated fire in this area resulting in loss of the "A" EDG in this cooling configuration could affect the performance of equipment credited in the SSA.

Comprehensive matrices of components by fire area are presented in the tables below. Matrix 1 lists the components that have been corrected or will be corrected on or before Refueling Outage 13 (RFO-13). Matrix 2 lists the components that will be corrected on or before RFO-16.

Energy Industry Identification System (EIIIS) codes are identified in the text within brackets [].

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
Harris Nuclear Plant – Unit 1	05000400	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	13 OF 23	
		2002	- 004	- 08		

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

I. DESCRIPTION OF EVENT (Continued)

<u>Matrix 1</u> <u>Components by Fire Area (RFO-13)</u>		
<u>1-A-BAL-B (261')</u>	<u>1-A-CSRA (286')</u>	<u>12-A-CR (305')</u>
1CC-252	1CC-252	1CS-165
1CS-165	1CS-165	1CS-166
1CS-166	1CS-166	<u>12-A-CRC1 (305')</u>
1CS-168	1CS-169	1CS-165
1CS-169	1CS-243	1CS-166
1CS-170	<u>1-A-CSR (286')</u>	<u>1-A-SWGRA (286')</u>
1CS-243	1CC-208 ^a	1CC-249 ^b
1CS-250	1CC-251 ^a	1CS-243 ^b
1CS-254	1CC-252	<u>1-A-SWGRB (286')</u>
1CS-257	1CH-279	1CC-208 ^a
1CS-261	1CH-660	1CC-251 ^a
<u>1-A-BAL-B (286')</u>	1CS-165	1CS-166
1CS-165	1CS-166	1CS-168
1RC-115	1CS-168	1CS-243 ^a
<u>1-A-BAL-C (286')</u>	1CS-217 ^a	1CS-341 ^a
1CC-208 ^a	1CS-220 ^a	1CS-382 ^a
1CC-251 ^a	1CS-240 ^a	1CS-423 ^a
1CS-166	1CS-243 ^a	1-A-BAL-A (190', 216', 236', & 261')
1CS-243 ^a	1CS-341 ^a	1CS-166
1CS-341 ^a	1CS-382 ^a	
1CS-382 ^a	1CS-423 ^a	
1CS-423 ^a	<u>1-A-EPA (261')</u>	
	1CC-207	
	1CS-165	
	1CS-166	

^a Condition of 1CC-208 and 1CC-251 has been corrected by modification #56427.

^b Upon further review, 1CC-249 and 1CS-243 meet the >20 ft. separation criterion and are resolved.

NRC FORM 366AU.S. NUCLEAR REGULATORY COMMISSION
(1-2001)

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Harris Nuclear Plant – Unit 1	05000400	2002	- 004	- 08	14 OF 23

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

I. DESCRIPTION OF EVENT (Continued)

Matrix 2
Components by Fire Area (RFO-16)

<u>1-A-BAL-B (261')</u>	<u>1-A-BAL-B (261')</u> <u>(Continued)</u>	<u>1-A-BAL-B (286')</u> <u>(Continued)</u>
1CC-207		
1CC-249	1RC-RCPA	1SI-301
1CH-115	1RC-RCPB	1SI-310
1CH-116	1SI-107	1SI-311
1CH-125	1SI-4	1SI-322
1CH-126	1SI-52	1SI-323
1CS-182	<u>1-A-BAL-B (286')</u>	1SI-86
1CS-214	1CC-207	<u>1-A-BAL-C (286')</u>
1CS-217	1CC-249	1MS-58
1CS-218	1CS-243	1MS-59
1CS-219	1CT-50	1MS-60
1CT-102	1CT-E004	1MS-61
1CT-105	1MS-58	1MS-62
1CT-50	1MS-59	1MS-63
1CT-E004	1MS-60	<u>1-A-CSRA (286')</u>
1MS-58	1MS-61	1CC-207
1MS-59	1MS-62	1CC-249
1MS-60	1MS-63	1CS-170
1MS-61	1RC-103	1CS-231
1MS-62	1RC-107	1CT-102
1MS-63	1RC-RCPA	1CT-105
1RC-103	1RC-RCPB	1CT-50
1RC-107	1SI-3	1CT-E004
1RC-116	1SI-300	1RC-103

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Harris Nuclear Plant – Unit 1	05000400	2002	- 004	- 08	15 OF 23

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

I. DESCRIPTION OF EVENT (Continued)

<u>Matrix 2</u> <u>Components by Fire Area (RFO-16) (Continued)</u>		
<u>1-A-CSRA (286')</u> <u>(Continued)</u>	<u>1-A-CSR B (286')</u> <u>(Continued)</u>	<u>1-A-EPA (286')</u> <u>(Continued)</u>
1RC-107	1CT-102	1CT-105
1RC-113	1CT-105	1MS-58
1RC-114	1CT-88	1MS-59
1RC-900	1SI-107	1MS-60
1RC-901	1SI-3	1MS-61
1RC-902	1SI-4	1MS-62
1RC-903	1SI-86	1MS-63
1RC-904	PT-402	<u>12-A-CR (305')</u>
1MS-58	PT-403	AH-6B-SB
1MS-59	<u>1-A-EPA (261')</u>	AH-7B-SB
1MS-60	1CT-102	1CH-115
1MS-61	1CT-105	1CH-116
1MS-62	1MS-58	1CH-125
1MS-63	1MS-59	1CH-126
1RC-RCPA	1MS-60	1CT-102
1RC-RCPB	1MS-61	1CT-105
1SI-107	1MS-62	1SW-1171
1SI-3	1MS-63	1SW-1204
1SI-4	1SI-107	<u>12-A-CRC1 (305')</u>
1SI-86	1SI-4	1CH-115
<u>1-A-CSR B (286')</u>	1SI-52	1CH-116
1AF-49	<u>1-A-EPB (261')</u>	1CH-125
1AF-51	1CT-102	1CH-126

NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION
(1-2001)

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Harris Nuclear Plant – Unit 1	05000400	2002	- 004	- 08	16 OF 23

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

I. DESCRIPTION OF EVENT (Continued)

<u>Matrix 2</u> <u>Components by Fire Area (RFO-16) (Continued)</u>	
12-A-CRC1 (305') <u>(Continued)</u>	<u>1-A-BAL-A (236')</u>
	1CS-291
1CT-102	<u>1-C (261')</u>
1CT-105	1RC-900
1SC-E011	1RC-901
1SC-E014	1RC-902
1SW-1171	1RC-903
1SW-1204	1RC-904
1SW-1208	1RC-905
<u>1-A-SWGRA (286')</u>	<u>1-A-ACP (286')</u>
1RC-107	1SW-39
1RC-RCPA	1DG-E003
<u>1-A-SWGRB (286')</u>	<u>12-A-BAL (286' & 305')</u>
1CS-171	1FB-8
1CS-217	1NI-107
1CS-220	1PM-87
1CS-240	
1RC-103	
1RC-RCPB	
1SI-3	
1SI-86	
1-A-BAL-A (190', 216', <u>236', & 261')</u>	
1AF-19	

NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION
(1-2001)**LICENSEE EVENT REPORT (LER)**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Harris Nuclear Plant – Unit 1	05000400	2002	- 004	- 08	17 OF 23

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

II. CAUSE OF EVENT

The cause of these conditions is inadequate original Safe Shutdown Analysis. Specifically, certain conductor-to-conductor interactions (i.e., hot shorts) or certain operator manual actions were not adequately evaluated in the initial Safe Shutdown Analysis.

III. SAFETY SIGNIFICANCE

All of the findings are based on scenarios that have not actually occurred. Therefore, there are no actual adverse safety consequences.

Potential safety consequences for postulated fires in fire areas 1-A-BAL-B and 1-A-EPA (261' elevation) that also result in spurious closure of certain SSA MOVs may include:

- Loss of suction flow and subsequent damage to the running CSIP credited by the SSA for charging flow and RCP seal cooling,
- Loss of flow to RCP thermal barrier heat exchangers credited by the SSA for RCP seal cooling,
- Loss of charging or high head safety injection flow credited by the SSA,
- Simultaneous spurious actuation of multiple valves in the charging system could result in loss of mini-flow to the CSIPs and loss of flow to charging or high head safety injection, and subsequent damage to the running CSIP,
- Simultaneous spurious actuation of multiple valves in the charging system and the component cooling water system could result in degradation of the RCP seals, possibly leading to an RCP seal LOCA without credited CSIPs.

Potential safety consequences for postulated fires in fire areas 1-A-BAL-B and 1-A-EPA (261' elevation) that also result in spurious opening of certain SSA MOVs may include:

- Spurious opening of valves in the containment spray system could result in transfer of RWST inventory to the containment recirculation sump. However, this water inventory would still be available for use, if needed, from the containment recirculation sump.
- Simultaneous spurious opening of multiple valves in the safety injection system could result in damage to the CSIP in service due to run out conditions.

Potential safety consequences for a postulated fire in fire area 1-A-BAL-B (286' elevation) that also results in spurious opening of certain SSA MOVs may include:

- Simultaneous spurious opening of multiple valves in the safety injection system could result in transfer of RWST inventory to the containment recirculation sump. However, this water inventory would still be available for use, if needed, from the containment recirculation sump.
- Simultaneous spurious opening of multiple valves in the safety injection system could result in damage to the CSIP in service due to run out conditions.

NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION
(1-2001)

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Harris Nuclear Plant – Unit 1	05000400	2002	- 004	- 08	18 OF 23

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

III. SAFETY SIGNIFICANCE (Continued)

Potential safety consequences for a postulated fire in fire area 1-A-EPB (261' elevation) that also results in spurious opening of certain SSA MOVs may include:

- Spurious opening of valves in the containment spray system could result in transfer of RWST inventory to the containment recirculation sump. However, this water inventory would still be available for use, if needed, from the containment recirculation sump.

Potential safety consequences for a postulated fire in fire area 1-A-BAL-C (286' elevation) that also results in spurious actuation of certain SSA MOVs may include:

- Loss of flow to RCP thermal barrier heat exchangers credited by the SSA for RCP seal cooling. However, RCP seals would still be protected by the normal seal injection function of the redundant charging/safety injection trains.
- Simultaneous spurious opening of multiple valves in the safety injection system could result in transfer of RWST inventory to the containment recirculation sump. However, this water inventory would still be available for use, if needed, from the containment recirculation sump.
- Simultaneous spurious opening of multiple valves in the safety injection system could result in damage to the CSIP in service due to run out conditions.

Potential safety consequences for a postulated fire in fire areas 1-A-CSRA (286' elevation), 1-A-CSR B (286' elevation), 12-A-CR (305' elevation) and 12-A-CRC1 (305' elevation) that also results in spurious actuation of certain SSA MOVs may include:

- Loss of suction flow and subsequent damage to the running CSIP credited by the SSA for charging flow and RCP seal cooling.
- Spurious opening of valves in the containment spray system could result in transfer of RWST inventory to the containment recirculation sump. However, this water inventory would still be available for use, if needed, from the containment recirculation sump.

Potential safety consequences for a postulated fire in fire areas 1-A-CSRA (286' elevation) and 1-A-CSR B (286' elevation) that also results in spurious opening of certain SSA MOVs may include:

- Simultaneous spurious opening of multiple valves in the safety injection system could result in damage to the CSIP in service due to run out conditions.

Potential safety consequences for a postulated fire in fire area 1-A-CSR B (286' elevation) that also results in spurious actuation of certain components include:

- Subsequent damage to the running CSIP credited by the SSA for charging flow and RCP seal cooling.
- Discharge of RWST inventory to the containment via the containment spray ring header, resulting in the water normally used for inventory makeup to the RCS not available from a suction source (i.e., the RWST) credited by the SSA.
- Loss of flow to RCP thermal barrier heat exchangers credited by the SSA for RCP seal cooling.
- Loss of RCS pressure and level indication credited by the SSA which could potentially impact pressure and level monitoring.

NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION (1-2001)				
LICENSEE EVENT REPORT (LER)				
1. FACILITY NAME	2. DOCKET	6. LER NUMBER		3. PAGE
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER
Harris Nuclear Plant – Unit 1	05000400	2002	- 004	- 08
				19 OF 23

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

III. SAFETY SIGNIFICANCE (Continued)

Potential safety consequences for a postulated fire in fire area 1-A-BAL-B (261' and 286' elevations) that also results in spurious actuation of certain components include:

- Discharge of RWST inventory to the containment via the containment spray ring header, resulting in the water normally used for inventory makeup to the RCS not being available from a suction source (i.e., the RWST) credited by the SSA.

Potential safety consequences for a postulated fire in fire area 1-A-SWGRB (286' elevation) that also results in spurious actuation of certain components include:

- Loss of flow to RCP thermal barrier heat exchangers credited by the SSA for RCP seal cooling.
- Simultaneous spurious opening of multiple valves in the safety injection system could result in damage to the CSIP in service due to run out conditions.
- Simultaneous spurious start of the "B" reactor coolant pump (after it had been secured) and the spurious opening of a pressurizer spray valve could result in an inadvertent pressurizer spray and subsequent depressurization.

Potential safety consequences for a postulated fire in fire area 1-A-BAL-A (190', 216', 236', and 286' elevations) that also results in spurious actuation of certain components include:

- Loss of AFW flow to the "A" and "C" steam generators credited by the SSA.
- Loss of suction flow and subsequent damage to the running CSIP credited by the SSA for charging flow and RCP seal cooling.

Potential safety consequences for a postulated fire in fire area 1-A-CSRA (286' elevation) that also results in spurious actuation of certain components include:

- Loss of flow to RCP thermal barrier heat exchangers for RCP seal cooling and loss of a boration flowpath credited by the SSA.
- Spurious actuation of multiple valves could result in transfer of some RCS inventory to the Pressurizer Relief Tank (PRT).
- Spurious actuation of multiple components could result in discharge of RWST inventory to the containment via the containment spray ring header, resulting in the water normally used for inventory makeup to the RCS not being available from a suction source (i.e., the RWST) credited by the SSA.

Potential safety consequences for a postulated fire in the two additional SSA fire areas 1-A-SWGRA (286' elevation) and 1-C (261' elevation in containment) and the discoveries of components or combinations of components in the previously identified SSA fire areas that also results in spurious actuation of certain components identified on October 20, October 26, and October 29, 2004 of this LER include:

- Simultaneous spurious start of the "A" reactor coolant pump (after it had been secured) and the spurious opening of a pressurizer spray valve could result in an inadvertent pressurizer spray and subsequent depressurization.
- Loss of flow to RCP thermal barrier heat exchangers credited by the SSA for RCP seal cooling.

NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION
(1-2001)**LICENSEE EVENT REPORT (LER)**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Harris Nuclear Plant – Unit 1	05000400	2002	- 004	- 08	20 OF 23

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

III. SAFETY SIGNIFICANCE (Continued)

- Transfer of some RCS inventory to containment atmosphere. However, the RCS high point vent system is designed to ensure that any transfer of coolant inventory is less than the make-up capacity of one charging pump in the event of a Safety Class 2 pipe break or inadvertent valve actuations. In addition, the path from the reactor vessel head utilizes a 3/8-inch diameter orifice, which also limits flow to less than the make-up capacity of one charging pump in the event of a Safety Class 2 pipe break or inadvertent valve actuations.

Potential safety consequences for a postulated fire in the two additional SSA fire areas 1-A-ACP (286' elevation) and 12-A-BAL (286' and 305' elevations) and the discoveries of components or combinations of components in the previously identified SSA fire areas that also results in spurious actuation of certain components identified on January 18, 2005 of this LER include:

- Diminished cooling capacity potentially affecting the ability to achieve and maintain safe shutdown as credited by the SSA.
- An inadvertent dilution or nitrogen injection to the RCS potentially reducing RCS inventory and natural circulation capability.
- An unexpected RCS reduction in RCS pressure potentially affecting the ability to achieve and maintain safe shutdown as credited by the SSA.
- Loss of mini-flow to the "A" CSIP, which is credited by the SSA for providing charging system flow.
- A spurious opening of "A" AFW flow control valve could result in an inadvertent filling of the "A" steam generator (SG).
- Loss of chilled water to the "A" switchgear room, loss of cooling fans to 236' RAB north hallway area, or loss of make-up capability or cooling water flow to certain chillers potentially affecting equipment credited in the SSA.
- An unexpected diversion of chilled water to the non-running chiller could result in an inadvertent filling of the chiller surge tank and lifting of its associated relief valve.
- Loss of auxiliary reservoir ESW traveling screens potentially affecting ESW cooling capability.
- Simultaneous spurious opening of one or more SG power-operated relief valves (PORVs) and mal-operation of its related SG PORV block valve could require manually closing the block valve.

Potential safety consequences for a postulated fire in two previously identified SSA fire areas, 1-A-BAL-A (236' elevation) and 1-A-BAL-B (261' elevation), that also results in a potential loss of components due to a manual operator action which may not be feasible with the presence of postulated smoke or due to damage by a postulated fire in the area include:

- One of the redundant trains credited by the SSA may not provide support for normal charging operation for RCS inventory control.
- Loss of the "A" EDG, which in a certain cooling configuration could affect the performance of equipment credited in the SSA.

NRC FORM 366AU.S. NUCLEAR REGULATORY COMMISSION
(1-2001)**LICENSEE EVENT REPORT (LER)**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Harris Nuclear Plant – Unit 1	05000400	2002	- 004	- 08	21 OF 23

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

III. SAFETY SIGNIFICANCE (Continued)

The defense-in-depth provided by the fire protection program mitigates some of these potential safety consequences by:

- Prevention of fire initiation,
- Prompt detection of fires or incipient fire conditions by installed automatic detection systems,
- Effective suppression of fires by installed automatic fire suppression systems with fire brigade backup.

Opening and de-energizing the CSIP suction cross-connect valves (1CS-168 and 1CS-169) also mitigates the potential safety consequences of a postulated fire in fire area 1-A-BAL-B.

These findings of unanalyzed conditions are being reported pursuant to 10 CFR 50.73(a)(2)(ii)(B). No systems, structures, or components were inoperable at the time of discovery that significantly contributed to the event.

IV. CORRECTIVE ACTIONS

Upon discovery, interim compensatory actions were implemented to minimize the impact of the postulated fires. These measures included de-energizing the CSIP suction cross-connect valves (1CS-168 and 1CS-169) to minimize susceptibility to mal-operation of components, and posting a roving fire watch in fire areas of concern.

The additional fire areas have been added to the roving fire watch as interim compensatory action for the condition identified on February 13, 2004. For the conditions identified on October 20, October 26, and October 29, 2004 of this LER, a roving fire watch was already posted in the fire areas of concern as interim compensatory actions for other safe shutdown related issues, except for fire area 1-C since the containment is closed during normal operations. Additional walkdowns of fire area 1-C in the area of interest were performed to ensure that no in situ ignition sources and no intervening or transient combustibles were in the area. For the other areas and the conditions identified on July 22 and August 4, 2005, the fire watch remains posted.

Complete a validation of the HNP safe shutdown analysis.

Restore the identified conditions of this LER to compliance by design changes or other methods approved by the NRC. The previously reported condition of 1CC-208 and 1CC-251 has been corrected (HNP Modification #56427).

These actions are scheduled to be completed by refueling outage (RFO) 13 (Currently scheduled for May 13, 2006) for the components listed on Matrix 1 of this LER. For the conditions listed on Matrix 2 of this LER, these actions are scheduled to be completed by RFO 16 (Currently scheduled for November 5, 2010).

NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION
(1-2001)

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Harris Nuclear Plant – Unit 1	05000400	2002	- 004	- 08	22 OF 23

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

V. PREVIOUS SIMILAR EVENTS

NRC Inspection Report 50-400/00-09 (dated February 3, 2000)

This inspection identified two unresolved items (URIs) concerning adequacy of a Thermo-Lag fire barrier to meet plant licensing basis requirements and the adequacy of the 10 CFR 50.59 for changes made to the FSAR to revise the fire rating of selected Thermo-Lag fire barriers. The identified fire barrier serves as the fire area separation barrier between the "B" Train Switchgear Room/Auxiliary Control Panel (ACP) Room and the "A" Train Cable Spreading Room. Based on Thermo-Lag barrier fire resistance tests conducted in 1994 and 1995, this fire barrier did not have the required three-hour fire resistance rating. Therefore, a single fire in the "B" Train Switchgear Room, of significant intensity and duration, could breach the Thermo-Lag fire barrier assembly and damage certain redundant "A" train cables and their associated functions of safe shutdown systems. The final significance determination for these two items was one notice of violation (White finding). The root cause was inadequate fire testing of the installed fire barrier. The corrective actions included modifications to the affected rooms and establishing review criteria to ensure that future fire barrier modifications do not invalidate test results. The root cause for this previous event is not significant in relation to the subject event, therefore, the previous corrective actions would not be expected to identify or prevent the deficiencies identified by this LER.

HNP LER 97-006-00 (reported 4/17/97)

This LER reported that an undocumented breach was identified in the thermo-lag wall while sealing penetrations through the Thermo-Lag Wall in the 286' Cable Spreading Room "A." Follow-up investigation revealed an additional thermo-lag fire barrier deficiency in a floor drain assembly in the cable spread room. These conditions do not comply with the 3-hour fire-rated barrier requirements specified in the HNP FSAR. The root cause was identified to be incomplete design, incomplete construction, and incomplete final construction walkdown. The penetration was modified per ESR 95-00715. The root cause investigation (CR 97-01123) stated, "Nothing indicates a common trend to the fact of an area of a Thermo-lag panel being missed both in design and in the final construction walkdown." The root cause for this previous event is not significant in relation to the subject event, therefore, the previous corrective actions would not be expected to identify or prevent the deficiencies identified by this LER.

HNP LER 97-020-00 (reported 9/12/97)

This LER reported that design discrepancies were identified during an Engineering review of the Safe Shutdown Analysis in Case of Fire. These discrepancies pertain to safety-related electrical cables in 261' elevation of the RAB for the EDG Fuel Oil Transfer Pumps "A" and "B". These cables did not comply with separation requirements to maintain safe shutdown capability. These deficiencies were caused by engineering oversight and inadequate design verification during initial plant construction. A plant modification was installed to provide the required protection for the cited cables. The root cause investigation (CR 97-03861) stated, "A review of the safe shutdown cables in the unit 2 areas north of column line 43 was performed and no additional cable protection discrepancies were found. Also, an in-depth review of an additional fire area (1-A-EPB) was performed . . . and no similar deficiencies were identified." The root cause for this previous event is significant in relation to the subject event. The previous corrective action did not identify or prevent the deficiencies identified by this LER because the valve identified in this fire area (1CT-102) was not included in the SSA. The root cause for the previous event performed a review in the additional fire area only of associated cables credited in the SSA.

NRC FORM 366AU.S. NUCLEAR REGULATORY COMMISSION
(1-2001)

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Harris Nuclear Plant – Unit 1	05000400	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	23 OF 23
		2002	- 004	- 08	

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

VI. COMMITMENTS

The actions committed to by Carolina Power & Light Company doing business as Progress Energy Carolinas, Inc. (PEC) in this document are identified below. Any other actions discussed in this submittal represent intended or planned actions by PEC. They are described for the NRC's information and are not regulatory commitments.

Commitment(s)	Scheduled Completion Date
1. Complete a validation of the HNP safe shutdown analysis.	June 30, 2006
2. Restore the conditions identified in Matrix 1 of this LER to compliance by design changes or other methods approved by the NRC.	Refueling Outage 13 (Current schedule May 13, 2006)
3. Restore the conditions identified in Matrix 2 of this LER to compliance by design changes or other methods approved by the NRC.	Refueling Outage 16 (Current schedule November 5, 2010)