

Palisades Nuclear Plant Operated by Nuclear Management Company, LLC

September 27, 2005

10 CFR 50.73(a)(2)(i)(B) 10 CFR 50.73(a)(2)(v)(D)

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555-0001

Palisades Nuclear Plant Docket 50-255 License No. DPR-20

Licensee Event Report 05-002-01, Emergency Diesel Generator 1-2 Excessively Loaded In Certain Postulated Post-Accident Scenarios

Supplemental Licensee Event Report (LER) 05-002-01 is enclosed. The event was originally reported on April 14, 2005, in accordance with 10 CFR 50.73(a)(2)(i)(B) and 10 CFR 50.73(a)(2)(v)(D). At that time, the evaluation of the safety significance was incomplete. The enclosed supplemental LER provides the updated safety significance information.

Summary of Commitments

This letter contains no new commitments and no revisions to existing commitments.

Paul A. Harden Site Vice President, Palisades Nuclear Plant Nuclear Management Company, LLC

Enclosure (1)

CC Administrator, Region III, USNRC Project Manager, Palisades, USNRC Resident Inspector, Palisades, USNRC

LEDE

27780 Blue Star Memorial Highway • Covert, Michigan 49043-9530 Telephone: 269.764.2000

ENCLOSURE 1

. in

LER 05-002-01, EMERGENCY DIESEL GENERATOR 1-2 EXCESSIVELY LOADED IN CERTAIN POSTULATED POST-ACCIDENT SCENARIOS

NRC FORM 366 U.S. NUCLEAR REGULATORY COMMISSION				APPROVED BY OMB NO. 3150-0104 EXPIRES 6-30-2007											
(6-2004) LICENSEE EVENT REPORT (LER) (See reverse for required number of digits/characters for each block)						Estimated burden per response to comply with this mandatory collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0066), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.									
FACILITY NAM	IE (1)				_		DOCKET NUMBER (2) PAGE (3)								
Palisades Nuclear Plant						05000-255						1 of	3		
Emergency Diesel Generator 1-2 Excessively Loaded In Certain Postulated Post-Accident Scenarios															
EV	ENT DATE (5)		LER NUMBER (6)			RE	REPORT DATE (7)			OTHER FA			CILITIES INVOLVED (8)		
мо	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO	мо	DAY	YEAR	FA	CILITY NAME		DOCKET NUMBER			
02	17	2005	2005	002	01	09	27	2005	FACILITY NAME		DOCKET NUMBER				
OPERA	TING		THIS REPORT IS SUBMITTE			MITTED	PURSU	ANT TO TH	HE REQUIREMENTS OF 10 C			FR •: (Check all that apply) (11)			
MODE	E (9)	1	20.2201(b)			20.22	0.2203(a)(3)(ii)			50.73(a)(2)(ii)(B)			50.73(a)(2)(ix)(A)		
POW	ER	100	20.2201(d) 20.2203(a)(1)			20.22	2203(a)(4)			50.73(a)(2)(iii)			50.73(a)(2)(x)		
LEVEL	. (10)	100				50.36	36(c)(1)(i)(A)		50.73(a)(2)(iv)(A)		73.71(a)(4)				
			20.2	203(a)(2)(i)		50.36	6(c)(1)(ii	;)(1)(ii)(A)		50.73(a)(2)(v)(A)		73.71	1(a)(5)	
f". .			20.2	20.2203(a)(2)(ii)			36(c)(2)			50.73(a)(2)(v)(B)			OTHER		
- 			20.2203(a)(2)(iii)			50.46	6(a)(3)(i	i)		50.73(a)(2)(v)(C)			Speci	ract below or in	
			20.2203(a)(2)(iv)			50.73(a)(2)(i)(A)		X	50.73(a)(2)(v)(D)					
			20.2203(a)(2)(v) X			50.73	50.73(a)(2)(i)(B)			50.73(a)(2)(vii)					
·			20.2203(a)(2)(vi)			50.73	50.73(a)(2)(i)(C)		50.73(a)(2)(viii)(A)						
· · · · · · · · · · · · · · · · · · ·			20.2	203(a)(3)(i)		50.73(a)(2)(ii)(A)			50.73(a)(2)(viii)(B)						
					NSEE	CON	FACT F	OR THIS L	ER	(12)					
NAME									Jae A	Je Area Code)					
Daniel G. Malone					(269) 764-2463										
· · · · · · · · · · · · · · · · · · ·	- <u>r</u>			LINE FOR EA	Спс	UMPO	JNENT FAILURE DESCRIBED IN THIS REPORT (13)								
				MANU- R		RTABLE		CALIEE		0.07514				MANU-	REPORTABLE
CAUSE	STSTEM		ONEN	FACTURER	10	EPIX	┥┝╴	CAUSE	╋	SYSIEM	COMPON	ENI		CTURER	TOEPIX
SUPPLEME		NTAL REPORT EXPECTED (1			<u>4)</u>	— , , , , , , , , , , , , , , , , , , , 		4	EXPECTED SUBMISSION DATE (15)		M	ONTH	DAY	YEAR	
YES (If yes, complete EXPE			CTED SUBMISSION DATE).				XNO								
ABSTRACT				<u></u>					-			L			· · · · · · · · · · · · · · · · · · ·
On Eabr	10n/ 17	2005 .	with th	a plant an	arat	ina a	t onr	rovinor	+-	L 4000/ .		~	oton	t dooi	
	ary 17,	2005, 1		e plant op		ing a	a app			ly 100%	bower,	a			yll mah <i>u</i> nta
Inadequa	icy was o	aiscove	erea w	nich affeci	នេ ពេ	ееп	nerge	ncy ale	ese	el genera	tor (ED	G)	1-Z	ioad a	inalysis.
For certa	in postu	ated p	ost-ac	cident sce	narı	0s, I	t was	detern	าเท	ed that th	ne pres	ssu	rizer	heate	ers that are
powered	from 24	00V sa	ifety bi	us 1-D, ma	ay a	utom	natica	lly re-e	ne	rgize afte	er initia	lly	bein	g sheo	d.Asa
result of t	the addit	ional lo	oad, E	DG 1-2 wo	buld	bec	ome	overloa	de	d, and co	ould trip	ро	n ov	er-cur	rent.
											-				
This is reportable in accordance with 10 CFR 50.73(a)(2)(i)(B) as a condition prohibited by the plant's															
Technical Specifications, and 10 CFR 50.73(a)(2)(v)(D) as a condition that could have prevented the															
fulfillment of the safety function of structures or systems that are needed to mitigate the															
consequences of an accident															
conseque	UNBUQUENUE VI AT AUNUETT.														
The condition was caused by a circuit modification that was implemented in 1986. The modification															

removed an original plant design feature that blocked automatic restoration of pressurizer heaters with a safety injection signal (SIS) present.

A temporary modification was subsequently completed to preclude the pressurizer heater supply breaker from automatically re-closing when pressurizer level recovers.

-			
NRC	FO	RM	366A
(1-20	01)		

REVISION

NUMBER

01

PAGE (3)

2 of 3

LER NUMBER (6)

SEQUENTIAL

NUMBER

002

--

--

YEAR

2005

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

DOCKET NUMBER (2)

05000-255

FACILITY NAME (1)

Palisades

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

EVENT DESCRIPTION

On February 17, 2005, with the plant operating at approximately 100% power, a latent design inadequacy was discovered which affects the emergency diesel generator (EDG) 1-2 [DG;EK] load analysis. For certain postulated post-accident scenarios, it was determined that the pressurizer heaters [PZR/EHTR;AB] that are powered from 2400V safety bus 1-D [BU;EB], may automatically re-energize after initially being shed. As a result of the additional load, EDG 1-2 would become overloaded, and could trip on over-current.

Breaker 152-211 [BKR;EB], supplies power to the pressurizer heaters from bus 1-D. The breaker automatically opens in response to a sustained undervoltage condition on bus 1-D, and is not automatically reconnected to the bus via the load sequencer, when the bus is subsequently repowered by EDG 1-2. However, following a review of plant drawings and documents, it was concluded that if certain conditions exist, primarily restoration of pressurizer level after an initial low pressurizer level condition, the breaker will automatically close, adding the pressurizer heater load to EDG 1-2. The added load was not previously identified in the EDG 1-2 load calculations.

Certain Final Safety Analysis Report (FSAR) design basis accident scenarios may result in an initial lowering of pressurizer level, with subsequent pressurizer level restoration (e.g. small break loss of coolant accident or main steam line break). For these scenarios, concurrent with other postulated design basis accident assumptions of loss of offsite power and failure of the opposite EDG, EDG 1-2 would be relied upon for powering safety related equipment, but would become overloaded by the pressurizer heater load.

This condition applies only to EDG 1-2. Pressurizer heaters cannot be powered from the redundant 2400V safety bus 1-C and EDG 1-1 without manual action.

This is reportable in accordance with 10 CFR 50.73(a)(2)(i)(B) as a condition prohibited by the plant's Technical Specifications, and 10 CFR 50.73(a)(2)(v)(D) as a condition that could have prevented the fulfillment of the safety function of structures or systems that are needed to mitigate the consequences of an accident.

CAUSE OF THE EVENT

Original plant design incorporated automatic isolation of pressurizer heater breaker 152-211 when a safety injection signal (SIS) was present. Automatic closure of the breaker was blocked until the SIS actuation signal was reset.

In December 1986, a circuit modification was implemented to eliminate the SIS blocking feature for automatic re-closure of pressurizer heater breaker 152-211. Consideration for the possibility of

			·····							
NRC FORM 366A (1-2001)			U.S. NUCLEAR	REGULATORY	COMMISSION					
LICENSEE EVENT REPORT (LER)										
TEXT CONTINUATION										
FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6	PAGE (3)						
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3 of 3					
Palisades	05000-255	2005	002	01						
TEXT (If more space is required, use additional copies of NRC Form 366A) (17)										
overloading EDG 1-2 with the added load of the pressurizer heaters was not satisfactorily addressed. Based on review of documentation associated with the modification, the only accident scenario that was considered was a large break loss of coolant accident (LBLOCA). In a LBLOCA, pressurizer level is assumed to not recover sufficiently to allow for automatic re-closure of pressurizer heater breaker 152-211.										
SAFETY SIGNIFICANCE										
The safety significance of the event is considered to be minimal, based on a qualitative review of FSAR safety analyses that credit emergency diesel generator operation for event mitigation. The review identified that for the accident analyses that could result in the described condition, alternate mitigating strategies are procedurally directed which enable successful response to the events. The alternate mitigating strategies include continued heat removal via feeding and steaming the steam generators [SG;AB], and passive makeup provided by the safety injection tanks [TK;BP]. In addition, the described condition would not be expected to occur until after peak fuel cladding temperature has occurred. Diagnosis and restoration of the EDG are procedurally directed, allowing recovery of emergency onsite power to mitigating equipment trains.										
CORRECTIVE ACTIONS										
EDG 1-2 was declared inoperable when the design inadequacy was confirmed.										
A temporary modification was subsequently completed to preclude pressurizer heater breaker 152-211 from automatically re-closing when pressurizer level recovers.										
A review of bus 1-C and bus 1-D loads was con EDGs. No additional discrepancies were identi	npleted to confir fied.	m the l	oading assu	mptions f	or the					
PREVIOUS SIMILAR EVENTS										
None										