www.exeloncorp.com



10 CFR 50.73

Exelůn

Nuclear

November 7, 2005 BW050102

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555-0001

> Braidwood Station, Unit 1 Facility Operating License No. NPF-72 NRC Docket No. STN 50-456

Subject: Submittal of Licensee Event Report Number 2005-002-00, Braidwood Unit 1 – "Feedwater Isolation Valve 1FW039A Fails to Stroke in the Required Time Due to Failure of Valve Air Regulator to Maintain Set Pressure"

The enclosed Licensee Event Report (LER) is being submitted in accordance with 10 CFR 50.73, "Licensee event report system", paragraph (a)(2)(i)(B). 10 CFR 50.73(a) requires an LER to be submitted within 60 days after discovery of the event; therefore, this report is being submitted by November 7, 2005.

Should you have any questions concerning this submittal, please contact Mr. Dale Ambler, Regulatory Assurance Manager, at (815) 417-2800.

Respectfully,

£ø Keith J. Polson

Site Vice President Braidwood Station

Enclosure: LER Number 2005-002-00

cc: Regional Administrator - Region III NRC Braidwood Senior Resident Inspector

JE22

U.S	. NUCLEAR F	EGULATO	RY COMMI	SSION A	PROVE	D BY OMB	NO. 3150-010	94	EXPIRES	: 06/30/2007
(6-2004) (6-2004) LICENSEE EVENT REPORT (LER) (See reverse for required number of digits/characters for each block)						bry collection ited into the arding burden -5 F52), U.S. or by internet of Information agement and n information the NRC may spond to, the				
				2.	. DOCKET NUMBER 3. PAGE 05000456 1 of 3					
- eedwater Is n Set Pressu	olation Val	ve 1FW0	39A Fails	s to Stro	ke in tl	ne Requ	ired Time I	Due to Fa	ilure of V	/alve Air
6. LER I	NUMBER	7. R	EPORT D	ATE		8.	OTHER FAC	LITIES INV	OLVED	
YEAR SEQU	UENTIAL REV JMBER NO.	MONTH	DAY	YEAR	FACILITY N/A	NAME			DOCKET	NUMBER
2005 - (00 - 200	11	07	2005	FACILITY N/A	NAME			DOCKET	NUMBER N/A
11. THIS 20.2201(b 20.2201(d 20.2203(a 20.2203(a 20.2203(a 20.2203(a 20.2203(a 20.2203(a 20.2203(a 20.2203(a 20.2203(a) 20.2203(a)	3 REPORT IS 1) 1) 1)(1) 1)(2)(i) 1)(2)(ii) 1)(2)(iii) 1)(2)(iii) 1)(2)(iv) 1)(2)(v) 1)(2)(v) 1)(2)(v)		ED PURSU 20.2203(a)(20.2203(a)) 20.2203(a)(50.36(c)(1)) 50.36(c)(1)) 50.36(c)(2) 50.36(c)(2) 50.46(a)(3) 50.73(a)(2) 50.73(a)(2)	(3) (i) (3) (ii) (4) (i) (A) (ii) (A) (ii) (A) (ii) (A) (i) (A) (i) (B)		QUIREMI 50.73(a) 50.73(a) 50.73(a) 50.73(a) 50.73(a) 50.73(a) 50.73(a) 50.73(a) 50.73(a) 50.73(a)	ENTS OF 10 ((2)(i)(C) (2)(ii)(A) (2)(ii)(B) (2)(ii) (2)(iv)(A) (2)(v)(A) (2)(v)(A) (2)(v)(B) (2)(v)(C) (2)(v)(D)	CFR§: (Che 50. 50. 50. 50. 50. 50. 50. 73. 73. 01 50. 50. 50. 50. 50. 50. 50. 50. 50. 50.	eck all that 73(a)(2)(vii 73(a)(2)(vii 73(a)(2)(vii 73(a)(2)(vii 73(a)(2)(ix) 73(a)(2)(x) 73(a)(2)(x) 71(a)(4) 71(a)(5) HER cify in Abstra	a <i>pply)</i>) i)(A) i)(B) (A) act below
<u> </u>		12 LICENS	EF CONT	ACT FOR	THIS L	FR		or ir	NRC Form	366A
neering Direc	ctor			Por e	11114 -	<u> </u>	TELE (81	PHONE NUMB 5) 417-38	ER (Include A	rea Code)
13. COMPLET	FE ONE LINE	FOR EAC	I COMPO		LURE D	ESCRIB	ED IN THIS R	EPORT		
	MANU- FACTURER	REPOR TO I	TABLE EPIX	CAU	SE	SYSTEM	COMPONENT	MANU- FACTURE	R REPO	ORTABLE O EPIX
RG	Fisher	١	(N/,	۹	N/A	N/A	N/A		N/A
4. SUPPLEMEN	NTAL REPOR	IT EXPECT	ED	× N	0	15. EX SUB	KPECTED MISSION	MONTH	DAY	YEAR
ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) On September 6, 2005, feedwater isolation valve 1FW039A failed its quarterly stroke time test with a measured stroke time of 6.58 seconds and a Technical Specification limit of 6.0 seconds. 1FW039A was declared inoperable and Technical Specification Limiting Condition for Operation (LCO) 3.6.3 Condition C was entered. In accordance with LCO 3.6.3 Condition C, the upstream isolation valve, 1FW041A was closed and administrative actions were taken to ensure 1FW039A and 1FW041A remained in the closed position. The cause of the failed stroke time for 1FW039A was foreign material entry into the regulator main seat area. This caused the regulator supply pressure to be greater than its setpoint, and resulted in additional time for the actuator and solenoid valves to exhaust the supplied air to allow the valve to close. There were no safety consequences impacting plant or public safety as a result of this event. This event is being reported pursuant to 10 CFR 50.73(a)(2)(i)(B).										
	U.S ISEE EVEN Preverse for r gits/character Feedwater Is in Set Pressu Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control Control	U.S. NUCLEAR R U.S. NUCLEAR R SEE EVENT REPO	U.S. NUCLEAR REGULATON	U.S. NUCLEAR REGULATORY COMMI SEE EVENT REPORT (LER) Preverse for required number of gits/characters for each block) Feedwater Isolation Valve 1FW039A Fails in Set Pressure <u>6. LER NUMBER</u> 7. REPORT D <u>7 YEAR</u> SEQUENTIAL REV NUMBER NO. MONTH DAY <u>5 2005 - 002 - 00 11 07</u> <u>11. THIS REPORT IS SUBMITTED PURSU</u> <u>20.2203(a)(1) 20.2203(a)</u> <u>20.2203(a)(2)(i) 50.36(c)(1)</u> <u>20.2203(a)(2)(i) 50.36(c)(2)</u> <u>20.2203(a)(2)(ii) 50.36(c)(2)</u> <u>20.2203(a)(2)(ii) 50.36(c)(2)</u> <u>20.2203(a)(2)(v) 50.73(a)(2)</u> <u>12. LICENSEE CONT</u> ineering Director <u>13. COMPLETE ONE LINE FOR EACH COMPO</u> M COMPONENT MANU- FACTURER REPORTABLE TO EPIX RG Fisher Y <u>14. SUPPLEMENTAL REPORT EXPECTED</u> Intel 15. EXPECTED SUBMISSION DATE) 00 spaces, i.e., approximately 15 single-spaced type 005, feedwater isolation valve 1FW039A fis and a Technical Specification limit of 6.0 tion Limiting Condition for Operation (LCC) he upstream isolation valve, 1FW041A wa /041A remained in the closed position. iled stroke time for 1FW039A was foreign or supply pressure to be greater than its se exhaust the supplied air to allow the valve ty consequences impacting plant or public reported pursuant to 10 CFR 50.73(a)(2)(U.S. NUCLEAR REGULATORY COMMISSION AN SEE EVENT REPORT (LER) Preverse for required number of gits/characters for each block) Feedwater Isolation Valve 1FW039A Fails to Stro- in Set Pressure <u>6. LER NUMBER</u> 7. REPORT DATE NUMBER NO. <u>11. THIS REPORT IS SUBMITTED PURSUANT TO</u> 20.2201(b) 20.2203(a)(3)(i) 20.2203(a)(2)(i) 20.2203(a)(2)(ii) 20.2203(a)(2)(ii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(ii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(ii) 20.2203(a)(2)(iii) 20.2203(a)(2)(ii) 20.2203(a)(2)(ii) 20.2203(a)(2)(ii) 20.2203(a)(2)(ii) 20.2203(a)(2)(ii) 20.2203(a)(2)(ii) 20.2203(a)(2)(ii) 20.2203(a)(2)(ii) 20.2203(a)(2)(ii) 20.2203(a)(2)(ii) 20.2203(a)(2)(ii) 20.2203(a)(2)(ii) 20.2203(U.S. NUCLEAR REGULATORY COMMISSION APPROVE Estimate in the presentation of the presentation conseling presentation of the presentation of the pres	U.S. NUCLEAR REGULATORY COMMISSION APPROVED BY OME Fearues: 50 hours. Fi licensing process and estimated burden per equest: 50 hours. Fi licensing process and particular Regulatory Co- parts in the Recor- Nuclear Regulatory Co- parts in the Recor- Nuclear Regulatory Co- ernal to indication 2 bockstone and tig- pot conduct or spone information cale-sina Feedwater Isolation Valve 1FW039A Fails to Stroke in the Requ- uin Set Pressure 6 LER NUMBER 7. REPORT DATE 8. 8 YEAR SEQUENTIAL NUMBER 7. REPORT DATE 8. 9 2005 - 002 00 11 07 2005 N/A 9 20.201(b) 20.2203(a)(3)(i) 50.73(a) 20.2201(b) 20.2203(a)(3)(i) 50.73(a) 20.2201(b) 20.2203(a)(3)(i) 50.73(a) 20.2203(a)(2)(ii) 50.36(c)(1)(i)(A) 50.73(a) 20.2203(a)(2)(ii) 50.36(c)(2)(ii) 50.73(a) 20.2203(a)(2)(iii) 50.36(c)(2)(iii) 50.73(a) 20.2203(a)(2)(iii) 50.36(c)(2)(iii) 50.73(a) 20.2203(a)(2)(iii) 50.36(c)(2)(iii) 50.73(a) 20.2203(a)(2)(iii) 50.37(a) 50.73(a) 20.2203(a)(2)(iii) 50.36(c)(2)(iii) 50.73(a) 20.2203	U.S. NUCLEAR REGULATORY COMMISSION APPROVED BY OMB: NO. 3150-01C Estimated burden per response to a field back to index in per response to a field back to index inde	U.S. NUCLEAR REGULATORY COMMISSION APPROVED BY OMB: NO. 3150-0164 Estimated burden per response to comply with it negative to the Reported Tessense to comply with it negative to the Reported Tessense to the Dark for the D	U.S. NUCLEAR REGULATORY COMMISSION APPROVED BY CME: NO. 3150-010 EXPIRES ISEE EVENT REPORT (LER) Serverse for required number of pits/characters for each block) Deverse for required number of pits/characters for each block) DEVENT REPORT (LER) DEVENT REPORT COLSPAN DEVENT REPORT (LER) DEVENT REPORT COLSPAN DEVENT REPORT DATE CONCRET NUMBER Set Pressure CONCRET NUMBER Set Pressure Set Pressure <t< td=""></t<>

٠

•

NRC FORM 366A

U.S. NUCLEAR REGULATORY COMMISSION

(1-2001) LICENSEE EVENT REPORT (LER)						
FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6	5)	PAGE (3)		
Braidwood, Unit 1	05000456	YEAR NUMBER	REVISION NUMBER			
		2005 - 002 -	00	2 OF 3		
NARRATIVE (If more space is required, use additional c	opies of NRC Form 366	A) (17)				
A. Plant Operating Conditions Before The	Event:					
Event Date: September 06, 2005	Event Date: September 06, 2005 Event Time: 1312					
Unit: 1 MODE: 1 Reactor Power: 99.9 percent						
Unit 1 Reactor Coolant System (RCS) [AB] Temperature: 58	7 degrees F, Pressure: 2	2238 psig			
3. Description of Event:						
There were no additional structures, systems or components inoperable at the beginning of the event that contributed to the severity of the event.						
On August 3, 2005, it was identified that fe timed in accordance with the In-Service Te for valves 1FW039A-D due to the stroke ti 3.0.3 requires that the valves be stroke tim	eedwater isolation v esting (IST) Program me surveillances no ned within 92 days t	alves (FW) [SJ] 1FW039 n. Surveillance Requirer of being performed within from the date of discover	A-D had not nent (SR) 3. the required y of the miss	been stroke 0.3 was entered d time frame. SR sed surveillance.		
Following replacement of the Unit 1 steam 1FW039A-D be stroke timed quarterly vers changed to reflect this and 1FW039A-D co predefines were subsequently revised to c	generators in 1998 sus every cold shut ontinued to be strok correctly require qua	3, the IST Program was re down. The station prede e timed on a cold shutdo arterly stroke timing of the	evised to rec fine program wn frequenc e 1FW039A-	quire that valves n had not been sy. The D valves.		
On September 6, 2005, the stroke time tes seconds. The Technical Specification Lim 1FW039A being greater than 6.0 seconds Condition for Operation (LCO) 3.6.3 Cond upstream isolation valve, 1FW041A, was o 1FW041A remained in the closed position	st of 1FW039A was it is 6.0 seconds. If , the valve was dec ition C was entered closed and adminis	performed. The measur Based on the surveillance lared inoperable and Tec . In accordance with LCC trative actions were taker	ed stroke tine stroke time chnical Spec O 3.6.3 conc n to ensure1	ne was 6.58 result for ification Limiting lition C, the FW039A and		
On September 9, 2005, troubleshooting determined that the 1FW039A regulator output pressure was 109 psig versus a required supply air pressure of 80 psig. The regulator could not be adjusted and was replaced with a new regulator with a setpoint of 80 psig.						
On September 10, 2005, 1FW039A was stroked with a stroke time of 5.18 seconds. Based on the acceptable stroke time results, the LCO was exited.						
Valves 1FW039B-D were stroke tested wit to be approximately 80 psig. This indicate various valve actuators similar to 1FW039	th acceptable stroke d that none of the d A.	e times and each of the root other regulators were sup	egulator sett plying unreg	ings were verified Julated air to the		
Cause of Event						

The cause of the failed stroke time for 1FW039A was the high air supply pressure that resulted in more time for the actuator and solenoid valves to exhaust the supplied air to allow the valve to close. The cause of the regulator supply pressure being greater than the setpoint of 80 psig was foreign material entry of a small piece of wire and a small piece of very hard plastic into the regulator main seat area. The small piece of wire is believed to have come

NRC FORM 366A (1-2001)

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)		
Braidwood Unit 1	05000456	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
	00000430	2005	- 002 -	00	3	OF	3

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

from a wire brush sometimes used by maintenance personnel for cleaning pipe/joint threads. The origin of the small piece of hard plastic could not be confirmed. The actuator was last overhauled and the regulator was replaced during the maintenance performed in October, 2001. Stroke time surveillances since the regulator was replaced (three occurrences) indicate that the valve was operating properly since that date. Introduction of the small piece of wire and plastic is believed to be an isolated case.

D. <u>Safety Consequences:</u>

There were no safety consequences impacting plant or public safety as a result of this event. The 1FW039A-D valves are normally closed and not required to be opened for any required functions. Upon failure to meet the Technical Specification requirement for stroke time, the upstream isolation valve was isolated in accordance with Technical Specifications.

This event did not result in a safety system functional failure.

E. Corrective Actions:

Corrective Actions include pursuing replacement of the 1FW039A-D valve non relief type regulators with relief type regulators and filters. The revision to the station predefine program to correctly require quarterly stroke timing of the 1FW039A-D valves has been completed.

F. Previous Occurrences:

There have been no previous similar events at Braidwood Station causing the FW039 valves to fail stroke time tests.

G. Component Failure Data:

<u>Manufacturer</u>	<u>Nomenclature</u>	<u>Model</u>	<u>Mfg. Part Number</u>
Fisher	Regulator	95H	95H-4 1