

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED: <b>State of Missouri E.M.A. 2302 Militia Drive Jefferson City, MO 65101</b>		2. NRC/REGIONAL OFFICE <b>U.S. Nuclear Regulatory Commission Region III 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4351</b>	
REPORT	2005/001		
3. DOCKET NUMBER(S) 030-07247	4. LICENSEE NUMBER(S) 24-07974-03	5. DATE(S) OF INSPECTION 11/9/2005	

**LICENSEE:**  
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.  
  
\_\_\_\_\_ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):
- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.  
  
(Violations and Corrective Actions)

**Licensee's Statement of Corrective Actions for Item 4, above.**

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Tony S. Go		11/9/05

NRC FORM 591M PART 3 (10-2003) 10 CFR 2.201		U.S. NUCLEAR REGULATORY COMMISSION	
<b>Docket File Information SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION</b>			
1. LICENSEE <b>State of Missouri E. M. A.</b>		2. NRC/REGIONAL OFFICE <b>U.S. Nuclear Regulatory Commission Region III</b>	
3. DOCKET NUMBER(S) <b>030-07247</b>		4. LICENSE NUMBER(S) <b>24-07974-03</b>	5. DATE(S) OF INSPECTION <b>11/09/2005</b>
6. INSPECTION PROCEDURES <b>87124</b>		7. INSPECTION FOCUS AREAS <b>03.01 - 03.07</b>	
<b>SUPPLEMENTAL INSPECTION INFORMATION</b>			
1. PROGRAM <b>3710</b>	2. PRIORITY <b>5</b>	3. LICENSEE CONTACT <b>James Kammerer</b>	4. TELEPHONE NUMBER <b>573-526-9100</b>
<input checked="" type="checkbox"/> Main Office Inspection		Next Inspection Date: <b>11/10</b>	
<input checked="" type="checkbox"/> Field Office			
<input type="checkbox"/> Temporary Job Site			
<b>PROGRAM SCOPE</b>			

NRC FORM 591M PART 3 (10-2003)

The licensee is an agency of the State of Missouri that manages the State Civil Defense survey instrument program for the State. The name of the agency is currently named the State of Missouri Emergency Management Agency. The facility is located five miles from the State Capitol in a secured National Guard Armory. The licensee is authorized to possess two instrument calibrators containing Cs-137 sealed sources. The licensee staff consisted of the RSO and two staff members that were authorized to operate these Cs-137 calibrators for calibrating radiation survey instrument devices. The licensee also recently acquired a generally licensed MiniRadiac Calibrator, Model No. FC-2 containing Cs-137.

#### Performance Observations

The inspector toured the storage area and found that the licensed materials were properly stored in a secured storage area located at the basement of the building, and the surrounding premises were secured by armed guards. The security at the facility was found adequate. The licensee performed the required leak tests at the required intervals. The licensee staff also trained and conducted public meetings involving with radiological emergency response throughout the State. The inspector did not find any violations during the current inspection.