NRC FORM 591M PAR (10-2003) 10 CFR 2.201	Т1		U.S. NUCLEAR REGULATORY COMMISSION		
10 01 1( 2.20 1	SAFETY INSI	PECTION REPORT A	ND COMPLIANCE IN	ISPECTION	
LICENSEE/LOCATION INSPECTED:     Philadelphia Health & Education Corporation     D/b/a Drexel University College of Medicine     245 North 15 <sup>th</sup> Street     Philadelphia, PA 19102-1192  REPORT Nos 2004-002			2. NRC/REGIONAL OFFICE  U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415		
3. DOCKET NUMBER(S		4. LICENSE NUMBER(S)		5. DATE(S) OF INSPECTI	ON
030-12998		37-07438-15		November 30, 200	5
LICENSEE:			·	·	
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:  1. Based on the inspection findings, no violations were identified. 2. Previous violation(s) closed.  3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.  3. Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s): 10 CFR 31.5 requires generally licensed devices to be disposed of by transfer to a person authorized by a specific license to receive the byproduct material in the device or as otherwise approved by the Commission.  Contrary to the above, on August 5, 2004, Kent Lambert, Director, Radiation Safety, Philadelphia Health & Education Corporation diba Drexel University College of Medicine notified NRC Region Iby facsimile (ML042300464) that on or about July 9, 2004, a General Licensed Source (GLS) containing approximately 26 microcuries of Cs-137, that was contained in a Beckman Model LS 7800 liquid scintillation counter was inadvertently transferred to a liquidation company, and then transferred to a salvage company or a landfill, and the equipment and source are not recoverable.  Mr. Lambert reported that one of the root causes for the event was that he was not authorized by his former license to remove the source from the equipment. He stated that he believes that if had authorization to remove the source from the equipment and source are not recoverable.  4. During					
I bearby of the total			•		
corrective actions is made	e in accordance with the rewill be achieved). I unde	cribed by me to the inspector requirements of 10 CFR 2.20 restand that no further written atted Name	l (corrective steps already to response to NRC will be req	aken, corrective steps which	will be taken,
LICENSEE'S REPRESENTATIVE	Sreekant Murthy		/	RA/	12/19/05
NRC INSPECTOR	Randolph C. Raglar	nd	/	'RA/	12/19/05