

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Warner-Lambert, LLC 2800 Plymouth Road Ann Arbor, Michigan 48106 REPORT 2006-001, - 002		2. NRC/REGIONAL OFFICE REGION III US NUCLEAR REGULATORY COMMISSION 2443 WARRENVILLE ROAD, SUITE 210 LISLE, ILLINOIS 60532	
3. DOCKET NUMBER(S) 030-04794	4. LICENSEE NUMBER(S) 21-01443-06	5. DATE(S) OF INSPECTION March 16, 2006	

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

 _____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):
- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

 (Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Geoffrey M. Warren		3/16/06

Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION

1. LICENSEE Warner-Lambert, LLC REPORT NUMBER(S) 2006-001, -002		2. NRC/REGIONAL OFFICE Region III	
3. DOCKET NUMBER(S) 030-04794	4. LICENSE NUMBER(S) 21-01443-06	5. DATE(S) OF INSPECTION March 16, 2006	
6. INSPECTION PROCEDURES USED 87126	7. INSPECTION FOCUS AREAS 03.01 - 03.07		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03620	2. PRIORITY 5	3. LICENSEE CONTACT Carol Lentz, RSO	4. TELEPHONE NUMBER 734-622-4467
------------------------------------	-------------------------	--	--

Main Office Inspection Next Inspection Date: **March 2011**

Field Office 1600 Huron Parkway, Ann Arbor, MI

Temporary Job Site _____

PROGRAM SCOPE

This licensee was a pharmaceutical research company, a subsidiary of Pfizer Inc., which performed research at this location under a research and development license. Approximately 400 personnel were approved to perform research under 180 authorized users in labs in the main facility and the facility at 1600 Huron Parkway in Ann Arbor. Around 100 of these authorized users possessed licensed material at the time of the inspection. The other facilities authorized under this license had no current use of licensed material. The researchers used primarily carbon-14 and tritium as tracers, though some labs were authorized for phosphorus-32 and other isotopes. Research ranged from in vitro testing to animal studies. Waste was disposed through decay in storage or shipped to commercial disposal or incineration facilities. The radiation safety staff performed routine audits of authorized users and laboratory areas.

Performance Observations

Licensee personnel explained how unsealed material was ordered, received, inventoried, secured, used, and disposed, and described how waste was packaged and shipped for disposal. Licensee personnel demonstrated survey meter QC and survey techniques, as well as procedures for the use of licensed materials. The inspector identified no concerns with these procedures. Interviews with licensee personnel indicated adequate knowledge of radiation safety and emergency procedures.

The inspector closed a violation from the previous inspection regarding survey meter calibration. The licensee had instituted a tracking system for the calibration of all survey meters at the facility. All survey meters that the inspector checked had a current calibration.