

April 3, 2006

SVPLTR # 06-0018

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-0001


Dresden Nuclear Power Station, Unit No. 2
Renewed Facility Operating License No. DRP-19
NRC Docket No. 50-237

Subject: Licensee Event Report 237/2006-001-00, "Unit 2 Isolation Condenser Declared Inoperable Due To Inadequate Backfilling Of Instrument Sensing Lines"

Enclosed is Licensee Event Report 237/2006-001-00, "Unit 2 Isolation Condenser Declared Inoperable Due To Inadequate Backfilling Of Instrument Sensing Lines," for Dresden Nuclear Power Station, Unit 2. This event is being reported in accordance with 10 CFR 50.73(a)(2)(v)(D), "Any event or condition that could have prevented the fulfillment of the safety function of structures or systems that are needed to mitigate the consequences of an accident."

Should you have any questions concerning this report, please contact Mr. Pedro Salas, Regulatory Assurance Manager, at (815) 416-2800.

Respectfully,

 ^{for D. Bost}

Danny G. Bost
Site Vice President
Dresden Nuclear Power Station

Enclosure

cc: Regional Administrator – NRC Region III
NRC Senior Resident Inspector – Dresden Nuclear Power Station

IE22

NRC FORM 366 (6-2004)		U.S. NUCLEAR REGULATORY COMMISSION		APPROVED BY OMB: NO. 3150-0104		EXP RES: 06/30/2007		
LICENSEE EVENT REPORT (LER) (See reverse for required number of digits/characters for each block)								
1. FACILITY NAME: Dresden Nuclear Power Station Unit 2				2. DOCKET NUMBER 05000237		3. PAGE 1 OF 3		
4. TITLE Unit 2 Isolation Condenser Declared Inoperable Due To Inadequate Backfilling Of Instrument Sensing Lines								
5. EVENT DATE			6. LER NUMBER		7. REPORT DATE		8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR
02	01	2006	2006	- 001 -	00	04	03	2006
							FACILITY NAME N/A	
							DOCKET NUMBER N/A	
							FACILITY NAME N/A	
							DOCKET NUMBER N/A	
9. OPERATING MODE 1		11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR§: (Check all that apply)						
		<input type="checkbox"/> 20.2201(b) <input type="checkbox"/> 20.2203(a)(3)(i) <input type="checkbox"/> 50.73(a)(2)(i)(C) <input type="checkbox"/> 50.73(a)(2)(vii)						
		<input type="checkbox"/> 20.2201(d) <input type="checkbox"/> 20.2203(a)(3)(ii) <input type="checkbox"/> 50.73(a)(2)(ii)(A) <input type="checkbox"/> 50.73(a)(2)(viii)(A)						
		<input type="checkbox"/> 20.2203(a)(1) <input type="checkbox"/> 20.2203(a)(4) <input type="checkbox"/> 50.73(a)(2)(ii)(B) <input type="checkbox"/> 50.73(a)(2)(viii)(B)						
		<input type="checkbox"/> 20.2203(a)(2)(i) <input type="checkbox"/> 50.36(c)(1)(i)(A) <input type="checkbox"/> 50.73(a)(2)(iii) <input type="checkbox"/> 50.73(a)(2)(ix)(A)						
		<input type="checkbox"/> 20.2203(a)(2)(ii) <input type="checkbox"/> 50.36(c)(1)(ii)(A) <input type="checkbox"/> 50.73(a)(2)(iv)(A) <input type="checkbox"/> 50.73(a)(2)(x)						
		<input type="checkbox"/> 20.2203(a)(2)(iii) <input type="checkbox"/> 50.36(c)(2) <input type="checkbox"/> 50.73(a)(2)(v)(A) <input type="checkbox"/> 73.71(a)(4)						
		<input type="checkbox"/> 20.2203(a)(2)(iv) <input type="checkbox"/> 50.46(a)(3)(ii) <input type="checkbox"/> 50.73(a)(2)(v)(B) <input type="checkbox"/> 73.71(a)(5)						
		<input type="checkbox"/> 20.2203(a)(2)(v) <input type="checkbox"/> 50.73(a)(2)(i)(A) <input type="checkbox"/> 50.73(a)(2)(v)(C) <input type="checkbox"/> OTHER						
		<input type="checkbox"/> 20.2203(a)(2)(vi) <input type="checkbox"/> 50.73(a)(2)(i)(B) <input checked="" type="checkbox"/> 50.73(a)(2)(v)(D)						
		Specify in Abstract below or in NRC Form 366A						
12. LICENSEE CONTACT FOR THIS LER								
FACILITY NAME Dresden Nuclear Power Station – George Papanic Jr.							TELEPHONE NUMBER (Include Area Code) (815) 416-2815	
13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT								
CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	REPORTABLE TO EPIX
NA					NA			
14. SUPPLEMENTAL REPORT EXPECTED					15. EXPECTED SUBMISSION DATE			
<input type="checkbox"/> YES (If yes, complete 15. EXPECTED SUBMISSION DATE)					<input checked="" type="checkbox"/> NO			
					MONTH DAY YEAR			
ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)								
<p>On February 1, 2006, at approximately 1943 hours (CST), with Unit 2 at approximately 98 percent power, Dresden Nuclear Power Station technicians were performing a calibration of the Isolation Condenser Steam/Condensate Line High Flow instrumentation when a technician observed an unexpected response during the return to service of the Isolation Condenser Condensate Line High Flow Differential Pressure Switch DPIS 2-1349B. The switch monitors flow in the Isolation Condenser Condensate Return line. The calibration was stopped. The Isolation Condenser was declared inoperable and isolated.</p> <p>Subsequent investigations determined that the observed unexpected response was the result of voids in the instrument sensing lines of the Isolation Condenser Steam/Condensate Line High Flow Differential Pressure Switch and that the instrumentation was operable with the voids present.</p> <p>The apparent cause of the voids in the instrument sensing lines of the Isolation Condenser Steam/Condensate Line High Flow Differential Pressure Switch was the failure of Procedure DOP 1300-11, "Unit 2 Isolation Condenser Fill and Vent," to identify that the sensing lines required backfilling after filling of the Isolation Condenser piping. A corrective action was created to revise Procedure DOP 1300-11 to require the backfilling of sensing lines after filling of the Isolation Condenser piping.</p>								

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISIO N NUMBE		
Dresden Nuclear Power Station Unit 2	05000237	2006	-- 001	-- 00	2	OF 3

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

Dresden Nuclear Power Station (DNPS) Unit 2 is a General Electric Company Boiling Water Reactor with a licensed maximum power level of 2957 megawatts thermal. The Energy Industry Identification System codes used in the text are identified as [XX].

A. Plant Conditions Prior to Event:

Unit: 02 Event Date: 02-01-2006
Reactor Mode: 1 Mode Name: Power Operation Power Level: 098 percent
Reactor Coolant System Pressure: 1000 psig

B. Description of Event:

On February 1, 2006, at approximately 1943 hours (CST), with Unit 2 at approximately 98 percent power, Dresden Nuclear Power Station technicians were performing a calibration of the Isolation Condenser (IC) [BL] Steam/Condensate Line High Flow instrumentation when a technician observed an unexpected response during the return to service of the IC Condensate Line High Flow Differential Pressure Switch DPIS 2-1349B. The switch monitors flow in the IC Condensate Return line. The calibration was stopped. The IC was declared inoperable and isolated. Subsequent investigations determined that the observed unexpected response was the result of voids in the instrument sensing lines of the IC Steam/Condensate Line High Flow Differential Pressure Switch.

An ENS call was made on February 2, 2006, at 0043 hours (CST) for the above-described event. The assigned ENS event number was 42300.

The IC was returned to service and declared operable on February 2, 2006 at 1819 hours (CST).

This event is being reported in accordance with 10 CFR 50.73(a)(2)(v)(D), "Any event or condition that could have prevented the fulfillment of the safety function of structures or systems that are needed to mitigate the consequences of an accident." The IC is a single train system and is credited in the loss of feedwater transient analysis.

C. Cause of Event:

The apparent cause of the voids in the instrument sensing lines of the IC Steam/Condensate Line High Flow Differential Pressure Switch was the failure of Procedure DOP 1300-11, "Unit 2 Isolation Condenser Fill and Vent," to identify that the sensing lines required backfilling after filling of the IC piping.

A review of the activities performed on the Unit 2 IC Condensate Return Line identified an activity performed in the fall of 2005 that could have caused the voids in the sensing lines. The activity involved the refilling of the IC piping in accordance with DOP 1300-11 after the lines had been drained for testing. DOP 1300-11 required the back filling of the sensing lines associated with the IC Steam/Condensate Line High Flow Differential Pressure Switch prior to completing the refilling of the

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISIO N NUMBE		
Dresden Nuclear Power Station Unit 2	05000237	2006	-- 001	-- 00	3	OF 3

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

IC Condensate Return Line. The preferred method is to backfill the sensing lines after completion of the filling of the IC piping.

A review of the performance of the Unit 3 IC Steam/Condensate Line High Flow Differential Pressure Switches DPIS 3-1349A and DPIS 3-1349B indicate that the sensing lines are filled and operating normally.

D. Safety Analysis:

The safety significance of the event is minimal. The IC during this event was in compliance with the requirements of Technical Specification 3.5.3, "IC System," and subsequent investigations determined that the IC Steam/Condensate Line High Flow instrumentation was operable with the voids present. Therefore, the consequences of this event had minimal impact on the health and safety of the public and reactor safety.

E. Corrective Actions:

Unit 2 Procedure DOP 1300-11 will be revised to require the backfilling of DPIS 2-1349A and DPIS 2-1349B sensing lines after filling of the Isolation Condenser piping.

Unit 3 Procedure DOP 1300-10, "Unit 3 Isolation Condenser Fill and Vent," will be revised to require the backfilling of DPIS 3-1349A and DPIS 3-1349B sensing lines after filling of the Isolation Condenser piping.

Unit 2 IC Condensate Line High Flow Differential Pressure Switches DPIS 2-1349A and DPIS 2-1349B sensing lines will be backfilled at the next Unit 2 forced outage of sufficient duration.

F. Previous Occurrences:

A review of DNPS Licensee Event Reports (LERs) for the last three years did not identify any similar events.

G. Component Failure Data:

NA