



Duke Energy - Oconee
Nuclear Station Steam
Generator Wear Root
Cause Update with NRC
April 10, 2006

C Thomas Alley

1

ENCLOSURE 2

Topics of discussion

- Introductions
- Review of Unit 1 and 2 ROTSG Wear
- Preliminary Probable Causes
 - Alloy 690 / 410S Tube Support Plate (TSP) material couple and Increased Wear Coefficient
 - Tube to TSP relative rotation and reduced contact area
 - Steam Nozzle Flow Restrictor Acoustic Excitation
 - Low Frequency Pressure Pulse
 - Hourglassed Broach Plate Annular Flow Instability
- Preliminary Metallurgical Observations
- Plan for Future Activities
- Conclusions

Babcock & Wilcox Canada

Pressure Vessel Division Nuclear Power Once-Through Steam Generator

Design objectives

- "Form fit and function" design to simplify licensing
- Retain all terminal points
- Overall performance consistent with existing steam generators
- Structural compatibility with Nuclear Steam Supply System
- Design for maximum reliability
- Minimize tube residual stress
- Avoid flow induced vibration
- Assure high steam superheat under all operating conditions
- Prevent loose parts
- Facilitate inspection and maintenance

Tube bundle arrangement:





- Full pitch pattern occupied by tubes or tie-rods
- No tube-free lane (eliminates moisture carry-up into superheat regions and localized high velocities)

Hour-glassed broached plate configuration:

- Reduces pressure drop
- Provides flat surface contacts between tube support plates and tubes
- Facilitates tubing
- More accessible for water lance, chemical or water slap cleaning

Main feedwater system:

- All welded leak-tight design, corrosion-erosion resistant
- Accessible for internal inspection



Babcock & Wilcox Canada
881 Coronation Blvd.
Cambridge, ON N1H 5V3
tel.: (519) 621-2130
fax: (519) 621-8661


ONS 1 Wear Distributions



ONS1 A	Tube Support Plate															Total
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	
%tw<=5					1			4	23	15	21	17	6	13		100
5<%tw<=10	4	5	5		2		9	46	318	383	344	228	110	121	1	1576
10<%tw<=15	1	2	2					8	89	157	102	83	49	50	5	548
15<%tw<=20									13	47	31	16	8	14	1	130
20<%tw<=25									1	19	15	3		2		40
25<%tw<=30										15	3	1				19
30<%tw<=35										8	4					12
35<%tw<=40										2	2					4
40<%tw<=45										2						2
45<%tw<=50																0
50<%tw<=55																0
55<%tw<=60																0
%tw>60																0
Total/Support	5	7	7	0	3	0	9	58	444	648	522	348	173	200	7	2431

ONS1-B	Tube Support Plate															Total
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	
%tw<=5		3	2		1		5	12	19	31	11	2	5	15	1	107
5<%tw<=10	1	9	6	5	2	1	30	34	253	402	174	4	55	174	10	1160
10<%tw<=15	1		1				4		28	130	80	2	5	68	2	321
15<%tw<=20									7	40	35			17	1	100
20<%tw<=25	1								2	15	11		1	3		33
25<%tw<=30										12	4					16
30<%tw<=35										5	3					8
35<%tw<=40										1	1					2
40<%tw<=45											2					2
45<%tw<=50																0
50<%tw<=55																0
55<%tw<=60																0
%tw>60																0
Total/Support	3	12	9	5	3	1	39	46	309	636	321	8	66	277	14	1749


ONS 1 Wear Distributions




Ocone 1-A

TSP (All)

- 1-5%
- 6-10%
- 11-15%
- 16-20%
- 21-25%
- 26-30%
- 31-35%
- 36-40%
- 41-45%
- >45%




ONS 1 Wear Distributions




Oconee 1-B

TSP (All)

- 1-5%
- 6-10%
- 11-15%
- 16-20%
- 21-25%
- 26-30%
- 31-35%
- 36-40%
- 41-45%
- >45%




ONS 2 Wear Distributions




ONS2-A
11-01-05

TSP (All)

- 1-5%
- 6-10%
- 11-15%
- 16-20%
- 21-25%
- 26-30%
- 31-35%
- 36-40%
- 41-45%
- >45%




ONS 2 Wear Distributions



ONS2-B
11-04-05

TSP (All)

- 1-5%
- 6-10%
- 11-15%
- 16-20%
- 21-25%
- 26-30%
- 31-35%
- 36-40%
- 41-45%
- >45%







Wear Indications per Steam Generator



		Original OTSG	Replacement OTSG
Oconee Unit 1	SGA	555	1797
	SGB	1232	1450
Oconee Unit 2	SGA	428	498
	SGB	566	699
Oconee Unit 3	SGA	350	Scheduled April/May 2006
	SGB	280	Scheduled April/May 2006

ONS 1 & 2 TSP Wear Frequency Comparison



Summary of Review of Eddy Current Data



■ ONS 1 Summary

- ONS1A, 2431 indications were found on 1797 tubes
- ONS1-B, 1749 indications were found on 1450 tubes
- Both ROTSGs 90% of the indications are less than or equal to 15% of the through wall thickness
- 50% of the indications are under 10% of the through wall thickness
- The vast majority of indications ($\approx 95\%$) are present in the superheated steam region on the 9th tube support plate and above
- All indication above the 9th support plate are predominately on the outer region of the bundle.

ONS1 Summary (cont'd)



- The highest frequency of indications is at the 10th support plate, with the 11th and 9th showing the next highest population,
 - The bleed port is located between the 9th and 10th support plate
 - the steam outlet nozzles are located at the elevation of the 11th support plate.
- Peripheral indications at the 10th TSP on both ROTSGs are more tightly distributed and show a tendency to form a “line” oriented relative to the steam nozzle orientation
- There is also a heavy defect concentration directly opposite the steam nozzles on the Y2 axis.
- The 15th support plate, which is directly below the high cross flow steam outlet region and has very few indications.
- For support plates 10 and above, there are very few indications in the interior with increasing occurrences towards the periphery
- The peak density of tube wear is typically a few rows away from the periphery edge
- Support plate 9 has a significant percentage of indications in the interior of the bundle.

ONS1 Summary (cont'd)



- ❑ Virtually all indications are tapered wear marks with an angle nominally between 0.3 and 1.2 degrees.
- ❑ Analysis of tube to TSP land clearances indicate no clear relationship between the size of the clearances and incidence of indications.
- ❑ The original OTSGs tube wear is compared against the replacements in which the distribution of the tube wear in the upper TSPs is similar; although there are more indications for the replacements during the first fuel first cycle, than the life span of the original units.
- ❑ The original OTSGs the 9th and 10th TSP have the most indications followed by the 8th and the remainder in the upper TSPs.
- ❑ The peak counts occur in the 10th and 11th TSP for the replacements followed by the remainder of the upper TSPs.
- ❑ Only TSPs 7 and 8 differ with significantly more indications in the OTSGs than the ROTSGs.

ONS2 Summary



- ONS2-A, 633 indications were found on 498 tubes
- ONS2-B, 903 indications were found on 699 tubes
- Both ROTSGs 90% of the indications are less than or equal to 13% of the through wall thickness and 50% of the indications are under 8% of the through wall thickness
- There are significantly less indications than ONS1 with a less severe wear depth distribution.
- The highest frequency of indications is at the 13th support plate for ONS2-A and the 12th support plate for ONS2-B. There is low incidence of indications on the 9th, 10th and 11th support plates when compared with ONS1.
- Relative to ONS1 there are an increased number of indications in the vicinity of the inspection ports in the lower bundle region below the 9th TSP.
- Based on ECT, wear is predominately single lobe contact similar to ONS1
- Preliminary review of X-Probe data shows no discernable orientation pattern .

Oconee Tube Wear Probable Cause



- To date, no singular technical root cause has been isolated, but five contributing causes have been identified by the Root Cause Team (BWC and Duke Energy)

- **Probable Technical Causes:**
 - 1) Alloy 690 / 410S tube support plate (TSP) material couple and increased wear coefficient
 - 2) Tube to TSP relative rotation and reduced contact area
 - 3) Main steam nozzle flow restrictor acoustic excitation
 - 4) Low frequency pressure pulse
 - 5) Hourglassed broach plate annular flow instability

Factors Investigated

- **Dynamic Pressure Induced Vibration**

- Feedwater Spray Nozzle Dynamic Excitation of Lower Shroud
- Feedwater Spray Nozzle Dynamic Pressure Excitation of Tubes

- **Acoustic Induced Vibration**

- Axial Acoustic Standing Waves between TSPs
- Acoustic Resonance with Cross Flow Vortex Shedding
- Steam Nozzle Flow Restrictor Acoustic Excitation of Tubes
- Feedwater Spray Nozzle Acoustic Excitation of Tubes

■ Structural Vibration

- Steam Nozzle Flow Restrictor Dynamic Excitation of Piping, Shell or Shroud
- Structural Vibration of Shell due to Mechanical Excitation of System including change in stiffness of ROTSG
- Structural Vibration of Shell due to Ineffective Upper Lateral Restraint
- Structural Vibration of Shell due to RCP excitation / unbalance
- Structural Excitation of Hot Leg (180° bend) due to RCS flow perturbations

Flow Induced Vibration

- Hourglassed Broached Hole Annular Flow Instability
- O.D. Axial Flow Turbulence Induced Excitation
- Axial flow inside tube causing lateral vibration
- Localized cross flow excitation at TSPs within a nominally axial flow field
- High Cross Flows and FIV loading in bleed port and steam exit region
- Localized 'jet pump' effect of feedwater spray nozzles
- Excessive Bleed Flow attributed to steam carryunder in lower feedwater downcomer
- Downcomer flow leakage through lower inspection port sleeves
- Flow Regime Instability

Flow Induced Vibration (cont'd)

- Porosity Related Flow Maldistribution at Tube Support Plates
- Correctness of standard FIV analysis addressing fluid-elastic instability (FEI), random turbulence (RT) and vortex shedding
- Effects of linear versus non-linear FIV analysis including 'clearance limited FEI'
- Unbalanced feedwater flow through spray nozzles
- 'U-tube' flow oscillations in lower bundle and downcomer

Factors Investigated (cont'd)



Mechanical / Material Interaction

- Effect of broached hole clearances
- Effect of tube tension including confirmation of prestrain
- Effect of damping in superheat region
- Relative mechanical interaction between tubes, TSPs, shroud and shell
- Effect of curved versus flat land
- Effect of improved tube / TSP alignment
- Material couple wear coefficient

Plant Operational Thermal Hydraulic Conditions and Geometry

Discussion of Probable Causes

Alloy 690 / 410S TSP Wear Coefficient



- A literature search of wear coefficients was conducted and found a wide variation of results for the same materials
- Comparison of the original material combination to the ROTSG material combination was initiated
- Room temperature sliding tests in a dry environment have provided repeatable consistent results showing that the wear coefficient for Alloy 690 / 410S is about an order of magnitude higher than Alloy 600 / carbon steel
- Comparative simultaneous testing in autoclave fretting machines at super heated conditions has been initiated to confirm the differences between the original material and ROTSG material combinations

Tube to TSP Relative Rotation and Reduced Contact



- Volumetric wear rate is proportional to work rate but through wall wear rate is related to the contacting surface area
- Dynamic contact between the tube and tube support 'land' should engage the full length of the land
- Relative angular rotation due to tube dynamic motion or rotation of the TSPs can increase the wear rate
- The Oconee ROTSGs TSPs are vertically positioned by both tie rod spacers starting from the lower tubesheet and by support blocks around the outer edge of the TSPs which are welded to the shroud I.D.

- Relative thermal expansion of the tie rods and the upper and lower shrouds, which are anchored at their bottom ends, cause vertical loads at the outer support blocks. These loads result in a dishing of the support plates
- The angular rotation of the support plate edge may be detrimental to wear due to the possibility of reduced contact area
- A relationship between the locations of the tapered wear marks and the angular rotation of the TSPs is still under review

Main Steam Nozzle Flow Restrictor Acoustic Excitation

- Any sudden shock loss in a steam system is a potential source of acoustic energy
- An illustration of acoustic energy generation and transmission in a piping system is shown in Figure 10-10 of Blevins (1994)




Fig. 10-10 A pipe run with an acoustical source at a valve.

Analytical Acoustic Analysis

- Determined acoustic energy from steam nozzle flow restrictor pressure drop and velocity using conventional analytical analysis
- Predicted ROTSG acoustic modes
- From acoustic sound pressure levels and mode shapes determined magnitude and frequency of tube lateral loads
- Applied acoustic loading as forced vibration on tubes along with FIV loads and support contact forces
- Based on analysis, acoustic energy maybe significant, especially in areas away from cross flow loads and generally covers regions where wear was observed

Main Steam Nozzle Flow Restrictor Acoustics cont'd



Search for acoustics

- Original and Replacement OTSG Loose Part Monitoring System spectral content reviewed
- Steam line piping (outside of containment) instrumented to measure pipe wall accelerations at Units 1, 2 and 3
- Microphone sound measurements taken around steam line
- Direct pressure transducer measurements taken at ROTSG inspection ports during power escalation following Unit 2 outage
- More pressure transducer measurements planned for Unit 3 outage as well as containment microphone being installed

Search for acoustics cont'd

- Unit 2 pressure transducer acoustic frequencies were detected but the amplitudes were not as intense as those from predictive analysis
- Steam line piping acceleration measurements detected the same acoustic frequencies as those measured by the ROTSG pressure transducers. Steam line piping accelerations are largest at Unit 1 followed by Unit 2 followed by Unit 3

Acoustic analysis conclusions

- Predictive analysis based on the pressure drop of the steam line flow restrictor and acoustic modal analysis indicates that the flow restrictor maybe an acoustic source that may explain the wear distribution within the bundle
- Field measurements and analysis of steam line accelerations indicate a potential that acoustic frequencies exists that may have potentially high energy levels
- Pressure transducer measurements at ONS-2 detected acoustic frequencies at intensities less than expected from ONS-1 investigations.

Low Frequency Pressure Pulse




- Unexpected high pressure, low frequency signals were observed at the 9th and 10th TSP, especially at lower power during startup of unit #2 in the fall 2006
- Signals still being evaluated. There is concern that they may not represent real pressure
- Calculations by consultant indicate that energy is sufficient to cause damage if signals are real.
- Signals at low power may be related to control valve operations.

Low Frequency Pressure Pulse



Low Frequency Pressure Transients during Low Power Operations




Pressure transients were initiated at TSP 9 but were detected also at the other TSP transducers. Note the magnitudes at the other locations were

Low Frequency Pressure Pulse




Low Frequency Pressure Transients during Low Power Operations



Low Frequency Pressure Pulse



Low Frequency Pressure Transients during Low Power Operations



Annular Flow Instability of Hourglassed Broached Hole



- Annular flow instability, also known as 'leakage-flow-induced' vibration, typically occurs in cases where a flexible object is situated within an annular flow passage
- Either the dynamics of the flow field or the varying position of the flexible object within the flow passage can cause a variation in the dynamic pressure around the central object
- The difference in dynamic pressure around the perimeter of the central object causes a net lateral pressure force which may be destabilizing. The motion caused by the lateral force may increase the dynamic pressure imbalance and cause further lateral motion, hence creating instability.

Annular Flow Instability of Hourglassed Broached Hole



Industry Experience with Annular Flow Instability

- Laboratory experiments of divergent nozzle annular flow instability show that a symmetric annular gap with divergent (expansion) angles of 5 to 15° can cause lateral vibration
- In some cases where the divergent profile had non-symmetric relief passages, annular flow instability was still observed
- Some research has shown that inlet convergent profiles are a stable configuration
- The Ocone ROTSG configuration does not match the profile of a classic unstable profile but has some features that make it suspect and consequently a test program in air and water flows was initiated


Annular Flow Instability of Hourglassed Broached Hole




3. Laboratory experiments

a) Gorman & al. 1987 (at EdF, in relation with PWR in-core)


Water
Angle=15°



Strong vibrations



Vibrations




No vibrations

Annular Flow Instability of Hourglassed Broached Hole




Original Broached Hole



Note: Plate thickness 1.5"


OTSG broached plate tube support

Original TSP Design



B&W Tube Support Plate Design

ROTSG Broached Holed Hole



Results of Analysis and Testing

- Air flow tests at hydraulic conditions equivalent to full power operation indicate that the hourglassed profile causes increased tube response relative to the original non-tapered flow passages
- The vibratory motions and frequencies measured do not result in an exceedingly high work rate at the support interface but are similar to those from cross flow FIV mechanisms
- Field data does not support annular flow instability as a singular root cause since axial flow is uniform at all radial positions while wear predominantly occurs around the periphery

Preliminary Metallurgical Studies

ONS 2 Tube Pulls




Two full length tubes were removed from ONS 2 during outage for metallurgical analysis


Westinghouse performing met exam

- Macro photography -complete
- Lab ECT - complete
- SEM/EDX – in progress
- Laser profilometry – in progress
- Meeting 4/11/05 to discuss results to date and future plans
- Wear tapered consistent with field ECT
- Sliding marks evident on upper bundle defects
- Preliminary observations of wear surface suggest more than one mode of tube motion likely

ONS 2 Tube Pulls



53-114, Pce 32, TSP 14, 110 Deg.




ONS 2 Tube Pulls



1 in

Top




53-114, Pce 28, TSP 12, 120 Deg.

2 mm

5

6

4




Future direction and conclusions

Status of ONS Steam Generator Root Cause Investigation



- Install instrumentation package during spring 06 unit #3 outage, perform analysis of data and compare to unit #2, update root cause report/assumptions
- Install instrumentation package during fall 06 unit #1 outage, perform analysis of data and compare results of all testing update root cause report/assumptions
- Perform 100% eddy current inspection of unit #1, establish time rate of wear, validate models and assumptions used in operability assessments and evaluations, update root cause report/assumptions
- Transition to corrective actions for probable causes

TEST INSPECTION PORT LOCATIONS



Concluding Remarks



- Root cause teams have been meeting on a regular basis and will continue through out the summer
- We now know more about what is not causing the wear scars and have 4-5 probable causes
- Testing and data analysis efforts will continue for units #3 this spring and unit #1 this fall
- Eddy current results for the fall 2006 outage on unit #1 will give us our first clues as to the time rate of wear and the if new wear scars have initiated
- Root cause effort should come to some conclusions and begin winding down by the end of the year unless unexpected results are found during the unit #1 re-inspection
- ECT will continue on each unit for the foreseeable future