

RI - DNMS Licensee Event Report Disposition

Licensee: TOM E J. UBINAS Radiology CRK
 Event Description: breaking source
 License No: 52 25487-4 Docket No: 630 35220 MLER-RI: 2006-014
 Event Date: 3-29-06 Report Date: 4-3-06 HQ Ops Event #:

1. REPORTING REQUIREMENT

<input type="checkbox"/>	10 CFR 20.1906 Package Contamination	<input type="checkbox"/>	10 CFR 30.50 Report
<input type="checkbox"/>	10 CFR 20.2201 Theft or Loss	<input type="checkbox"/>	10 CFR 35.3045 Medical Event
<input type="checkbox"/>	10 CFR 20.2203 30 Day Report	<input type="checkbox"/>	License Condition
<input checked="" type="checkbox"/>	Other <u>10 CFR 35.67, 35.3067</u>		

2. REGION I RESPONSE

<input type="checkbox"/>	Immediate Site Inspection	Inspector/Date	
<input type="checkbox"/>	Special Inspection	Inspector/Date	
<input type="checkbox"/>	Telephone Inquiry	Inspector/Date	
<input checked="" type="checkbox"/>	Preliminary Notification/Report	<input type="checkbox"/>	Daily Report
<input type="checkbox"/>	Information Entered in RI Log	<input type="checkbox"/>	Review at Next Inspection
<input type="checkbox"/>	Report Referred To:		

3. REPORT EVALUATION

<input checked="" type="checkbox"/>	Description of Event	<input checked="" type="checkbox"/>	Corrective Actions
<input checked="" type="checkbox"/>	Levels of RAM Involved	<input checked="" type="checkbox"/>	Calculations Adequate
<input checked="" type="checkbox"/>	Cause of Event	<input type="checkbox"/>	Additional Information Requested from Licensee <u>N/A</u>

4. MANAGEMENT DIRECTIVE 8.3 EVALUATION

<input checked="" type="checkbox"/>	Release w/Exposure > Limits	<input type="checkbox"/>	Deliberate Misuse w/Exposure > Limits
<input checked="" type="checkbox"/>	Repeated Inadequate Control	<input type="checkbox"/>	Pkgng Failure > 10 rads/hr or Contamination > 1000x Limits
<input checked="" type="checkbox"/>	Exposure 5x Limits	<input type="checkbox"/>	Large# Indivs w/Exp > Limits or Medical Deterministic Effects
<input checked="" type="checkbox"/>	Potential Fatality	<input type="checkbox"/>	Unique Circumstances or Safeguards Concerns
<input type="checkbox"/>	If any of the above are involved:	<input type="checkbox"/>	Considered Need for AIT
<input type="checkbox"/>	Considered Need for IIT		
	Decision/Made By/Date:		

5. MANAGEMENT DIRECTIVE 8.10 EVALUATION (additional evaluation for medical events only)

<input checked="" type="checkbox"/>	Timeliness - Inspection Meets Requirements (5 days for overdose / 10 days for underdose)
<input checked="" type="checkbox"/>	Medical Consultant Used-Name of Consultant/Date of Report:
<input checked="" type="checkbox"/>	Medical Consultant Determined Event Directly Contributed to Fatality
<input checked="" type="checkbox"/>	Device Failure with Possible Adverse Generic Implications
<input type="checkbox"/>	HQ or Contractor Support Required to Evaluate Consequences

6. SPECIAL INSTRUCTIONS OR COMMENTS

review during next inspection

Non-Public Inspector Signature: [Signature] Date: 5/4/06
 Public-SISP REVIEW COMPLETE Branch Chief Initials: [Signature] Date: 5/4/06

P.O. BOX 70321, S.J.
PUERTO RICO 00936-7921
TEL. (787) 764-5666
FAX (787) 767-7040

Penny

**TOME & UBINAS
RADIO
ONCOLOGY
CENTER**

To: *Hector Bermudez*

From: *Luis Rivera, RSO NRC License*

Fax: *404-562-4955*

Pages: *2 includes cover #52-2548*

Phone:

Date: *4/3/6*

-01

Re:

cc: *Director, Office of Nuclear & Material
Safety + Safeguards*

Urgent For Review

Please Comment

Please Reply

Please Recycle

• Comments:

Apr 03 2006 7:34PM HP LASERJET FAX

P-2

**Tome and Ublñas Radio Oncology Center
NRC license # 52-25487-01**

Date: April 3, 2006

Re: Report of a leaking source

This report of a leaking source is pursuant to 10 CFR 35.67 and the reporting requirements as described in 10 CFR 35.3067.

Model Number: STM 1251

Serial Number: n/a

Radionuclide: I-125

Estimated Activity: apparent activity of 0.340 mCi on 03/29/06

Result of the Test: Survey instrument readings and subsequent wipe test result revealed the presence of more than 0.005 microcuries.

Date of the test: 3/29/06

Action Taken: An I-125 seed (model STM 1251) jammed in the Mick applicator during a transperineal prostate seed implant. Survey meter readings indicated the source was in the applicator. Water was flushed through the applicator into a basin in an attempt to retrieve the seed. While the seed did not flush into the basin, survey meter readings of the water in the basin revealed radioactivity. At this point we proceeded with the assumption of a ruptured source (subsequent wipe tests confirmed our assumption). The Mick applicator and the water basin were then immediately removed from use and isolated. A second mick applicator was used to finish the procedure and as such the written directive for the patient was met. The operating room was isolated to verify that there was no spread of radioactive contamination. No one was permitted in the room. All personnel that were present in the room were surveyed for radiation. All results were negative. Subsequent wipe tests of the areas adjacent to the contaminated applicator were negative for contamination. A survey of the patient's urine at the end of the procedure was negative for radiation. The patient was sent home with a catheter. He returned the following day for catheter removal. A survey of the urine in the catheter was negative for radiation.