

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION



1. LICENSEE/LOCATION INSPECTED: Driesenga & Associates 455 E 8 th St Holland, MI 49723		2. NRC/REGIONAL OFFICE REGION III US NUCLEAR REGULATORY COMMISSION 2443 WARRENVILLE ROAD, SUITE 210 LISLE, ILLINOIS 60532	
REPORT 03035313/2006001, <i>007</i>			
3. DOCKET NUMBER(S) 03033782	4. LICENSEE NUMBER(S) 21-26634-01	5. DATE(S) OF INSPECTION May 16, 2006	

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

1. Based on the inspection findings, no violations were identified.

2. Previous violation(s) closed.

3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Ed Kulzer	<i>E. L. Kulzer</i>	5/17/06

Docket File Information
**SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION**



1. LICENSEE Driesenga & Associates REPORT 2006-001,004		2. NRC/REGIONAL OFFICE Region III	
3. DOCKET NUMBER(S) 030-33782	4. LICENSE NUMBER(S) 21-26634-01	5. DATE(S) OF INSPECTION May ,2006	
6. INSPECTION PROCEDURES USED 87124	7. INSPECTION FOCUS AREAS 03.01 - 03.07		
SUPPLEMENTAL INSPECTION INFORMATION			
1. PROGRAM 03121	2. PRIORITY 5	3. LICENSEE CONTACT James Henning	4. TELEPHONE NUMBER 616.396.0255
<input type="checkbox"/> Main Office Inspection		Next Inspection Date: <u>May 2011</u>	
<input checked="" type="checkbox"/> Field <u>552 South 8th St., Kalamazoo, MI</u>			
<input checked="" type="checkbox"/> Temporary Job Site <u>Vicksburg High School & Stadium Drive</u>			

PROGRAM SCOPE

The licensee is an engineering firm that employs 18 individuals. The licensee possesses three Troxler 3440 moisture density gauges, for use daily/weekly during the construction season (May-November) for soils engineering projects. The licensee does not perform any service or maintenance activities on its gauges; these services are performed by the manufacturer. Currently, the licensee employs six authorized gauge users who have completed manufacturers training. The gauges are stored in a locked cabinet in the licensee's facility located at 552 South 8th Street, Kalamazoo, Michigan.

Performance Observations

The inspector observed operations at a temporary job site located at Vicksburg High School. The operator possessed required shipping papers which contained all appropriate information and were accessible in the transport vehicle. The operator demonstrated an adequate level of understanding of emergency and handling procedures during job-site interviews. Security during transport and at the job-site was described and observed respectively with no problems noted.