



BRUCE H HAMILTON  
Vice President  
Oconee Nuclear Station

Duke Energy Corporation  
ON01VP / 7800 Rochester Highway  
Seneca, SC 29672

864 885 3487  
864 885 4208 fax  
bhhamilton@duke-energy.com

June 30, 2006

U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555-0001

Subject: Duke Power Company,  
Oconee Nuclear Station, Unit 3  
Docket No. 50-287  
Steam Generator Inservice Inspection  
Steam Generator Tube Plugging and Repair 30-day Report

As required by Technical Specification 5.6.8, a, this letter provides the number of tubes plugged or repaired during the Steam Generator (SG) Tube Inservice Inspection for the Unit 3 Cycle 22 refueling outage:

<u>Steam Generator</u>	<u>No. of Tubes Repaired</u>	<u>Reason/Repair Method</u>
A	0	No SG tubes exceeded plugging limit.
B	0	No SG tubes exceeded plugging limit.

For your information, 100% eddy current inspections were performed on Steam Generators 3A and 3B during this refueling outage.

Please address any questions to Randy Todd at (864) 885-3418.

Very Truly Yours,

Bruce H. Hamilton,  
Site Vice President,  
Oconee Nuclear Station

A047

US Nuclear Regulatory Commission  
June 30, 2006  
Page 2

cc:

Mr. William D. Travers  
Administrator, Region II  
U.S. Nuclear Regulatory Commission  
Atlanta Federal Center  
61 Forsyth St., SWW, Suite 23T85  
Atlanta, GA 30303

L. N. Olshan, Project Manager, Section 1  
Project Directorate II  
Division of Licensing Project Management  
Office of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555-0001

D. W. Rich  
Senior NRC Resident Inspector  
Oconee Nuclear Station

US Nuclear Regulatory Commission  
June 30, 2006  
Page 3

bcc: B. Graham Davenport  
Parker Downing, Jr.  
Jeff D. Gilreath  
Randall P. Todd

Reene V. Gambrell

Lisa F. Vaughn  
C. Jeff Thomas - MNS  
Randall D. Hart - CNS  
Robert L. Gill -NAID  
ELL  
NSRB  
Document Management - (OS-18.0)