

July 10, 2006

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Mail Stop P1-137  
Washington, DC 20555-0001

ULNRC05308

Ladies and Gentlemen:



**DOCKET NUMBER 50-483  
CALLAWAY PLANT UNIT 1  
UNION ELECTRIC CO.  
FACILITY OPERATING LICENSE NPF-30  
LICENSEE EVENT REPORT 2006-003-00  
Turbine Trip at 47% Power with Rods in Auto Leads to  
Manual Reactor Trip and Aux Feedwater Actuation**

The enclosed licensee event report is submitted in accordance with 10CFR50.73(a)(2)(iv)(A), to report an event where inadequate procedural guidance resulted in Emergency Safety Feature actuations of Feedwater Isolation, Auxiliary Feedwater and a Manual Reactor Trip following a manual turbine trip from 47 percent power.

This letter does not contain new commitments.

Sincerely,

*L. E. Thibault*  
L. E. Thibault  
Director, Plant Operations

JWH/slk

Enclosure

*JED*

ULNRC05308

July 10, 2006

Page 2

Mr. Bruce S. Mallett  
Regional Administrator  
U.S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 400  
Arlington, TX 76011-4005

Senior Resident Inspector  
Callaway Resident Office  
U.S. Nuclear Regulatory Commission  
8201 NRC Road  
Steedman, MO 65077

Mr. Jack N. Donohew (2 copies)  
Licensing Project Manager, Callaway Plant  
Office of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Mail Stop O-7D1  
Washington, DC 20555-2738

Missouri Public Service Commission  
Governor Office Building  
200 Madison Street  
PO Box 360  
Jefferson City, MO 65102-0360

Records Center  
Institute of Nuclear Power Operations  
700 Galleria Parkway  
Atlanta, GA 30339

**LICENSEE EVENT REPORT (LER)**  
 (See reverse for required number of digits/characters for each block)

Estimated burden per response to comply with this mandatory collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

<b>1. FACILITY NAME</b> Callaway Plant Unit 1	<b>2. DOCKET NUMBER</b> 05000 483	<b>3. PAGE</b> 1 OF 8
--	--------------------------------------	--------------------------

**4. TITLE**  
Turbine Trip at 47% Power with Rods in Auto Leads to Manual Reactor Trip and Aux. Feedwater Actuation

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
05	12	2006	2006	- 004 -	00	07	10	2006	None	
									FACILITY NAME	DOCKET NUMBER

<b>9. OPERATING MODE</b>  MODE 1	<b>11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR§: (Check all that apply)</b>									
	<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)						
<b>10. POWER LEVEL</b>  047	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)						
	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)						
	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)						
	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)						
	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)						
	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)						
<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER							
<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	Specify in Abstract below or in NRC Form 366A							

**12. LICENSEE CONTACT FOR THIS LER**

FACILITY NAME K. A. Mills, Supervising Engr Regional Regulatory Affairs/Safety Analysis	TELEPHONE NUMBER (Include Area Code) (573) 676-4317
--	--

**13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT**

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX

<b>14. SUPPLEMENTAL REPORT EXPECTED</b>	<b>15. EXPECTED SUBMISSION DATE</b>
<input checked="" type="checkbox"/> YES (If yes, complete 15. EXPECTED SUBMISSION DATE) <input type="checkbox"/> NO	MONTH: 08 DAY: 11 YEAR: 2006

**ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)**

On 5/12/2006 reactor power was being reduced to 45% for a planned maintenance activity. Reactor power had been lowered to approximately 48% when vibration on main turbine bearings started rising eventually reaching the turbine trip criteria. The turbine was manually tripped at 0047 on 5/12/2006. Subsequently with the control rods in automatic, rods stepped in as designed. The control rods continually stepped in reducing power below 10% in approximately four minutes. Feedwater flow was controlled through the Main Feedwater Regulating Valves which are not normally in service below 20% power. At 0052, the Steam Generator High-High Level setpoint was exceeded on the 'A' Steam Generator resulting in a Feedwater Isolation Signal and Motor Driven Auxiliary Feedwater Actuation Signal. All safety systems responded as designed. A manual reactor trip was initiated at 0053 in accordance with procedural guidance for the loss of both main feedwater pumps. The cause of this event is an inadequate mitigation strategy in OTO-AC-00001, "Turbine Trip below P-9" (50% power permissive setpoint). The inadequate procedure was the result of an inadequate procedure change review process used in 1991. Corrective Actions to Prevent Recurrence include revision of the procedure change review process and revision of OTO-AC-00001 to incorporate an appropriate mitigation strategy.

**LICENSEE EVENT REPORT (LER)**

FACILITY NAME (1)	DOCKET (2) NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Callaway Plant Unit 1	05000483	2006	004	- 00	2 OF 8

**NARRATIVE** (If more space is required, use additional copies of NRC Form 366A) (17)

**I. DESCRIPTION OF THE REPORTABLE EVENT**

**A. REPORTABLE EVENT CLASSIFICATION**

50.73(a)(2)(iv)(A) – Manual or Automatic Actuation of Systems Listed in 50.73(a)(2)(iv)(B):

- (1) Reactor protection system (RPS) including: reactor scram or reactor trip; and
- (6) PWR auxiliary or emergency feedwater system.

**B. PLANT OPERATING CONDITIONS PRIOR TO THE EVENT**

Mode 1, 47 Percent Reactor Power

**C. STATUS OF STRUCTURES, SYSTEMS OR COMPONENTS THAT WERE INOPERABLE AT THE START OF THE EVENT AND THAT CONTRIBUTED TO THE EVENT**

No structures, systems or components were Inoperable at the start of the event which contributed to the event.

**D. NARRATIVE SUMMARY OF THE EVENT, INCLUDING DATES AND APPROXIMATE TIMES**

At 1754 on 5/8/2006, Reactor Coolant System (RCS) Loop 2 Channel 3 Flow Transmitter, BBFT0426, was declared Inoperable, and the plant entered a 72-hour action statement under Tech Spec 3.3.1.M. The recovery plan included a downpower to 45% to replace the transmitter. The downpower was scheduled to begin at 1900 on 5/11/2006 and continue through the transmitter replacement at 0100 on 5/12/2006 with a return to full power beginning at approximately 0700 on 5/12/2006.

The load reduction commenced as scheduled and proceeded as planned down to approximately 49% power. Just after clearing the P-9 bistables (50% power permissive setpoint) the high-load and low-load valves for the Moisture Separator Reheaters (MSRs) were not responding as expected. At approximately 0035 on 5/12/2006 an investigation was initiated on the operation of the MSR valves during the downpower. Subsequent evaluations determined the closing circuit for these MSR valves was not functioning in automatic control.

While stabilizing power below P-9, a turbine vibration alert was received and investigated in accordance with alarm response procedure OTA-RK-0026, "Annunciator Response Procedure MCB Panel RK026". Plant computer points showed rising vibration levels above 8 mils, and numerous vibration alarms were received on bearings 5, 6, 7 and 8. Off-Normal procedure OTO-AC-00002, "Turbine Vibration", was entered. At Step 2, the Reactor Operator (RO) reported turbine vibration at 11.46 mils. At Step 4, the RO reported that turbine vibration was rising. It was determined that a turbine trip was required. Plant conditions were evaluated to be less than the P-9 setpoint and direction was given for a manual turbine trip, which occurred at 0047. OTO-AC-00002 was exited and a transition made to OTO-AC-00001, "Turbine Trip below P-9".

The turbine stop valves immediately closed on initiation of the turbine trip. The resultant spike in pressure in the 'A' Steam Generator (S/G) caused the level in the generator to shrink by approximately 16 percent. In conjunction with sudden loss of the turbine as a load, a corresponding reduction in steam flow occurred. The control rods stepped in automatically, and the condenser steam dumps opened in the trip mode. At approximately 00:47:50 (approximately 40 seconds after the turbine trip), condenser steam dump Group 2 appears to have closed based on a review of plant computer data. This caused a

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2) NUMBER (2)	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
Callaway Plant Unit 1	05000483	2006	004	- 00	3	OF 8

**NARRATIVE** (If more space is required, use additional copies of NRC Form 366A) (17)

decrease in steam flow, an increase in steam pressure, and a resulting shrink of the narrow range level. Subsequently, the steam dumps began to modulate to maintain RCS average temperature at 557 degrees F, as designed.

A follow up evaluation determined that Group 2 steam dumps (as monitored by a representative condenser steam dump valve, ABUV0039) did not open as expected during this transient. Although an extensive circuit analysis was not performed to evaluate this aspect of the transient, the control logic should have opened Group 2 approximately 3 to 4 seconds after Group 1 initially opened and approximately 3 to 4 seconds prior to Group 3 initially opening. However, Group 2 opened after Group 3, apparently Group 2 did not open, as anticipated, on the load reject controller during this transient. The group may have opened on a S/G HI-1 pressure signal instead. It was determined that this apparent malfunction was likely the cause of the 'B' Atmospheric Steam Dump (ASD) opening for approximately 7 seconds during the transient. However, beyond the momentary operation of the 'B' ASD, this apparent malfunction is not considered to have had any significant impact on the plant response following the peak pressure spike since the Group 2 valves subsequently opened and the ASD compensated for the delay in operation of the affected condenser steam dumps.

As stated above, S/G levels initially lowered as expected and then began to rise. During performance of OTO-AC-00001, the 'B' main feedwater pump was tripped. The Main Feedwater Regulating Valves (MFRVs) were operating as expected to restore S/G water levels.

Approximately 1 minute 40 seconds after the turbine trip, 'A' S/G reached the minimum level experienced during the transient. At this point the inventory that had been injected into the S/G had heated enough that thermal expansion caused the narrow range S/G level indication to rise rapidly. Since level was still below the level control setpoint for about the next 43 seconds, the feedwater flow controller had not yet started to close the MFRV. This continued to allow more feedwater to be injected into the S/G.

At approximately 0049 (1 minute 50 seconds after the turbine trip), condenser steam dump control was shifted to the steam pressure mode by the operators. By this time, RCS average temperature was approaching 557 degrees F; consequently this action does not appear to have had any significant affect.

About 2 minutes 30 seconds after the turbine trip, the MFRVs began to modulate to the closed position. MFRVs continued to close for about the next two and a half minutes until fully closed. At 0051 (about 3 minutes 50 seconds after the turbine trip), feedwater flow had been reduced below steam flow as reflected in plant computer data. However, by Control Room trend recorders, feedwater flow had been reduced to less than steam flow even earlier in the transient. This reduction in feedwater flow did not stop the S/G level increase since thermal expansion of the existing inventory was still occurring.

During this timeframe, a transfer from the MFRVs to the MFRV Bypass Valves was initiated. This action, however, did not cause the P-14 (Steam Generator High-High Level) signal which was received later in the event. When the step was reached in OTO-AC-00001 to transfer S/G level control from the MFRVs to the MFRV Bypass Valves, reactor power level was approximately 10 to 12 percent and S/G levels were near 60 percent. Direction was given to perform the transfer per Attachment 'A' of OTO-AC-00001. About this same time, S/G levels had turned (reduced) for a short duration and then started to rise. The trend recorders for S/G level control indicated that feedwater flow was lower than steam flow. This indicated to the RO that S/G levels should be turning and trending back to normal levels; however, the levels continued to rise. The operating crew believed there was a need to transfer to the MFRV Bypass Valves for control of the S/G levels. Therefore, the RO continued with performance of Attachment 'A'.

At 00:53:07, during the transition to bypass feedwater control, the P-14 setpoint was exceeded in the 'A'

**LICENSEE EVENT REPORT (LER)**

FACILITY NAME (1)	DOCKET (2) NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Callaway Plant Unit 1	05000483	2006	004	00	4 OF 8

**NARRATIVE** (If more space is required, use additional copies of NRC Form 366A) (17)

steam generator. The P-14 signal caused a Feedwater Isolation Signal (FWIS), which tripped the 'A' Main Feedwater Pump (MFP) and initiated a Motor Driven Auxiliary Feedwater Pump Actuation Signal (MDAFAS). The Control Room Supervisor (CRS) informed the Shift Manager (SM) there was an auxiliary feedwater actuation. Reactor power was less than 12% and the CRS recommended a manual reactor trip. The SM concurred and the operating crew manually tripped the reactor at 00:53:33, and then transitioned to Emergency Operating Procedure E-0, "Reactor Trip or Safety Injection".

E-0 was entered, and all immediate actions were completed. All equipment functioned as designed. At 0058, the crew transitioned from E-0 to ES-0.1, "Reactor Trip Response". During the performance of ES-0.1, all equipment functioned as designed. Pressurizer level and pressure control were verified to be functioning normally. The crew exited ES-0.1 and transitioned to OTG-ZZ-00008, "Normal Unit Recovery Guideline Following Reactor Trip". The plant was stabilized in Mode 3, reactor trip breakers were reset at 03:26, the auxiliary feedwater system was reset for automatic operation at 03:37, and feedwater supply was transitioned from auxiliary feedwater to the startup feedwater pump at 03:45.

A review of the event determined OTO-AC-00001 was revised in 1991 to place rod control in automatic. Leaving rod control in automatic during this event resulted in a significant power reduction from 47% power to less than 10% power in approximately four minutes. The controls for the MFRVs are tuned to operate at higher power levels. Therefore, having rod control in automatic resulted in the MFRVs operating outside their normal range leading to high S/G levels, which contributed to safety system actuations and a manual reactor trip.

**E. METHOD OF DISCOVERY OF EACH COMPONENT, SYSTEM FAILURE, OR PROCEDURAL ERROR**

Given the initial conditions of this event, a reactor trip following a turbine trip below 50 percent power was self-revealing through the occurrence of the event. Procedural deficiencies were discovered through the use of a seven-step root cause analysis. Interviews with the operating crew were conducted to gather information and to validate facts. The root cause team developed an Events and Causal Factors Chart and identified one Causal Factor. The TapRoot(R) method was used to determine the Root Cause of the Causal Factor. The TapRoot(R) Root Cause Tree identified one Root Cause. By asking one additional "Why", the team clarified the Root Cause by associating it with the station procedure change review process in effect in 1991.

**II. EVENT DRIVEN INFORMATION**

**A. SAFETY SYSTEMS THAT RESPONDED**

Safety systems that responded to this event included the FWIS, the MDAFAS, and the reactor protection system manual trip function. The responses of these and other non-safety systems that responded to this event are described in the Narrative Summary.

**B. DURATION OF SAFETY SYSTEM INOPERABILITY**

No structures, systems or components were Inoperable during the event which contributed to the event.

**C. SAFETY CONSEQUENCES AND IMPLICATIONS OF THE EVENT.**

This event was evaluated with the Callaway Probabilistic Risk Assessment (PRA) model. The evaluation determined that the Conditional Core Damage Probability (CCDP) of the event was less than 1E-6;

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2) NUMBER (2)	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
Callaway Plant Unit 1	05000483	2006	004	00	5	OF 8

**NARRATIVE** (If more space is required, use additional copies of NRC Form 366A) (17)

therefore, this event was of very low risk significance. Use of the PRA model to evaluate the event provides for a comprehensive, quantitative assessment of the potential safety consequences and implications of the event, including the consideration of alternative conditions beyond those analyzed in the FSAR.

**III. CAUSE(S) OF THE EVENT AND CORRECTIVE ACTION(S)**

A seven-step root cause analysis process was used to evaluate this event. Interviews with the operating crew were conducted to gather information and to validate facts. The Root Cause Team developed an Events and Causal Factors Chart and identified one Causal Factor. The TapRoot(R) method was used to determine the Root Cause of the Causal Factor, and led the team to identify a Root Cause associated with the station procedure change review process in effect in 1991.

**CAUSAL FACTOR CF-1:** OTO-AC-00001 does not require rod control to be in Manual below 15% power. This is inconsistent with Callaway Plant design basis.

The actions of OTO-AC-00001 directed rod control to be placed in the automatic mode of operation without terminating the power decrease as to allow for controlled plant shutdown. This created a situation in which the rod control system decreased reactor power to a level below which the MFRVs could adequately control S/G level. This power reduction occurred so quickly that S/G level control could not be manually transferred to the MFRV Bypass Valves. The mitigation strategy outlined in OTO-AC-00001 for responding to a turbine trip below P-9 was not appropriate.

**ROOT CAUSE RC-1:** When OTO-AC-00001 was revised in 1991 to place rod control in automatic, an inadequate review of the FSAR and other design documents was performed. This review did not identify that the normal power range for automatic rod control is between 15 and 100% full power.

**CORRECTIVE ACTION TO PREVENT RECURRENCE CATPR-1A:** Since 1991 procedure APA-ZZ-00101, "Preparation, Review, and Approval of Written Instructions", has been revised to require that reviewers be designated by the department head as qualified reviewers and that a validation or verification be performed prior to issuance of a major procedure revision. Currently, APA-ZZ-00101 specifically requires that the procedure writer review Controlled Documents, Licensing Basis Documents, References, Commitments and Associated Work Documents. APA-ZZ-00101 was also revised to require a qualification process for procedure writers.

**CORRECTIVE ACTION TO PREVENT RECURRENCE CATPR-1B:** Revise the mitigation strategy implemented per OTO-AC-00001, "Turbine Trip below P-9". Different strategies will be evaluated for implementation including, but not limited to: tripping the reactor upon a Turbine Trip; and including instructions to place rod control in manual below 40% power but prior to reaching 25% power, and stabilizing power at that level followed by a power reduction to take the unit to Mode 3.

**CORRECTIVE ACTION CA-1:** Provide training to operators prior to issuance of revised OTO-AC-00001.

**CORRECTIVE ACTION CA-2:** Evaluate if a revision to OTO-AD-00001, "Loss of Condenser Vacuum", is required to address rod control operation at reduced power levels (< 20% power). This action was derived from the extent of condition review discussed below.

**LICENSEE EVENT REPORT (LER)**

FACILITY NAME (1)	DOCKET (2) NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Callaway Plant Unit 1	05000483	2006	004	00	6 OF 8

**NARRATIVE** (If more space is required, use additional copies of NRC Form 366A) (17)

Procedure OTO-AC-00001 underwent a Major Revision and Validation in 2004 with the revision being issued in 2005 as part of an Emergency Operating Procedure upgrade project. The revised procedure was validated in the simulator. The root cause analysis originally identified inadequate low power simulator modeling as an "Other Issue", which is being independently resolved under the Callaway corrective action program. Subsequent to the plant event, additional actual-plant transient data became available, allowing comparison runs to be performed in the simulator on 7/7/2006 that demonstrated acceptable agreement between plant and simulator performance. As a result, the impact of simulator modeling on the root cause and causal factor of the event will be reassessed. A supplemental LER will be submitted to address any changes to the characterization of the root cause.

The procedure review and approval process has been significantly strengthened since 1991. The process now requires a validation or verification, which it did not in 1991. CATPR-1A minimizes the potential for similar procedural issues from occurring as it provides a process for the review and approval of a procedure prior to the issuance of a major revision.

CATPR-1B will prevent recurrence as the procedure will provide definitive instructions for rod control operation for turbine trip transients occurring below P-9.

Several other issues, including those listed below, were evaluated for impact on this event. These items were determined not to be causal factors or contributors to this event. The resolution of each item is described in detail in the root cause analysis report.

- (1) Decision to open MFRV Bypass Valves in an attempt to transfer feedwater control when steam generator levels were at approximately 80% may have contributed to the P-14 actuation signal.
- (2) Step sequencing within procedure OTO-AC-00001 may not have been adequate to ensure a timely transfer from the MFRVs to the MFRV Bypass Valves following a turbine trip from P-9.
- (3) Manual control of the MFRVs was not established during this level transient which, had it occurred, may have prevented reaching the High-High S/G level setpoint.
- (4) Post Refuel 14 startup test activities may not have been adequate for identifying the susceptibility of a P-14 actuation following a turbine trip below the P-9 permissive.

Extent of condition and extent of cause reviews were conducted as part of the root cause analysis. The Off-Normal (OTO) procedures were reviewed to determine any having direction to place rod control in automatic and which could potentially be in use at low power levels (less than 25%). Three procedures met these criteria: OTO-AC-00002; OTO-AD-00001; and OTO-MA-00001, "Turbine Load Rejection". All three procedures have transitions to OTO-AC-00001 when a turbine trip is necessary below 50% power. OTO-MA-00008, "Rapid Load Reduction", also met the criteria but has guidance to begin transferring S/G level control from the MFRVs to the Bypass Valves at a sufficiently high power to complete the transfer prior to reaching 20% power. The procedure also contains appropriate guidance to ensure rod control is placed in manual at 15% power. OTO-AD-00001 reduces turbine load in response to lowering condenser vacuum and could potentially be in use at low power with no guidance on operation of control rods. OTO-AD-00001 does direct performance of OTO-MA-00008 if a rapid load decrease is required. OTO-MA-00001 responds to a load reject, specifically a setback or runback, and is not likely to be in use at low levels but does direct transition to OTO-AC-00001 if turbine trip is required.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2) NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Callaway Plant Unit 1	05000483	2006	004	00	7 OF 8

**NARRATIVE** (If more space is required, use additional copies of NRC Form 366A) (17)

The extent of cause portion of the review evaluated the generic potential for inadequate procedural guidance. In the case of OTO-AC-00001, the procedure was revised using the process existing in 1991. The procedure writing process under APA-ZZ-00101 has been strengthened since the time the OTO-AC-00001 automatic rod control revision was generated. In addition, APA-ZZ-00101 requires a qualification process for procedure writers and provides a methodology for review and approval to minimize the potential for an incorrect procedure. This includes additional verification or validation techniques to ensure that each procedure is adequate.

**IV. PREVIOUS SIMILAR EVENTS**

External and internal Operating Experience was reviewed for applicability to this event. No similar events were found in the Industry operating experience database. A review of LERs generated since 2001 was also conducted. There were three events where high S/G level resulted in a FWIS, as follows:

- (1) Indian Point Unit 2 LER 01-001-00, Turbine Trip During Startup Results In Auxiliary Feedwater System Actuation;
- (2) South Texas Unit 2 LER 02-003-01, Automatic Reactor Trip Due To Main Turbine Trip Caused By High Water Level In 2b Steam Generator; and
- (3) Catawba Unit 1 LER 03-001-00, High Steam Generator Level Turbine Trip Causes Reactor Trip And Automatic Start Of Motor Driven Auxiliary Feedwater System Pumps

A review of these events determined that they are not relevant operating experience with respect to this event.

A search of the Callaway corrective action system (CARS) identified four relevant occurrences similar to the event discussed here:

- (1) CAR 199002930: Turbine Trip/Reactor Trip – Plant shutdown of 20% per hour was in progress due to chemistry concerns. LER 90-016-00, Reactor Trip on Low Steam Generator Level Which Resulted From A Turbine Trip on A Spurious Moisture Separator Reheater High Level Signal;
- (2) CAR 199201323: Main Feedwater Isolation signal was received. LER 92-006-00, Main Feedwater Isolation Signal Due to the Spurious Opening of Main Steam Dump Valves;
- (3) CAR 199601921: Received a P-14 Hi-Hi Turbine Trip. LER 1996-006-00, Received A P-14 -HI Turbine Trip on 'B' S/G Shortly After Synching to the Grid; and
- (4) CAR 200401167: Reactor Trip due to low S/G water level. LER 2004-005-00, Inadequate Feedwater Heating During Plant Startup Causes Turbine Trip And Subsequent Reactor Trip.

A review of these events determined the first two events are not relevant operating experience with respect to this event. The third event documented a FWIS due to High-High S/G level during a swapover from the MFRV Bypass Valves to the MFRVs. At that time in plant operation, the swapover was performed at around 6 to 10 % power because of the capability of the MFRV Bypass Valves. Corrective Actions for this event

**LICENSEE EVENT REPORT (LER)**

FACILITY NAME (1)	DOCKET (2) NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Callaway Plant Unit 1	05000483	2006	- 004	- 00	8 OF 8

**NARRATIVE** (If more space is required, use additional copies of NRC Form 366A) (17)

were to modify the trim on the MFRV Bypass Valves to allow operation the MFRV Bypass Valves up to 30% power. In addition, a modification was installed to increase the amount of pre-heating by routing main steam to the Feedwater heaters. These corrective actions have been proven to be very effective since their implementation.

While there are similarities between the fourth event and the current event, it is not considered to be directly applicable because of several differences. The similarities include swinging steam generator levels, changing power levels, and transferring between the MFRVs and the Bypass Valves. However, there are significant differences such as: initiators of the events, operating crew response to the events, clarity of related procedural guidance, and S/G responses because of the S/G replacement between the events. In addition, the corrective actions for the fourth event were primarily focused on normal operations, such as power ascension and downpowers and not intended to apply to transient conditions such as in the current event.

**V. ADDITIONAL INFORMATION**

None