



**Pacific Gas and
Electric Company®**

James R. Becker
Vice President
Diablo Canyon Operations and
Station Director

Diablo Canyon Power Plant
P. O. Box 56
Avila Beach, CA 93424

805.545.3462
Fax: 805.545.4234

July 14, 2006

PG&E Letter DCL-06-084

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-0001

Docket No. 50-323, OL-DPR-82
Diablo Canyon Unit 2

60-Day Response to Revision 1 of NRC Order EA-03-009, "Issuance of First Revised NRC Order (EA-03-009) Establishing Interim Inspection Requirements for Reactor Pressure Vessel Heads at Pressurized Water Reactors"

Dear Commissioners and Staff:

On February 11, 2003, the NRC issued Order EA-03-009 for interim inspection requirements for reactor pressure vessel heads at pressurized water reactor facilities. On February 20, 2004, the NRC issued the First Revised Order EA-03-009, which superseded Order EA-03-009. Revision 1 of the Order modified the requirements regarding nondestructive examination of the penetration nozzles and requires that, within 60 days after returning a unit to operation, licensees provide a description of the inspections performed in accordance with the Order and describe any leaks or boron deposits found during the inspection.

During the Diablo Canyon Power Plant (DCPP) Unit 2 thirteenth refueling outage (2R13), completed on May 25, 2006, PG&E performed a bare metal visual inspection of 100 percent of the reactor pressure vessel (RPV) head penetrations, including 360 degrees around each of the vessel head penetration nozzles and the head vent penetration. Visual inspection of greater than 95 percent of the RPV head surface was also performed to identify any degradation. No evidence of vessel head penetration nozzle leakage or cracking, or degradation of the RPV head was identified. PG&E also performed nonvisual nondestructive volumetric examination on all 79 reactor head penetration tubes, including the head vent penetration. The examination detected no discontinuities or indications of boric acid leak paths, and no flaws needing disposition or corrective action were identified. In addition, PG&E performed a visual inspection to identify potential boric acid leaks from the pressure-retaining components above the RPV head. Minor localized dry boric acid deposits on small valve packing glands were identified and corrected. Enclosure 1 contains the 60-day response for DCPP Unit 2 (2R13) required by the first revision of NRC Order EA-03-009.

A member of the STARS (Strategic Teaming and Resource Sharing) Alliance
Callaway • Comanche Peak • Diablo Canyon • Palo Verde • South Texas Project • Wolf Creek

A101



If you have questions or require additional information, please contact Mr. Stan Ketelsen at (805) 545-4720.

Sincerely,

James R. Becker
Vice President Diablo Canyon Operations and Station Director

Why1/4279/A0665423

Enclosures

cc: Diablo Distribution
cc/enc: Edgar Bailey, DHS
Terry W. Jackson, Senior Resident Inspector
Bruce S. Mallett, Region IV
Alan B. Wang, NRR

UNITED STATES OF AMERICA
 NUCLEAR REGULATORY COMMISSION

In the Matter of PACIFIC GAS AND ELECTRIC COMPANY Diablo Canyon Power Plant Unit 2))))))	Docket No. 50-323 Facility Operating License No. DPR-82
---	----------------------------	---

AFFIDAVIT


James R. Becker, being of lawful age, first being duly sworn upon oath states that he is Vice President Diablo Canyon Operations and Station Director of Pacific Gas and Electric Company; that he has executed this response to the first revision of NRC Order EA-03-009 on behalf of said company with full power and authority to do so; that he is familiar with the content thereof; and that the facts stated therein are true and correct to the best of his knowledge, information, and belief.



James R. Becker
Vice President Diablo Canyon Operations and Station Director

Subscribed and sworn to before me on this 14th day of July, 2006, by James R. Becker, personally known to me or proved to me on the basis of satisfactory evidence to be the person who appeared before me.

Karen T. Mason
 Notary Public
 County of San Luis Obispo
 State of California



60-Day Response to NRC order EA-03-009, "Issuance of First Revised NRC Order (EA-03-009) Establishing Interim Inspection Requirements for Reactor Pressure Vessel heads at Pressurized Water Reactors"

NRC Required Information:

The first revision of NRC Order EA-03-009, dated February 20, 2004, required that, for each inspection required in Paragraph C of the Order, the Licensee shall submit a report detailing the inspection results within 60 days after returning the plant to operation. For each inspection required in Paragraph D of the Order, the Licensee shall submit a report detailing the inspection results within 60 days after returning the plant to operation if a leak or boron deposit was found during the inspection.

PG&E Response:

Diablo Canyon Power Plant (DCPP) Unit 2 has accumulated approximately 13.09 total effective degradation years prior to the Unit 2 thirteenth refueling outage (2R13). Therefore, PG&E was required to perform an inspection in accordance with NRC Order EA-03-009, Sections IV.C.(5) and IV.D.

During 2R13, which was completed on May 25, 2006, PG&E complied with Section IV.C.(5)(a) of Revision 1 of the Order by performing a bare metal visual examination of the reactor pressure vessel (RPV) head penetrations, including 360 degrees around each of the vessel head penetration nozzles and the head vent penetration. The bare metal visual inspection to identify degradation covered greater than 95 percent of the RPV head surface. The only area not covered by the bare metal visual inspection was that area inaccessible due to support structure interference. However, the inspection included those areas of the RPV head upslope and downslope from the support structure interference. No evidence of boron or corrosive product was found and no evidence of Vessel Head Penetration nozzle leakage or cracking, or degradation of the RPV head was identified.

During 2R13, PG&E also complied with Section IV.C.(5)(b)(i) of Revision 1 of the Order by performing a nonvisual nondestructive volumetric examination on all 79 reactor head penetration tubes (RHPT), including the head vent penetration. A combination of ultrasonic and eddy current testing methods was used with probes delivered to the tubes by a remote positioning device (or manually in the case of the head vent tube). The inspection encountered limitations to the Order's specified examination areas in some of the RHPTs due to the large as-built configuration of the J-welds, the chamfer at the end of the tubes, and the geometry of the transducers on the examination probes. The inspection coverage above the J-groove satisfies the order requirements for all penetrations. The inspection coverage below the J-groove weld on the downhill

side of the penetrations was achieved for all locations examined using the open housing tool and some of the penetrations examined with the gap scanner tool. In all cases, the examination coverage exceeded the 0.3" minimum criteria established by NRC approval for relaxation from the requirements of Section IV.C.(5)(b) of Revision 1 of the Order for DCP Unit 2, as stated in the April 21, 2006 Letter, "Diablo Canyon Power Plant, Unit No. 2 – Relaxation of Requirements Associated with First Revised Order (EA-03-009) dated February 20, 2004, Regarding Alternate Examination Coverage for Reactor Pressure Vessel Head Penetration Nozzles (TAC No.MD0024)." The examinations detected no discontinuities or indications of boric acid leak paths, no flaws needing disposition, and no corrective actions were identified.

Finally, during 2R13, PG&E complied with Section IV.D of Revision 1 of the Order by performing a visual inspection to identify potential boric acid leaks from pressure-retaining components above the RPV head. Minor dry boric acid accumulations were identified on three small reactor coolant system valves located above the head. In each case, the deposit originated from the valve packing gland area and did not affect local components or the reactor head. Maintenance was performed on all three valves during the outage to remedy the cause of leakage.