

INDIANA MICHIGAN POWER*

A unit of American Electric Power

August 2, 2006

Indiana Michigan Power Cook Nuclear Plant One Cook Place Bridgman, MI 49106 AEP.com

AEP:NRC:2573-33 10 CFR 50.73 10 CFR 50.4

Docket No. 50-316

U. S. Nuclear Regulatory Commission Attn: Document Control Desk Mail Stop O-P1-17 Washington, DC 20555-0001

Donald C. Cook Nuclear Plant Unit 2 LICENSEE EVENT REPORT 316/2006-005-00 FAILURE TO COMPLY WITH TECHNICAL SPECIFICATION SURVEILLANCE REQUIREMENT 3.6.1.1

In accordance with the criteria established by 10 CFR 50.73 entitled Licensee Event Report System, the following report is being submitted:

LER 316/2006-005-00: "Failure to Comply with Technical Specification Surveillance Requirement 3.6.1.1"

There are no commitments contained in this submittal.

Should you have any questions, please contact Ms. Susan D. Simpson, Regulatory Affairs Manager, at (269) 466-2428.

Sincerely,

Kaurener Juseben

Lawrence J. Weber Plant Manager

HLE/rdw

Attachment



AEP:NRC:2573-33

U. S. Nuclear Regulatory Commission Page 2

c: J. L. Caldwell, NRC Region III
K. D. Curry – AEP Ft. Wayne, w/o attachment
J. T. King, MPSC – w/o attachment
MDEQ – WHMD/RPMWS – w/o attachment
NRC Resident Inspector
P. S. Tam, NRC Washington DC

	266									NO 2150	040/		EV		612012007
INRC Form 366 U.S. NUCLEAR REGULATORY COMMISS (6-2004)					SION	Estimated burden per response to comply with this mandatory collection request: 50 hours									
						Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555- 0001, or by internet e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104). Office of Management and									
(See reverse for required number of digits/characters for each block)						Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.									
1. FACILITY NAME						1	2. DO	CKET NU	MBER		3. PAGE				
Donald C. Cook Nuclear Plant Unit 2						05000-316				1 of 3					
4. TITLE															
Failure to Comply with Technical Specification Surveillance Requirement 3.6.1.1															
5. E	VENT D	ATE		6. LER NUMBER				7. REPORT DATE 8. OT				HER FACILITIES INVOLVED			
MONTH	DAY	YEAR		SEQUENTIAL NUMBER	REVISION		итн	DAY	YEAR	FACILITY			DOCK	DOCKET NUMBER	
04	40	2006	2006		00		。	02	2006	FACILITY	Y NA	ME	DOCK	ETN	UMBER
	IU	2000	2008	005 -	- 00		0		2000						
9. OPEr	ATING	MODE		11. THIS REPO	ORT IS SUBMIT	TED I	PURS	UANT TO	THE RE	QUIREMENT	's o	F 10 CFF	S: (Che	ck all	that apply)
	8.4.4	do 6		20.2201(b) 20.220			03(a)(3	3(a)(3)(i) 50.73(a)(2)(i)(C)				50.73(a)(2)(vii)			
	IVIC						J3(a)(.	$(a)(3)(1)$ \Box 50.73(a)(2)(1)(A))	□ 50.73(a)(2)(viii)(A)			(A) (D)
				□ 20.2203(a)(1) □ 20.220			US(8)(* (a)(1)(i	4) $\Box 50.73(a)(2)(ii)(B)$,	□ 50.73(a)(2)(viii)(B)			(D) (A)
10. POV	/ER LE\	/EL		\Box 20.2203(a)(2		50.30	(c)(1)(1)(A) = 50.73(a)(2)(11) = 50.73(a)(2)(11) = 50.73(a)(2)(11)(A) = 50.73(a)(11)(A)				50.73(a)().73(a)(2)(IX)(A)) 73(a)(2)(v)			
								(1)(1)(X) = 0.73(a)(2)(1)(X)			v N	\Box 73 71(a)(4)			
	(0%		\Box 20.2203(a)(2)(iii) \Box 50.36(c)(iii) \Box 50.46(a)				$\frac{1}{2} = \frac{1}{2} = \frac{1}$							
				\square 20.2203(a)(2	$\Box 20.2203(a)(2)(y) \qquad \Box 50.73(a)(2)(y)(A) \qquad \Box 50.73(a)(2)(y)(C) \qquad \Box OTHER$					DTHER	-,				
$\Box 20.2203(a)(2)(v)$)(vi) 🖂	50.73(0.73(a)(2)(i)(B) 50.73(a)(2)(v)(D)				,)	Specify in Abstract below or in NRC Form 366A			
12. LICENSEE CONTACT FOR THIS LER															
	Y NAMI	3						•			LEP	HUNEN	JMBER (Includ	Area Code)
			Susan S	impson, Regu	atory Affairs	Man	nager					(269	9) 466-2	2428	
ļ		r	13. COM	PLETE ONE LINE	FOR EACH C	OMPO	ONEN	T FAILUI	RE DESC	RIBED IN TH	IS R	REPORT		-,	
CAUSE	SYST			MANUFACTURER	REPORTABLE TO EPIX	_	CAL		SYSTEM	COMPONEN			MANUFACTURER		ORTABLE TO EPIX
14. SUPPLEM			JPPLEME	ENTAL REPORT EXPECTED					15. EXPECTED			MONT	H D	<u>AY</u>	YEAR
Y	ES (If Y	'es, comple	ete EXPE	CTED SUBMISSION DATE). X			NO SUBMISSION DATE								
ABSTR	ACT (Lin	nit to 1400 s	paces, i.e.,	approximately 15 sir	igle-spaced typev	vritten I	lines)	1					1		1
On Ar	oril 10	2006	2-SI-18	9. FCCS Safe	etv Valves I	Disch	hard	e Heac	ler To F	Pressurize	r R	elief Ta	ank Co	ntai	nment
Isolati	on Ch	eck Val	ve. had	a required s	urveillance	inter	nali	nspect	ion per	formed or	n it t	that po	tentiall	v aff	ected
the va	lve's l	eak tiar	ntness r	prior to perfor	mina the re	auire	ed as	s-found	B&C t	vpe leak r	ate	test.	This re	sulte	ed in
being	unabl	e to me	et the T	echnical Spe	cification S	urve	illan	ce Rec	uireme	nt (SR) 3	6.1	1.1 to p	erform	the	
as-fou	ind B&	C type	leak ra	te test.					•	· · /		•			
The cause of performing the required surveillance internal inspection prior to a required as-found leak rate test															
was a weakened barrier in that the work activity instructions did not require verification of completion of the															
as-found leak rate test prior to beginning the internal inspection.															
Corrective Actions taken were performance of an acceptable as-left leak rate test following the internal															
inspection, and revising the valve's surveillance internal inspection work activity to verify completion of the															
recurring work activities for Appendix J components that potentially affect a valve's leak tightness to require a															
verification of completion of the as-found B&C type leak rate test prior to performing an activity.															

This event is reportable in accordance with 10 CFR 50.73(a)(2)(i)(B), due to being unable to meet SR 3.6.1.1. NRC FORM 366 (6-2004)

U.S. NUCLEAR REGULATORY COMMISSION

NRC FORM 366A

(1-2001)

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET		3. PAGE			
Donald C. Cook Nuclear Plant Unit #	0500031	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 of 3	
		2006	- 005	00	20.0	

17. NARRATIVE (If more space is required, use additional copies of NRC Form (366A)

Conditions Prior to Event

Unit 2 was in refueling outage U2C16, in Mode 6.

Description of Event

On April 10, 2006, 2-SI-189, ECCS Safety Valves Discharge Header To Pressurizer Relief Tank Containment Isolation Check Valve [ISV], had a required surveillance inspection performed on it that potentially affected the valve's leak tightness prior to performing the required as-found leak rate test. This resulted in being unable to meet the Technical Specification Surveillance Requirement (SR) 3.6.1.1 for Containment. SR 3.6.1.1 requires that leakage rate testing be performed in accordance with the Containment Leakage Rate Testing Program. Donald C. Cook Nuclear Plant's Containment Leakage Rate Testing Program specifies as-found testing prior to performing maintenance, repairs, or inspections that could reduce containment leakage integrity.

Valve 2-SI-189, ECCS Safety Valves Discharge Header To Pressurizer Relief Tank Containment Isolation Check Valve, was disassembled per Job Order Activity (JOA) R0267698-04 and an internal visual inspection performed per JOA R0267698-03 prior to performance of the required as-found type B&C leak rate test. The scheduling for these activities was correct and the appropriate logic ties were in the schedule.

This event is reportable in accordance with 10 CFR 50.73(a)(2)(i)(B), due to being unable to meet SR 3.6.1.1. This event occurred, and was identified, on April 10, 2006. The non-compliance with the Appendix J program requirements was identified on April 12, 2006. The initial review for applicability to 10 CFR 50.73 reporting requirements determined that the event was not required to be reported. Subsequent review and discussion between the plant staff and the Nuclear Regulatory Commission determined, after the 60-day time frame had expired, that the event was required to be reported. Therefore, this Licensee Event Report (LER) is being submitted greater than 60 days after the event.

Cause of Event

The cause of performing the required surveillance internal inspection prior to a required as-found leak rate test was a weakened barrier in that the work activity instructions did not require verification of completion of the as-found leak rate test prior to beginning the internal inspection.

Analysis of Event

The valve disassembly activities performed on 2-SI-189 on April 10, 2006, were for a required surveillance internal inspection. There were no outstanding corrective maintenance activities for 2-SI-189 nor was the valve leakage integrity suspect. Additionally, 2-SI-189 is not on an extended surveillance frequency under the Appendix J program as other more restrictive surveillance requirements outside of the Appendix J program require this valve to be disassembled and inspected on a refueling outage frequency.

U.S. NUCLEAR REGULATORY COMMISSION

NRC FORM 366A (1-2001)

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET		6. LER NUMBER			
Donald C. Cook Nuclear Plant Linit #	0500031	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3 of 3	
		2006	- 005	00	0010	

17. NARRATIVE (If more space is required, use additional copies of NRC Form (366A)

Prior to the valve disassembly activities performed on 2-SI-189 on April 10, 2006, the as-left B&C test performed during the previous Unit 2 refueling outage (October 19, 2004) was satisfactory. No maintenance was performed on 2-SI-189 between the satisfactory test on October 19, 2004 and April 10, 2006. Additionally, no flow is expected past this valve during the operating cycle and a review of station Condition Reports between October 2004 and April 2006 did not identify any instances where there was flow past this valve. Thus, it can be concluded that the valve remained in the closed seated position from the satisfactory October 2004 as-left B&C test throughout the last operating cycle.

2-SI-189 is a containment isolation check valve that provides a one-way flow path from Residual Heat Removal [BP] safety valve 2-SV-104W [RV] to the Pressurizer Relief Tank [TK]. Failure of this valve does not contribute to core damage frequency, and additional component failures would be required for the failure to contribute to large early release frequency, which would still be well below 1.0 E-8. Therefore, this event was not risk significant.

Corrective Actions

100

Corrective Actions taken were performance of an acceptable as-left leak rate test following internal inspection of 2-SI-189, and revising the surveillance internal inspection work activity for 2-SI-189 to verify completion of the as-found test prior to performing valve disassembly.

Corrective Actions to be taken include revising all recurring work activities for Appendix J components that potentially affect a valve's leak tightness to require a verification of completion of the as-found B&C type leak rate test prior to performing an activity.

Previous Similar Events

A review was conducted of station Condition Reports and LERs for the previous 3 years. No similar events were identified.